



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19014173/Qsf3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 01-07-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3859U	Veh. Inspected	SMJ 4873P
Policy No.		Coverage (\$)	0.00
Claim No.	D19005182MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	14/08/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE HYBRID 1.5	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GP72003987	Colour	RED
Odometer	62322	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/08/2019	Inspection Date	18/03/2020
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------