ASS. REC. BY:	(S/TP 19014183/ ky f352)
/ IF MARTA	ASSIGNMENT
From: Date:	
Estimated Cost:	Veh No: STS 253 7 LYr Regn: OP, 09
OD TP I WS I TP RES I OD RES I EVA I INV I MY	Type: M/Car/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
at Workshop m/s Vvci Luc	Make: lay Vios c.c 18PZ
of	- Colour M. 13/Get AC: Insured Cold Line
Insured:	Sp.Reading 25058 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: MR 053114 9365123210
Sum Insured: Excess:	Och. Cond. Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Control Leaked Burnt or
	JUANKIM OF
(Policy Condition)	Tyre Size: F: 185/60R15
Remark: The veh had commenced its N/S O/S	Α
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO (YOKO or
Bal, or Market Value:	Eroni Eroni
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 2 Rear
GIA / PR Seen: Consistent?: Yes or No	L/Bail, 2 mm R/Bail, 3 mm
Est. Repairs: // days Res.: Yes or No	D.O.A. 79/5/10
Lum Sum: 26 % 3 Val.: Yes or No	Survey held at 0.0.1. 3/6/19
CA / REV / REP. / 24 HRS	
Date:Person Contacted: Vehicle: IN / OUT	Des. of Damages : Frt Rear I O/S / N/S / U/C / Rooftop or
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
- 1 Fix pars To	overtire affected due to collision.
SJS 3537 L - (S/J(S 17000 269/KV h 302	D. A.
13211 2/04D- CS/SPE/70/03/22/ 60	- // / / / / /
Confirm L/s \$6350-00	(Red 3934-02, 38%)
RECEIVED 0 5	SEP 2019
Onte/Ture, File Pass to?	
Prell. Report	ays Of Repair:
11 11 11 - 1 -	PSURVEY No. of Trin:
2 clala -	Survey Fee: 170
Add Fee:	Site Insn (\$
Report Format :	Interview (s
Lump Sum / I.B.I: (S	Tech Inve (\$
	Weekend (\$
4/5 \$6350-00	
	107AL 378

- Police sketch plan & keys
- Police investigation result show our insured at fault 4.
- 5. Your client's owner and driver I/C and driving licence
- 6. Insurance policy cover at the material time of accident
- 7. Registration card (front & back updated)/VOC
- Police photos/ scene accident photos all vehicles
- 9. Original adjuster report, bill and receipt
- 10, Original adjuster photo with clear of chassis number and odometer reading color photo
- After repair photos color photo

Thanks & Regards,

Hamiza Rinti Mohamad

Claims Executive - Third Party

BERJAYA~SOMPO Insurance Berhad

1-38-1 & 1-38-2, Menara Bangkok Bank, Laman Sentral Berjaya, No. 105, Jalan Ampang, 50450 Kuala Lumpur

Tel: 03- 2170 7300 EXT 6098

Fax: 03-2170 4905 / 03-2170 4906

[Quoted text hidden]

E-mail and any files transmitted with it are confidential and are intended solely for the use of the addressee. This communication represents the sender's personal views and opinions, which do not necessarily reflect those of Berjaya Sompo Insurance Berhad (62605-U). If you are not the intended recipient or the person responsible for delivering the e-mail to the intended recipient, please be advised that you have received this e-mail by error and that any use, dissemination, forwarding, printing or copying of this email is unauthorized. Kindly immediately notify info@bsompo.com.my.

This message (including any attachments) is intended only for the use of the individual or entity to which it is addressed and may contain information that is non-public, proprietary, privileged, confidential, and exempt from disclosure under applicable law or may constitute as attorney work product. If you are not the intended recipient, you are hereby notified that any use, dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, notify us immediately by telephone and (i) destroy this message if a facsimile or (ii) delete this message immediately if this is an electronic communication. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for Investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report

25/05/2019 12:22

Date Of Accident

24/05/2019 18:00

Exact Location Of Accident

ALONG PIE BEFORE ENG NEO EXIT

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SJS2537L

Insured/Policyholder

Name Of Registered Owner

KH LEASING PTE. LTD.

Co Reg No

201611813C

Email Address

NOEMAIL

Mobile Phone No

Alternative Phone No.

OFFICE-90910899

Vehicle Particulars

Manufacturer

TOYOTA VIOS

Model

Exact Purpose for which vehicle was being used at time of accident

WORK PURPOSE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

THIRD PARTY

Fleet Policy

NO

Policy Number

5103235011

Cover Note Number

Driver

Name of Driver

KOH KIN SIAH @TAN KIN SIAH

NRIC No

S1259291D

Date Of Birth

12/08/1957

Occupation

OUTDOOR

Date Of Driving Pass

22/07/1977

Driving Experience

41 YEARS AND 10 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-90910899

Fax Number

Contact Number

Name of Driver

LOO CHEE SOING

NRIC/Passport Number

F8418775P

Contact Number

91313113

Address

Postcode

Insurance Company Name

Nature Of Damage

REFER POLICE REPORT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLM3104D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NA

NRIC/Passport Number

Contact Number

NA

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

KOH KIN SIAH @TAN KIN SIAH

Service and posts

Approximate Age

Injuries Sustain

NECK AND BACK

Injured person in which vehicle?

SJS2537L

Were seat belts worn?

Was this injured conveyed to hospital by

NO

ambulance?

BLK 436 ANG MO KIO AVE 10

Address

#04-1351

Postcode

560436

Address

BLK 436 ANG MO KIO AVE 10

#10-1351

Postcode

560436

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

JGC7684 (COMMERCIAL VEHICLE)

Number of vehicles (including own vehicle)

involved in the accident

3

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: NA

assenger i

GENDER:

: MALE

Passenger 2

NAME:

: NA

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

BUKIT PANJANG

Police Station Address

ROAD: 1 SEGAR ROAD , POSTCODE: 677738 , COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-8929999 - FAX NO:

Was notice of intended Prosecution given?

If Yes,against whom?

NO

Circumstances of Accident

REFER POLICE REPORT AND ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

JGC7684

Vehicle Make/Model/Colour

Details Of Properties

SKETCH PLAN		
	l (c)	
and the second s		
		A-87252237 L
		B - JGC7684
	1 1 1 1 1 1 1 1 1	1 B 2810-10-1
	and a second of the second of the second of	1 - SLM3104D
1	- 1	1 - 2 - 321 (31040
- Se		and the same of the same
A		
1	1 L. C. 2 1 1 1 1 1 2	
DESCRIBE CIRCUMSTANCES O	F THE ACCIDENT	
Refer Police Re		
Rufer Police Ke	DOCK.	
L. Control		
time of the second		
	20	8.
		(A)
	9	
DECLARATION		
I/We declare the Corllegon particular	lars are true in every respect.	1
(0)	VC A-//	1 locart
(2018118130)	1316	4000
		(
Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder)	Reporting Centre Personnel' Signature
Water Market	Date & Time:	Name: NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation,
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Deatre Personnel's Signature

Name:

NRIC/FIN No.

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:

SJ52537L

Vehicle Type:

N18 - Passenger (Co) Company Car (Single Rate)

Vehicle Attachment 1:

No Attachment

Vehicle Scheme:

Normal

Vehicle Make:

TOYOTA

Vehicle Model:

VIOS E AUTO

Chassis No.:

MR053HY9305123210

Propellant:

Petrol

Engine No.:

1NZX943265

Engine Capacity:

1497 cc

Maximum Power Output :

80.0 kW (107 bhp)

Maximum Laden Weight:

1505 kg

Unladen Weight:

1095 kg

Year Of Manufacture:

2009

Original Registration Date :

06 Aug 2009

Lifespan Expiry Date:

COE Category:

A - Car (1600cc & below)

PQP Paid:

\$14,664.00

COE Expiry Date:

05 Aug 2024

Road Tax Expiry Date:

05 Feb 2020

Inspection Due Date:

05 Aug 2020 31 Aug 2019

Intended Transfer Date:

CO2 Emission:

CO Emission:

HC Emission:

NOx Emission: PM Emission:

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable. Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

Total Amount Payable:

Amount Before GST GST Amount Amount After GST (\$\$) (5\$) (5\$) 25.00 25.00

25.00

Message

Transfer Fee:

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire P.	ARF/COE	Rebate f	for Registered	Vehicle
------------	---------	----------	----------------	---------

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1813C
Vehicle Details	
Vehicle No.:	SJS2537L
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOSEAUTO
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	1NZX943265
Chassis No.:	MR053HY9305123210
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,717.00
Original Registration Date:	06 Aug 2009
First Registration Date:	06 Aug 2009
Transfer Count:	1
Actual ARF Paid:	\$12,717.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Aug 2019
PARF Rebate Amount: Intended COE Rebate Details	\$6,358.00
COE Expiry Date:	05 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,310.00
COE Rebate Amount:	\$242.00
Total Rebate Amount:	\$6,600.00

The information contained herein is correct as at 04 Jun 2019

OK

盛 刻 摩 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: welleemotorworks@gmail.com Not Norharke USy &? Rusmy Ash Pains

Business Regn No: 269436/00J

29, May 2019

KH Leasing Pte Ltd

Accident involving vehicle no: SJS2537L/JGC7684/SLM3104D

DOA: 24/05/2019 AT Along PIE before Eng Neo Exit

RE: Estimate cost of repair for vehicle no: SJS2537L

To supply—

Description			C	lty		Amount		
Rear bumper		3.	1	12	7	431.90		
Rear bumper side retainer	@98.5	50	2	4	21	197.00	_	
Rear bumper retainer-small	@33.2	20	2		01	66.40		
Rear bumper foglamp	@87.7	0	2	NISIM		175.40	4	
Rear bumper damper	@67.4	10	2		Sn	134.80	8	
Rear bumper clip				/	u	38.00	<u> </u>	
End panel		3.0	1	(U	12,	608.00	_	
End panel top garnish	*	(- -)	1		nd	213.50	7	10
Spare tyre panel			1			673.60	R	
Fender,Rh & Lh	@899	9.60	2	ols Bu		1,799.20	4	
Spare tyre board			1	ß	4	121.60	X	12 92.35 5N
Boot weatherstrip			1	Pil	ms	184.70	306	10 92.35 2N
Lid	. "		1	Y:	3er	556.20		
Lid lock			1	F	The	102.00	_	
Lid-TOYOTA logo			1	/	Re	50.20	_	
Lid-Vios emblem	*		1	,	2h	47.00		25
Lid handle			1		do	277.80		
Taillamp	@32	8	2	(ins	656.00	_	
Taillamp clip	@16		2 -	,	m	32.00		
Taillamp gasket	@26	0	2		ne	52.00		
Front support panel			1.		1	427.90	K	
Front bumper enforcement			1	5 3	1	268.60	7	
Bonnet lock		,	1		n	87.60	*	
Headlamp	@42	7.80	. 2	dls cm	•	855.60	2	A .
Front bumper	¥1		1	-13	in	482.20	~	
Front bumper retainer	@52		2		219	104.00		
Front grille			1		m	172.30		*
Front bumper lower grille			1	C.	ns	123.20		
Parts						8,938.70		
Parts less 25%		The southern March of the second	-			2,234.68	5)	
		LKK Auto Cor		nts hence notify		6,704.03		
		the Repairer of	pr-me i	ollowing:				

- · To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

To remove/reinstall rear windscreen glass.

To remove rear seater cushion,inner garnish enable repair job carryout.

Reinstall after job done.

To remove/replace radiator,condenser,fan assemble. Recharge air con gas.

To remove damaged parts and attachments,front n rear.

Cut n weld damaged panel,fender.

Straighten chassis frames where necessary.

Replace/align all parts into position.

To spray paint

1,300.00

1,650.00

10,284.02



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internati	onale Des Experts En Autom	obile	
WE	LEE MOTOR WO	RKS	Ref : CS/TP19014183	3/Kyf3s2	
	OCK 9 SIN MING IN	IDUSTRIAL ESTATE #01-32	Date: 05-09-2019		
ON	BEHALF OF KH LI	EASING PTE. LTD.	Code: TP389		
1.		Policy Particulars	:- THIRD PARTY CLAIR	И	
	Insured Veh.		Veh. Inspected	SJS 2537L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From		Assign Date	03/06/2019	
2.		Vehicle Part	iculars & Condition		
1100	Make & Model	TOYOTA VIOS (A)	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	MR053HY9305123210	Colour	METALLIC BLACK	
	Odometer	250586	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.		Condit	ions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	185/60 R15	YOKOHAMA	2 mm	
	L/H Front Tyre	185/60 R15	YOKOHAMA	2 mm	
	R/H Rear Tyre	185/60 R15	YOKOHAMA	3 mm	
	L/H Rear Tyre	185/60 R15	YOKOHAMA	3 mm	
4.		Descripti	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE RE ETAILS.	AR AND FRONT PORTION		
5.			al Information		
	Accident Date	24/05/2019	Inspection Date	03/06/2019	
	Survey held at	WEI LEE MOTOR WORKS	***************************************		
	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.				
5a.	5a. Remarks				
	A)THE INSPECTION B)IN ACCORDANCE	ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W	THOUT PREJUDICE" BASIS /E HAVE NOT AUTHORISE	S. D REPAIRS.	
5b.		Estimate	Days of Repair		
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	16 Working Day	rs	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 2537L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BENT	431.90	431.90
2	REAR BUMPER SIDE RETAINER @ \$98.50	CRACKED	197.00	197.00
2	REAR BUMPER RETAINER - SMALL @ \$33.20	DISTORTED	66.40	66.40
2	REAR BUMPER FOGLAMP @ \$87.70	N/S CRACKED	175.40	87.70
2	REAR BUMPER DAMPER @ \$67.40	SERVICEABLE	134.80	e-
1	REAR BUMPER CLIP	NECESSARY	38.00	38.00
1	END PANEL	BENT	608.00	608.00
1	END PANEL TOP GARNISH	DENTED	213.50	213.50
1	SPARE TYRE PANEL	BENT	673.60	673.60
2	FENDER, RH & LH @ \$899.60	O/S BUCKLED	1,799.20	899.60
1	SPARE TYRE BOARD	SERVICEABLE	121.60	-
1	LID	BUCKLED	556.20	556.20
1	LID LOCK	JAMMED	102.00	102.00
1	LID - TOYOTA LOGO	NECESSARY	50.20	50.20
1	LID - VIOS EMBLEM	NECESSARY	47.00	47.00
1	LID HANDLE	WARPED	277.80	277.80
2	TAILLAMP @ \$328.00	CRACKED	656.00	656.00
2	TAILLAMP CLIP @ \$16.00	NECESSARY	32.00	32.00
2	TAILLAMP GASKET @ \$26.00	NECESSARY	52.00	52.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	427.90	19 -
1	FRONT BUMPER ENFORCEMENT	TO REPAIR SEE LABOUR	268.60	110
1	BONNET LOCK	TO REPAIR SEE LABOUR	87.60	0=
2	HEADLAMP @ \$427.80	O/S CRACKED	855.60	427.80
1	FRONT BUMPER	BUCKLED	482.20	482.20
2	FRONT BUMPER RETAINER @ \$52.00	DISTORTED	104.00	104.00
1	FRONT GRILLE	CRACKED	172.30	172.30
1	FRONT BUMPER LOWER GRILLE	CRACKED	123.20	123.20
	LESS 25% DISCOUNT	7	-2,188.50	-1,574.60
	χ.		6,565.50	4,723.80
1	BOOT WEATHERSTRIP (50%) (SN)	DISTORTED / DENTED	184.70	92.35

Report Ref No. CS/TP19014183/Kyf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-46.18	-
			138.52	92.35
	LABOUR			
	TO REMOVE / REINSTALL REAR WINDSCREEN GLASS.		160.00	120.00
	TO REMOVE REAR SEATER CUSHION, INNER GARNISH ENABLE REPAIR JOB CARRYOUT. REINSTALL AFTER JOB DONE.		220.00	120.00
	TO REMOVE / REPLACE RADIATOR, CONDENSER, FAN ASSEMBLE. RECHARGE AIR CON GAS.	NOT NECESSARY	250.00	-
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS, FRONT AND REAR. CUT AND WELD DAMAGED PANEL, FENDER. STRAIGHTEN CHASSIS FRAME WHERE NECESSARY. REPLACE / ALIGN ALL PARTS INTO POSITION. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL, FRONT BUMPER ENFORCEMENT AND BONNET LOCK.		1,300.00	1,300.00
	TO SPRAY PAINT.		1,650.00	1,600.00
	*		3,580.00	3,140.00
	GRAND TOTAL		10,284.02	7,956.15
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,350.00

Report Ref No. CS/TP19014183/Kyf3s2

KONG SENG CHEONG

Licensed Appraiser