

ASS. REC. BY:

REF: CS/C72 19014189/K9 f 302 Special Instruction:

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of 671

Date/Time: 15.8.19 10:44am

Estimated Cost: _____ Bill to: _____

Bill to:

$$OD \left(TP / WS / TP \text{ RES} / OD \text{ RES} / EVA / INV / MV / CS \right)$$

To inspect Vehicle No: **SGA 9802E**

Insured: GBB 15904

at Workshop m/s Lai Huat

Tel: 64533110

of 160 sin ming Drive #04-01

Policy No: DM CVS N 15574919033

Claim No: SNM 19D 203765102

Sum Insured:

Excess

Make of Veh:
(Client's Record)

D.O.A. 13.3.19

CA / REV / REP. / REV 24 HRS

H.O.D. www.hod.com.tr

Date/Time: 15.8.19 11.11 a.m

Person Contacted

Jenny

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	S&A 9822E - NAT INV (190142) 1/14
	GBB 150704 - X
9/12	④ 4062-13 Confirmed
11/12/19	The repair cost should be from Fig ④ 4057-93 instead of CRD ④ 0.73, 0'1.) already informed Dennis & she agreed

ASSIGNMENT

From: Date: 15.8.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGA 9802E

at Workshop n/s: Lai Huat

at 160 Sin Ming Drive #04-01

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1-3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGA 9802E Yr Regn: 05 / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 C.C. 1496

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 92229 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN 63M 42A 840310353

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 13/8/19 D.O.I. 15/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

11/12/2019

RECEIVED 12 DEC 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 12/12 1919

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS, ☐ SI

☐ Photos

☐ Others

☐

TOTAL:

Report Format: MER-TP

Lump Sum / I.B.I. (\$) 4057.93

270

270

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Aug 2019 Sendback Est	15 Aug 2019 10:09 S\$3,592.66	15 Aug 2019 10:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	LOCHERS TRADING, Co. Reg. No.: 42244400J		
Main Claimant:	LOH SIOW NEE, ID: S7619891H		
Vehicle Reg. No.:	SGA9802E	Date of Loss:	13/08/2019 08:00 - :59 [50 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D203765C02	Policy/Cover Note No.:	DMCVSN15574919033
Vehicle Reg. No. (Insured):	GBB1590Y	Policy No. (Claimant):	A 29124166 QMX
		Excess:	S\$0.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/08/2019]		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/08/2019 14:34
Date Of Accident	13/08/2019 08:45
Exact Location Of Accident	PIONEER ROAD TOWARDS TUAS VIADUCT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGA9802E
Insured/Policyholder	
Name Of Registered Owner	LOH SIOW NEE
NRIC No	S7619891H
Email Address	CLOHSN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90110852
Alternative Phone No	OTHERS-90110852

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 L 4-DOOR SEDAN SP.6EAT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29124166 QMX
Cover Note Number	

Driver

Name of Driver	LOH CHION YAU
NRIC No	S2080159Z
Date Of Birth	10/11/1951
Occupation	OUTDOOR
Date Of Driving Pass	06/08/1974
Driving Experience	45 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96347084
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 409 BUKIT BATOK WEST AVENUE 4 #10-164
Postcode	650409
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB1590Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LOKE
NRIC/Passport Number	
Contact Number	96386480
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SME9048Z
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

KIM

NRIC/Passport Number

Contact Number

96162813

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to report to the police process.
2. This report must be **completed by the Policyholder and/or the Authorized Driver**
3. Information provided must be **truthful and accurate as possible**. Any false report is considered a criminal offence of mischief. Such may also incurring a criminal offence of **negligence policy liability**.
4. The insured and subscribers of this form are responsible and accountable for the accuracy of the information provided.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Insurance Management system established by the General Insurance Association of Singapore (GIA) for nothing and that copies of this report will be a file in a database system applicable to interested parties.
7. In the judgment of this report for the accident, you hereby consent to the forwarding of this report to the centre and to copies of this report being made available elsewhere.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data (personal information set out in this form) and my other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all relevant authorities (including all relevant agencies involved in the accident claim process) and those agencies who are involved in this accident may be subsequently referred to as the "Users", the Singapore Police, the Ministry of Defence, the Ministry of Home Affairs and any relevant government agency authority (such as the police), for the purposes of:
 - (i) collecting, handling and/or dealing with my claims including the settlement of the claims and any necessary expenses related to the claims;
 - (ii) investigating the accident and for my claims;
 - (iii) carrying out and/or dealing with my claims and/or responding to my enquiries for me;
 - (iv) administering my claims including the handling of my enquiries, statements, reports, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the service and/or the external cover of my claims (such as my claims); and/or
 - (v) complying with any other law that may require, processing, handling and/or dealing with my claims and/or for the "Purposes".
- (b) My insurer, my workshop and/or my insurer may be permitted to collect, use, disclose and/or process my personal information for the purposes of the above purposes and
- (c) My personal information may be collected, used, disclosed and/or processed by my insurer, my workshop and/or my insurer for the purposes of the above purposes and
- (d) My personal information will also be collected and used for other purposes for the purposes of handling my claims, investigation and management of my claims and/or for the purposes of the above purposes.
- (e) The information collected under this form is for the purposes of:
 - (i) in all cases, to assist my insurer, my workshop and/or my insurer in handling my claims, investigation, handling my enquiries, reports, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the service and/or the external cover of my claims (such as my claims); and/or
 - (ii) for complying with any other law that may require, processing, handling and/or dealing with my claims and/or for the "Purposes".

Policyholder's Signature
Date & Time:

13 AUG 2019

Authorized Driver's Signature
Date & Time:

13 AUG 2019

Resulting Insured Person's Signature
Name:

DATE/TIME: 13 AUG 2019

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13 August 2019 at around 8:00am, I was travelling along Pioneer Road going towards Tuas Viaduct. As I was driving on Tuas Viaduct, vehicle 9ME 90482 in front of me suddenly braked. I quickly braked my vehicle 3CA 2612 and stopped within + hitting vehicle 9ME 90482. Suddenly from behind, vehicle (G8B 1590) hit me and my car moved forward and hit vehicle 9ME 90482. Vehicle G8B 1590 hit the back of my vehicle 3CA 2612 on the left side of my vehicle as the driver claimed that he tried to swerve to avoid direct impact. Hence my vehicle was hit from the back on the left side by G8B 1590. The impact caused my vehicle to move forward and hit the vehicle in front (9ME 90482). All 3 vehicles were travelling on the 1st lane of Tuas Viaduct.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Police Officer's Signature
Date & Time: 13/8/19 2:30pm

Driver's Signature
(If driver is not the policyholder)
Date & Time: 13/8/19 2:30pm

Reporting Officer/Personnel's Signature
Name: Jimmy Lim
NRIC No: 305272736

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
 Individual Ownership

MOTOR MAX
Comprehensive

Certificate No. A 29124166 QMX

Excess : SGD500
 Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
 SGA9802E

2. Name of Policyholder
 Loh Siow Nee

3. Effective Date of the Commencement of Insurance for the purposes of the Act
 15/05/2019

4. Date of Expiry of Insurance
 14/05/2020

5. Persons or Classes of Persons entitled to drive*

Loh Siow Nee

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
 The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG
 AUTHORISED WORKSHOP LISTED IN THE ATTACHED.**

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers


 for Chief Executive Officer

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 891H

Vehicle Details

Vehicle No.: SGA9802E
Vehicle to be Exported: Yes
Intended Deregistration Date: 13 Aug 2019
Vehicle Make: MAZDA
Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour: Silver
Manufacturing Year: 2015
Engine No.: P520282586
Chassis No.: JM6BM42A8G0310353
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$17,431.00
Original Registration Date: 15 May 2015
First Registration Date: 15 May 2015
Transfer Count: 0
Actual ARF Paid: \$7,431.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 May 2025
PARF Rebate Amount: \$5,573.00

Intended COE Rebate Details

COE Expiry Date: 14 May 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$68,589.00
COE Rebate Amount: \$39,457.00
Total Rebate Amount: \$45,030.00

The information contained herein is correct as at 13 Aug 2019

OK

Enquire Vehicle Insurance Details

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Name
GBB1590Y	13 Aug 2019 / 08:50:00	Successful C01	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

[Previous](#)[OK](#)



Thank you

Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 13 Aug 2019, 14:31:37.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No. 	Asset Type	Asset ID	Asset Owner ID	Transaction Type
1	Vehicle	GBB1590Y	-	18.32 Insurance Enquiry (GIRO Pay
• Log Date/Time 13 Aug 2019 / 14:33:01				

Lai Huat (Meng Kee) Motor Pte Ltd

160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: TP-GBB 1590Y

Assessment number: 70778

Version: 1810

Date calculated: 15/08/2019 9:55 AM

Full Report

Registration: SGA 9802E

Printed: 15/08/2019 9:55 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GBB 1590Y	Date of Incident:	13/08/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MAZDA
Model:	3 (BM/BN)
Sub Model:	AMBITION
Model Sheet Number:	36 68 03
Registration:	SGA 9802E
VIN number:	
Odometer:	

Model Specs

FROM 03/2015	AIR CONDITIONING	GRILLE TRIM CHROMED	FOG LAMPS
REAR PARKING SYSTEM	REARVIEW CAMERA	1.5 LTR 74KW	6-SPEED GEARBOX
TYRES 205/60 VR 16	4-DOOR SALOON	TWO COAT METALLIC	PREPARE OFF VEHICLE

*Not with a
Murray Bypain
7 days*

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R FRONT NUMBER PLATE		1.0	4.20
NO NUMBER	R + R FRONT CENTRE BUMPER MOULDING		1.0	4.20
NO NUMBER	R + R FRONT BUMPER		3.0	12.60
S0204A-R-X)	RENEW RADIATOR GRILLE		5.0	21.00
NO NUMBER	RENEW REAR END PANEL (BUMPER REMOVED)		43.0	180.60
	INCLUDES: BUMPER CARRIER REMOVE AND REFIT			
NO NUMBER	RENEW L/TAILLAMP ATTACHMENT		10.0	42.00
S0206H-R-X	RENEW REAR BUMPER		6.0	25.20
	INCLUDES: RR BUMPER, BOTH OUT REARLAMPS AND ALL REQUIRED PARTS REMOVE AND REFIT			
S1218C-ZAX	R + R BOOTLID TRIM		2.0	8.40

*LIK Auto Consultants hence notify
owner of the following:*

- To return vehicle after spray painting
- To display damaged parts being repaired
- Parts prices are subject to confirmation
- Third party survey is not a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary claim is not to be processed and is subject to final approval from Insurance Company

Acknowledged by Reparer:
Signature:

Lai Huat (Meng Kee) Motor Pte Ltd

160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming

Autocity
575722

Claim Reference: TP-GBB 1590Y

Assessment number: 70778

Version: 1810

Date calculated: 15/08/2019 9:55 AM

Full Report

Registration: SGA 9802E

Printed: 15/08/2019 9:55 AM

		WU	Price SGD
T0520A-R-X)	R + R TAILGATE CAMERA	2.0	8.40
S0417X-R-X	R + R MANUFACTURER BADGE	2.0	8.40
NO NUMBER	R + R TYPE BADGE	2.0	8.40
2931	BOOTLID REPAIR	20 30.0*	126.00
3481	L/R SIDE PANEL REPAIR	15 20.0*	84.00
3901	BOOTFLOOR REPAIR	15 20.0*	84.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		14.70	147.0
Total of Labour			617.40

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR PANEL NEW PART PAINTING	19.0
	L/TAILLAMP PANEL SURFACE PAINT	4.0
	REAR BUMPER NEW PART PAINT K1R	14.0
	BOOTLID REPAIR PAINTING >50%	26.0
	L/R SIDE PANEL REPAIR PAINTING >50%	22.0
	L/R OUT PARKING SENS SURFACE PAINT PLAST.	3.0
	R/R OUT PARKING SENS SURFACE PAINT PLAST.	3.0
	L/R INN PARKING SENS SURFACE PAINT PLAST.	3.0
	R/R INN PARKING SENS SURFACE PAINT PLAST.	3.0
	R/R SIDE PANEL SURFACE PAINT	7.0
	BOOTFLOOR SURFACE PAINT	11.0

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	20.90
4193	L/TAILLAMP PANEL SURFACE PAINT	2.49
2581	REAR BUMPER NEW PART PAINT K1R	72.32
2931	BOOTLID REPAIR PAINTING >50%	37.13
3481	L/R SIDE PANEL REPAIR PAINTING >50%	28.05
2675	L/R OUT PARKING SENS SURFACE PAINT PLAST.	0.37
2676	R/R OUT PARKING SENS SURFACE PAINT PLAST.	0.37
2677	L/R INN PARKING SENS SURFACE PAINT PLAST.	0.37
2678	R/R INN PARKING SENS SURFACE PAINT PLAST.	0.37
3482	R/R SIDE PANEL SURFACE PAINT	17.68
3901	BOOTFLOOR SURFACE PAINT	35.61

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: TP-GBB 1590Y

Assessment number: 70778

Version: 1810

Date calculated: 15/08/2019 9:55 AM

Full Report

Registration: SGA 9802E

Printed: 15/08/2019 9:55 AM

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		115.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	145.0	609.00

Material Cost - Paint

	Price SGD
New Part Painting	20.90
New Part Painting - Plastic K1R	72.32
Repair Painting	65.18
Surface-/Blend Paint	55.78
Surface Painting Plastic	1.48
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	253.26

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Supplier	Price SGD	
0257	FRONT NUMBER PLATE	KNPL3		0.00	*
0349	FRT BUMPER GRILLE	BHN150712B		200.00	—
0354	FRT CTR BUMPER MLDG	BHN150717D		155.00	—
0367	CTR FRT BUMPER MLDG	B45A500S0C		15.00	2
0369	L/F BUMPER MOULDING	BJS7507K1		75.00	2
0370	R/F BUMPER MOULDING	BJS7507J1		75.00	✓
0433	MANUFACTURER BADGE	C23551731A		25.00	✓
2581	REAR BUMPER	BHR250221A8N		550.00	✓
2613	L/R BUMPER REFLECTOR	D350515L0E		30.00	✓
2640	REAR BUMPER SUPPORT	BHN150260		250.00	✓
2675	L/R OUT PARKING SENS	KD4767UC113		85.00	✓
2711	REAR PANEL	B4YA7075Z		245.00	2
3020	BADGE MODEL	BHN151721		28.00	—
3021	MANUFACTURER BADGE	BHN151730		30.00	—
4193	L/TAILLAMP PANEL	BJY77144Y		165.00	✓
4985	RR LUGG COMPART TRIM	BHN16889XA		50.00	✓
				Savings	0.00
				Subtotal	1,978.00
				Fixed Sundry Parts Price	100.00

f: OEM Parts

n: Non-OEM Parts

u: Used parts

Lai Huat (Meng Kee) Motor Pte Ltd

**160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming**

Autocity

575722

Claim Reference: TP-GBB 1590Y

Assessment number: 70778

Version: 1810

Date calculated: 15/08/2019 9:55 AM

Full Report

Registration: SGA 9802E

Printed: 15/08/2019 9:55 AM

2,078.00

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE SN	35.00
	Total Extras	35.00

Final Calculation

	SGD	SGD
Parts	1,978.00	
Fixed Sundry Parts Price	100.00	
Total Parts		2,078.00
Labour Time Base 10 WU/h		
Total 147.0 WU X 42.00 SGD/h	617.40	
Total of Labour		617.40
Total Of Extras		35.00
Paint Work Time Base 10 WU/h		
Labour Cost 145.0 WU X 42.00 SGD/h	609.00	
Material Cost	253.26	
Total Paint Including Material		862.26
Repair Cost Excludes GST		3,592.66
GST (+7.0%)		251.49
Repair Cost Included GST		3,844.15

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

4,058.66

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

Claimant Insurer: MSIG Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	70778
Policy No:		Date of Loss:	13/08/2019
Vehicle Reg. No.:	SGA9802E	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LOH CHION YAU		
Make/Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Vehicle Reg. Date:	15/05/2015
Vehicle Colour:	SILVER	Chassis No:	JM6BM42A8G0310353
Engine No:	P520282586		
Odometer:	92229 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	1,978.00
Miscellaneous Items	135.00
Labour	617.40
Paintwork Labour	862.26
Towing	0.00
Gross Total (S\$)	3,592.66
+ GST 7.00% (S\$)	251.49
Nett Amount (S\$)	3,844.15

This claim is handled by: JENNY LIM LAI FOONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 15 Aug 2019)**Parts:** 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SGA9802E/15/08/2019 10:09**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Spare Parts	0.00	0.00	*1,978.00 F ✓
Total Parts (S\$)						1,978.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SGA9802E/15/08/2019 10:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Special nett item	35.00 ✓
2	1	Sundry Parts	100.00 ✓
Sub Total (S\$)			135.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Total Paint Including Material	New 895.13	862.26
<u>Labour Items</u>			
2	Total of Labour	New 533.50	617.40
Gross Labour Cost (S\$)			1,479.66

Lai Huat (Meng Kee) Motor Pte Ltd/SGA9802E/15/08/2019 10:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
LOCHERS TRADING

Singapore

Claimant Insurer: MSIG Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	70778
Policy No:	DMCVSN15574919033	Date of Loss:	13/08/2019
Vehicle Reg. No.:	SGA9802E	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LOH CHION YAU		
Make/Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Vehicle Reg. Date:	15/05/2015
Vehicle Colour:	SILVER	Chassis No:	JM6BM42A8G0310353
Engine No:	P520282586		
Odometer:	92229 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	466.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	466.00
+ GST 7.00% (S\$)	32.62
Nett Amount (S\$)	498.62
+ Previous Estimates (S\$)	3,844.15
Claim Total (S\$)	4,342.77

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2019)**Parts:** 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SGA9802E/29/11/2019 15:23**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*UPP RAD GRILLE COVER	0.00	0.00	<i>nd</i> *160.00 F	✓
2	1		*L/F BUMPER COVER	0.00	0.00	<i>nd</i> *15.00 F	✓
3	1		*L/R COVER	0.00	0.00	<i>nd</i> *16.00 F	✓
4	1		*L/BUMPER BRACKET	0.00	0.00	<i>nd</i> *15.00 F	✓
5	1		*R/BUMPER BRACKET	0.00	0.00	<i>nd</i> *15.00 F	✓
6	1		*L/REINF EXTENSION	0.00	0.00	<i>By</i> *180.00 F	✓
7	1		*L/F WING DEFLECTOR	0.00	0.00	<i>cm</i> *65.00 F	✓
						Total Parts (S\$)	466.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SGA9802E/29/11/2019 15:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lai Huat (Meng Kee) Motor Pte Ltd/SGA9802E/29/11/2019 15:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: TP-GBB 1590Y
Repairer Reference: 70778
Date calculated: 11/12/2019 1:43 PM

Full Report
Registration: SGA 9802E
Printed: 11/12/2019 1:43 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	TP-GBB 1590Y	Date of Incident:	13/08/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle			
Manufacturer:	MAZDA		
Model:	3 (BM/BN)		
Sub Model:	AMBITION		
Model Sheet Number:	36 68 03		
Registration:	SGA 9802E		
VIN number:			
Odometer:			
Model Specs			
FROM 03/2015	AIR CONDITIONING	GRILLE TRIM CHROMED	FOG LAMPS
REAR PARKING SYSTEM	REARVIEW CAMERA	1.5 LTR 74KW	6-SPEED GEARBOX
TYRES 205/60 VR 16	4-DOOR SALOON	TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R FRONT BUMPER LEFT COVER CAP	1.0		4.20
NO NUMBER	R + R FRONT CENTRE BUMPER MOULDING	1.0		4.20
NO NUMBER	R + R FRONT BUMPER	3.0		12.60
S0204A-R-X)	RENEW RADIATOR GRILLE	5.0		21.00
NO NUMBER	R + R L/F LOWER AIR DEFLECTOR	5.0		21.00
NO NUMBER	RENEW REAR END PANEL (BUMPER REMOVED) INCLUDES: BUMPER CARRIER REMOVE AND REFIT	43.0		180.60
NO NUMBER	RENEW L/TAILLAMP ATTACHMENT	10.0		42.00
NO NUMBER	RENEW L/R WHEELHOUSE REAR REINFORCEMENT	7.0		29.40
S0206H-R-X	RENEW REAR BUMPER INCLUDES: RR BUMPER, BOTH OUT REARLAMPS AND ALL REQUIRED ATTACHED- PARTS REMOVE AND REFIT	6.0		25.20
S1218C-ZAX	R + R BOOTLID TRIM	2.0		8.40
T0520A-R-X)	R + R TAILGATE CAMERA	2.0		8.40
S0417X-R-X	R + R MANUFACTURER BADGE	2.0		8.40
NO NUMBER	R + R TYPE BADGE	2.0		8.40
2931	BOOTLID REPAIR	20.0*		84.00
3481	L/R SIDE PANEL REPAIR	15.0*		63.00
3901	BOOTFLOOR REPAIR	15.0*		63.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		13.90	139.0	583.80
Total of Labour				583.80

Paint

Paint Work		SYSTEM AZT		Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC			WU	Price SGD
	REAR PANEL NEW PART PAINTING			19.0	
	L/REINF EXTENSION SURFACE PAINT			4.0	
	L/TAILLAMP PANEL SURFACE PAINT			4.0	
	REAR BUMPER NEW PART PAINT K1R			14.0	
	L/R COVER NEW PART PAINT K1R			3.0	
	BOOTLID REPAIR PAINTING >50%			26.0	
	L/R SIDE PANEL REPAIR PAINTING >50%			22.0	
	L/R OUT PARKING SENS SURFACE PAINT PLAST.			3.0	
	R/R OUT PARKING SENS SURFACE PAINT PLAST.			3.0	
	L/R INN PARKING SENS SURFACE PAINT PLAST.			3.0	
	R/R INN PARKING SENS SURFACE PAINT PLAST.			3.0	
	R/R SIDE PANEL SURFACE PAINT			7.0	
	BOOTFLOOR SURFACE PAINT			11.0	

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	20.90
2719	L/REINF EXTENSION SURFACE PAINT	2.49

Paint Material Per Part

Code	Description	Price SGD
4193	L/TAILLAMP PANEL SURFACE PAINT	2.49
2581	REAR BUMPER NEW PART PAINT K1R	72.32
2611	L/R COVER NEW PART PAINT K1R	0.98
2931	BOOTLID REPAIR PAINTING >50%	37.13
3481	L/R SIDE PANEL REPAIR PAINTING >50%	28.05
2675	L/R OUT PARKING SENS SURFACE PAINT PLAST.	0.37
2676	R/R OUT PARKING SENS SURFACE PAINT PLAST.	0.37
2677	L/R INN PARKING SENS SURFACE PAINT PLAST.	0.37
2678	R/R INN PARKING SENS SURFACE PAINT PLAST.	0.37
3482	R/R SIDE PANEL SURFACE PAINT	17.68
3901	BOOTFLOOR SURFACE PAINT	35.61

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		122.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	15.20	152.0

Material Cost - Paint

	Price SGD
New Part Painting	20.90
New Part Painting - Plastic K1R	73.30
Repair Painting	65.18
Surface-/Blend Paint	58.27
Surface Painting Plastic	1.48
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	256.73

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0283	L/BUMPER BRACKET	BHN1500U1E		15.00
0284	R/BUMPER BRACKET	BHN1500T1F		15.00
0323	UPP RAD GRILLE COVER	B63B50033A51		160.00
0347	L/F BUMPER COVER	BJS850C21		15.00
0349	FRT BUMPER GRILLE	BHN150712B		200.00
0354	FRT CTR BUMPER MLDG	BHN150717D		155.00
0367	CTR FRT BUMPER MLDG	B45A500S0C		15.00
0369	L/F BUMPER MOULDING	BJS7507K1		75.00
0370	R/F BUMPER MOULDING	BJS7507J1		75.00
0433	MANUFACTURER BADGE	C23551731A		25.00
2581	REAR BUMPER	BHR250221A8N		550.00
2611	L/R COVER	BHN150EL1BB		16.00
2613	L/R BUMPER REFLECTOR	D350515L0E		30.00
2640	REAR BUMPER SUPPORT	BHN150260		250.00
2675	L/R OUT PARKING SENS	KD4767UC113		85.00
2711	REAR PANEL	B4YA7075Z		245.00
2719	L/REINF EXTENSION	B4YA7141XA		180.00

Code	Description	Part Number	Supplier	Price SGD
3020	BADGE MODEL	BHN151721		28.00
3021	MANUFACTURER BADGE	BHN151730		30.00
4193	L/TAILLAMP PANEL	BJY77144Y		165.00
4985	RR LUGG COMPART TRIM	BHN16889XA		50.00
8789	L/F WIND DEFLECTOR	BHN1501V1A		65.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,444.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			2,544.00

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE SN	35.00*
	Total Extras	35.00

Final Calculation

	SGD	SGD
Parts	2,444.00	
Fixed Sundry Parts Price	100.00	
Total Parts		2,544.00
Labour Time Base 10 WU/h		
Total 139.0 WU X 42.00 SGD/h	583.80	
Total of Labour		583.80
Total Of Extras		35.00
Paint Work Time Base 10 WU/h		
Labour Cost 152.0 WU X 42.00 SGD/h	638.40	
Material Cost	256.73	
Total Paint Including Material		895.13
Repair Cost Excludes GST		4,057.93
GST (+7.0%)		284.06
Repair Cost Included GST		4,341.99

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Aug 2019 Sendback Est	15 Aug 2019 10:09 \$3,592.66	15 Aug 2019 10:44 Edit Adj Rpt	\$4,057.93 Edit Estimates	\$4,057.93 View Rpt		Pending for Survey Report Cancel Case
Supp #1	29 Nov 2019 15:23	29 Nov 2019 15:23 \$466.00	29 Nov 2019 15:23			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	LOCHERS TRADING, Co. Reg. No.: 422444003		
Main Claimant:	LOH SIOW NEE, ID: S7619891H		
Vehicle Reg. No.:	SGA9802E	Date of Loss:	13/08/2019 08:00 - :59 [50 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D203765C02	Policy/Cover Note No.:	DMCVSN15574919033
Vehicle Reg. No. (Insured):	GBB1590Y	Policy No. (Claimant):	A 29124166 QMX
		Excess:	S\$0.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/08/2019]		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGA9802E (SNM19D203765C02)
[GBB1590Y]
TP
LOH SIOW NEE
Aug 13 2019 8:00AM
[LOCHERS TRADING]
Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	14/08/19 09:43	Accident Statement	Load HTM	
2	15/08/19 10:09	Repairer Estimates	Load HTM	
3	29/11/19 15:23	Repairer Estimates Suppl. #1	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	15/08/19 10:03	Front View	Load JPG	☒
2	15/08/19 10:03	Front View Left	Load JPG	☒
3	15/08/19 10:03	Front View Right	Load JPG	☒
4	15/08/19 10:03	Rear View	Load JPG	☒
5	15/08/19 10:03	Rear View Left	Load JPG	☒
6	15/08/19 10:03	Rear View Right	Load JPG	☒
7	15/08/19 10:03	Chassis Number	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/19 15:47	General View	Load JPG	☒
2	11/12/19 15:47	General View	Load JPG	☒
3	11/12/19 15:47	General View	Load JPG	☒
4	11/12/19 15:47	General View	Load JPG	☒
5	11/12/19 15:47	General View	Load JPG	☒
6	11/12/19 15:47	General View	Load JPG	☒
7	11/12/19 15:47	General View	Load JPG	☒
8	11/12/19 15:47	General View	Load JPG	☒
9	11/12/19 15:47	Odometer Reading	Load JPG	☒
10	11/12/19 15:47	Chassis Number	Load JPG	☒
11	11/12/19 15:47	General View	Load JPG	☒
12	11/12/19 15:47	General View	Load JPG	☒
13	11/12/19 15:47	General View	Load JPG	☒
14	11/12/19 15:47	General View	Load JPG	☒
15	11/12/19 15:47	General View	Load JPG	☒
16	11/12/19 15:47	General View	Load JPG	☒
17	11/12/19 15:47	General View	Load JPG	☒
18	11/12/19 15:47	General View	Load JPG	☒
19	11/12/19 15:47	General View	Load JPG	☒
20	11/12/19 15:52	DISMANTLE PHOTOS	Load JPG	☒
21	11/12/19 15:52	DISMANTLE PHOTOS	Load JPG	☒
22	11/12/19 15:52	DISMANTLE PHOTOS	Load JPG	☒
23	11/12/19 15:52	DISMANTLE PHOTOS	Load JPG	☒
24	11/12/19 15:52	DISMANTLE PHOTOS	Load JPG	☒
25	11/12/19 15:52	DISMANTLE PHOTOS	Load JPG	☒
26	11/12/19 15:53	BEFORE PAINT PHOTOS	Load JPG	☒
27	11/12/19 15:53	BEFORE PAINT PHOTOS	Load JPG	☒
28	11/12/19 15:53	BEFORE PAINT PHOTOS	Load JPG	☒
29	11/12/19 15:53	BEFORE PAINT PHOTOS	Load JPG	☒
30	11/12/19 15:53	BEFORE PAINT PHOTOS	Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
31	11/12/19 15:53	BEFORE PAINT PHOTOS		Load JPG	☒
32	11/12/19 15:53	BEFORE PAINT PHOTOS		Load JPG	☒
33	11/12/19 15:53	BEFORE PAINT PHOTOS		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	15/08/19 10:08	Certificate of Insurance		Load PDF	
2	15/08/19 10:08	Enquire PARF / COE Rebate for Registered Vehicle		Load PDF	
3	15/08/19 10:08	LTA Search		Load PDF	
4	15/08/19 10:09	Audatex Report		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/12/19 10:26	Supplementary		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	04/09/19 02:24	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	14/08/19 09:43	Accident Photo		Load JPG	☒
2	14/08/19 09:43	Accident Photo		Load JPG	☒
3	14/08/19 09:43	Accident Photo		Load JPG	☒
4	14/08/19 09:43	Chassis Number		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	13/08/19 15:06	Sketch Plan		Load TIF	
2	13/08/19 15:07	Owner's NRIC & Driving Licence / Driver's		Load TIF	
3	13/08/19 15:07	Certificate of Insurance		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119014189/KQF3E2

Date: 23/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN15574919033

Claimant Vehicle No : SGA9802E Insured Vehicle No : GBB1590Y

Date of Loss: 13/08/2019 Nature of Claim: TP Claim No: SNM19D203765C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGA9802E

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520282586

Reg. Date: 15/05/2015 (Man. Year: 2015) Chassis No: JM6BM42A8G0310353

Colour: Metallic Grey Odometer: 92229 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R15 Rear Tyre Size: 205/60 R15

Front Left Side: Falken 9 mm Rear Left Side: Falken 9 mm

Front Right Side: Falken 9 mm Rear Right Side: Falken 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,444.00	2,444.00	0.00	0.00
Miscellaneous Items	135.00	135.00	0.00	0.00
Labour	617.40	583.80	33.60	5.44
Paintwork Labour	862.26	895.13	-32.87	-3.81
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,058.66	4,057.93	0.73	0.02
+ GST 7.00/7.00% (S\$)	284.11	284.06	0.05	0.02
Nett Amount (S\$)	4,342.77	4,341.99	0.78	0.02

INSPECTION

Date of Assignment: 15/08/2019 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Date Inspected: 15/08/2019 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2019)
Parts:	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGA9802E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		1,978.00 F	*1,978.00 F
Supplementary #1						
2	1		*UPP RAD GRILLE COVER	Dented	160.00 F	*160.00 F
3	1		*L/F BUMPER COVER	Dented	15.00 F	*15.00 F
4	1		*L/R COVER	Dented	16.00 F	*16.00 F
5	1		*L/BUMPER BRACKET	Distorted	15.00 F	*15.00 F
6	1		*R/BUMPER BRACKET	Distorted	15.00 F	*15.00 F
7	1		*L/REINF EXTENSION	Bent	180.00 F	*180.00 F
8	1		*L/F WING DEFLECTOR	Cracked	65.00 F	*65.00 F
Total Parts (S\$)					2,444.00	2,444.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Special nett Item	35.00	35.00
2	1	Sundry Parts (NECESSARY)	100.00	100.00
Sub Total (\$\$)			135.00	135.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	862.26	895.13
<u>Labour Items</u>				
2	Total of Labour	New	617.40	583.80
Gross Labour Cost (\$\$)			1,479.66	1,478.93

Report was unsubmitted during this print-out.

< END OF ESTIMATES >