

ASS. REC. BY:

REF:

TMI / CC3 / TMI19014193 / Kgd3 / 12

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S / R / Im / STD A / R / Im or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

GIA not ready

11 Rm 34501 (Red 41881.88, 92%)

SHD 9912T - CC3 / TMI19014193 / Kgd3

GBJ 642X - X

15/8/19 @ 3.33pm Email GIA, police report &amp; estimate to TMI.

RECEIVED 21 AUG 2019

DUA: 3175/18

Date/Time, File Pass to?

☐

: Prell. Report

1) 21/8 2019

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

F. m/s

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

MER TP

3450

250

11

261

## Shiau Chan (LKKAUTO)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Wednesday, 21 August 2019 2:25 PM  
**To:** Shiau Chan (LKKAUTO)  
**Subject:** RE: TP VEHICLE SHD 9912T (DOA: 11/08/2019) -- AAD1908-067  
**Attachments:** image001.wmz

Hi Shiau Chan

Amount confirmed \$ 3,450 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shiau Chan (LKKAUTO) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Tuesday, 20 August, 2019 4:17 PM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** TP VEHICLE SHD 9912T (DOA: 11/08/2019)

Dear Wai Yin,

Based on our surveyor's estimate making, the calculation of repair cost will be at Lump Sum \$3,450.00 before GST and 3 repair days.

Kindly check.

Best Regards,  
**Shiau Chan (Ms) | Case Handler**  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 15 August 2019 3:33 PM  
**To:** Motor Claims  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 11/08/2019, SHD 9912T (TP VEHICLE), GBJ 642X (OI VEHICLE)  
**Attachments:** SHD9912 EST.pdf; SHD9912 PR.pdf; SHD9912 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the SHD 9912T at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 14/08/2019.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	878K

**Vehicle Details**

Vehicle No.:	SHD9912T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Aug 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001182
Chassis No.:	VF1ABL15AUC277440
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	05 Jun 2014
First Registration Date:	05 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2022
PARF Rebate Amount:	\$8,748.00

**Intended COE Rebate Details**

COE Expiry Date:	04 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$20,136.00
<b>Total Rebate Amount:</b>	<b>\$28,884.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Aug 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/08/2019 11:17
Date Of Accident	11/08/2019 23:00
Exact Location Of Accident	RANGOON ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9912T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	TAN TOH HENG
NRIC No	S1180524H
Date Of Birth	16/12/1955
Occupation	OUTDOOR
Date Of Driving Pass	05/05/1978
Driving Experience	41 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97681873
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 8 MARSILING DRIVE #13-34
Postcode	730008
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE
Passenger 4	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS WEST N.P.C
Police Station Address	ROAD: 1 WOODLANDS STREET 12 , POSTCODE: 738622 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20190812/2006

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	E-SCOOTER
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOBILE EQUIPMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	GBJ642X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN

Rongdon Road

A = SHD 9912T  
B = E-SCOOTER  
C = GBJ 642X

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190812/2006

1 of 3

Police Station Of Origin:  
Woodlands West N.P.C.  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No: 1800-363 9999

Report No. T/20190812/2006

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/08/2019 01:20		Vide Report No.: A/20190811/0179		Station Diary No.: 12	
<b>Informant's Particulars</b>					
Name of Informant: TAN TOH HENG			Address: APT BLK 8 MARSILING DRIVE #13-34 SINGAPORE 730008		
ID Type / ID No.: NRIC NO / S1180524H			Contact No.: Home/Office: Mobile: 97681873		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 63	Date of Birth: 16/12/1955	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 11/08/2019 11:00	Type of Location: Straight Road
Location:  RANGOON ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: CHAIN COLLISION			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBJ642X	Van				Slightly Damaged	0
SHD9912T	TAXI				Slightly Damaged	4

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20190812/2006

Police Station Of Origin:  
Woodlands West N.P.C.  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No: 1800-363 9999

2 of 3

Report No. T/20190812/2006

## CONTINUATION OF REPORT

Driver:			
Name	TAN TOH HENG	ID No.	S1180524H
Related Vehicle	SHD9912T (TAXI)	Contact No.	97681873
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 11/08/2019 at about 2300hrs , I was driving a passenger along Rangoon road towards Kitchener Road . I then felt an impact on the left side of my taxi . I then came to a stop vehicle and discovered my vehicle to be Involved with an accident . Police came to scene. I further discovered that a PMD had collided with the van and the rider of the PMD fell and hit my taxi . I wish to state that my left side mirror is damaged .



**SINGAPORE  
POLICE FORCE**



T/20190812/2006

Police Station Of Origin:  
Woodlands West N.P.C.  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No: 1800-363 9999

3 of 3

Report No. T/20190812/2006

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

Sgt 2 ELTON DE LAURE

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

12/08/2019 01:20

Officer In Charge Of Case:

TP / GIT /

SI MOHAMMAD ABDILLAH BIN PADIL

Contact No: 65476246

Classification Of Case:

Authentication Stamp:

NP168

Sgt ELTON  
(T10034)

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9912T****AAD1908-067**

*Not Authorised*  
*61 Pny 8 34501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

14 AUG 2019

**SHD 9912T**

VF1ABL15AUC277440

RENAULT

LATITUDE

11.8.19

**TOKIO MARINE**

5/6/2014

PART		LIST	
1	BUMPER COVER FRT	\$	CM 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	CM 181.75 ✓
1	BUMPER ABSORBER FRT	\$	SL 394.68 X
1	BUMPER RETAINER FRT LH	\$	SL 151.41 X
1	BUMPER SUPPORT FRT	\$	SL 123.88 X
1	BUMPER UNDERTRAY FRT	\$	SL 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	CM 266.80 ✓
1	BUMPER FOG LAMP GRILLE LH	\$	Art SL 207.21 ✓
1	BUMPER BEAM FRT	\$	R 914.08
1	HEADLAMP LH	\$	SL 1,184.43
1	HEADLAMP PANEL FRT LH	\$	R 152.15
1	FENDER PANEL FRT LH	\$	R 783.83
1	WHEELARCH FRT LH	\$	SL 278.84
1	FENDER BRACKET LOWER LH	\$	SL 15.79
1	FENDER INSULATOR LH	\$	SL 130.84
1	FRONT BRACE PANEL	\$	R 177.22
1	RADIATOR GRILLE	\$	SL 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	SL 225.36
1	RADIATOR GRILLE FRAME	\$	SL 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	SL 615.90
1	FRAME FULL SUPPORT BRACKET	\$	R 89.79
1	BONNET	\$	R 1,941.63
1	BONNET INSULATOR	\$	SL 405.73
1	BONNET STRUT LH	\$	SL 88.61
1	BONNET STRUT RH	\$	SL 88.61
1	BONNET HINGE LH	\$	R 348.31
1	BONNET HINGE RH	\$	R 348.31
1	BONNET LOCK	\$	R 305.48
1	BONNET CABLE	\$	SL 119.19

X

**Trans-cab Auto Services Pte Ltd****AAD1908-067**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9912T**

1	BONNET CABLE COVER	\$	Sn	161.03	X
1	BONNET SEAL OUTER	\$	Sn	92.36	X
1	BONNET SEAL INNER	\$	Sn	157.28	X
1	AIR CLEANER BOX	\$	Sn	464.20	X
1	AIR CLEANER HOSE	\$	Sn	175.85	X
1	AIR CLEANER LOWER	\$	Sn	271.26	X
1	DOOR PANEL FRT LH	\$	N	2,844.66	X
1	DOOR MIRROR ASSY LH	\$	Bn	1,483.40	✓
1	DOOR HARNESS WIRE LH	\$	Sn	2,670.00	} X
1	ROCKER PANEL INNER GARNISH LH	\$	Sn	466.51	
1	ROCKER PANEL INNER LH	\$	N	1,024.79	
1	ROCKER PANEL OUTER LH	\$	N	1,184.99	
1	ROCKER PANEL CENTER LH	\$	N	990.25	
1	LOWER ARM LH L70Y	\$	Sn	685.76	
1	KNUCKLE ARM LH L70Y	\$	Sn	846.98	
1	ABSORBER FRT LH L70Y	\$	Sn	360.54	
1	DRIVESHAFT LH	\$	N	1,747.45	} X
1	STABILIZER BAR FRT	\$	Sn	604.65	
<b>TOTAL</b>		<b>\$</b>		<b>30,565.56</b>	
<b>10%</b>		<b>\$</b>		<b>3,056.56</b>	
		<b>\$</b>		<b>27,509.00</b>	

**Special Nett**

1	BUMPER CLIP FRT	\$	Nn	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	Nn	12.00	} X
1	BUMPER SUPPORT CLIP FRT LH	\$	Nn	10.50	
1	BUMPER GRILLE LOWER CLIP	\$	Nn	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Nn	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	Nn	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	Nn	30.00	
1	WHEELARCH CLIP FRT LH	\$	Nn	30.50	
1	FRONT LEFT TYRE	\$	Sn	300.00	} X
1	FRONT LEFT TYRE RIM	\$	Sn	380.00	
1SET	Front licence plate with holder	\$	Sn	80.00	} X
1	WINDSCREEN SEALANT	\$	Nn	253.80	
1	FRONT WINDSCREEN MOULDING	\$	Nn	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	Nn	100.00	
6	BONNET INSULATOR CLIP L70Y	\$	Nn	7.30	

**Trans-cab Auto Services Pte Ltd**

AAD1908-067

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9912T**

2	BONNET STRUT L70Y	\$	Sh 88.61	X
2	BONNET CABLE CLIP L70Y	\$	nn 6.31	X
2	BONNET CABLE COVER SCREW L70Y	\$	nn 10.85	X
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn 52.00	X
1SET	RADIATOR GRILLE SCREW	\$	nn 16.00	X
1	FRONT DOOR STICKER 'Trans-Cab'	\$	nn 80.00	60sm
1	FRONT DOOR STICKER 'Classic'	\$	nn 80.00	15a
<b>TOTAL</b>		<b>\$</b>	<b>1,882.88</b>	
<b>TOTAL PARTS</b>		<b>\$</b>	<b>29,391.88</b>	

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	4001
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	5 380.00	X
To transfer of front windscreen fittings and conduct water seepage test.	\$	5 170.00	X
To check steering geometry and computer wheel alignment	\$	5 220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	5 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	5 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	7201
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	5 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	5 380.00	X

**Trans-cab Auto Services Pte Ltd****AAD1908-067**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9912T**

To transfer of front door fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To rust-proofing of the affected areas.	\$	nn 170.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00 X
<b>TOTAL</b>	<b>\$</b>	<b>15,940.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>45,331.88</b>

**LUMP SUM (REPAIR DAY)****20 days****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19014193/KQD3N2

Date: 23/08/2019

**REFERENCE**

<b>Handling Insurer:</b>	Tokio Marine Insurance Singapore Ltd	<b>Policy No:</b>	MJ001454
<b>Claimant Vehicle No :</b>	SHD9912T	<b>Insured Vehicle No :</b>	GBJ642X
<b>Date of Loss:</b>	11/08/2019	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	M1906242

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

<b>Reg No:</b>	SHD9912T	<b>Engine No:</b>	M9R8839C001182
<b>Make &amp; Model:</b>	RENAULT LATITUDE, 2.0 L (A)	<b>Chassis No:</b>	VF1ABL15AUC277440
<b>Reg. Date:</b>	05/06/2014 (Man. Year: 2014)	<b>Odometer:</b>	885775 km
<b>Colour:</b>	Metallic White/Red		
<b>Engine Capacity:</b>	1995 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>

**CONDITION OF TYRES**

<b>Front Tyre Size:</b>	215/60R16	<b>Rear Tyre Size:</b>	215/60R16
<b>Front Left Side:</b>	Giti 8 mm	<b>Rear Left Side:</b>	Giti 7 mm
<b>Front Right Side:</b>	Giti 8 mm	<b>Rear Right Side:</b>	Giti 7 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	29,391.88	3,199.72	26,192.16	89.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,940.00	1,140.00	14,800.00	92.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>45,331.88</b>	<b>4,339.72</b>	<b>40,992.16</b>	<b>90.43</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,450.00</b>		
<b>(S\$)</b>	45,331.88	3,450.00	41,881.88	92.39
<b>+ GST 7.00/7.00% (S\$)</b>	3,173.23	241.50	2,931.73	92.39
<b>Nett Amount (S\$)</b>	<b>48,505.11</b>	<b>3,691.50</b>	<b>44,813.61</b>	<b>92.39</b>

**INSPECTION**

<b>Date of Assignment:</b>	16/08/2019	
<b>Date Inspected:</b>	14/08/2019	<b>Inspected At:</b>
		Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
		2, Ang Mo Kio Street 63
		Singapore 569111
<b>Estimated Period of Repair:</b>	3.0 days	

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2019)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD9912T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Cracked	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Cracked	181.75 FL	*181.75 FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*- FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
7	1		*BUMPER GRILLE LOWER FRT	Cracked	266.80 FL	*266.80 FL
8	1		*BUMPER FOG LAMP GRILLE LH	Missing	207.21 FL	*207.21 FL
9	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
10	1		*HEADLAMP LH	Serviceable	1,184.43 FL	*- FL
11	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
12	1		*FENDER PANEL FRT LH	Repair	783.83 FL	*- FL
13	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
14	1		*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
15	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
16	1		*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
17	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	*- FL
18	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
19	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
20	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
21	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
22	1		*BONNET	Repair	1,941.63 FL	*- FL
23	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
24	1		*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
25	1		*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
26	1		*BONNET HINGE LH	Repair	348.31 FL	*- FL
27	1		*BONNET HINGE RH	Repair	348.31 FL	*- FL
28	1		*BONNET LOCK	Repair	305.48 FL	*- FL
29	1		*BONNET CABLE	Serviceable	119.19 FL	*- FL
30	1		*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
31	1		*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
32	1		*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
33	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
34	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
35	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
36	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
37	1		*DOOR MIRROR ASSY LH	Broken	1,483.40 FL	*1,483.40 FL
38	1		*DOOR HARNESS WIRE LH	Serviceable	2,670.00 FL	*- FL
39	1		*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
40	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
41	1		*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	*- FL
42	1		*ROCKER PANEL CENTER LH	Repair	990.25 FL	*- FL
43	1		*LOWER ARM LH L70Y	Serviceable	685.76 FL	*- FL
44	1		*KNUCKLE ARM LH L70Y	Serviceable	846.98 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*ABSORBER FRT LH L70Y	Serviceable	360.54 FL	*-FL
46	1		*DRIVESHAFT LH	Repair	1,747.45 FL	*-FL
47	1		*STABILIZER BAR FRT	Serviceable	604.65 FL	*-FL
48	1		*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
49	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*-FS
50	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*-FS
51	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*-FS
52	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*-FS
53	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*-FS
54	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*-FS
55	1		*WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*-FS
56	1		*FRONT LEFT TYRE	Serviceable	300.00 FS	*-FS
57	1		*FRONT LEFT TYRE RIM	Serviceable	380.00 FS	*-FS
58	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*-FS
59	1		*WINDSCREEN SEALANT	Not Necessary	253.80 FS	*-FS
60	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*-FS
61	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
62	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*-FS
63	2		*BONNET STRUT L70Y	Serviceable	88.61 FS	*-FS
64	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*-FS
65	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*-FS
66	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*-FS
67	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*-FS
68	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
69	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>32,448.44</b>	<b>3,539.58</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>3,056.56</b>	<b>339.86</b>
<b>Total Parts (\$\$)</b>	<b>29,391.88</b>	<b>3,199.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	400.00
2	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
3	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	720.00
9	TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
10	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
11	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
13	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
14	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
15	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>15,940.00</b>	<b>1,140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >