

AS REC BY:

REF: CS/C1219014195/ EVF362

Special Instruction:

Survivor

910

ASSIGNMENT (Office)

From (Person)

Elaine Cheney

of

C72

Date/Time:

12.8.19 13.44 p.m.

~~Estimated Cost:~~

Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No. _____

SLT (784)

Insured:

SLD 3013E

at Workshop m/s

New Tlc Automobile

Tel:

67622081

of

BK 25 Kaki Bukit Road 4 #01-61

Policy No.

DM PCSN 1737241902

Claim No:

SN M 19D 202727C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

TGA

8. 8. 19

CA / REV / REP. / REV 24 HRS

140

H.O.D. Endorsement:

Date/Time

15.8.19 2.05 PM

Person Contacted:

Winnie

Vehicle ~~IN~~ OUT

LOUT

Date/Time	Action/Instruction (✓) Estimate Inspection: 399 F woodland road
	SLT 6734J -x
	SLD 3013E -x

ASS. REC'D BY: steveREF: CT1

ASSIGNMENT

From: _____ Date: 15/8/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 6784 Jat Workshop m/s Yew Tee Automobileof 6116 6 woodlands Road 399 F

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLT 6784 J Yr Regn: 07/11/2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda civic / HYBRID cc 1496Colour: pearl white A/C: Insured / Std / NI / NASp Reading: 024914km T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: R431253135Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60/R 16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 8/8/19 D.O.I. 15/8/19Survey held at Yew Tee AutomobileDes. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Noted: This case already inform workshop incharge person know it limit repair don't exceed \$33K, see to workshop was to make not.
	MV - 79,000
	PV - 43,746
	NV - 35,254
	16/8/19 Steve call the boss sky 97471475 mention 33K upper limit.
	19/8/19 call show (97472762) repair limit 35K
	3/10/19 Finalize conf \$34,100, 15 day (Yew Tee)
	(Red 39,265.84, 53K)

RECEIVED OCT 2019

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 15

1)

☐ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

3/10 - typist

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Wash end (\$)

Survey Fee:

Transportation:

S + PS \$

Photos

Others

TOTAL

270

270

Report Format:

Merimen

Lump Sum / M.B. / \$ 45 \$34,100/2

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Aug 2019		15 Aug 2019 13:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:									
Main Claimant:	TAN TING TING (CHEN TINGTING), ID: S8338294E								
Vehicle Reg. No.:	SLT6784J	Date of Loss:	08/08/2019 13:00 - :59						
Claim Type:	TP / SNM19D203727C02	Policy/Cover Note No.:	DMPCSN1737211902						
Vehicle Reg. No. (Insured):	SLD3013E	Policy No. (Claimant):	5098271236-01						
		Excess:	S\$1,250.00						
Repairer:	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Bldg 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel: 67023113								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/08/2019]								
Adj Asg. Remarks:	TP workshop requested Marcus to survey their vehicle.								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: YT(HQ) <utauto@singnet.com.sg>
Sent: Monday, 19 August 2019 4:06 PM
To: 'YT(HQ)'; Steve Chen (LKK Auto)
Cc: Admin A; Veron Chen (LKKAUTO); Mei Kwan (LKKAUTO)
Subject: RE: SLT6784J Repair Limit

Hi

How u get 33K we go through sgcar mart all also no have \$33k

Best Regards

Shaun Teh L M

9743 2262

www.yewteegroup.com

info@yewteegroup.com

Like Us On Facebook

Managing Director of

-YEW TEE AUTOMOBILE TECH PTE LTD

-YEW TEE (CAMBODIA) AUTOMOBILE CO. LTD



WEST HQ:

Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081
Fax: 6760 4895
Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4
Unit No #01-60/61
Singapore 417800
DID: 6702 3113 (3 Lines)
Fax: 6702 3773
Email: utauto2@singnet.com.sg

NORTH Branch:

Mega@Woodlands
39 Woodlands Close #01-12
Singapore 737856
DID: 6256 2081 (3 Lines)
Fax: 6256 2533
Email: info@yewteegroup.com

please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(HQ)

Sent: Monday, 19 August, 2019 3:22 PM

To: 'Steve Chen (LKK Auto)' <SteveChen@lkkauto.com>; 'Yew Tee (HQ)' <utauto@singnet.com.sg>

Cc: 'Admin A' <admin-a@lkkauto.com>; 'Veron Chen (LKKAUTO)' <veronchen@lkkauto.com>; 'Mei Kwan (LKKAUTO)'

<Meikwan@lkkauto.com>; info@yewteegroup.com

Subject: RE: SLT6784J Repair Limit

Dear All,

Refer to the email below,

Please let's us have your breakdown on the repair limit \$33k ASAP,

As the owner got a replacement car start to the accident date until now,

Thank you!



Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID: 62562081

Email: info@yewteegroup.com

From: YT(HQ) <info@yewteegroup.com>

Sent: Monday, August 19, 2019 11:19 AM

To: 'Steve Chen (LKK Auto)' <SteveChen@lkkauto.com>; 'Yew Tee (HQ)' <utauto@singnet.com.sg>

Cc: 'Admin A' <admin-a@lkkauto.com>; 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>; 'Mei Kwan (LKKAuto)' <Meikwan@lkkauto.com>

Subject: RE: SLT6784J Repair Limit

Dear All,

Refer to the email below,

Please let's us have your breakdown on the repair limit \$33k.

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 /6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID: 62562081

Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(HQ) <info@yewteegroup.com>

Sent: Friday, 16 August 2019 2:35 pm

To: 'Steve Chen (LKK Auto)' <SteveChen@lkkauto.com>; 'Yew Tee (HQ)' <utauto@singnet.com.sg>

Cc: 'Admin A' <admin-a@lkkauto.com>; 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>; 'Mei Kwan (LKKAuto)' <Meikwan@lkkauto.com>

Subject: RE: SLT6784J Repair Limit

Hi Steve,

Repair limit \$33k is too low,

Based on our calculation, ERV for this vehicle between \$39k to \$40k.

Please re-calculate.

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 /6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID:62562081

Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>

Sent: Friday, 16 August 2019 11:05 am

To: 'Yew Tee (HQ)' <utauto@singnet.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; YT(HQ) <info@yewteegroup.com>

Subject: SLT6784J Repair Limit

Dear Vinnie,

As per our communication earlier. The above vehicle repair limit \$33k.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Friday, August 16, 2019 10:15 AM

To: YT(HQ); Steve Chen (LKK Auto); Veron Chen (LKKAuto)

Cc: 'Yew Tee (HQ)'; Admin A

Subject: RE: SLT6784J Repair Limit *** LKK REF: CS/CTI19014195/Evf3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Steve / Veron,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) <info@yewteegroup.com>

Sent: Friday, 16 August, 2019 9:56 AM

To: Admin A <admin-a@lkkauto.com>

Cc: 'Yew Tee (HQ)' <utauto@singnet.com.sg>

Subject: SLT6784J Repair Limit

Dear Sir/Madam,

Please advise on the repair limit soon.

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 /6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID:62562081

Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Veron Chen (LKKAUTO)

From: Steve Chen (LKK Auto)
Sent: Friday, 16 August 2019 11:05 AM
To: 'Yew Tee (HQ)'
Cc: Admin A; Veron Chen (LKKAUTO); Mei Kwan (LKKAUTO); YT(HQ)
Subject: SLT6784J Repair Limit

Dear Vinnie,

As per our communication earlier. The above vehicle repair limit \$33k.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Friday, August 16, 2019 10:15 AM
To: YT(HQ); Steve Chen (LKK Auto); Veron Chen (LKKAUTO)
Cc: 'Yew Tee (HQ)'; Admin A
Subject: RE: SLT6784J Repair Limit *** LKK REF: CS/CTI19014195/Evf3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Steve / Veron,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.
Best Regards,
Mei Kwan | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) <info@yewteegroup.com>
Sent: Friday, 16 August, 2019 9:56 AM

To: Admin A <admin-a@lkkauto.com>
Cc: 'Yew Tee (HQ)' <utauto@singnet.com.sg>
Subject: SLT6784J Repair Limit

Dear Sir/Madam,

Please advise on the repair limit soon.

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 /6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID:62562081
Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	294E
Vehicle Details	
Vehicle No.:	SLT6784J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	LEB5953152
Chassis No.:	RU31253135
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$25,291.00
Original Registration Date:	07 Nov 2017
First Registration Date:	07 Nov 2017
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	06 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,996.00
COE Rebate Amount:	\$39,996.00
Total Rebate Amount:	\$43,746.00

The information contained herein is correct as at 15 Aug 2019

8-3

OK

Depreciation = 9200 year¹ = 766

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLT6784J		
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	VEZEL HYBRID 1.5X AUTO		
Chassis No. :	RU31253135		
Propellant :	Petrol-Electric		
Engine No. :	LEB5953152		
Motor No. :	H12363358		
Engine Capacity :	1496 cc		
Power Rating :	22.0 kW		
Maximum Power Output :	112.0 kW (150 bhp)		
Maximum Laden Weight :	1555 kg		
Unladen Weight :	1280 kg		
Year Of Manufacture :	2017		
Original Registration Date :	07 Nov 2017		
Lifespan Expiry Date :	-		
COE Category :	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium :	\$49,996.00		
COE Expiry Date :	06 Nov 2027		
Road Tax Expiry Date :	06 Nov 2019		
PARF Eligibility Expiry Date :	06 Nov 2027		
Inspection Due Date :	06 Nov 2020		
Intended Transfer Date :	16 Aug 2019		
CO2 Emission :	94.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$22,408.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 06 Nov 2019. You may renew the road tax from 07 Aug 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 06 Nov 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 07 Nov 2019 to 06 May 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	341.00	-	341.00
Total Amount Payable :			366.00
Amount Payable (From 07 Nov 2019 to 06 Nov 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	682.00	-	682.00
Total Amount Payable :			707.00

You may print this page for reference.

[OK](#)
[Print](#)


DAVANTI
 Proven Performance Tyre
FREE


SGCARMART CARNIVAL
 31 Aug & 1 Sep 10am - 8pm
 Downtown East Carpark B
SEE YOU @ BOOTH 2!

SPARKO Kuffs @ \$356
FREE 1 Essential Servicing & 1 Grooming (worth \$236 total)
 Plus Many Other Benefits!


SPARKO
 CAR CARE

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

High Loan & Trade In, Free Choice Of Spray!



Warranty & Free Servicing
 Deposit
 Deposit

Auto Inn
 An Destination For Car Buyers

click here to view
 our **PRISTINE USED CARS**
 at **GREAT PRICES**

Browse by Category

= Back (1 2) Next =

Sort by Date Posted

20 results/page

23 vehicles

Honda Vezel hybrid

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Vezel hybrid		Any	Any	2017	Any	Any	Any	Available
	Honda Vezel Hybrid 1.5A		\$78,800	\$9,690 /yr	28-Jun-2017	1,496 cc	53,250 km	SUV	Available
Fuel Type: Petrol-Electric Tip Top Condition, 1 Owner, Sale. New Paintwork. Call Now For Viewing Appointment. Posted: 15-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel Hybrid 1.5A X		\$78,500	\$10,040 /yr	10-Mar-2017	1,496 cc	4,900 km	SUV	Available
Fuel Type: Petrol-Electric 3 Years On 100000Km Warranty. High Trade In. Prime Motor & Leasing Posted: 14-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel Hybrid 1.5A X		\$73,800	\$9,440 /yr	03-Mar-2017	1,496 cc	50,000 km	SUV	Available
Fuel Type: Petrol-Electric The Honda Vezel, A Conventional Crossover SUV That's Known For It's Great Looks And Good Driving Dynamics. Soft Touch Materials, Elegant Center Console, LED Lighting And Auto Air Conditioning With Touch Screen Controls That Give The Car An Extra Luxurious Feel... Posted: 12-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel Hybrid 1.5A X		\$79,000	\$9,860 /yr	17-May-2017	1,496 cc	-	SUV	Available
Fuel Type: Petrol-Electric Elegant Silver SUV, Powerful Drive With 150 Bhp, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available. Prime Motor & Leasing Posted: 11-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	The Toyota Previa is the de facto MPV The Toyota Previa is an MPV that excels with its space, practicality and a level of luxury some may not reach. Find out more!								
	Honda Vezel Hybrid 1.5A X		\$82,800	\$9,590 /yr	28-Dec-2017	1,496 cc	28,000 km	SUV	Available
Fuel Type: Petrol-Electric Offer Bank Interest Rate From 1.98%. Free 2 Years Hybrid Battery Warranty With Certified 120 Points Test Report With Detailed Chassis Inspection. Extra Passengers Safety With Honda Sensing Technology. Blue Body With Black Interior. 1 x Free Servicing At Our Authorize... Dynamic Motoring Posted: 06-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel Hybrid 1.5A RS		\$78,800	\$10,200 /yr	10-Jan-2017	1,496 cc	54,600 km	SUV	Available
Fuel Type: Petrol-Electric Hybrid RS Sensing Limited Edition Worth \$10k More. Rare With Full Servicing Records From Optima Werkz. Free 6 Months Engine, Gearbox & Hybrid Battery Warranty. Free 3 Servicing Package. Free iRoad V9 Front And Rear In-Car Camera. Only 1 Owner. New Car... Performance Carz Pte Ltd Posted: 05-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
Compare	nda Vezel Hybrid 1.5A RS		\$84,800	\$10,220 /yr	15-Aug-2017	1,496 cc	41,000 km	SUV	Available
nda Sensing									

**Fuel Type:** Petrol-Electric

Celebrate SG 54th Birthday! \$540 Petrol Voucher For This Weekend Only! Highest Specification In It's Class. Hot Premium Chili Red Hybrid RS Sensing Limited Edition. With Full Servicing Records From JKS Motor Works. Engine, Gearbox & Hybrid Battery Warranty For 8...

Hua Yang Credit Pte Ltd

Posted: 06-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

PREMIUM

**Honda Vezel Hybrid 1.5A X****\$52,988**

\$9,770 /yr

10-Nov-2017

1,496 cc

36,000 km

SUV

Available

Fuel Type: Petrol-Electric

1 Owner. Original Paint And Condition. Most Popular Compact SUV, Act Fast And Call Now For Viewing Before It Gone.

Cycle & Carriage. Fulco Motor Dealer

Posted: 06-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$76,800**

\$9,530 /yr

31-May-2017

1,496 cc

37,092 km

SUV

Available

Fuel Type: Petrol-Electric

13 Years Old Bidded 2 Digits Car Plate Going Along, FOC! Low Mileage Done 37092km. Tip Top Condition, Must See. 1 Owner, Sale Due To Overseas Job Post. New Paintwork, Optional Warranty Available. 100% Accident Free. Owner Consignment. Call Now!

Lake View Credit Pte Ltd

Posted: 04-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

PREMIUM

**Honda Vezel Hybrid 1.5A X****Honda Sensing****\$74,822**

\$9,490 /yr

30-Mar-2017

1,496 cc

52,229 km

SUV

Available

Fuel Type: Petrol-Electric

Full Specs Honda Sensing Vezel At The Price Of Non Sensing Vezel. Super Worthwhile! 1 Owner With 52k KM Done. Accident Free With New Paintwork Done. Definitely The Lowest Priced Sensing Vezel In Pre-Owned Market. Excellent Fuel Economy Of Up To 24km/L. Price...

Posted: 03-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Celebrating 60 years of MINI**

As MINI celebrates its 60th anniversary, we look at some key features of the car that has made it an endearing automotive icon. Find out more

Find out more!

**Honda Vezel Hybrid 1.5A X****Honda Sensing****\$83,800**

\$10,480 /yr

17-May-2017

1,496 cc

52,778 km

SUV

Available

Fuel Type: Petrol-Electric

Special Offer 1.5% Interest Rate. Honda Sensing. Excellent Fuel Efficiency At Up To 24.2 km/L. Well Maintained By 1 Owner. Call/SMS/Whatsapp For Viewing Appointment.

Republic Auto

Posted: 03-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$77,800**

\$9,800 /yr

20-Apr-2017

1,496 cc

-

SUV

Available

Fuel Type: Petrol-Electric

Low Mileage, 1 Owner, Immaculate Condition, In House Loan Available And High Trade In Available Too. Contact Our Sales Team For More Information.

Posted: 02-Aug-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$78,800**

\$9,790 /yr

31-May-2017

1,496 cc

31,288 km

SUV

Available

Fuel Type: Petrol-Electric

Nice Old/Bidded 2 Digits Car Plate Going Along, FOC! Low Mileage Done 31288km! Excellent Condition, Must See. 1 Owner, Sale Due To Overseas Job Posting. New Paintwork, Optional Warranty Package Available. 100% Accident-Free. Owner Consignment. Call Now!

Lake View Credit Pte Ltd

Posted: 31-Jul-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

PREMIUM

**Honda Vezel Hybrid 1.5A X****Honda Sensing****\$84,888**

\$9,890 /yr

12-Dec-2017

1,496 cc

29,386 km

SUV

Available

Fuel Type: Petrol-Electric

5 Years Warranty By Hitachi, Low Mileage, 1 Owner, Immaculate Condition, Interest Rate As Low As 1.98%, 100% Loan Available. Call Us Now!

Posted: 31-Jul-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$78,388**

\$9,900 /yr

13-Apr-2017

1,496 cc

59,989 km

SUV

Available

Fuel Type: Petrol-Electric

1 Owner, Cheapest In Market! Low Mileage, Low Depreciation. (Free 2 Years Premium Warranty With \$500 Services Credits), Well Maintained Unit, Immaculate Condition, Not PHY Unit! (High And Flexible Loan Available Up 100% At Low Interest Rate From 1.98%), H...

Hamilton Autohub Pte Ltd

Posted: 29-Jul-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$79,800**

\$9,840 /yr

23-Jun-2017

1,496 cc

21,000 km

SUV

Available

Fuel Type: Petrol-Electric

Low Fuel Consumption With Hybrid, In House Loan Available, High Trade In.

Motor & Leasing

Posted: 28-Jul-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Complete



Honda Vezel Hybrid 1.5A X **\$80,000** **\$10,420 /yr** **20-Jan-2017** **1,496 cc** **64,153 km** **SUV** **Available**

Fuel Type: Petrol-Electric
 1 Owner Only! Low Mileage Done! Not A Private Hirer Unit, Very Well Kept In Rare Condition. View And Believe, Buy It From Us With A Peace Of Mind, Discover The Greatness Of This Car. Consignment Unit! Trade In Welcome! Loan And Insurance Available! Call Now For... [Consignment](#)

Prem Roy Motoring
 Posted: 25-Jul-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel Hybrid 1.5A X Honda Sensing **\$81,888** **\$9,930 /yr** **11-Aug-2017** **1,496 cc** **40,700 km** **SUV** **Available**

Fuel Type: Petrol-Electric
 Female Owner, 1 Owner, Consignment Unit, Trade In Welcome, Loan And Insurance Available, Call Now For Viewing Appointment. [Consignment](#)

Prem Roy Motoring
 Posted: 19-Jul-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel Hybrid 1.5A X **\$81,800** **\$9,470 /yr** **29-Dec-2017** **1,496 cc** **12,000 km** **SUV** **Available**

Fuel Type: Petrol-Electric
 Only 1 Owner, Authentic Low Mileage Done, Silent Undercarriage, Smooth Gearbox Transmission, Accident Free, Perfect Chassis. No Repairs Needed. High In House Financing Available Easily, Call Us Now Or Visit Us Today At Carros Centre, Kranji Road, For A No Obliga... [Consignment](#)

Posted: 15-Jul-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel Hybrid 1.5A X Honda Sensing **\$77,500** **\$9,980 /yr** **17-Feb-2017** **1,496 cc** **39,000 km** **SUV** **Available**

Fuel Type: Petrol-Electric
 1 Owner Low Mileage Unit! Very Well Maintained Black Interiors. Original White Paintwork With Bodykit. Side Step, Spoiler. Sports Rims With P54 Tyres. Trade In/ Flexible Loan Available! Call Now To View! Viewing By Appointment Only.

360 VR Cars
 Posted: 01-Jul-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Make: Model: Price: Depreciation: Regi Unit: Eng Cap: Mileage: Veh Type: Status:

For old advertisements, view Expired ads

« Back (1 2) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & CPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda Vezel hybrid, Honda Vezel hybrid Singapore, used Honda Vezel hybrid Singapore, used Honda Vezel hybrid, used vehicles Singapore or even buy used Honda Vezel hybrid Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/08/2019 18:01
Date Of Accident	08/08/2019 13:00
Exact Location Of Accident	KPE TOWARDS ECP MCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT6784J
Insured/Policyholder	
Name Of Registered Owner	TAN TING TING (CHEN TINGTING)
NRIC No	S8338294E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91393796
Alternative Phone No	OFFICE-91393796

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098271236-01
Cover Note Number	

Driver

Name of Driver	NG KOK LIANG
NRIC No	S8212908A
Date Of Birth	26/04/1982
Occupation	INDOOR
Date Of Driving Pass	12/10/2001
Driving Experience	17 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91393796
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	82 EDGEDALE PLAINS #08-08
Postcode	828736
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	7
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4439999 - FAX NO: 62444376
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD3013E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKP7722P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJX4991T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SHC455K
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SGQ2172B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number SMH1878G
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name NG KOK LIANG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLT6784J
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address 82 EDGEDALE PLAINS #08-08
Postcode 828736

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renewate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 8/8/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

1725

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Front car Jam brake , I applied my brake as well but CAR B couldn't stop in time and collided into my rear portion. The strong impact caused my car move forward and collided into CAR C rear portion.

Total 7 vehicles involved in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 08/08/19
1425

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190808/2148

1 of 3

Police Station Of Origin:

Eunos NPP

629 Bedok Reservoir Road #01-1620

SINGAPORE 470629

Tel No: 1800-4439999

Report No. T/20190808/2148

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/08/2019 17:55	Vide Report No.:	Station Diary No.: 26
--	------------------	--------------------------

Informant's Particulars

Name of Informant: NG KOK LIANG	Address: 82 EDGEDALE PLAINS #08-08 SINGAPORE 828736		
ID Type / ID No.: NRIC NO / S8212908A	Contact No.: Home/Office: Mobile: 91393796		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 37	Date of Birth: 26/04/1982	Type of Informant: Driver
Race: Chinese	Language: English		Institution / School Name:
Occupation: SALES ENGINEER	Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 08/08/2019 13:00	Type of Location: Straight Road
Location: Along Road 1 KALLANG PAYA LEBAR EXPRESSWAY Towards MCE at 8KM mark				
Weather: Sunny	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: Dual Carriage Way	Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear	Anyone conveyed by ambulance: No			

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKP7722P	Car	VOLVO		Silver	Seriously Damaged	0
SLD3013E	Car	TOYOTA	LEXUS NX200T LUXURY S/R	White	Seriously Damaged	0
SLT6784J	Car	HONDA	VEZEL HYBRID 1.5X AUTO	White	Seriously Damaged	0

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190808/2148

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

2 of 3

Report No. T/20190808/2148

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NG KOK LIANG	ID No.	S8212908A
Related Vehicle	SLT6784J (Car)	Contact No.	91393796
Hospital/Clinic	MOUNT ELIZABETH NOVENA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	08/08/2019	Date Discharge	08/08/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On the above mentioned date and time, I was driving my vehicle bearing plate number, SLT6784J on KPE towards MCE on the most right lane. I am aware that I was following a silver in colour Volvo. Suddenly, the car in front jammed the brakes and I too brake hard. I was able to stop in time to prevent from hitting the Volvo.

Moments later, I felt a great impact from the rear and my car was jolted forward and hit onto the Volvo. The impact caused my car airbags to be activated and my vehicle was not able to move from its spot. I wish to state that I have an in-car camera that recorded the incident and the memory card was handed over to the Traffic Police officer who came to the accident. I did not need any immediate medical attention. However, I felt pain on my entire right hand and from my neck to my lower back. Thus, I went to Mount Elizabeth Novena to make a check and was given 4 days of medical leave from 8/8/2019 to 11/8/2019.

POLICE REPORT Pg. 1



SINGAPORE
POLICE FORCE



T/20190808/2148

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 3


Report No. T/20190808/2148

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 3 RADIN SALIHUL 'IMRAN BIN RADIN FADLI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 08/08/2019 17:55
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436	Classification Of Case: TP / AEIT /
Authentication Stamp NP166	

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTKB/TP/1908/012
Policy No:	5098271236-01	Date of Loss:	08/08/2019
Vehicle Reg. No.:	SLT6784J	Driveable?	yes
Driver Age:	15/01/2020	Third Party Vehicle No.:	SLD3013E
Any Injuries?	yes	Contact No:	91393796
Insured/Claimant:	TAN TING TING (CHEN TINGTING)	Driver:	NG KOK LIANG

Make/Model:	Honda, Vezel - RU1	Vehicle Reg. Date:	07 Nov 2017
Vehicle Colour:	white	Engine Number:	LEB5953152
Chassis No:	RU31253135	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss CHAIN COLLISION
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	43,968.08
Miscellaneous Items	1,363.00
Labour	6,260.00
Paintwork Labour	73,365.84
Towing	0.00
Gross Total(S\$):	53,776.08
GST 7.00%(S\$):	3,764.33
Nett Amount(S\$):	57,540.41

This claim is handled by: Sky Toh T C

83901.04

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT BONNET ✓ DD	892.00	-20.00	713.60
2	1	FRONT BONNET HINGE LH ✓ BT	45.00	-20.00	36.00
3	1	FRONT BONNET HINGE RH ✓ BT	45.00	-20.00	36.00
4	1	BONNET INSULATOR ✓ CRU	145.00	-20.00	116.00
5	1	BONNET LOCK ✓ BT	130.00	-20.00	104.00
6	2	RUBBER CENTRE ✓ CRU	70.00	-20.00	56.00
7	2	CORNER RUBBER ✓ TN	70.00	-20.00	56.00
8	2	SIDE RUBBER X X NAI	70.00	-20.00	56.00
9	1	BONNET STAND X NAI	48.00	-20.00	38.40
10	1	FRONT BUMPER ✓ BR	800.00	-20.00	640.00
11	1	FRONT BUMPER LOWER AIR GRILLE ✓ cut	87.00	-20.00	69.60
12	1	FRONT BUMPER LOWER LIP RX ✓ CRU	380.00	-20.00	304.00
13	1	FRONT BUMPER LIP RUBBER X NAI	110.00	-20.00	88.00
14	2	FOG LAMP COVER (4/H) ✓ CRU	90.00	-20.00	72.00
15	1	FRONT BUMPER REINFORCEMENT ✓ DD	320.00	-20.00	256.00
16	2	FRONT HEADLAMP BRACKET (4/H) ✓ BR (RH) / BR	110.00	-20.00	88.00
17	1	FRONT BUMPER SIDE RETAINER LH ✓ BR	25.00	-20.00	20.00
18	1	FRONT BUMPER SIDE RETAINER RH ✓ BR	25.00	-20.00	20.00
19	1	FRONT BUMPER TOWING COVER X NN	28.00	-20.00	22.40
20	1	FRONT GRILLE BASE ✓ BR	350.00	-20.00	280.00
21	1	FRONT GRILLE OUTER GARNISH ✓ BR	385.00	-20.00	308.00
22	1	FRONT GRILLE LOWER CHROME ? / CUT	110.00	-20.00	88.00
23	1	FRONT EMBLEM ✓ REC	35.00	-20.00	28.00
24	1	FRONT GRILLE TOP COVER ✓ cut	85.00	-20.00	68.00
25	1	FRONT GRILLE CENTRE BRACKET ✓ BR	75.00	-20.00	60.00
26	1	FRONT WIPER GARNISH X NAI	240.00	-20.00	192.00
27	2	FRONT GRILLE SIDE BRACKET ? / BR	70.00	-20.00	56.00
28	1	FRONT HEADLAMP LED RH ✓ BR	1,820.20	-20.00	1,456.16
29	1	FRONT HEADLAMP LED LH ✓ BR	1,820.20	-20.00	1,456.16
30	2	FRONT FOG LAMP (4/H) ? / BR	656.00	-20.00	524.80
31	1	FRONT FENDER LH ✓ DD	558.00	-20.00	446.40
32	1	FRONT FENDER RH ✓ DD	558.00	-20.00	446.40
33	1	FRONT FENDER WHEEL ARCH GARNISH LH ✓ CRU	195.00	-20.00	156.00
34	1	FRONT FENDER WHEEL ARCH GARNISH RH X NAI	195.00	-20.00	156.00
35	1	FRONT FENDER INNER SHIELD X NAI	130.00	-20.00	104.00
36	1	ENGINE UNDER COVER X NAI	120.00	-20.00	96.00
37	1	ENGINE UNDER LH X / CRU	110.00	-20.00	88.00
38	1	FRONT SUPPORT PANEL ✓ DD	576.00	-20.00	460.80
39	1	AIR DUCT ✓ BR	107.00	-20.00	85.60
40	1	AIR DUCT TUBE X / CRU	56.00	-20.00	44.80
41	1	AIR CON CONDENSER ✓ DD	750.00	-20.00	600.00
42	1	RADIATOR ✓ DD	1,376.60	-20.00	1,101.28
43	1	RADIATOR FAN COWLING ? / BR	225.00	-20.00	180.00
44	1	RADIATOR FAN BLADE ? X NAI	87.00	-20.00	69.60
45	1	RADIATOR FAN MOTOR ? X NAI	398.00	-20.00	318.40
46	1	AIR CON COWLING ? X NAI	228.00	-20.00	182.40
47	1	AIR CON FAN BLADE ? X NAI	88.00	-20.00	70.40
48	1	AIR CON MOTOR ? X NAI	308.00	-20.00	246.40
49	1	AIR CON PIPE ALUMINIUM ? X NAI	295.00	-20.00	236.00
50	1	AIR CON SUCTION HOSE ? X NAI	285.00	-20.00	228.00
51	1	AIR CON DISCHARGE PIPE ? X NAI	270.00	-20.00	216.00
52	1	RADIATOR SPARE TANK ? / CRU	62.00	-20.00	49.60
53	1	ENGINE MOUNTING RH X NAI	354.00	-20.00	283.20

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
54	1	ENGINE MOUNTING LH X NMI	335.00	-20.00	268.00
55	1	INTAKE MANIFOLD ✓ cut	406.00	-20.00	324.80
56	1	ECU UNIT ENGINE X NMI	2,750.00	-20.00	2,200.00
57	1	REAR TAILGATE ✓ DO	1,100.00	-20.00	880.00
58	1	REAR TAILGATE LAMP RH ? / OR	330.00	-20.00	264.00
59	1	REAR TAILGATE LAMP LH ✓ CRU	330.00	-20.00	264.00
60	2	REAR OUTER TAIL LAMP (LH) ✓ BR (RH) ? / CRU	850.00	-20.00	704.00
61	1	TAILGATE EMBLEM ✓ REC	45.00	-20.00	36.00
62	1	VEZEL EMBLEM ✓ REC	43.00	-20.00	34.40
63	1	HYBRID EMBLEM ✓ REC	75.00	-20.00	60.00
64	1	FRONT WINDSCREEN GLASS - / OR 2000/2000	0.00	-20.00	0.00
65	1	REAR WINDSCREEN GLASS MOULDING ✓ REC	149.00	-20.00	119.20
66	1	REAR WIPER BLADE X NMI	48.00	-20.00	38.40
67	1	REAR WIPER MOTOR X NMI	205.00	-20.00	164.00
68	1	REAR BUMPER ✓ DO	963.00	-20.00	770.40
69	1	REAR BUMPER SIDE RETAINER LH ✓ BR	35.00	-20.00	28.00
70	1	REAR BUMPER SIDE RETAINER RH ✓ BR	35.00	-20.00	28.00
71	1	REAR BUMPER REFLECTOR LH ✓ cut	156.00	-20.00	124.80
72	1	REAR BUMPER REFLECTOR RH X NMI	156.00	-20.00	124.80
73	1	REAR BUMPER LOWER COVER ✓ CRU	260.00	-20.00	208.00
74	1	REAR EXHAUST ? / DO	726.00	-20.00	580.80
75	1	REAR END PANEL ✓ DO	530.70	-20.00	424.56
76	2	TAILLAMP PANEL (LH) DO ✓	270.00	-20.00	216.00
77	1	REAR TAILGATE LOCK ✓ Jam	96.60	-20.00	77.28
78	1	REAR TAILGATE INNER TOP GARNISH ✓ BR	153.00	-20.00	122.40
79	1	TAILGATE HANDLE X NMI	25.00	-20.00	20.00
80	1	REAR FENDER INNER TRIM RH (LH) ✓ CRU	244.00	-20.00	195.20
81	1	CARGO BOX ? / CRU	193.00	-20.00	154.40
82	1	SPARE TYRE TOP BOARD ✓ CRU	430.00	-20.00	344.00
83	1	REAR FLOOR PANEL ? / DO	875.00	-20.00	700.00
84	1	REAR END PANEL TOP GARNISH ✓ CRU	107.00	-20.00	85.60
85	2	INNER TRIM TOP X NMI	100.00	-20.00	80.00
86	2	REAR PILLAR INNER GARNISH X NMI	190.00	-20.00	152.00
87	1	REAR WIPER ARM X NMI	50.00	-20.00	40.00
88	1	REAR EXHAUST CHROME PIPE ✓ cut	135.00	-20.00	108.00
89	1 (1 SH)	REAR HYBRID BATTERY ? X Refer Supp.	8,500.00	-20.00	6,800.00
90	1 (1 SH)	REAR HYBRID BATTERY TOP ALUMINIUM ? X Refer Supp.	825.00	-20.00	260.00
		COVER ?			10,000
91	1 (1 SH)	REAR HYBRID BATTERY CASING X Refer Supp.	256.00	-20.00	204.80
92	1	DASHBOARD ✓ BR	1,260.00	-20.00	1,008.00
93	1	DASHBOARD AIRBAG LH ✓ BR	2,236.80	-20.00	1,789.44
94	1	STEERING AIRBAG ✓ BR	1,605.00	-20.00	1,284.00
95	1	AIRBAG ECU ✓ REC	980.00	-20.00	784.00
96	2	FRONT AIRBAG SENSOR ✓ REC	340.00	-20.00	272.00
97	1	FRONT SEAT BELT RH ✓ Jam	680.00	-20.00	544.00
98	1	FRONT SEAT BELT LH ✓ Jam	680.00	-20.00	544.00
99	1	DOOR PILLAR CENTRE INNER TOP X NMI	310.00	-20.00	248.00
100	1	GARNISH			
		DOOR PILLAR CENTRE INNER LOWER X NMI	305.00	-20.00	244.00
101	1	GARNISH			
101	1	REAR WHEEL ARCH GARNISH LH ✓ CRU	154.00	-20.00	123.20
102	1	REAR WHEEL ARCH GARNISH RH X NMI	154.00	-20.00	123.20
103	1	REAR FENDER CORNER GARNISH RH X / CRU	270.00	-20.00	216.00
104	1	REAR FENDER CORNER GARNISH LH X / CRU	270.00	-20.00	216.00
105	2	REAR FENDER INNER SHIELD ✓ CRU (LH)	440.00	-20.00	352.00
106	1	REAR AXLE ? / QT	1,800.00	-20.00	1,440.00
107	1	REAR CHASSIS MEMBER LH ? / DO	2,200.00	0.00	2,200.00

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
108	1	REAR CHASSIS MEMBER RH <i>? X R</i>	2,200.00	0.00	2,200.00
109	1	REAR DOOR LH <i>X R</i>	0.00	0.00	0.00
110	1	REAR DOOR RH <i>X NNI</i>	0.00	0.00	0.00

Total Parts (S\$) 43,968.08

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	21	FRONT GRILLE CLIP <i>✓ see</i>	90.00	0.00	90.00 <i>15</i>
2	2	FRONT FENDER INNER SHIELD CLIPS <i>see</i>	76.00	0.00	76.00 <i>20</i>
3	1	REAR NUMBER PLATE <i>✓ (V)</i>	45.00	0.00	45.00 <i>35</i>
4	2	REAR NUMBER PLATE LAMP <i>X NNI</i>	60.00	0.00	60.00 <i>X</i>
5	1	REAR REVERSE SENSOR <i>✓ BR</i>	240.00	0.00	240.00 <i>200</i>
6	1	BATTERY <i>X Runga / CRU</i>	180.00	0.00	180.00 <i>✓</i>
7	1	REAR REVERSE CAMERA <i>X NNI</i>	540.00	0.00	540.00 <i>X</i>
8	1	ERP BRACKET <i>✓ see</i>	12.00	0.00	12.00 <i>12 ✓</i>
9	1	FRONT WINDSCREEN SEALANT <i>✓ see</i>	60.00	0.00	60.00 <i>40</i>
10	1	REAR WINDSCREEN SEALANT <i>✓ see</i>	60.00	0.00	60.00 <i>40</i>

Sub Total (S\$) 1,363.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 <i>50</i>
2	1	To Dismantle & Refit Front Dashboard & related wire harness & related parts.	350.00	0.00	350.00 <i>150</i>
3	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	0.00	180.00 <i>? 80 /</i>
4	1	To Remove and Refit Front Bumper Sensor.	80.00	0.00	80.00 <i>X</i>
5	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 <i>20</i>
6	1	To Computer Reset and Re-program all fault code.	350.00	0.00	350.00 <i>100</i>
7	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	0.00	120.00 <i>100</i>
8	1	To Transfer Rear Tailgate.	80.00	0.00	80.00 <i>50</i>
9	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	0.00	180.00 <i>70</i>
10	1	To Dismantle and Refit Front Windscreen Glass.	100.00	0.00	100.00 <i>✓</i>
11	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00 <i>✓</i>
12	1	Towing Charges.	80.00	0.00	80.00 <i>60</i>
13	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	120.00	0.00	120.00 <i>X</i>
14	1	To Online ECU Programming.	580.00	0.00	580.00 <i>300 /</i>
15	1	To Dismantle and Refit Rear Undercarriage.	180.00 <i>(photo)</i>	0.00	180.00 <i>? 150 /</i>
16	1	To Conduct Computer Wheel Alignment.	80.00	0.00	80.00 <i>X ? 60 /</i>
17	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power	3,500.00	0.00	3,500.00 <i>2300</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
-----	-----	-------------	--------	-------	------------

tools.

Gross Labour Cost (S\$) 6,260.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
-----	-----	-------------	--------	-------	------------

1	1	To Carry-Out Body Cavity Preservation.	60.00	0.00	60.00 30
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00 30
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	0.00	80.00 X
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	2,000.00	0.00	2,000.00 1800

Gross Labour Cost (S\$) 2,185.00 5500

< END OF ESTIMATES >

16/8/19

4.00pm

15/8/19

Hock Ann

P5311883

without

prejudice

L/S repair

15 day

resurvey after paint

P- 25,662.64

M- 542

L- 5500

31,704.64

Supp- 10,929.88

42,625.52

L/S- 34,100.41

= 34,100

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate

Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1908/012
Policy No:	5098271236-01	Date of Loss:	08/09/2019
Vehicle Reg. No.:	SLT6784J	Driveable?	yes
Driver Age:	15/01/2020	Third Party Vehicle No.:	SLD3013E
Any Injuries?	yes	Contact No:	91393796
Insured/Claimant:	TAN TING TING (CHEN TINGTING)	Driver:	NG KOK LIANG

Make/Model:	Honda, Vezel - RU1	Vehicle Reg. Date:	07/12/2017
Vehicle Colour:	white	Engine Number:	LEB5953152
Chassis No:	RU31253135	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss CHAIN COLLISION

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

Amount

Parts	19,573.76
Miscellaneous Items	16.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00

Gross Total(S\$): 19,589.76

GST 7.00%(S\$): 1,371.28

Nett Amount(S\$): 20,961.04

This claim is handled by: SHUYI

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT HEADLAMP LOWER BRACKET RH X <i>MAI</i>	110.00	110.00	-20.00	88.00
2	1	FRONT TEMPERATURE SENSOR / <i>BR</i>	195.00	195.00	-20.00	156.00
3	1	FRONT WINDSCREEN GLASS X <i>Required</i>	2,450.00	2,450.00	-20.00	1,960.00
4	1	FRONT WINDSCREEN GLASS MOULDING <i>PEC</i>	235.40	235.40	-20.00	188.32
5	1	REAR TAILGATE INNER TRIM BOARD / <i>BR</i>	331.70	331.70	-20.00	265.36
6	1	REAR TAILGATE OUTER GARNISH / <i>BR</i>	240.30	240.30	-20.00	192.24
7	1	REAR TAILGATE OUTER GARNISH LOGO X <i>Required</i>	53.00	53.00	-20.00	42.40
8	1	REAR TAILGATE RUBBER / <i>CRV</i>	153.70	153.70	-20.00	122.96
9	1	REAR END PANEL KEYLESS SENSOR / <i>BR</i>	195.00	195.00	-20.00	156.00
10	1	REAR SPARE TYRE PANEL LOWER X <i>R</i>	320.00	320.00	-20.00	256.00
		CROSSMEMBER				
11	1	REAR SPARE TYRE PANEL LOWER / <i>DO</i>	170.00	170.00	-20.00	136.00
		HORIZONTAL CROSSMEMBER				
12	1	REAR UNDERCOVER X <i>Replaced item 73</i>	190.60	190.60	-20.00	152.48
13	1	AIR CLEANER BOX RESONATOR X <i>MAI</i>	211.90	211.90	-20.00	169.52
14	1	AIR CLEANER RESONATOR JOINT PIPE X <i>MAI</i>	110.60	110.60	-20.00	88.48
15	1	REAR HYBRID BATTERY (1 SET) <i>BR/CRV</i>	19,500.00	19,500.00	-10.00	15,600.00
		<i>Rcpt</i> Total Parts (\$\$)				19,573.76

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT WIPER BLADE LH / <i>CRV</i>	16.00	16.00	0.00	16.00
		Sub Total (\$\$)				16.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Gross Labour Cost (\$\$)				0.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Gross Labour Cost (\$\$)				0.00

13,631.10
 - 20%
 10,904.88
 + 16
 10,920.88

< END OF ESTIMATES >

Steve 29/8/19

Veron Chen (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Monday, 9 September 2019 6:18 PM
To: Admin-D (LKKAuto)
Subject: FW: OUR REF: SNM19D203727-SLD3013E-CML - FW: Accident involving SLT6784J (NTUC) claiming against SLD3013E (China Taiping) on 08.08.2019
Attachments: TP letter.jpeg

[CS/CTI19014195/Evf3](#)

From: YT(HQ) <info@yewteegroup.com>
Sent: Monday, 9 September, 2019 12:01 PM
To: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>; 'Elaine Cheong' <elaine.cheong@sg.cntaiping.com>; 'Alfred Toh' <alfred.toh@sg.cntaiping.com>; 'Chee So Chow' <sochow.chee@sg.cntaiping.com>
Cc: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Steve Chen (LKK Auto) <SteveChen@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: OUR REF: SNM19D203727-SLD3013E-CML - FW: Accident involving SLT6784J (NTUC) claiming against SLD3013E (China Taiping) on 08.08.2019

Dear all,

Owner just inform us and said that her front in car camera still with Traffic Police, not sure whether got damaged or not,

But In case there is damage on the camera we will arrange re-survey again,

If the camera was spoiled due to accident,

Attached the police acknowledgement slip ,

FYI,

Thank you.

Best Regards

SHUYI



Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 /6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 62562081
Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Tuesday, 13 August 2019 11:54 am
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; YT(HQ) <info@yewteegroup.com>
Subject: OUR REF: SNM19D203727-SLD3013E-CML - FW: Accident involving SLT6784J (NTUC) claiming against SLD3013E (China Taiping) on 08.08.2019

Dear Elaine,

Please conduct PRS for SLT6784J.

Note : officer in charge – Elaine Cheong 63896530.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: YT(KB) [<mailto:info@yewteegroup.com>]
Sent: Tuesday, August 13, 2019 9:38 AM
To: Claims Dept of CTI
Cc: utauto@singnet.com.sg
Subject: Accident involving SLT6784J (NTUC) claiming against SLD3013E (China Taiping) on 08.08.2019

Hi Motor Claim,

Attached GIA Report.

Kindly arrange PRI at **Kaki Bukit**.

Please let us have the list of surveyor for choose to conduct the pre-repair survey.

Kindly let us have the liability and officer-in-charge too.

Thank You 😊

Best Regards



Yew Tee Automobile Tech Pte Ltd

Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4,
#01-61, Singapore 417800

Office: 6702 3113

Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



SINGAPORE POLICE FORCE
ACKNOWLEDGEMENT SLIP

Ref: Report No: F/20190808/075

I, SS 7100323 Khorui Anik

(Recipient's Name, Contact No. / NRIC or Passport No. / Rank and No.)

of TP

(Address / Police Station / NPC / NPP)

hereby acknowledge receipt of the below mentioned items of:

1 01 BUCK IRON QT IN-car camera (with SD card)

2 Alto

3

4

5

6

7

8

9

10

from Ng Kok Liang 88212908A

(Name, NRIC or Passport No. / Rank and No.)

of NO. 82 Edgehill premis #09-08

(Address / Police Station / NPC / NPP)

on 08/08/19

(Date)

at

1235h

(Time)

Witnessed by / * Handed over by:

(* Delete if applicable)

(Signature)

Ng Kok Liang 88212908A
(Name, NRIC or Passport No. / Rank and No.)

Received by:

(Signature)

SS 7100323 Khorui
(Name, Contact No. / NRIC or Passport No. / Rank and No.)

Other Remarks: TP 10 Softyorn Tel: 65476247

Steve Chen (LKK Auto)

From: YT(HQ) <info@yewteegroup.com>
Sent: Wednesday, October 02, 2019 3:14 PM
To: Steve Chen (LKK Auto)
Cc: utauto@singnet.com.sg
Subject: RE: SLT6784J Finalize

Hi Steve,

Ok confirm ,

Thank you.

Best Regards

SHUYI



Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 /6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 62562081
Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Friday, 27 September 2019 4:52 pm
To: YT(HQ) <info@yewteegroup.com>
Cc: utauto@singnet.com.sg
Subject: SLT6784J Finalize

Dear Sir,

Kindly refer our finalize \$34,100.00 (L/S, before GST). 15 repair days.

Kindly confirm.

Thanks.

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) [<mailto:info@yewteegroup.com>]
Sent: Friday, September 27, 2019 3:23 PM
To: Steve Chen (LKK Auto)
Cc: utauto@singnet.com.sg
Subject: RE: SLT6784J SUPPLY

Hi Steve,

Pls ignore my previous email,

Kindly find attached the estimate report,

And let us have the marking soon,

Thank you.

Best Regards

SHUYI

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Aug 2019		15 Aug 2019 13:44 Edit Adj Rpt	S\$34,100.00 Edit Estimates	S\$34,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	TAN TING TING (CHEN TINGTING) , ID: S8338294E								
Vehicle Reg. No.:	SLT6784J	Date of Loss:	08/08/2019 13:00 - :59 [21 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203727C02	Policy/Cover Note No.:	DMPCSN1737211902						
Vehicle Reg. No. (Insured):	SLD3013E	Policy No. (Claimant):	5098271236-01						
		Excess:	S\$1,250.00						
Repairer:	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Bk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel: 67023113								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 26/08/2019]								
Adj Asg. Remarks:	TP workshop requested Marcus to survey their vehicle.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT6784J (SNM19D203727C02)
[SLD3013E]
TP
TAN TING TING (CHEN TINGTING)
Aug 8 2019 1:00PM
[-]
Yew Tee Automobile Tech Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser v	
Assessment Reports				1 per page v	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	08/08/19 19:08	Accident Statement		Load HTML	
Photos/Images				3 per page v	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	08/08/19 19:07	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	08/08/19 19:07	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	08/08/19 19:07	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	08/08/19 19:07	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	08/08/19 19:07	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	08/08/19 19:07	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	08/08/19 19:07	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	08/08/19 19:07	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	08/08/19 19:07	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/09/19 10:31	General View		Load JPG	☒
2	27/09/19 10:31	General View		Load JPG	☒
3	27/09/19 10:31	General View		Load JPG	☒
4	27/09/19 10:31	General View		Load JPG	☒
5	27/09/19 10:31	General View		Load JPG	☒
6	27/09/19 10:31	General View		Load JPG	☒
7	27/09/19 10:31	General View		Load JPG	☒
8	27/09/19 10:31	General View		Load JPG	☒
9	27/09/19 10:31	General View		Load JPG	☒
10	27/09/19 10:31	General View		Load JPG	☒
11	27/09/19 10:31	General View		Load JPG	☒
12	27/09/19 10:31	General View		Load JPG	☒
13	27/09/19 10:31	General View		Load JPG	☒
14	27/09/19 10:31	General View		Load JPG	☒
15	27/09/19 10:31	General View		Load JPG	☒
16	27/09/19 10:31	General View		Load JPG	☒
17	27/09/19 10:31	General View		Load JPG	☒
18	27/09/19 10:31	General View		Load JPG	☒
19	27/09/19 10:31	General View		Load JPG	☒
20	27/09/19 10:31	General View		Load JPG	☒
21	27/09/19 10:31	General View		Load JPG	☒
22	27/09/19 10:31	General View		Load JPG	☒
23	27/09/19 10:31	General View		Load JPG	☒
24	27/09/19 10:31	General View		Load JPG	☒
25	27/09/19 10:31	General View		Load JPG	☒
26	27/09/19 10:31	General View		Load JPG	☒
27	27/09/19 10:31	General View		Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print
					☒
28	27/09/19 10:31	General View		Load JPG	☒
29	27/09/19 10:31	General View		Load JPG	☒
30	27/09/19 10:31	General View		Load JPG	☒
31	27/09/19 10:31	General View		Load JPG	☒
32	27/09/19 10:32	General View		Load JPG	☒
33	27/09/19 10:32	General View		Load JPG	☒
34	27/09/19 10:32	General View		Load JPG	☒
35	27/09/19 10:32	General View		Load JPG	☒
36	27/09/19 10:32	General View		Load JPG	☒
37	27/09/19 10:32	General View		Load JPG	☒
38	27/09/19 10:32	General View		Load JPG	☒
39	27/09/19 10:32	General View		Load JPG	☒
40	27/09/19 10:32	General View		Load JPG	☒
41	27/09/19 10:32	General View		Load JPG	☒
42	27/09/19 10:32	General View		Load JPG	☒
43	27/09/19 10:32	General View		Load JPG	☒
44	27/09/19 10:32	General View		Load JPG	☒
45	27/09/19 10:32	General View		Load JPG	☒
46	27/09/19 10:32	General View		Load JPG	☒
47	27/09/19 10:32	General View		Load JPG	☒
48	27/09/19 10:32	General View		Load JPG	☒
49	27/09/19 10:32	General View		Load JPG	☒
50	27/09/19 10:32	General View		Load JPG	☒
51	27/09/19 10:32	General View		Load JPG	☒
52	27/09/19 10:32	General View		Load JPG	☒
53	27/09/19 10:32	General View		Load JPG	☒
54	27/09/19 10:32	General View		Load JPG	☒
55	27/09/19 10:32	General View		Load JPG	☒
56	27/09/19 10:32	General View		Load JPG	☒
57	27/09/19 10:32	General View		Load JPG	☒
58	27/09/19 10:32	General View		Load JPG	☒
59	27/09/19 10:32	General View		Load JPG	☒
60	27/09/19 10:32	General View		Load JPG	☒
61	27/09/19 10:32	General View		Load JPG	☒
62	27/09/19 10:32	General View		Load JPG	☒
63	27/09/19 10:32	General View		Load JPG	☒
64	27/09/19 10:32	General View		Load JPG	☒
65	27/09/19 10:32	General View		Load JPG	☒
66	27/09/19 10:32	General View		Load JPG	☒
67	27/09/19 10:32	General View		Load JPG	☒
68	27/09/19 10:32	General View		Load JPG	☒
69	27/09/19 10:32	General View		Load JPG	☒
70	27/09/19 10:32	General View		Load JPG	☒
71	27/09/19 10:32	General View		Load JPG	☒
72	27/09/19 10:32	General View		Load JPG	☒
73	27/09/19 10:32	General View		Load JPG	☒
74	27/09/19 10:32	General View		Load JPG	☒
75	27/09/19 10:32	General View		Load JPG	☒
76	27/09/19 10:32	General View		Load JPG	☒
77	27/09/19 10:32	General View		Load JPG	☒
78	27/09/19 10:32	General View		Load JPG	☒
79	27/09/19 10:32	General View		Load JPG	☒
80	27/09/19 10:32	General View		Load JPG	☒
81	27/09/19 10:32	General View		Load JPG	☒
82	27/09/19 10:32	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
83	27/09/19 10:32	General View	 Load JPG	☒
84	27/09/19 10:32	General View	 Load JPG	☒
85	27/09/19 10:32	General View	 Load JPG	☒
86	27/09/19 10:32	General View	 Load JPG	☒
87	27/09/19 10:32	General View	 Load JPG	☒
88	27/09/19 10:32	General View	 Load JPG	☒
89	27/09/19 10:32	General View	 Load JPG	☒
90	27/09/19 10:32	General View	 Load JPG	☒
91	27/09/19 10:32	General View	 Load JPG	☒
92	27/09/19 10:32	General View	 Load JPG	☒
93	27/09/19 10:32	General View	 Load JPG	☒
94	27/09/19 10:32	General View	 Load JPG	☒
95	27/09/19 10:32	General View	 Load JPG	☒
96	27/09/19 10:32	General View	 Load JPG	☒
97	27/09/19 10:32	General View	 Load JPG	☒
98	27/09/19 10:32	General View	 Load JPG	☒
99	27/09/19 10:32	General View	 Load JPG	☒
100	27/09/19 10:32	General View	 Load JPG	☒
101	27/09/19 10:32	General View	 Load JPG	☒
102	27/09/19 10:32	General View	 Load JPG	☒
103	27/09/19 10:32	General View	 Load JPG	☒
104	27/09/19 10:32	General View	 Load JPG	☒
105	27/09/19 10:32	General View	 Load JPG	☒
106	27/09/19 10:32	General View	 Load JPG	☒
107	27/09/19 10:32	General View	 Load JPG	☒
108	27/09/19 10:32	General View	 Load JPG	☒
109	27/09/19 10:32	General View	 Load JPG	☒
110	27/09/19 10:32	General View	 Load JPG	☒
111	27/09/19 10:32	General View	 Load JPG	☒
112	27/09/19 10:32	General View	 Load JPG	☒
113	27/09/19 10:32	General View	 Load JPG	☒
114	27/09/19 10:32	General View	 Load JPG	☒
115	27/09/19 10:32	General View	 Load JPG	☒
116	27/09/19 10:32	General View	 Load JPG	☒
117	27/09/19 10:32	Chassis Number	 Load JPG	☒
118	27/09/19 10:32	General View	 Load JPG	☒
119	27/09/19 10:32	General View	 Load JPG	☒
120	27/09/19 10:32	General View	 Load JPG	☒
121	27/09/19 10:32	Odometer Reading	 Load JPG	☒
122	27/09/19 10:32	General View	 Load JPG	☒
123	27/09/19 10:32	General View	 Load JPG	☒
124	27/09/19 10:32	General View	 Load JPG	☒
125	27/09/19 10:32	General View	 Load JPG	☒
126	27/09/19 10:32	General View	 Load JPG	☒
127	27/09/19 10:32	General View	 Load JPG	☒
128	27/09/19 10:32	General View	 Load JPG	☒
129	27/09/19 10:32	General View	 Load JPG	☒
130	27/09/19 10:32	General View	 Load JPG	☒
131	27/09/19 10:32	General View	 Load JPG	☒
132	27/09/19 10:32	General View	 Load JPG	☒
133	27/09/19 10:32	General View	 Load JPG	☒
134	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
135	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
136	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
137	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
138	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
139	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
140	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
141	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
142	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
143	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
144	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
145	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
146	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
147	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
148	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
149	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
150	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
151	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
152	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
153	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
154	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
155	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
156	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
157	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
158	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
159	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
160	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
161	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
162	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
163	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
164	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
165	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
166	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
167	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
168	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
169	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
170	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
171	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
172	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
173	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
174	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
175	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
176	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
177	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
178	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
179	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
180	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
181	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
182	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
183	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
184	27/09/19 10:33	Photographs of Damaged Parts	 Load JPG	☒
185	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
186	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
187	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
188	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
189	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
190	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
191	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
192	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
193	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒
194	27/09/19 10:33	Photographs of Damaged Parts	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
195	27/09/19 10:33	Photographs of Damaged Parts		☒
196	27/09/19 10:33	Photographs of Damaged Parts		☒
197	27/09/19 10:33	Photographs of Damaged Parts		☒
198	27/09/19 10:33	Photographs of Damaged Parts		☒
199	27/09/19 10:33	Photographs of Damaged Parts		☒
200	27/09/19 10:33	Photographs of Damaged Parts		☒
201	27/09/19 10:33	Photographs of Damaged Parts		☒
202	27/09/19 10:33	Photographs of Damaged Parts		☒
203	27/09/19 10:33	Photographs of Damaged Parts		☒
204	27/09/19 10:33	Photographs of Damaged Parts		☒
205	27/09/19 10:33	Photographs of Damaged Parts		☒
206	27/09/19 10:33	Photographs of Damaged Parts		☒
207	27/09/19 10:33	Photographs of Damaged Parts		☒
208	27/09/19 10:33	Photographs of Damaged Parts		☒
209	27/09/19 10:33	Photographs of Damaged Parts		☒
210	27/09/19 10:33	Photographs of Damaged Parts		☒
211	27/09/19 10:33	Photographs of Damaged Parts		☒
212	27/09/19 10:33	Photographs of Damaged Parts		☒
213	27/09/19 10:33	Photographs of Damaged Parts		☒
214	27/09/19 10:33	Photographs of Damaged Parts		☒
215	27/09/19 10:33	Photographs of Damaged Parts		☒
216	27/09/19 10:33	Photographs of Damaged Parts		☒
217	27/09/19 10:33	Photographs of Damaged Parts		☒
218	27/09/19 10:33	Photographs of Damaged Parts		☒
219	27/09/19 10:33	Photographs of Damaged Parts		☒
220	27/09/19 10:33	Photographs of Damaged Parts		☒
221	27/09/19 10:33	Photographs of Damaged Parts		☒
222	27/09/19 10:33	Photographs of Damaged Parts		☒
223	27/09/19 10:33	Photographs of Damaged Parts		☒
224	27/09/19 10:33	Photographs of Damaged Parts		☒
225	27/09/19 10:33	Photographs of Damaged Parts		☒
226	27/09/19 10:33	Photographs of Damaged Parts		☒
227	27/09/19 10:33	Photographs of Damaged Parts		☒
228	27/09/19 10:33	Photographs of Damaged Parts		☒
229	27/09/19 10:33	Photographs of Damaged Parts		☒
230	27/09/19 10:33	Photographs of Damaged Parts		☒
231	27/09/19 10:33	Photographs of Damaged Parts		☒
232	27/09/19 10:33	Photographs of Damaged Parts		☒
233	27/09/19 10:33	Photographs of Damaged Parts		☒
234	27/09/19 10:33	Photographs of Damaged Parts		☒
235	27/09/19 10:33	Photographs of Damaged Parts		☒
236	27/09/19 10:33	Photographs of Damaged Parts		☒
237	27/09/19 10:33	Photographs of Damaged Parts		☒
238	27/09/19 10:33	Photographs of Damaged Parts		☒
239	27/09/19 10:33	Photographs of Damaged Parts		☒
240	27/09/19 10:33	Photographs of Damaged Parts		☒
241	27/09/19 10:33	Photographs of Damaged Parts		☒
242	27/09/19 10:33	Photographs of Damaged Parts		☒
243	27/09/19 10:33	Photographs of Damaged Parts		☒
244	27/09/19 10:33	Photographs of Damaged Parts		☒
245	27/09/19 10:33	Photographs of Damaged Parts		☒
246	27/09/19 10:33	Photographs of Damaged Parts		☒
247	27/09/19 10:33	Photographs of Damaged Parts		☒
248	27/09/19 10:33	Photographs of Damaged Parts		☒
249	27/09/19 10:33	Photographs of Damaged Parts		☒
250	27/09/19 10:33	Photographs of Damaged Parts		☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
251	27/09/19 10:33	Photographs of Damaged Parts		☒
252	27/09/19 10:33	Photographs of Damaged Parts		☒
253	27/09/19 10:33	Photographs of Damaged Parts		☒
254	27/09/19 10:33	Photographs of Damaged Parts		☒
255	27/09/19 10:33	Photographs of Damaged Parts		☒
256	27/09/19 10:33	Photographs of Damaged Parts		☒
257	27/09/19 10:33	Photographs of Damaged Parts		☒
258	27/09/19 10:33	Photographs of Damaged Parts		☒
259	27/09/19 10:33	Photographs of Damaged Parts		☒
260	27/09/19 10:33	Photographs of Damaged Parts		☒
261	27/09/19 10:33	Photographs of Damaged Parts		☒
262	27/09/19 10:33	Photographs of Damaged Parts		☒
263	27/09/19 10:33	Photographs of Damaged Parts		☒
264	27/09/19 10:33	Photographs of Damaged Parts		☒
265	27/09/19 10:33	Photographs of Damaged Parts		☒
266	27/09/19 10:33	Photographs of Damaged Parts		☒
267	27/09/19 10:33	Photographs of Damaged Parts		☒
268	27/09/19 10:33	Photographs of Damaged Parts		☒
269	27/09/19 10:33	Photographs of Damaged Parts		☒
270	27/09/19 10:33	Photographs of Damaged Parts		☒
271	27/09/19 10:33	Photographs of Damaged Parts		☒
272	27/09/19 10:33	Photographs of Damaged Parts		☒
273	27/09/19 10:33	Photographs of Damaged Parts		☒
274	27/09/19 10:33	Photographs of Damaged Parts		☒
275	27/09/19 10:33	Photographs of Damaged Parts		☒
276	27/09/19 10:35	Photographs of Damaged Parts		☒
277	27/09/19 10:35	Photographs of Damaged Parts		☒
278	27/09/19 10:35	Photographs of Damaged Parts		☒
279	27/09/19 10:35	Photographs of Damaged Parts		☒
280	27/09/19 10:35	Photographs of Damaged Parts		☒
281	27/09/19 10:35	Photographs of Damaged Parts		☒
282	27/09/19 10:35	Photographs of Damaged Parts		☒
283	27/09/19 10:35	Photographs of Damaged Parts		☒
284	27/09/19 10:35	Photographs of Damaged Parts		☒
285	27/09/19 10:35	Photographs of Damaged Parts		☒
286	27/09/19 10:35	Photographs of Damaged Parts		☒
287	27/09/19 10:35	Photographs of Damaged Parts		☒
288	27/09/19 10:35	Photographs of Damaged Parts		☒
289	27/09/19 10:35	Photographs of Damaged Parts		☒
290	27/09/19 10:35	Photographs of Damaged Parts		☒
291	27/09/19 10:35	Photographs of Damaged Parts		☒
292	27/09/19 10:35	Photographs of Damaged Parts		☒
293	27/09/19 10:35	Photographs of Damaged Parts		☒
294	27/09/19 10:35	Photographs of Damaged Parts		☒
295	27/09/19 10:36	Photographs of Damaged Parts		☒
296	27/09/19 10:36	Photographs of Damaged Parts		☒
297	27/09/19 10:36	Photographs of Damaged Parts		☒
298	27/09/19 10:36	Photographs of Damaged Parts		☒
299	27/09/19 10:36	Photographs of Damaged Parts		☒
300	27/09/19 10:36	Photographs of Damaged Parts		☒
301	27/09/19 10:36	Photographs of Damaged Parts		☒
302	27/09/19 10:36	Photographs of Damaged Parts		☒
303	27/09/19 10:36	Photographs of Damaged Parts		☒
304	27/09/19 10:36	Photographs of Damaged Parts		☒
305	27/09/19 10:36	Photographs of Damaged Parts		☒
306	27/09/19 10:36	Photographs of Damaged Parts		☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
307	27/09/19 10:36	Photographs of Damaged Parts		☒
308	27/09/19 10:36	Photographs of Damaged Parts		☒
309	27/09/19 10:36	Photographs of Damaged Parts		☒
310	27/09/19 10:36	Photographs of Damaged Parts		☒
311	27/09/19 10:36	Photographs of Damaged Parts		☒
312	27/09/19 10:36	Photographs of Damaged Parts		☒
313	27/09/19 10:36	Photographs of Damaged Parts		☒
314	27/09/19 10:36	Photographs of Damaged Parts		☒
315	27/09/19 10:36	Photographs of Damaged Parts		☒
316	27/09/19 10:36	Photographs of Damaged Parts		☒
317	27/09/19 10:36	Photographs of Damaged Parts		☒
318	27/09/19 10:36	Photographs of Damaged Parts		☒
319	27/09/19 10:36	Photographs of Damaged Parts		☒
320	27/09/19 10:36	Photographs of Damaged Parts		☒
321	27/09/19 10:36	Photographs of Damaged Parts		☒
322	27/09/19 10:36	Photographs of Damaged Parts		☒
323	27/09/19 10:36	Photographs of Damaged Parts		☒
324	27/09/19 10:36	Photographs of Damaged Parts		☒
325	27/09/19 10:36	Photographs of Damaged Parts		☒
326	27/09/19 10:36	Photographs of Damaged Parts		☒
327	27/09/19 10:36	Photographs of Damaged Parts		☒
328	27/09/19 10:36	Photographs of Damaged Parts		☒
329	27/09/19 10:36	Photographs of Damaged Parts		☒
330	27/09/19 10:36	Photographs of Damaged Parts		☒
331	27/09/19 10:36	Photographs of Damaged Parts		☒
332	27/09/19 10:36	Photographs of Damaged Parts		☒
333	27/09/19 10:36	Photographs of Damaged Parts		☒
334	27/09/19 10:36	Photographs of Damaged Parts		☒
335	27/09/19 10:36	Photographs of Damaged Parts		☒
336	27/09/19 10:36	Photographs of Damaged Parts		☒
337	27/09/19 10:36	Photographs of Damaged Parts		☒
338	27/09/19 10:36	Photographs of Damaged Parts		☒
339	27/09/19 10:36	Photographs of Damaged Parts		☒
340	27/09/19 10:36	Photographs of Damaged Parts		☒
341	27/09/19 10:36	Photographs of Damaged Parts		☒
342	27/09/19 10:36	Photographs of Damaged Parts		☒
343	27/09/19 10:36	Photographs of Damaged Parts		☒
344	27/09/19 10:36	Photographs of Damaged Parts		☒
345	27/09/19 10:36	Photographs of Damaged Parts		☒
346	27/09/19 10:36	Photographs of Damaged Parts		☒
347	27/09/19 10:36	Photographs of Damaged Parts		☒
348	27/09/19 10:36	Photographs of Damaged Parts		☒
349	27/09/19 10:36	Photographs of Damaged Parts		☒
350	27/09/19 10:36	Photographs of Damaged Parts		☒
351	27/09/19 10:36	Photographs of Damaged Parts		☒
352	27/09/19 10:36	Photographs of Damaged Parts		☒
353	27/09/19 10:36	Photographs of Damaged Parts		☒
354	27/09/19 10:36	Photographs of Damaged Parts		☒
355	27/09/19 10:36	Photographs of Damaged Parts		☒
356	27/09/19 10:36	Photographs of Damaged Parts		☒
357	27/09/19 10:36	Photographs of Damaged Parts		☒
358	27/09/19 10:36	Photographs of Damaged Parts		☒
359	27/09/19 10:36	Photographs of Damaged Parts		☒
360	27/09/19 10:36	Photographs of Damaged Parts		☒
361	27/09/19 10:36	Photographs of Damaged Parts		☒
362	27/09/19 10:36	Photographs of Damaged Parts		☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
363	27/09/19 10:36	Photographs of Damaged Parts		☒
364	27/09/19 10:36	Photographs of Damaged Parts		☒
365	27/09/19 10:36	Photographs of Damaged Parts		☒
366	27/09/19 10:36	Photographs of Damaged Parts		☒
367	27/09/19 10:36	Photographs of Damaged Parts		☒
368	27/09/19 10:36	Photographs of Damaged Parts		☒
369	27/09/19 10:36	Photographs of Damaged Parts		☒
370	27/09/19 10:36	Photographs of Damaged Parts		☒
371	27/09/19 10:36	Photographs of Damaged Parts		☒
372	27/09/19 10:36	Photographs of Damaged Parts		☒
373	27/09/19 10:36	Photographs of Damaged Parts		☒
374	27/09/19 10:36	Photographs of Damaged Parts		☒
375	27/09/19 10:36	Photographs of Damaged Parts		☒
376	27/09/19 10:36	Photographs of Damaged Parts		☒
377	27/09/19 10:36	Photographs of Damaged Parts		☒
378	27/09/19 10:36	Photographs of Damaged Parts		☒
379	27/09/19 10:36	Photographs of Damaged Parts		☒
380	27/09/19 10:36	Photographs of Damaged Parts		☒
381	27/09/19 10:36	Photographs of Damaged Parts		☒
382	27/09/19 10:36	Photographs of Damaged Parts		☒
383	27/09/19 10:36	Photographs of Damaged Parts		☒
384	27/09/19 10:36	Photographs of Damaged Parts		☒
385	27/09/19 10:36	Photographs of Damaged Parts		☒
386	27/09/19 10:36	Photographs of Damaged Parts		☒
387	27/09/19 10:36	Photographs of Damaged Parts		☒
388	27/09/19 10:36	Photographs of Damaged Parts		☒
389	27/09/19 10:36	Photographs of Damaged Parts		☒
390	27/09/19 10:38	After Repair Photo		☒
391	27/09/19 10:39	After Repair Photo		☒
392	27/09/19 10:39	After Repair Photo		☒
393	27/09/19 10:39	After Repair Photo		☒
394	27/09/19 10:39	After Repair Photo		☒
395	27/09/19 10:39	After Repair Photo		☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/08/19 13:50	PRS - SLT67843		☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	08/08/19 18:32	Sketch Plan [Linked Accident Report Documents]		☒
2	08/08/19 18:32	Sketch Plan #2 [Linked Accident Report Documents]		☒
3	08/08/19 18:33	POLICE REPORT [Linked Accident Report Documents]		☒
4	08/08/19 18:33	POLICE REPORT [Linked Accident Report Documents]		☒
5	08/08/19 18:33	POLICE REPORT [Linked Accident Report Documents]		☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	08/08/19 19:08	Accident Statement		☒
Photos/Images			3 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	08/08/19 19:07	Accident Photo		☒
2	08/08/19 19:07	Accident Photo		☒
3	08/08/19 19:07	Accident Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
				☒
4	08/08/19 19:07	Accident Photo	 Load JPG	☒
5	08/08/19 19:07	Accident Photo	 Load JPG	☒
6	08/08/19 19:07	Accident Photo	 Load JPG	☒
7	08/08/19 19:07	Accident Photo	 Load JPG	☒
8	08/08/19 19:07	Accident Photo	 Load JPG	☒
9	08/08/19 19:07	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	08/08/19 18:32	Sketch Plan	 Load TIF	
2	08/08/19 18:32	Sketch Plan #2	 Load TIF	
3	08/08/19 18:33	POLICE REPORT	 Load TIF	
4	08/08/19 18:33	POLICE REPORT	 Load TIF	
5	08/08/19 18:33	POLICE REPORT	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119014195/EVF3E2

Date: 15/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1737211902
Claimant Vehicle No :	SLT6784J	Insured Vehicle No :	SLD3013E
Date of Loss:	08/08/2019	Nature of Claim:	TP
		Claim No:	SNM19D203727C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT6784J	Engine No:	LEB5953152
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31253135
Reg. Date:	07/11/2017 (Man. Year: 2017)	Odometer:	24914 km
Colour:	Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	74,056.04	37,095.12	36,960.92	49.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,445.00	5,500.00	2,945.00	34.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	82,501.04	42,595.12	39,905.92	48.37
Approved Total (Overridden) (S\$)		34,100.00		
(S\$)	82,501.04	34,100.00	48,401.04	58.67
+ GST 7.00/7.00% (S\$)	5,775.07	2,387.00	3,388.07	58.67
Nett Amount (S\$)	88,276.11	36,487.00	51,789.11	58.67

INSPECTION

Date of Assignment:	15/08/2019	
Date Inspected:	15/08/2019 Inspected At:	399F Woodland Road Repairer : Yew Tee Automobile Tech Pte Ltd
Estimated Period of Repair:	15.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT8784J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	892.00 FL	*892.00 FL
2	1		*FRONT BONNET HINGE LH	Bent	45.00 FL	*45.00 FL
3	1		*FRONT BONNET HINGE RH	Bent	45.00 FL	*45.00 FL
4	1		*BONNET INSULATOR	Crushed	145.00 FL	*145.00 FL
5	1		*BONNET LOCK	Bent	130.00 FL	*130.00 FL
6	2		*RUBBER CENTRE	Crushed	70.00 FL	*70.00 FL
7	2		*CORNER RUBBER	Torn	70.00 FL	*70.00 FL
8	2		*SIDE RUBBER	Not Necessary	70.00 FL	*- FL
9	1		*BONNET STAND	Not Necessary	48.00 FL	*- FL
10	1		*FRONT BUMPER	Broken	800.00 FL	*800.00 FL
11	1		*FRONT BUMPER LOWER AIR GRILLE	Cut	87.00 FL	*87.00 FL
12	1		*FRONT BUMPER LOWER LIP	Crushed	380.00 FL	*380.00 FL
13	1		*FRONT BUMPER LIP RUBBER	Not Necessary	110.00 FL	*- FL
14	1		*FOG LAMP COVER	N/S Crushed	90.00 FL	*45.00 FL
15	1		*FRONT BUMPER REINFORCEMENT	Dented	320.00 FL	*320.00 FL
16	2		*FRONT HEADLAMP BRACKET	Broken	110.00 FL	*110.00 FL
17	1		*FRONT BUMPER SIDE RETAINER LH	Broken	25.00 FL	*25.00 FL
18	1		*FRONT BUMPER SIDE RETAINER RH	Broken	25.00 FL	*25.00 FL
19	1		*FRONT BUMPER TOWING COVER	Not Necessary	28.00 FL	*- FL
20	1		*FRONT GRILLE BASE	Broken	350.00 FL	*350.00 FL
21	1		*FRONT GRILLE OUTER GARNISH	Broken	385.00 FL	*385.00 FL
22	1		*FRONT GRILLE LOWER CHROME	Cut	110.00 FL	*110.00 FL
23	1		*FRONT EMBLEM	Necessary	35.00 FL	*35.00 FL
24	1		*FRONT GRILLE TOP COVER	Cut	85.00 FL	*85.00 FL
25	1		*FRONT GRILLE CENTRE BRACKET	Broken	75.00 FL	*75.00 FL
26	1		*FRONT WIPER GARNISH	Not Necessary	240.00 FL	*- FL
27	2		*FRONT GRILLE SIDE BRACKET	Broken	70.00 FL	*70.00 FL
28	1		*FRONT HEADLAMP LED RH	Broken	1,820.20 FL	*1,820.20 FL
29	1		*FRONT HEADLAMP LED LH	Broken	1,820.20 FL	*1,820.20 FL
30	1		*FRONT FOG LAMP	N/S Broken	656.00 FL	*354.00 FL
31	1		*FRONT FENDER LH	Dented	558.00 FL	*558.00 FL
32	1		*FRONT FENDER RH	Dented	558.00 FL	*558.00 FL
33	1		*FRONT FENDER WHEEL ARCH GARNISH LH	Crushed	195.00 FL	*195.00 FL
34	1		*FRONT FENDER WHEEL ARCH GARNISH RH	Not Necessary	195.00 FL	*- FL
35	1		*FRONT FENDER INNER SHIELD	Not Necessary	130.00 FL	*- FL
36	1		*ENGINE UNDER COVER	Not Necessary	120.00 FL	*- FL
37	1		*ENGINE UNDER LH	Crushed	110.00 FL	*110.00 FL
38	1		*FRONT SUPPORT PANEL	Dented	576.00 FL	*576.00 FL
39	1		*AIR DUCT	Broken	107.00 FL	*107.00 FL
40	1		*AIR CON CONDENSER	Dented	750.00 FL	*750.00 FL
41	1		*RADIATOR	Dented	1,376.60 FL	*1,376.60 FL
42	1		*RADIATOR FAN COWLING	Broken	225.00 FL	*225.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*RADIATOR FAN BLADE	Not Necessary	87.00 FL	*- FL
44	1		*RADIATOR FAN MOTOR	Not Necessary	398.00 FL	*- FL
45	1		*AIR CON COWLING	Not Necessary	228.00 FL	*- FL
46	1		*AIR CON FAN BLADE	Not Necessary	88.00 FL	*- FL
47	1		*AIR CON MOTOR	Not Necessary	308.00 FL	*- FL
48	1		*AIR CON PIPE ALUMINIUM	Not Necessary	295.00 FL	*- FL
49	1		*AIR CON SUCTION HOSE	Not Necessary	285.00 FL	*- FL
50	1		*AIR CON DISCHARGE PIPE	Not Necessary	270.00 FL	*- FL
51	1		*RADIATOR SPARE TANK	Crushed	62.00 FL	*62.00 FL
52	1		*ENGINE MOUNTING RH	Not Necessary	354.00 FL	*- FL
53	1		*ENGINE MOUNTING LH	Not Necessary	335.00 FL	*- FL
54	1		*INTAKE MANIFOLD	Cut	406.00 FL	*406.00 FL
55	1		*ECU UNIT ENGINE	Not Necessary	2,750.00 FL	*- FL
56	1		*REAR TAILGATE	Dented	1,100.00 FL	*1,100.00 FL
57	1		*REAR TAILGATE LAMP RH	Broken	330.00 FL	*330.00 FL
58	1		*REAR TAILGATE LAMP LH	Cracked	330.00 FL	*330.00 FL
59	2		*REAR OUTER TAIL LAMP	N/S Broken / O/S Cut	880.00 FL	*880.00 FL
60	1		*TAILGATE EMBLEM	Necessary	45.00 FL	*45.00 FL
61	1		*VEZEL EMBLEM	Necessary	43.00 FL	*43.00 FL
62	1		*HYBRID EMBLEM	Necessary	75.00 FL	*75.00 FL
63	1		*FRONT WINDSCREEN GLASS	Broken	2,100.00 FL	*2,100.00 FL
64	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	149.00 FL	*149.00 FL
65	1		*REAR WIPER BLADE	Not Necessary	48.00 FL	*- FL
66	1		*REAR WIPER MOTOR	Not Necessary	205.00 FL	*- FL
67	1		*REAR BUMPER	Dented	963.00 FL	*963.00 FL
68	1		*REAR BUMPER SIDE RETAINER LH	Broken	35.00 FL	*35.00 FL
69	1		*REAR BUMPER SIDE RETAINER RH	Broken	35.00 FL	*35.00 FL
70	1		*REAR BUMPER REFLECTOR LH	Cut	156.00 FL	*156.00 FL
71	1		*REAR BUMPER REFLECTOR RH	Not Necessary	156.00 FL	*- FL
72	1		*REAR BUMPER LOWER COVER	Crushed	260.00 FL	*260.00 FL
73	1		*REAR EXHAUST	Dented	726.00 FL	*726.00 FL
74	1		*REAR END PANEL	Dented	530.70 FL	*530.70 FL
75	1		*TAILLAMP PANEL	N/S Dented	270.00 FL	*135.00 FL
76	1		*REAR TAILGATE LOCK	Jammed	96.60 FL	*96.60 FL
77	1		*REAR TAILGATE INNER TOP GARNISH	Broken	153.00 FL	*153.00 FL
78	1		*TAILGATE HANDLE	Not Necessary	25.00 FL	*- FL
79	1		*REAR FENDER INNER TRIM L/H	Crushed	244.00 FL	*244.00 FL
80	1		*CARGO BOX	Crushed	193.00 FL	*193.00 FL
81	1		*SPARE TYRE TOP BOARD	Crushed	430.00 FL	*430.00 FL
82	1		*REAR FLOOR PANEL	Dented	875.00 FL	*875.00 FL
83	1		*REAR END PANEL TOP GARNISH	Crushed	107.00 FL	*107.00 FL
84	2		*INNER TRIM TOP	Not Necessary	100.00 FL	*- FL
85	2		*REAR PILLAR INNER GARNISH	Not Necessary	190.00 FL	*- FL
86	1		*REAR WIPER ARM	Not Necessary	50.00 FL	*- FL
87	1		*REAR EXHAUST CHROME PIPE	Cut	135.00 FL	*135.00 FL
88	1		*SET REAR HYBRID BATTERY }	Broken / Crushed	19,500.00 FL	*10,000.00 FL
89	1		*SET REAR HYBRID BATTERY TOP ALUMINIUM COVER }		0.00 FL	*- FL
90	1		*SET REAR HYBRID BATTERY CASING }		0.00 FL	*- FL
91	1		*DASHBOARD	Broken	1,260.00 FL	*1,260.00 FL
92	1		*DASHBOARD AIRBAG LH	Broken	2,236.80 FL	*2,000.00 FL
93	1		*STEERING AIRBAG	Broken	1,605.00 FL	*1,300.00 FL
94	1		*AIRBAG ECU	Necessary	980.00 FL	*980.00 FL
95	2		*FRONT AIRBAG SENSOR	Necessary	340.00 FL	*340.00 FL
96	1		*FRONT SEAT BELT RH	Jammed	680.00 FL	*680.00 FL
97	1		*FRONT SEAT BELT LH	Jammed	680.00 FL	*680.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*DOOR PILLAR CENTRE INNER TOP GARNISH	Not Necessary	310.00 FL	*- FL
99	1		*DOOR PILLAR CENTRE INNER LOWER GARNISH	Not Necessary	305.00 FL	*- FL
100	1		*REAR WHEEL ARCH GARNISH LH	Crushed	154.00 FL	*154.00 FL
101	1		*REAR WHEEL ARCH GARNISH RH	Not Necessary	154.00 FL	*- FL
102	1		*REAR FENDER CORNER GARNISH RH	Crushed	270.00 FL	*270.00 FL
103	1		*REAR FENDER CORNER GARNISH LH	Crushed	270.00 FL	*270.00 FL
104	1		*REAR FENDER INNER SHIELD	N/S Crushed	440.00 FL	*220.00 FL
105	1		*REAR AXLE	Bent	1,800.00 FL	*1,800.00 FL
106	1		*REAR CHASSIS MEMBER LH	Dented	2,200.00 FL	*797.00 FL
107	1		*REAR CHASSIS MEMBER RH	Repair	2,200.00 FL	*- FL
108	1		*REAR DOOR LH (NPA)	Repair	0.00 FL	*- FL
109	1		*REAR DOOR RH (NPA)	Not Necessary	0.00 FL	*- FL
110	1		*FRONT GRILLE CLIP (2PCS)	Necessary (1Pc Only)	90.00 FS	*15.00 FS
111	2		*FRONT FENDER INNER SHIELD CLIPS	Necessary	76.00 FS	*20.00 FS
112	1		*REAR NUMBER PLATE	Cut	45.00 FS	*35.00 FS
113	2		*REAR NUMBER PLATE LAMP	Not Necessary	60.00 FS	*- FS
114	1		*REAR REVERSE SENSOR	Broken	240.00 FS	*200.00 FS
115	1		*BATTERY	Crushed	180.00 FS	*180.00 FS
116	1		*REAR REVERSE CAMERA	Not Necessary	540.00 FS	*- FS
117	1		*ERP BRACKET	Necessary	12.00 FS	*12.00 FS
118	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
119	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
120	1		*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	110.00 FL	*- FL
121	1		*FRONT TEMPERARURE SENSOR	Broken	195.00 FL	*195.00 FL
122	1		*FRONT WINDSCREEN GLASS	Repeated	2,450.00 FL	*- FL
123	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	235.40 FL	*235.40 FL
124	1		*REAR TAILGATE INNER TRIM BOARD	Broken	331.70 FL	*331.70 FL
125	1		*REAR TAILGATE OUTER GARNISH	Broken	240.30 FL	*240.30 FL
126	1		*REAR TAILGATE OUTER GARNISH LOGO	Repeated	53.00 FL	*- FL
127	1		*REAR TAILGATE RUBBER	Crushed	153.70 FL	*153.70 FL
128	1		*REAR END PANEL KEYLESS SENSOR	Broken	195.00 FL	*195.00 FL
129	1		*REAR SPARE TYRE PANEL LOWER CROSSMEMBER	Repair	320.00 FL	*- FL
130	1		*REAR SPARE TYRE PANEL LOWER HORIZONTAL CROSSMEMBER	Dented	170.00 FL	*170.00 FL
131	1		*REAR UNDERCOVER	Repeated	190.60 FL	*- FL
132	1		*AIR CLEANER BOX RESONATOR	Not Necessary	211.90 FL	*- FL
133	1		*AIR CLEANER RESONATOR JOINT PIPE	Not Necessary	110.60 FL	*- FL
134	1		*SET REAR HYBRID BATTERY	Repeated	19,500.00 FL	*- FL
135	1		*FRONT WIPER BLADE LH	Cut	16.00 FS	*16.00 FS
136	1		*AIR DUCT TUBE	Crushed	56.00 FL	*56.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	92,225.30	46,229.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	18,169.26	9,134.28
Total Parts (\$\$)	74,056.04	37,095.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	100.00	50.00
2	TO DISMANTLE & REFIT FRONT DASHBOARD & RELATED WIRE HARNESS & RELATED PARTS	New	350.00	150.00
3	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS	New	180.00	80.00
4	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	80.00	0.00
5	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	80.00	20.00
6	TO COMPUTER RESET AND RE-PROGRAM ALL FAULT CODE	New	350.00	100.00
7	TO PRESSURE TEST AIR CON CONDENSER AND RADIATOR FOR LEAKAGE	New	120.00	100.00
8	TO TRANSFER REAR TAILGATE	New	80.00	50.00
9	TO REMOVE & REFIT AIR-CON COMPRESSOR, AIR-CON MOTOR, CONDENSER, PIPES & VACUUM, INCLUDING REFILLING OF GAS	New	180.00	20.00
10	TO DISMANTLE AND REFIT FRONT WINDSCREEN GLASS	New	100.00	100.00
11	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS	New	100.00	100.00
12	TOWING CHARGES	New	80.00	60.00
13	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	120.00	0.00
14	TO ONLINE ECU PROGRAMMING	New	580.00	300.00
15	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE	New	180.00	150.00
16	TO CONDUCT COMPUTER WHEEL ALIGNMENT	New	80.00	60.00
17	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	3,500.00	2,300.00
18	TO CARRY-OUT BODY CAVITY PRESERVATION	New	60.00	30.00
19	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	45.00	30.00
20	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	80.00	0.00
21	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	2,000.00	1,800.00
Gross Labour Cost (\$\$)			8,445.00	5,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >