Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19014210/KKA3Q2

Date: 04/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100401300

Claimant
Vehicle No: SLT2645D

Insured Vehicle No: SFT3233Z

Date of Loss: 12/08/2019 Nature of Claim: TP Claim No: 3380847756SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT2645D

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRS059051

Reg. Date: 24/10/2017 (Man. Year: 2017) Chassis No: JTDKB3FU503562523

Colour: Metallic Pearl White Odometer: 109085 km

Engine Capacity: 1798 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Pirelli 9 mm Rear Left Side: Pirelli 9 mm
Front Right Side: Pirelli 9 mm Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,096.20	2,115.68	1,980.52	48.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	428.06	372.36	55.70	13.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,524.26	2,488.04	2,036.22	45.01
+ GST 7.00/7.00% (S\$)	316.70	174.16	142.54	45.01
Nett Amount (S\$)	4,840.96	2,662.20	2,178.76	45.01
+ Car Rental (4.0 x S\$73.94/day) (S\$)		295.76		
i d	Doc/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	2,965.41		

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 14/08/2019 Inspected At: Esteem Performance Pte Ltd (HQ)

Blk 5033 Ang Mo Kio Ind Park 2, #01-

259

Singapore 569536

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: Khanchna Pothuraj

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LWR AIR GRILLE	Not Necessary	148.60 FL	*- FL
2	1		*L/F BUMPER COVER	Serviceable	25.70 FL	*- FL
3	1		*R/F BUMPER COVER	Serviceable	25.70 FL	*- FL
4	1		*FRONT BUMPER	Cracked	450.80 FL	*450.80 FL
5	1		*FRT LWR BUMPER REINF	Repair	245.30 FL	*- FL
6	1		*FRT BUMPER REINF	Repair	711.50 FL	*- FL
7	1		*FRT BUMPER ABSORBER	Not Necessary	89.81 FL	*- FL
8	1		*FRT LWR BUMP ABSORB	Not Necessary	135.70 FL	*- FL
9	1		*FRONT GRILLE	Serviceable	321.90 FL	*- FL
10	1		*LEFT HEADLAMP ASSY	Mtg Cracked	2,531.60 FL	*2,531.60 FL
11	1		*FRONT BUMPER	Necessary	40.00 FL	*40.00 FL
12	1		*RH FRONT BUMPER	Not Necessary	107.20 FL	*- FL
13	1		*LH FRONT BUMPER	Not Necessary	107.20 FL	*- FL
14	1		*LH FOG LAMP	Not Necessary	910.70 FL	*- FL
F=Fra	anchise	part. L=ListIte	mDisc.			
				Sub Total (S\$)	5,851.71	3,022.40
	- List Item Discount on L Items 30.00/30.00% (S\$)			1,755.51	906.72	
				Total Parts (S\$)	4,096.20	2,115.68

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
24.0 WU X 50.00 SGD/H	New	120.00	95.00
LABOUR COST 41.0 WU X50.00 SGD/H	New	205.00	175.00
MATERIAL COST	New	103.06	102.36
	Gross Labour Cost (S\$)	428.06	372.36
Poport was	unsubmitted during this print out		
	Dur Items 24.0 WU X 50.00 SGD/H LABOUR COST 41.0 WU X50.00 SGD/H MATERIAL COST	Dur Items 24.0 WU X 50.00 SGD/H LABOUR COST 41.0 WU X50.00 SGD/H MATERIAL COST New	Dur Items 24.0 WU X 50.00 SGD/H New 120.00 LABOUR COST 41.0 WU X50.00 SGD/H New 205.00 MATERIAL COST New 103.06 Gross Labour Cost (S\$) 428.06

< END OF ESTIMATES >