

合合車廠私人有限公司
HUP HUP WORKSHOP PTE. LTD.

27-A, JURONG PORT ROAD, #01-29, SINGAPORE 619101
TEL: 6265 5270, 6261 3407, 6265 1966 FAX: 6261 8456
Business Regn. / GST Regn. No. 19-8004325-G

Date: 13/08/2019

M/s AXA INSURANCE PTE LTD

VEHICLE NO. SMM 7602U

MAKE HONDA VEZEL

Our Ref: HHW/TP 2411/2019

Your Ref:

✓ 1 PC	TAIL GATE	bt ✓	\$1,100.90
✓ 1 PC	REAR WINDSCREEN OUTER MOULDING	nr ✓	\$151.80
✓ 1 PC	TAIL GATE (VEZEL) NAME PLATE	nr ✓	\$43.00
✓ 1 PC	REAR BUMPER	de ✓	\$850.60
✓			
LH 2 PCS	REAR BUMPER RED REFLECTOR	LHac ✓, RH-X	@\$148.50 \$297.00
✓ 1 PC	TAIL GATE INNER LOCK	nr X	\$151.80
✓ 1 PC	TAIL GATE TRIMBOARD	nr X	\$193.40
X 1 PC	END PANEL	Rx	\$441.80
✓ 1 PC	REAR EXHAUST PIPE - photo	bt ✓	\$598.60
X 2 PCS	REAR SIDE BUMPER	Rx	@\$195.00 \$390.00
X 1 PC	REAR FENDER GARNISH LH	nr X	\$210.80
✓ 1 PC	REAR SPARE TYRE LOWER COVER - photo	de ✓	\$190.00
✓ 10 PCS	CLIPS	nr ✓	@\$3.90 \$39.00
	Tanpuk 97495749		
	wp 16/8/19 @ 4pm	3122.40	\$4,658.70
	Part by Part, Resurvey before paint LESS 20%	2497.92	\$931.74
	5 days		\$3,726.96
	Tanpuk R / khand.com		
	Resurvey 2/8/19		
	BALANCE C/F		\$3,726.96

合合車廠私人有限公司
HUP HUP WORKSHOP PTE. LTD.

Date: 13/08/2019

VEHICLE NO. SMM 7602U

MAKE HONDA VEZEL

Your Ret:

	BALANCE B/F		\$3,726.96
✓ 1 SET	REVERSE SENSOR & FIXING	200	250 ✓
2 PCS	REAR WINDSCREEN SEALANT	all ✓	@\$40.00
			280
	LABOUR CHARGE TO CUT, WELD, REMOVE, REAR END PANEL AND REPLACE IT. ALIGN, ADJUST, REPAIR TAIL GATE FRAME, REAR SPARE TYRE COMPARTMENT, EXHAUST PIPE.	800	\$1,200.00
	DISMANTLE, REPAIR / FIX PARTS AND TRANSFER MECHANISM & ACCESSORIES.		
	SPRAY PAINT ON TAIL GATE-INSIDE/OUTSIDE, END PANEL-INSIDE/OUTSIDE, REAR BUMPER, REVERSE SENSOR, SPARE TYRE COMPARTMENT. REAR TWO FENDERS.	750	\$1,000.00
	TOTAL	1350	\$6,256.96

Parts 2497.92

8N 280

10600 1350

\$ 4127.92

5 days

page 2

N.B : Estimate does not include 7% GST