

INSURER

INS. CASE OWNER:

CC3 / III1901 4220, T156302

LKK:

IDAC:

Surveyor:

Taufiq

DOI:

ASSIGNMENT

2/9/19

Date / Time:

15/8/19

Registered in Merimen:

15/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SH 9943C

Name of Insured:

LTP

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A.:

14/8/19

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

KJARENTHAM SLO RAMASAMY

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MUT1900017

Policy No.:

MLOM0015

Make / Model:

H9UNDAI

Place of Accident:

FINLAYSON GREEN (near RIGHT

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SUQ 6292



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

URGENT  
URGENT  
URGENT

Date/Time		STAGE	DATE / PIC
		Non-Reporting 1st (1st):	
		Non-Reporting 1st (2nd):	
		Non-Reporting 1st (Final):	
		Notification 1st (if non-pickup):	
		Call OI:	
		After call 1st to OI:	
		Documentation Check List:	Handler Typist
		Notification 1st (if non-pickup):	
		After call 1st to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GLA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$S	days) Reduction:	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	Nil.
Repair Cost:	\$S		
Loss of Rental (LOR):	\$S	days)	
Loss of Use (LOU):	\$S	days)	
Loss of Income (LOI):	\$S	days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>		LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]
GLA/LTA Search	\$S		
Medical:	\$S		
Disbursement:	\$S	(e.g. Tow/ Independent)	
Legal Cost	\$S		
Total:	\$S	Global Sum \$S:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$S	Name 1:	Performance Motors Ltd
Payee 2: (Strike if N.A.)	\$S	Name 2:	
Payee 3: (Strike if N.A.)	\$S	Name 3:	

Business

Taylor

REF:

III

W

# ASSIGNMENT

From

Date:

2-9-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SLQ 625R

at Workshop m/s Performana  
of 303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT  
Luthian

Veh No:

SLQ 625R

Yr Regn:

2017, June

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X1

c.c 1499

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

47940

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBSAHY 20905.H4885

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A

D.O.I

2/9/19 CL-20

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PIP \$ 10489.05 and \$ 1513.70 (17%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

D + Rd. \$

Phone

Other

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 19740155PW GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

380, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

15 AUG 2019

Estimate No. : b1 52327  
Date Estimated : 15/08/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Teo Yi Sheng Jason  
Blk 150 Ang Mo Kio Avenue 5  
#05-3048  
Singapore  
Singapore 560150

- ACCOUNT - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ625R	5H48085	27/06/2017	X1 sDrive18i	0

## DESCRIPTION

## VALUE

To replace front bumper, fender right and attachments.

1700 2,550.00

Painting front bumper and fender right.

1996 2,218.00

To replace left or right headlight.

408 481.00

To replace tyre and wheel rim including balancing. (1x).

80 94.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)

451 531.00

To carry out body cavity preservation.  
(Per panel).

100 118.00

Sundries.

150 80.00

Total Labour 1: 6,072.00

## DESCRIPTION

## QTY PRIC

## VALUE

LIGHT ALLOY WHEEL Y SPK 569

1 1,006.00

1000 1,006.00

RH WHEEL HOUSING STRUT EXTENSION

1 147.10

100 147.10

FRT RH SIDE PANEL

1 664.00

100 664.00

FRT BUMPER PANEL PRIMED (PDC/PMA)

1 854.55

100 854.55

RH OPEN GRID (BASIC PDC)

1 111.45

100 111.45

FRT BUMPER PANEL LOWER SECTION (PDC)

1 281.80

213.65 281.80

FRT RH WHEEL ARCH TRIM

1 151.00

100 151.00

RH HEADLIGHT LED TECHNOLOGY

1 2,670.85

100 2,670.85

Total Parts : 5,886.75

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401859M GST Reg. No. M2-0020081-X  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 436180  
Fax: 63445773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64706631 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 52327  
Date Estimated : 15/08/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ625R	5H48085	27/06/2017	X1 sDrive18i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
Date & Time: 2/9/19 10:00 Excess S\$ \_\_\_\_\_  
Surveyor's Name: Taufik Sign: [Signature]  
Surveyor's Tel: 97495249 Authorised: Yes / No  
Authorised Date: 2/9/19 Time: \_\_\_\_\_  
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No  
Surveyor's E-mail: taufik@lkh.com.sg  
No. of Working Days Recommend: 05 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,072.00
Parts	:	5,886.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	837.11
Grand Total	:	12,795.86

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



## Supplementary

Estimate No. : **b1 52327**  
Date Estimated : **15/08/2019**  
Prepared By : **Inthiran A/L Thurasamy**

### - ESTIMATE REPAIR FOR -

**Teo Yi Sheng Jason**  
**Blk 150 Ang Mo Kio Avenue 5**  
**#05-3048**  
**Singapore**  
**Singapore 560150**

### - ACCOUNT - 219

**India Int'L Insurance Pte Ltd**  
**64 Cecil Street**  
**#04-05 IOB Building**  
**Singapore 049711**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLQ625R</b>	<b>5H48085</b>	<b>27/06/2017</b>	<b>X1 sDrive18i</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# EXPANDING RIVET BLACK	1.40	10.00		14.00
-------------------------	------	-------	--	-------

### # SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	14.00
Total Labour & Parts :	14.00

11972.75

BMW Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X  
 Toll-Free Number (1800-2255268)

111, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax: 64747770

111, Kampong Arang Road  
 East Coast Centre  
 Singapore 435158  
 Fax: 63448773

111, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax: 64794401 (AfterSales)  
 64794424 (Motorsrad)



GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

15 AUG 2019

Estimate No.	: b1 52327	Page No. : 1 of 5
Date Estimated	: 15/08/2019	
Prepared By	: Inthiran A/L Thurasamy	

<b>- ESTIMATE REPAIR FOR -</b> <b>Teo Yi Sheng Jason</b> <b>Blk 150 Ang Mo Kio Avenue 5</b> <b>#05-3048</b> <b>Singapore</b> <b>Singapore 560150</b>	<b>- ACCOUNT - 219</b> <b>India Int'L Insurance Pte Ltd</b> <b>64 Cecil Street</b> <b>#04-05 IOB Building</b> <b>Singapore 049711</b>
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ625R	5H48085	27/06/2017	X1 sDrive18i	0

DESCRIPTION	VALUE
To replace front bumper, fender right and attachments.	1700 2,550.00
Painting front bumper and fender right.	1996 2,218.00
To replace left or right headlight.	408 481.00
To replace tyre and wheel rim including balancing. (1x)	80 94.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)	451 531.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries.	150.7 80.00

Total Labour 1: **6,072.00**

DESCRIPTION	QTY	PRIC	VALUE
LIGHT ALLOY WHEEL Y SPK 569	1	1,006.00	cut ✓ 1,006.00
RH WHEEL HOUSING STRUT EXTENSION	1	147.10	? ✓ 147.10
FRT RH SIDE PANEL	1	664.00	64 ✓ 664.00
FRT BUMPER PANEL PRIMED (PDC/PMA)	1	854.55	del ✓ 854.55
RH OPEN GRID (BASIC PDC)	1	111.45	? ✓ 111.45
FRT BUMPER PANEL LOWER SECTION (PDC)	1	281.80	213.65 cut ✓ 281.80
FRT RH WHEEL ARCH TRIM	1	151.00	cut ✓ 151.00
RH HEADLIGHT LED TECHNOLOGY	1	2,670.85	cut ✓ 2,670.85
Total Parts :			<b>5,886.75</b>



## Final Report

Estimate No. : **b1 52327**  
Date Estimated : **15/08/2019**  
Prepared By : **Inthiran A/L Thurasamy**

**- ESTIMATE REPAIR FOR -**  
**Teo Yi Sheng Jason**  
**Blk 150 Ang Mo Kio Avenue 5**  
**#05-3048**  
**Singapore**  
**Singapore 560150**

**- ACCOUNT - 219**  
**India Int'L Insurance Pte Ltd**  
**64 Cecil Street**  
**#04-05 IOB Building**  
**Singapore 049711**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLQ625R</b>	<b>5H48085</b>	<b>27/06/2017</b>	<b>X1 sDrive18i</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments, front right fender, front right wheel arch trim including remove attachments to facilitate repairs and knock out dented area caused by the accident.	1,700.00		1,700.00
To respray front bumper and front right fender.	1,996.00		1,996.00
To replace right LED technology headlight including program and conduct tests for proper function.	408.00		408.00
To replace front right wheel rim including balancing. (1x).	80.00		80.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)	451.00		451.00
To carry out body cavity preservation. (Per panel).	100.00		100.00
Sundries.	150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
LIGHT ALLOY WHEEL Y SPK 569	1,006.00	1.00		1,006.00
FRT RH SIDE PANEL	664.00	1.00		664.00
FRT BUMPER PANEL PRIMED (PDC/PMA)	854.55	1.00		854.55
FRT BUMPER PANEL LOWER SECTION (PDC	213.65	1.00		213.65
# EXPANDING RIVET BLACK	1.40	10.00		14.00
FRT RH WHEEL ARCH TRIM	151.00	1.00		151.00
RH HEADLIGHT LED TECHNOLOGY	2,670.85	1.00		2,670.85

### # SUPPLEMENTARY ITEMS

Total Labour :	4,885.00
Total Parts :	5,574.05
Total Labour & Parts :	10,459.05
Deduction for Excess :	0.00

## Hsiao Tong (LKKAUTO)

---

**From:** Taufikh (LKKAUTO)  
**Sent:** Thursday, 3 October 2019 12:04 PM  
**To:** 'Toh Jing Xuan'  
**Cc:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: FINAL REPORT / SLQ625R / DS CLAIM

Hi Toh,

COR \$10,459.05 , 5 days.

Regards  
Taufikh  
Lkk Auto

---

**From:** Toh Jing Xuan [mailto:toh.jing.xuan@simedarby.com.sg]  
**Sent:** Tuesday, 17 September 2019 8:19 PM  
**To:** taufikh@lkkauto.com  
**Subject:** FINAL REPORT / SLQ625R / DS CLAIM

Dear Taufikh,

We refer to above matter and attachment Final Report.

Kindly confirm quantum for COR:

Total Labour : \$4,885.00  
Total Parts : \$5,574.05  
Total Labour and Parts : \$10,459.05

Repair work days : 5 days.

Thank you.

Best regard,

Toh Jing Xuan (Ms)  
PML - Body and Paint  
DID: 63190122  
Fax: 64743229

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."





**AVG**

This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Hsiao Tong (LKKAUTO)

---

**From:** Anthony Teo Chin Yong <anthony.teo.cy@simedarby.com.sg>  
**Sent:** Friday, 30 August 2019 8:49 AM  
**To:** Mekavathanan Sarangapani; Cresendo Llorca Lagman; PBSP  
**Cc:** Sundari Nagarajan - III; Gabriel Wee; Hsiao Tong (LKKAUTO); Olivia Lau (LKKAUTO); Bernard Wan Chong Huat  
**Subject:** RE: III Ref:MCT19080287/01/sn; Accdt invg SH9943C(III) & SLQ625R on 14.8.19

Dear Mega,

Thank you for your support and approval for the direct settlement of the above caption.

My team will engage LKK for the inspection of the vehicle.

Best regards,

Anthony Teo  
Aftersales Director  
Performance Motors Limited  
A Member of the Sime Darby Group



**From:** Mekavathanan Sarangapani <mekavathanan@iii.com.sg>  
**Sent:** Friday, August 30, 2019 8:45 AM  
**To:** Anthony Teo Chin Yong <anthony.teo.cy@simedarby.com.sg>; Cresendo Llorca Lagman <cresendo.lagman@simedarby.com.sg>; PBSP <pml-pbsp@simedarby.com.sg>  
**Cc:** Sundari Nagarajan - III <sundari@iii.com.sg>; Gabriel Wee <Gabriel@iii.com.sg>; Hsiao Tong (chewht@lkkauto.com) <chewht@lkkauto.com>; Olivia Lau (olivialau@lkkauto.com) <olivialau@lkkauto.com>  
**Subject:** FW: III Ref:MCT19080287/01/sn; Accdt invg SH9943C(III) & SLQ625R on 14.8.19

Without Prejudice

Dear Anthony,

As discussed, we are agreeable to direct settlement for this case.

Please arrange for your clients vehicle to inspected by our appointed panel of surveyors , M/s LKK soon .

Best Regards,

Mekavathanan  
HOD  
Motor Claims Department  
India International Insurance Pte Ltd  
64 Cecil Street, #04/#05 IOB Building, Singapore 049711  
DID: 6347 6105 Fax: 6224 4174

**From:** Sundari Nagarajan - III  
**Sent:** Tuesday, 27 August, 2019 5:38 PM  
**To:** 'PBSP' <pml-pbsp@simedarby.com.sg>  
**Subject:** III Ref:MCT19080287/01/sn; Accdt invg SH9943C(III) & SLQ625R on 14.8.19

Dear Caroline

We refer to the above accident and our telephone conversation a while ago. As requested we are attaching herewith the video recording of the accident from our IV. As you can see there are 3 lanes to your client's right. Your client should have given enough space for the 3 vehicles on the right lane to make a turn. However, he made a sharp right turn without giving way to our ID to make a turn and as such has cut into our ID's lane.

The fact that our IV went straight after the accident is due to the effect of the accident.

Regards,

**Sundari Nagarajan**  
Motor Claims Department  
India International Insurance Pte Ltd  
64, Cecil Street, #04/#05 IOB Building  
Singapore 049711  
DID: 63476071  
FAX: 62244174  
[sundari@iii.com.sg](mailto:sundari@iii.com.sg)  
[www.iii.com.sg](http://www.iii.com.sg)  
Regn No.: 198703792K

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Aug 2019 16:13	Clim Dtl Modified	Claimant's Name: -> TEO YI SHENG JASON. Claimant's ID: -> S8341723D.	[A] Lau Shu Pei
2	15 Aug 2019 16:13	Clim Veh Model Changed	(205228) BMW X1 1.5 SDRIVE 181 (A).	[A] Lau Shu Pei
3	15 Aug 2019 16:13	Clim Created	Reg No: SLQ625R. Acct Date: 2019/08/14. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Performance Motors Limited (Alexandra)	[A] Lau Shu Pei
4	15 Aug 2019 16:13	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	15 Aug 2019 16:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/26	[A] Lau Shu Pei
6	15 Aug 2019 16:13	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	15 Aug 2019 16:13	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
8	15 Aug 2019 16:13	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Lau Shu Pei
9	20 Aug 2019 14:42	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 50% Remarks : conflicting version. Both parties turning	[A] VIVIAN LAU PEI FENG
10	20 Aug 2019 17:36	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/26. Mandate Remarks: We are awaiting video from TP. We will revert once we receive the AVF. You may request AVF from TP also	[I] Sundari Nagarajan
11	20 Aug 2019 17:36	Adj Mandate Set	Maintained:We are awaiting video from TP. We will revert once we receive the AVF. You may request AVF from TP also	[I] Sundari Nagarajan
12	21 Aug 2019 10:19	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
13	22 Aug 2019 12:09	Adj Mandate Request	Cur.Req:0.00:PODS - Express Settlements PODS III Ref: MCT19080287 LKK Ref: CC3/III19014220/wb3 Accident on 14/08/2019 involving SH 9943C (India) and SL Q 625R (TP) Dear Sundari We advise liability as follows for Direct Set	[A] VIVIAN LAU PEI FENG
14	22 Aug 2019 12:34	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan
15	22 Aug 2019 14:14	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan
16	22 Aug 2019 15:27	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan
17	22 Aug 2019 15:27	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
18	22 Aug 2019 15:28	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
19	22 Aug 2019 17:17	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/08/26. Mandate Remarks: We have uploaded our IV video. According to him, before he could even make a right turn, TP vehicle hit IV.	[I] Sundari Nagarajan
20	22 Aug 2019 17:17	Adj Mandate Set	Maintained:We have uploaded our IV video. According to him, before he could even make a right turn, TP vehicle hit IV.	[I] Sundari Nagarajan
21	22 Aug 2019 17:17	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
22	22 Aug 2019 17:22	Video Downloaded	Downloaded Video - Accident-IV	[A] VIVIAN LAU PEI FENG
23	22 Aug 2019 17:35	Video Downloaded	Downloaded Video - Accident-TP	[A] CHEW HSIAO TONG
24	22 Aug 2019 17:35	Video Downloaded	Downloaded Video - Accident-IV	[A] CHEW HSIAO TONG
25	22 Aug 2019 17:44	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
26	22 Aug 2019 17:44	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan
27	22 Aug 2019 17:46	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
28	22 Aug 2019 18:25	Video Downloaded	Downloaded Video - Accident-TP	[A] HOW MEI KWAN
29	22 Aug 2019 18:26	Video Downloaded	Downloaded Video - Accident-IV	[A] HOW MEI KWAN
30	23 Aug 2019 14:44	Video Downloaded	Downloaded Video - Accident-IV	[A] Chong Pui Lin
31	23 Aug 2019 14:45	Video Downloaded	Downloaded Video - Accident-TP	[A] Chong Pui Lin
32	23 Aug 2019 14:48	Adj Mandate Request	Cur.Req:0.00:PODS LIABILITY: 100% REMARKS: BASE ON OI AVF, OI IS TRAVELLING ON "ONLY TURN RIGHT" LANE AND TP IS TRAVELLING ON "EITHER STRAIGHT OR TURN RIGHT LANE". HOWEVER OI DID NOT TURN RIGHT BUT TRAVEL STRAIGHT THUS TPV COLLIDED INTO OI.	[A] Chong Pui Lin
33	26 Aug 2019 14:51	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
34	26 Aug 2019 14:53	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan

## AUDIT TRAIL

No.	On	Audit	Remarks	By
35	26 Aug 2019 14:56	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/08/26. Mandate Remarks: TP made a very sharp right turn without giving our ID way to make a right turn. You may notice our ID was just out of the lane and would have made a right turn, when TP cut into our ID's lane.	[I] Sundari Nagarajan
36	26 Aug 2019 14:56	Adj Mandate Set	Maintained:TP made a very sharp right turn without giving our ID way to make a right turn. You may notice our ID was just out of the lane and would have made a right turn, when TP cut into our ID's lane. We offer 50%	[I] Sundari Nagarajan
37	27 Aug 2019 15:35	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
38	27 Aug 2019 15:35	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
39	27 Aug 2019 15:37	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
40	27 Aug 2019 16:35	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
41	27 Aug 2019 16:35	Video Downloaded	Downloaded Video - Accident-IV	[I] Mekavathanan Sarangapani
42	27 Aug 2019 16:46	Video Downloaded	Downloaded Video - Accident-IV	[I] Mekavathanan Sarangapani
43	27 Aug 2019 16:47	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
44	27 Aug 2019 16:54	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
45	27 Aug 2019 16:55	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
46	27 Aug 2019 16:55	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
47	27 Aug 2019 16:55	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
48	27 Aug 2019 16:58	Video Downloaded	Downloaded Video - Accident-IV	[I] Mekavathanan Sarangapani
49	27 Aug 2019 16:59	Video Downloaded	Downloaded Video - Accident-IV	[I] Mekavathanan Sarangapani
50	27 Aug 2019 17:00	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
51	29 Aug 2019 14:50	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan
52	30 Aug 2019 12:04	Video Downloaded	Downloaded Video - Accident-IV	[I] Gabriel Wee
53	30 Aug 2019 12:05	Video Downloaded	Downloaded Video - Accident-TP	[I] Gabriel Wee
54	24 Sep 2019 10:18	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: Refer to email from Mr Meka dated 30/08/2019	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None



Go

## ACTIVITY

[20/08/2019 14:42] VIVIAN LAU PEI FENG:

PODS

Liability: 50%

Remarks : conflicting version. Both parties turning

## Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2250489	20 Aug 2019 10:40:28	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SLQ62SR	5H9943C	11.77
2253858	22 Aug 2019 12:34:23	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SLQ62SR	Sundari Nagarajan	xx.xx
2254051	22 Aug 2019 14:14:47	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SLQ62SR	Sundari Nagarajan	xx.xx



## Print Received Message

This mail is associated with :

**\*SLQ625R (MCT19080287)  
[SH9943C]**

TP

TEO YI SHENG JASON

Aug 14 2019 11:00AM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 24/09/2019 13:01 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$0.00) - SLQ625R - Claim Handler: Sundari Nagarajan

Approved:0.00:Agreed to do direct settlement. Revert with your quantum advice. Please request TP WS to raise Tax Invoice for Cost of repairs in III's name

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Aug 2019 16:13	Clim Dtl Modified	Claimant's Name: -> TEO YI SHENG JASON. Claimant's ID: -> S8341723D.	[A] Lau Shu Pei
2	15 Aug 2019 16:13	Clim Veh Model Changed	(205228) BMW X1 1.5 SDRIVE 18I (A).	[A] Lau Shu Pei
3	15 Aug 2019 16:13	Clim Created	Reg No: SLQ625R. Acct Date: 2019/08/14. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Performance Motors Limited (Alexandra)	[A] Lau Shu Pei
4	15 Aug 2019 16:13	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	15 Aug 2019 16:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/26	[A] Lau Shu Pei
6	15 Aug 2019 16:13	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] Lau Shu Pei
7	15 Aug 2019 16:13	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
8	15 Aug 2019 16:13	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Lau Shu Pei
9	20 Aug 2019 14:42	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 50% Remarks : conflicting version. Both parties turning	[A] VIVIAN LAU PEI FENG
10	20 Aug 2019 17:36	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/26. Mandate Remarks: We are awaiting video from TP. We will revert once we receive the AVF. You may request AVF from TP also.	[I] Sundari Nagarajan
11	20 Aug 2019 17:36	Adj Mandate Set	Maintained:We are awaiting video from TP. We will revert once we receive the AVF. You may request AVF from TP also	[I] Sundari Nagarajan
12	21 Aug 2019 10:19	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
13	22 Aug 2019 12:09	Adj Mandate Request	Cur.Req:0.00:PODS - Express Settlements PODS III Ref: MCT19080287 LKK Ref: CC3/III19014220/wb3 Accident on 14/08/2019 involving SH 9943C (India) and SL Q 625R (TP) Dear Sundari We advise liability as follows for Direct Set	[A] VIVIAN LAU PEI FENG
14	22 Aug 2019 12:34	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan
15	22 Aug 2019 14:14	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan
16	22 Aug 2019 15:27	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan
17	22 Aug 2019 15:27	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
18	22 Aug 2019 15:28	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
19	22 Aug 2019 17:17	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/08/26. Mandate Remarks: We have uploaded our IV video. According to him, before he could even make a right turn, TP vehicle hit IV.	[I] Sundari Nagarajan
20	22 Aug 2019 17:17	Adj Mandate Set	Maintained:We have uploaded our IV video. According to him, before he could even make a right turn, TP vehicle hit IV.	[I] Sundari Nagarajan
21	22 Aug 2019 17:17	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
22	22 Aug 2019 17:22	Video Downloaded	Downloaded Video - Accident-IV	[A] VIVIAN LAU PEI FENG
23	22 Aug 2019 17:35	Video Downloaded	Downloaded Video - Accident-TP	[A] CHEW HSIAO TONG
24	22 Aug 2019 17:35	Video Downloaded	Downloaded Video - Accident-IV	[A] CHEW HSIAO TONG
25	22 Aug 2019 17:44	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
26	22 Aug 2019 17:44	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan
27	22 Aug 2019 17:46	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
28	22 Aug 2019 18:25	Video Downloaded	Downloaded Video - Accident-TP	[A] HOW MEI KWAN
29	22 Aug 2019 18:26	Video Downloaded	Downloaded Video - Accident-IV	[A] HOW MEI KWAN
30	23 Aug 2019 14:44	Video Downloaded	Downloaded Video - Accident-IV	[A] Chong Pui Lin
31	23 Aug 2019 14:45	Video Downloaded	Downloaded Video - Accident-TP	[A] Chong Pui Lin
32	23 Aug 2019 14:48	Adj Mandate Request	Cur.Req:0.00:PODS LIABILITY: 100% REMARKS: BASE ON OI AVF, OI IS TRAVELLING ON "ONLY TURN RIGHT" LANE AND TP IS TRAVELLING ON "EITHER STRAIGHT OR TURN RIGHT LANE". HOWEVER OI DID NOT TURN RIGHT BUT TRAVEL STRAIGHT THUS TPV COLLIDED INTO OIV.	[A] Chong Pui Lin
33	26 Aug 2019 14:51	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
34	26 Aug 2019 14:53	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan



## AUDIT TRAIL

No.	On	Audit	Remarks	By
35	26 Aug 2019 14:56	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/08/26. Mandate Remarks: TP made a very sharp right turn without giving our ID way to make a right turn. You may notice our ID was just out of the lane and would have made a right turn, when TP cut into our ID's lane.	[I] Sundari Nagarajan
36	26 Aug 2019 14:56	Adj Mandate Set	Maintained:TP made a very sharp right turn without giving our ID way to make a right turn. You may notice our ID was just out of the lane and would have made a right turn, when TP cut into our ID's lane. We offer 50%	[I] Sundari Nagarajan
37	27 Aug 2019 15:35	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
38	27 Aug 2019 15:35	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
39	27 Aug 2019 15:37	Video Downloaded	Downloaded Video - Accident-IV	[I] Sundari Nagarajan
40	27 Aug 2019 16:35	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
41	27 Aug 2019 16:35	Video Downloaded	Downloaded Video - Accident-IV	[I] Mekavathanan Sarangapani
42	27 Aug 2019 16:46	Video Downloaded	Downloaded Video - Accident-IV	[I] Mekavathanan Sarangapani
43	27 Aug 2019 16:47	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
44	27 Aug 2019 16:54	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
45	27 Aug 2019 16:55	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
46	27 Aug 2019 16:55	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
47	27 Aug 2019 16:55	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
48	27 Aug 2019 16:58	Video Downloaded	Downloaded Video - Accident-IV	[I] Mekavathanan Sarangapani
49	27 Aug 2019 16:59	Video Downloaded	Downloaded Video - Accident-IV	[I] Mekavathanan Sarangapani
50	27 Aug 2019 17:00	Video Downloaded	Downloaded Video - Accident-TP	[I] Mekavathanan Sarangapani
51	29 Aug 2019 14:50	Video Downloaded	Downloaded Video - Accident-TP	[I] Sundari Nagarajan
52	30 Aug 2019 12:04	Video Downloaded	Downloaded Video - Accident-IV	[I] Gabriel Wee
53	30 Aug 2019 12:05	Video Downloaded	Downloaded Video - Accident-TP	[I] Gabriel Wee
54	24 Sep 2019 10:18	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: Refer to email from Mr Meka dated 30/08/2019	[A] CHEW HSIAO TONG
55	24 Sep 2019 13:01	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/08/26. Mandate Remarks: Agreed to do direct settlement. Revert with your quantum advice. Please request TP WS to raise Tax Invoice for Cost of repairs in III's name	[I] Sundari Nagarajan
56	24 Sep 2019 13:01	Adj Mandate Set	Approved:0.00:Agreed to do direct settlement. Revert with your quantum advice. Please request TP WS to raise Tax Invoice for Cost of repairs in III's name	[I] Sundari Nagarajan
57	18 Oct 2019 14:33	Adj Rpt Initiated		[A] HUEY YON
58	18 Oct 2019 14:33	Clim Dtl Modified	Insured ID: -> 0.	[A] HUEY YON
59	18 Oct 2019 14:33	Clim Dtl Modified	JPJ Reg. Date: -> 2017/06/27.	[A] HUEY YON
60	18 Oct 2019 14:33	Clim Details Notified		[A] HUEY YON
61	18 Oct 2019 14:43	Adj Mandate Request	Cur.Req:11591.18:PODS Liability: 100% *Quantum: (a)CORw/GST: \$11,191.18 + (b)LOU(5days x \$80.00): \$400.00 = Total: \$11,591.18 *Vehicle Model: BMW X1 (1499cc) *5 recommendation repair days *For your approval please.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None

Go

## ACTIVITY

[20/08/2019 14:42] VIVIAN LAU PEI FENG:

PODS

Liability: 50%

Remarks : conflicting version. Both parties turning

## Merimen Billing for this case - Transaction History

Bill Ref No.	Bill Date	Bill Type	Acc. Type	Acc. Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2250489	20 Aug 2019 10:40:28	TP Case (Insurer)	Motor	LKK Auto Consultants	India International	SLQ625R	SH9943C	11.77

				Pte Ltd	Insurance Pte Ltd (HQ)			
2253858	22 Aug 2019 12:34:23	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SLQ625R	Sundari Nagarajan	xx.xx
2254051	22 Aug 2019 14:14:47	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SLQ625R	Sundari Nagarajan	xx.xx
2317786	18 Oct 2019 14:33:51	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLQ625R	SH9943C	11.77

## Print Received Message

This mail is associated with :

**\*SLQ625R (MCT19080287)**

**[SH9943C]**

TP

TEO YI SHENG JASON

Aug 14 2019 11:00AM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 21/10/2019 10:59 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$11591.18) - SLQ625R - Claim Handler: Sundari Nagarajan

Approved:11591.18:Please request TP WS to raise Tax Invoice for Cost of repairs in III's name



# CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VPA/P2012719 Account No. : 13854  
Coverage : Comprehensive  
Sum Insured : Market Value At The Time Of Loss  
Name of Policy Holder : TEO YI SHENG JASON  
Vehicle Registration No. : SLQ625R  
Period of Insurance : From 27/12/2018 To 26/12/2019 (Both Dates Inclusive)

## PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

- (a) The Policyholder  
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner  
(b) Any other person who is driving on the Policyholder's order or with his permission  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

## LIMITATIONS AS TO USE\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business  
The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess : SGD 600.00

An Additional Excess is applicable as follows:

S\$500.00 for Unnamed Authorized Driver &/or Declared Young & Inexperienced Driver.

S\$5,000.00 for Undeclared Young and Inexperienced Driver.

(Please refer to your policy on the terms & conditions)

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

  
Authorized Signature

Issued by - SGTRUPT2 on 12/12/2018

## IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Tuesday, 22 October 2019 5:35 PM  
**To:** PBSP  
**Cc:** CS A Team; Admin A  
**Subject:** RE: \*Urgent / Ill Ref:MCT19080287/01/sn; Accdt invg SH9943C(III) & SLQ625R on 14.8.19  
**Attachments:** DV\_SLQ625R.pdf

Without Prejudice

Dear Sirs/Mdm,

Thank you for your patience.

We confirm settlement at \$11,591.18(all-in).

Please duly sign the DV attached and return the original copy to us (LKK) for our necessary action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Tuesday, 22 October 2019 5:05 PM  
**To:** Hsiao Tong (LKKAUTO) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Cc:** CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** Re: \*Urgent / Ill Ref:MCT19080287/01/sn; Accdt invg SH9943C(III) & SLQ625R on 14.8.19

Dear Hsiao Tong

This case is urgent case.

Please confirm the settlement quickly.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Sent:** Thursday, 17 October 2019 7:19 AM  
**To:** PBSP <[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)>  
**Cc:** CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>; 甯珺 @ <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** RE: \*Urgent / III Ref:MCT19080287/01/sn; Accdt invg SH9943C(III) & SLQ625R on 14.8.19

Without Prejudice

Dear Sirs/Mdm,

Noted. We will get back to you asap.

Best Regards,  
**Hsiao Tong, Chew** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)>  
**Sent:** Wednesday, 16 October 2019 11:51 AM  
**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>  
**Subject:** \*Urgent / III Ref:MCT19080287/01/sn; Accdt invg SH9943C(III) & SLQ625R on 14.8.19

Dear LKK

Please refer to attach LOD which was posted to your office some time on 10.10.2019.

Kindly let us have your expeditious settlement.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended

Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



LKK Auto Consultants Pte Ltd  
Blk 51 Paya Ubi Industrial Park  
Ubi Avenue 1, #02-25  
Singapore 408933  
Attention: Motor Claims (Hsiao Tong)

Your Ref:

Our Ref:

Date:

22 October 2019

Subject:

**ACCIDENT INVOLVING SLQ625R AND SH9943C ON 14.08.2019**

Dear Sirs

We refer to the above matter.

We are pleased to enclose the Discharge Voucher duly executed by our client.

Please let us have your settlement cheque made in favour of "Performance Motors Limited" within the next 14 days.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Cresendo Lagman  
Customer Service Manager, Body & Paint

Performance Motors  
Limited  
1800-Call-BMW  
(1800-2255-2655)

[www.pml.com.sg](http://www.pml.com.sg)

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel AfterSales:  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
#01-01  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel AfterSales:  
6319 0527  
Fax 6479 6624

280  
Kampong Alam Rd  
East Coast Centre  
Singapore 438180  
Tel AfterSales:  
6319 0888  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No:  
197401539W





India Int'l Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711  
Attention: Motor Claims

**"Without Prejudice"**

Your Ref:

Our Ref:

Date:

Subject:

10 October 2019

**ACCIDENT INVOLVING VEHICLES SLQ625R & SH9943C ON 14.08.2019**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	: S\$ 11191.18
Loss of use	: S\$ 400.00 (S\$80.00 x 5 days)
Total	: S\$ 11591.18

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & Certificate of Insurance
3. Copy of Letter of Authorisation

Performance Motors  
Limited  
1800-Call-BMW  
(1800-2255-269)

[www.pml.com.sg](http://www.pml.com.sg)

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel AfterSales:  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
#01-01  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel AfterSales:  
6319 0527  
Fax 6479 6624

280  
Kampong Arang Rd  
East Coast Centre  
Singapore 438180  
Tel AfterSales:  
6319 0888  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No:  
197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to [pml-pbsp@sime-darby.com.sg](mailto:pml-pbsp@sime-darby.com.sg).

Yours sincerely

  
Cresendo Lagman  
Customer Service Manager, Body & Paint

# Performance Motors Limited

A member of the Sime Darby Group



## LETTER OF AUTHORISATION

ACCIDENT INVOLVING 3LQ62SR & SH9943C ON 14.03.2019.

I, Teo Yi Sheng Jason owner of Vehicle Registration No. 3LQ62SR  
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and  
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all  
documents whatsoever in relation to this matter and to accept and receive any payment  
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation  
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if  
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement  
amount in respect of such claim shall constitute the full discharge of my claim in respect of  
such loss and damage.

Signed by:

Name : Teo Yi Sheng Jason (Date)

NRIC No.: S8341723D

In the presence of:

Name : (Date)

NRIC No.:

Witness Name: Teo Yi Sheng Jason  
Performance Motors Limited  
300 Alexandra Road  
Sime Darby Performance Centre  
Singapore 119944

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER

#### III- Direct Settlement (PODS)

India Ref: MCT19080287  
Claimant Ref: SLQ625R

We/I, Performance Motors Limited ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 11,191.18 (repair cost), S\$ 400.00 (loss of use/~~vehicle~~), S\$        (search fee), vehicle no. SLQ625R that was damaged pursuant to the accident which occurred on 14/08/2019 (date) at Marina Boulevard - Beside One Raffles (location) involving vehicle no. SH9943C (insured vehicle). This is pursuant to the inspection conducted on 02/09/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TEO YI SHENG JASON ("the third party claimant") of vehicle no. SLQ625R to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLQ625R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 11,591.18 to Performance Motors Limited

Dated this 22 day of OCTOBER 20 19

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

Inthiran A/L Thurasamy  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:

LKK Auto Consultants Pte Ltd

199607198R

51 Ubi Avenue 1

#01-25 Paya Ubi Ind. Park S(408933)



MTH



101, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438160  
Tel. 63190888 (AfterSales)  
Fax. 63449773

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190538 (AfterSales)  
63190533/630 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1392758

Page No. : 1 of 2

Date IN : 02/09/2019

Invoice Number : 2157814 / WSB

Invoice Date : 03/10/2019

Motor Claim Advisor: Inthiran A/L Thurasamy

Payment Terms : 30 Days From Invoice

Invoice By : Toh Jing Xuan

## - CUSTOMER INFORMATION -

Mr Teo Yi Sheng Jason  
Blk 150 Ang Mo Kio Avenue 5  
#05-3048  
Singapore  
Singapore 560150

## - INVOICE TO - 219

India Int'l Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO.  
SLQ625R

CHASSIS NO.  
WBAHS120905H48085

REGN. DATE  
27/06/2017

MODEL  
X1 SDRIVE18I

MILEAGE  
47940

## - - - - LABOUR 1 - - - -

To replace front bumper and attachments, front right fender, front right wheel arch trim including remove attachments to facilitate repairs and knock out dented area caused by the accident.

NETT  
1,700.00

To respray front bumper and front right fender.

1,996.00

To replace right LED technology headlight including program and conduct tests for proper function.

408.00

To replace front right wheel rim including balancing.

80.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)

451.00

To carry out body cavity preservation.

100.00

(Per panel).

Sundries.

150.00

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

0.00

DATE OF ACCIDENT : 14.08.2019. 3RD PARTY CAR : SH9943C.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON 02.09.2019 AT 10:20AM. AUTHORISED REPAIR BY MR MEKAVATHANAN FROM INDIA INT'L INSURANCE ON 30.08.2019 VIA EMAIL.

PROPOSE LOSS OF USE = \$80x5. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.

0.00

Total Labour 1: **4,885.00**

## - - - - PARTS - - - -

FRT BUMPER PANEL PRIMED (PDC/PMA)  
FRT BUMPER PANEL LOWER SECTION (PDC  
FRT RH SIDE PANEL  
FRT RH WHEEL ARCH TRIM  
RH HEADLIGHT LED TECHNOLOGY  
LIGHT ALLOY WHEEL Y SPK 569  
EXPANDING RIVET BLACK

Qty	Retail Price	NETT
1	854.55	854.55
1	213.65	213.65
1	664.00	664.00
1	151.00	151.00
1	2,670.85	2,670.85
1	1,006.00	1,006.00
10	1.40	14.00

Total Parts : **5,574.05**

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438380  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/538 (Motorrad)  
Fax. 64794401 (AfterSales)  
64794424 (Motorrad)

**SERVICE TAX INVOICE**Repair Order No. : **B1 1392758**Page No. : **2 of 2**Date IN : **02/09/2019**Invoice Number : **2157814 / WSB**Invoice Date : **03/10/2019**Motor Claim Advisor: **Inthiran A/L Thurasamy**Payment Terms : **30 Days From Invoice**Invoice By : **Toh Jing Xuan**

- - - - L A B O U R 2 - - - -

NETT

0.00

Total Labour 2:

0.00

Labour Charges : **4,735.00**  
Parts Charges : **5,574.05**  
Lubricant/Misc : **150.00**

Total Labour & Parts Charges : **S\$ 10,459.05**  
Less Insurance Excess : **S\$ 0.00**  
Invoice Total Amount Exclude GST : **S\$ 10,459.05**  
GST @ 7% : **S\$ 732.13**  
Invoice Total Amount Include GST : **S\$ 11,191.18**

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 11,191.18**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Aug 2019 <a href="#">Edit Reg</a>		15 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$10,459.05</b> <a href="#">Edit Estimates</a>	<b>\$10,459.05</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 0									
Main Claimant: <b>TEO YI SHENG JASON</b> , ID: S8341723D									
Vehicle Reg. No.: <b>SLQ625R</b>		Date of Loss: 14/08/2019 11:00 - :59 [25 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / MCT19080287</b>		Policy/Cover Note No.: MCOM0015							
Vehicle Reg. No. (Insured): <b>SH9943C</b>		Policy No. (Claimant): VPA/P2012719							
		Excess:							
Repairer: <b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: <b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sundari Nagarajan</b> - 6347 6071]									
Claimant's Insurer: <b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 26/08/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (21/10/2019): Alert - Adj Mandate Approved (\$11591.18) - SLQ625R - Claim Handler: Sundari Nag...</li> <li>III_SG (24/09/2019): Alert - Adj Mandate Approved (\$0.00) - SLQ625R - Claim Handler: Sundari Nagaraj...</li> <li>III_SG (26/08/2019): Alert - Adj Mandate Maintained - SLQ625R - Claim Handler: Sundari Nagarajan</li> <li>III_SG (22/08/2019): Alert - Adj Mandate Maintained - SLQ625R - Claim Handler: Sundari Nagarajan</li> <li>III_SG (20/08/2019): Alert - Adj Mandate Maintained - SLQ625R - Claim Handler: Sundari Nagarajan</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLQ625R (MCT19080287)  
[SH9943C]

TP

TEO YI SHENG JASON

Aug 14 2019 11:00AM

[COMFORT TRANSPORTATION PTE LTD]  
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
<b>Video</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print		
1	22/08/19 12:34	Video - Accident-TP		Load MP4			
2	22/08/19 14:14	Video - Accident-IV		Load MP4			
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
2	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
3	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
4	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
5	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
6	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
7	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
8	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
9	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
10	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
11	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
12	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
13	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
14	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
15	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
16	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
17	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
18	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
19	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
20	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
21	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
22	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
23	24/09/19 10:19	General View		Load JPG	<input checked="" type="checkbox"/>		
24	18/10/19 14:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
25	18/10/19 14:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
26	18/10/19 14:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
27	18/10/19 14:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
28	18/10/19 14:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>						1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	15/08/19 16:14	TP ESTIMATE		Load PDF			
2	15/08/19 16:14	TP GIA REPORT		Load PDF			
3	03/09/19 17:07	TP ESTIMATE- MARKED		Load PDF			
4	25/10/19 08:21	WORKSHOP INVOICE		Load PDF			
5	25/10/19 08:21	AUTHORISATION TO ACT FORM		Load PDF			
6	25/10/19 08:21	DISCHARGE VOUCHER		Load PDF			
7	25/10/19 08:21	LOD		Load PDF			
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print		
1	20/08/19 10:40	Singapore Accident Statement IV SH9943C		Load PDF			

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19014220/T1PB3Q2

Date: 25/10/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No: SLQ625R Insured Vehicle No: SH9943C  
 Date of Loss: 14/08/2019 Nature of Claim: TP Claim No: MCT19080287

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLQ625R  
 Make & Model: BMW X1, 1.5 SDRIVE 18i (A) Engine No: F369H402B38A15A  
 Reg. Date: 27/06/2017 (Man. Year: 2017) Chassis No: WBAHS120905H48085  
 Colour: White Odometer: 47940 km  
 Engine Capacity: 1499 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/50R18 Rear Tyre Size: 225/50R18  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,050.75	5,724.05	326.70	5.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,992.00	4,735.00	1,257.00	20.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,042.75</b>	<b>10,459.05</b>	<b>1,583.70</b>	<b>13.15</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>842.99</b>	<b>732.13</b>	<b>110.86</b>	<b>13.15</b>
<b>Nett Amount (S\$)</b>	<b>12,885.74</b>	<b>11,191.18</b>	<b>1,694.56</b>	<b>13.15</b>
<b>+ Loss of Use (5.0 x S\$80.00/day) (S\$)</b>		<b>400.00</b>		
<b>Nett Liability (S\$)</b>		<b>11,591.18</b>		

## INSPECTION

Date of Assignment: 15/08/2019

Date Inspected: 02/09/2019 Inspected At:

Performance Motors Limited  
 (Alexandra)  
 303 Alexandra Road, Sime Darby  
 Performance Centre  
 Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2019)
<b>Parts:</b> M1-SUV	BMW X1 1.5 SDRIVE 18i (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ625R)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LIGHT ALLOY WHEEL Y SPK 569	Cut	1,006.00 FS	*1,006.00 FS
2	1		*RH WHEEL HOUSING STRUT EXTENSION	Not Necessary	147.10 FS	*- FS
3	1		*FRT RH SIDE PANEL	Bent	664.00 FS	*664.00 FS
4	1		*FRT BUMPER PANEL PRIMED (PDC/PMA)	Deformed	854.55 FS	*854.55 FS
5	1		*RH OPEN GRID (BASIC PDC)	Not Necessary	111.45 FS	*- FS
6	1		*FRT BUMPER PANEL LOWER SECTION PDC	Cut	281.80 FS	*213.65 FS
7	1		*FRT RH WHEEL ARCH TRIM	Cut	151.00 FS	*151.00 FS
8	1		*RH HEADLIGHT LED TECHNOLOGY	Cut	2,670.85 FS	*2,670.85 FS
9	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
10	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
<b>Total Parts (S\$)</b>					<b>6,050.75</b>	<b>5,724.05</b>

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER,FENDER RIGHT AND ATTACHMENTS	New	2,550.00	1,700.00
2	PAINTING FRONT BUMPER AND FENDER RIGHT	New	2,218.00	1,996.00
3	TO REPLACE LFT OR RIGHT HEADLIGHT	New	481.00	408.00
4	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	451.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>5,992.00</b>	<b>4,735.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >