



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672




Date Generated : 14/08/2019

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SG1020Z
Case Reference Number	BUS/08/19/6001
Registration Date	27/12/2017
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Lim Peng Hooi
Type of Accident	Head to Rear
Accident Date and Time	9/8/2019 5:08 PM
Accident Reported Date and Time	9/8/2019 6:45 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1020Z-REAR PORTION SKP5206B (TP) INSURED WITH AIG
Prepared Date and Time	14/8/2019 10:11 AM
Chassis Number	WEB62808323129419
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,650.00	\$0.00
Total Spray Cost	\$432.00	\$0.00
Total Spare Part Cost	\$5,988.64	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$9,070.64	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	5
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	14/08/2019 10:39 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/08/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$2,650.00				2120			
Total Labour		\$2,650.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$432.00				340			
Total Spray Painting & Panel Beating		\$432.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009909	BODY RH		BUMPER:REAR,RH,FOR MB CITARO O530	1.00	\$837.84	10.00	\$754.06	Replace	OR
6009907	Body		BUMPER:REAR,CENTR E.FOR MB CITARO O530	1.00	\$1,791.33	10.00	\$1,612.20	Replace	OR
6009880	VE		LAMP,TAI:REAR RH,FOR MB CITARO O530	1.00	\$1,261.71	10.00	\$1,135.54	Replace	X
6010010	VE		LAMP,EXTERIOR:REAR FOGLAMP,FOR MB CITARO	1.00	\$63.15	10.00	\$56.84	Replace	X
		MA6286402114	CROSS BAR REAR BUMPER (SBS VERSION)	1.00	\$2,700.00	10.00	\$2,430.00	Replace	OR
Total					\$6,654.03		\$5,988.64		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Steve
8322 8813

unz Mark 14/8/19, 2:30pm
5 dy
LBS P/P
Ry AK SM
Ref

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: