

KANCHANA



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111 X

ESTIMATE FOR SLE7806C*RA

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No 36069
Reg No/Reg Date SLE7806C*RA / 01/08/2016
Date In/Mile 01/11/14
Chassis No WDP2060462R172303
Engine No 27491030610395
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 029 988 Diamond Sil/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator
WN000512	Credit	04/09/2019/ 10:37	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPNSON				
POLICY NO/ACC DATE : 5100872530-01 // 8-8-2019				
DRIVE IN/TP VEH NUMBER : 10-8-2019 // YP9110B - ERGO				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
A BPILAB				
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES				
RESPRAY FRONT BUMPER & RH/FRONT FENDER & BONNET				
A BPILAB				
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
A BPILAB				
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT				
M FRONT BUMPER same repair	1.00	1557.32	00.00	1557.32
M RIGHT FRONT FENDER by repair	1.00	909.44	00.00	909.44
M BONNET cut	1.00	2083.09	00.00	2083.09
M BONNET SPRING ELEMENT 1. x 1.00	2.00	33.02	00.00	66.04
M RIGHT HEADLAMP UNIT 1. x 1.00	1.00	3231.97	00.00	3231.97
A BPILAB				
TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT				
S TYRESALES1				
Tyre sales 1 - RIGHT FRONT TYRE X				
Replacement of 1 pc of Tyre (include labour)				
Supply 1 pc tubeless valve - FOC				
Go Chee Han				
DILY 6771 4336 HP 9181 7717				
Email: cheehan.goh@cyclecarriage.com.sg				
Cycle & Carriage Industries Pte Ltd				
Customer Service Centre - Pandan Loop				

Confirmed & accepted by

Nett 14,647.86
7% GST on 14647.86 1025.35

Authorized signatory and company stamp

Total Payable 15,673.21

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Page 1 of 1



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SLE7806C*RA

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No 36069
Reg No/Reg Date SLE7806C*RA / 01/08/2016
Date In/Mileage 04/09/2019 / 61443
Chassis No WDF2050412R17303
Engine No 27491030610395
Make/Model MB/MB C 180 SEDAN (W205) *AVANTGARDE / A
Colour/Trim 029 988 Diamond Sil/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator
WN000512	Credit	11/09/2019/ 19:04		371 / Go Chee Han
Description of Goods / Services	Qty	Unit Price	Disc%	Amount

7 REQUEST
Customer Request
M BENSON

POLICY NO/ACC DATE : 5100872530-01 // 8-8-2019
DRIVE IN/TP VEH NUMBER : 10-8-2019 // YP9110B - ERGO
DATE IN/DATE SURVEY: 4-9-2019 1630 // Rasul - LKK
BY/AUTHORIZED ON : 2-9-2019 1622 // Khanchna - LKK

A BPILAB				2400.00 ✓
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES				1800.00 ✓
RESPRAY FRONT BUMPER & RH/FRONT FENDER & BONNET				
A BPILAB			0.10	380.00 ✓
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMOIR TO IDENTIFICATION STANDARD. NETT				
A BPILAB				120.00 ✓
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT				
X RIGHT FRONT FENDER	1.00	909.44	00.00	909.44 ✓
X BONNET	1.00	2083.09	00.00	2083.09 ✓
A BPILAB				540.00 ✓
TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT				
X SEAM SEAL	1.00	63.93	00.00	63.93
X INFORMATION LABEL	1.00	38.14	00.00	38.14

Confirmed & accepted by

Nett 8,334.60
7% GST on 8334.60 583.42

Authorized signatory and company stamp

Total Payable 8,918.02

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLE7806C*RA

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document information

WIP No 36069
Reg No/Reg Date SLE7806C*RA / 01/08/2016
Date In/Mileage 04/09/2019 / 61443
Chassis No WDF2050452R17103
Engine No 27491030610395
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 029 988 Diamond S11/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	Operator	Description of Goods/Services	Qty	Unit Price	Disc%	Amount
WN000512	Credit	11/09/2019/ 19:04	CH	371 / Go Chee Han				

M BPNSUN	THIS IS NOT AN OFFICIAL TAX INVOICE							
DATE IN/DATE SURVEY: 4-9-2019 1630								
BY/AUTHORIZED ON : 2-9-2019 1622								
X SEAM SEAL								
X INFORMATION LABEL								

ESTIMATE

Confirmed & accepted by

7% GST on Nett 102.07 7.14
Total Payable 109.21

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany