

INS. CASE OWNER:

CC4/LPC19014235/ G ea3n2

LKK:

IDAC:

Surveyor:

X62

DOI:

16/8/2019

Date / Time: 15/08/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SJD 5067K

Claim No. : 19/19/19/VP05/022213

Name of Insured : LONH TANH NAM

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II : \$\$ D.O.A : 10/08/2019

Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L) YES / NO

Insured Liability : % Final ? Yes / No

GBH 9440M

INSRS:
WSP:
Tel: YONG SING MOTOR
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	GBH 9440M - X	SJD 5067K - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List: Handler Typist	
			Notification ltr (if non-pickup)	
			After call ltr to OI:	
			Authorisation To Act:	
			Release Voucher:	
			Final Repair Bill:	
			Car Rental Invoice:	
			Towing Invoice:	
			LTA / GIA :	
			Medical Bill:	
			PIR:	
			Mandate/Reject Instruction:	
			LOD	
			Payment Breakdown Form:	
			Post-Repair Photos:	
			Others:	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: X62

Repair Cost: P/P \$5 7,065.10 (6 days) Reduction: 87 % Email ☒ Call ☐

FINAL SETTLEMENT Date/Time: 06.12.19 Confirm with ZH YONG Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : NIL. If NO or B 28, Ass. Lia :

Repair Cost: 2/6/ \$54,349.55 TP GONG HU REP, OI GONG DOON SUP, OI BUREAU TP HONG

Loss of Rental (LOR): \$5 800.00 (8 days) x 100

Loss of Use (LOU): \$5 - (\$ x days)

Loss of Income (LOI): \$5 - (\$ x days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: \$5 7.99

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$5 2,157.04 Global Sum \$5:

FINAL PAYMENT Date/Time: 06.12.19 Confirm with: ZH YONG Email ☒ Call ☐

Payee 1: \$5 2,157.04 Name 1: YONG SING MOTOR WORKS

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

COPY SENT
21/12/2019

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +450

ASS. FILED BY:

6ul

REF:

LPC

ASSIGNMENT

From:

Date:

16/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

QBH 9440

at Workshop m/s

Yang Sing Motor

of

53 Defu Lane 12

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

QBH 9440M

Yr Regn:

01 Nov 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace 2.8 c.c 2754

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

141 41

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

60H 20110107.37

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/80 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

16-08-19

Survey held at

w/s

3pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P: 7/4, 045.00 (RED: 92,830.00 87%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Phone

Others

TOTAL

Report Format:

Lump Sum / L.B./:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wheel align (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 19/19/19/VP05/022213
Our ref: CC4/LPC19014235/Gea3

Date: 19/08/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBH 9440M

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/08/2019 at the premises of M/s Yong Sing Motor Works and have the following to report:-

Workshop Estimate Amount	: S\$	32,365.00
Revised Estimate Amount	: S\$	4,840.00
"Check" Items Amount	: S\$	300.00
Total (Including Check Items)	: S\$	5,140.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6.0 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	200A
Vehicle Details	
Vehicle No.:	GBH9440M
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 2.8 AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1GD8309294
Chassis No.:	GDH2011010737
Maximum Power Output:	-
Open Market Value:	\$34,227.00
Original Registration Date:	01 Nov 2018
First Registration Date:	01 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$1,712.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$24,538.00
COE Rebate Amount:	\$22,592.00
Total Rebate Amount:	\$22,592.00

The information contained herein is correct as at 16 Aug 2019


OK

Yong Sing Estimate Repair

Vehicle Registration Number : GBH 9440M
 Make / Model : HIACE DX 2.5 AUTO
 Chassis No : GDH2011010737
 Year of Manufacture : 2018
 Registration Date : 1-Nov-18
 Type of Repair (TP/OD/WS) : TP
 Date/Time of Accident : 7 AUGUST 2019 / 09:25 hrs
 Rental Vehicle : Yes ☒ No ☐
 Remark : TP

Case Ref. No. : YS/19/0069

The damages on the vehicle are as indicated in the following diagram



	Yong Sing estimate breakdown cost	Adjusted by Surveyor, if applicable
Total Labour Cost	\$ 2,000.00	\$ -
Total Spray Painting Cost	\$ 2,100.00	\$ -
Total Spare Parts Cost	\$ 26,435.00	\$ -
Other Charges	\$ 1,830.00	\$ -
TOTAL	\$ 32,365.00	\$ -
Lump Sum Repair, if any : _____		
No. of Repair Days	[10] days	[] days

SURVEYOR'S Remark

6 Days.
 P/P ~~lump sum~~ repair.
 before/after repair photos.
 Gino Qian - 82880282
 16/8/19.

LOK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 1 - Labour & Panel Beating Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO REMOVE & INSTALL ALL REPLACE ITEM, TO REPAIR RH PORTION	\$2,000.00	600 ✓
Total Labour Cost	\$2,000.00	\$0.00

Part 2 - Spray Painting Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO RESPRAY DOOR SUB-ASSY, SLIDE, RH	\$600.00	250 ✓
TO RESPRAY REAR PANEL RH	\$600.00	250 ✓
TO RESPRAY REAR BUMPER	\$600.00	X { NN
TO RESPRAY SILLMEMBER RH	\$300.00	X { NN
Total Spray Painting Cost	\$2,100.00	\$0.00

Part 3 - Other Costs - Accident Repair Related Expenses

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$150.00	40 ✓
TO TRANSFER DOOR MECHANISM RH	\$200.00	60 ✓
TO PROVIDE ANTI RUST COATING	\$250.00	50 ✓
TO CONDUCT WIRE CHECKING	\$100.00	X { NN
TO VACCUMM AND CLEAN ON INTERIOR	\$80.00	X { NN
TO CHECK WATER LEAKAGE ON INSTALLED PARTS	\$150.00	X { NN
TO REMOVE AND REFIT BOTH GLASS WINDOW RH	\$300.00	60 ✓
TO DO 4 WHEEL ALIGNMENT TYRE BALANCING	\$200.00	30 ✓
TO REMOVE AND REFIT UNDERCARRIAGE COMPARTMENT	\$400.00	X NN
Total Other Costs	\$1,830.00	\$0.00

Part 4 - Spare Parts / Material Usage

Item	Part Name	Part No	Qty	List Price (\$)	Discount (25%)	Final Price (\$)	Repair @ Replace (/) (Yong Sing Request)	Repair @ Replace (/) (Surveyor Recommend)
1	DOOR SUB-ASSY. SLIDE. RH <i>Buc</i>	67003-26340	1	\$ 2,500.00	25%	\$ 1,875.00	Replace	
2	WEATHERSTRIP, REAR DOOR, RH <i>X</i>	57871-26010	1	\$ 520.00	25%	\$ 390.00	Replace	
3	COVER, SLIDE DOOR SERVICE HOLE, NO 2 (TRIM) <i>X</i>	6785126030	1	\$ 441.00	25%	\$ 330.75	Replace	
4	MOULDING, REAR DOOR TRIM, NO 2 RH <i>X</i>	57745-26011	1	\$ 450.00	25%	\$ 337.50	Replace	
5	BOARD SUB-ASSY. REAR DOOR TRIM, RH <i>X</i>	5761326080 <i>NN</i>	1	\$ 620.00	25%	\$ 465.00	Replace	
6	HANDLE ASSY. REAR DOOR OUTSIDE, RH <i>X</i>	6923026070	1	\$ 260.00	25%	\$ 195.00	Replace	
7	CASE, REAR DOOR OUTSIDE HANDLE, RH <i>X</i>	6924126030	1	\$ 340.00	25%	\$ 255.00	Replace	
8	HANDLE SUB-ASSY. REAR DOOR INSIDE, RH <i>X</i>	6920726010B1	1	\$ 380.00	25%	\$ 285.00	Replace	
9	LOCK ASSY. SLIDE DOOR, FRONT RH <i>X</i>	6937026010	1	\$ 655.00	25%	\$ 491.25	Replace	
10	PLATE ASSY. SLIDE DOOR FRONT LOCK STRIKER <i>X</i>	6944026050	1	\$ 120.00	25%	\$ 90.00	Replace	
11	PLATE ASSY. SLIDE DOOR LOCK STRIKER <i>X</i>	6947026100	1	\$ 100.00	25%	\$ 75.00	Replace	
12	STRIKER, SLIDE DOOR OPEN, RH <i>X</i>	6948526020	1	\$ 420.00	25%	\$ 315.00	Replace	
13	LOCK ASSY. SLIDE DOOR FULL OPEN STOP RH <i>X</i>	6905026011	1	\$ 499.00	25%	\$ 374.25	Replace	
14	ACTUATOR ASSY. REAR DOOR LOCK, RH <i>X</i>	6913026020	1	\$ 550.00	25%	\$ 412.50	Replace	
15	CONTROL ASSY. SLIDE DOOR LOCK REMOTE, RH <i>X</i>	6963026222	1	\$ 880.00	25%	\$ 660.00	Replace	
16	BASE SUB-ASSY. SLIDE DOOR LOWER ROLLER, RH <i>X</i>	6802926070	1	\$ 367.00	25%	\$ 275.25	Replace	
17	ROLLER ASSY. SLIDE DOOR, LOWER RH <i>X</i>	6835026080	1	\$ 380.00	25%	\$ 285.00	Replace	
18	PLATE, SLIDE DOOR LOWER RAIL, RH <i>X</i>	6839426010	1	\$ 233.00	25%	\$ 174.75	Replace	
19	HINGE ASSY. SLIDE DOOR, CENTER RH <i>X</i>	6838026030	1	\$ 210.00	25%	\$ 157.50	Replace	
20	ROLLER ASSY. SLIDE DOOR, UPPER RH <i>X</i>	6831026051	1	\$ 180.00	25%	\$ 135.00	Replace	
21	ROLLER, SLIDE DOOR, RH <i>X</i>	6833126071	1	\$ 266.00	25%	\$ 199.50	Replace	
22	PANEL, QUARTER, RH <i>X Repair</i>	6161126510	1	\$ 3,050.00	25%	\$ 2,287.50	Replace	
23	WINDOW ASSY. SIDE, FRONT RH <i>X</i>	6810326010	1	\$ 1,200.00	25%	\$ 900.00	Replace	
24	WINDOW ASSY. SIDE, REAR RH <i>X</i>	6207326051	1	\$ 1,450.00	25%	\$ 1,087.50	Replace	
25	TYRE <i>/ GCR 1008 (SN)</i>		1	\$ 300.00	25%	\$ 225.00	Replace	
26	WHEEL, DISC <i>X NN</i>	4261126180	1	\$ 1,200.00	25%	\$ 900.00	Replace	
27	CAP, WHEEL <i>/ Cut</i>	4260226010	1	\$ 300.00	25%	\$ 225.00	Replace	
28	CARRIER ASSY. DIFFERENTIAL, REAR <i>X</i>	4111026432	1	\$ 3,420.00	25%	\$ 2,565.00	Replace	
29	SHAFT, REAR AXLE, RH <i>X</i>	4231126310	1	\$ 1,700.00	25%	\$ 1,275.00	Replace	
30	ABSORBER ASSY. SHOCK, REAR RH <i>X</i>	4853180725	1	\$ 270.00	25%	\$ 202.50	Replace	
31	SPRING ASSY. REAR RH <i>X</i>	4821026A02	1	\$ 672.00	0%	\$ 672.00	Replace	
32	DRUM SUB-ASSY. REAR BRAKE <i>X</i>	4243126200	1	\$ 855.00	25%	\$ 641.25	Replace	
33	COVER, REAR BUMPER <i>/ Cut</i>	5215926490	1	\$ 700.00	25%	\$ 525.00	Replace	
34	SUPPORT, REAR BUMPER SIDE, RH <i>X</i>	5215526150	1	\$ 211.00	25%	\$ 158.25	Replace	
35	SUPPORT, REAR BUMPER SIDE, NO 2 RH <i>X</i>	5215726110 <i>NN</i>	1	\$ 211.00	25%	\$ 158.25	Replace	
36	PROTECTOR, SIDE MUDGUARD, FRONT RH <i>X</i>	6992526050	1	\$ 525.00	25%	\$ 393.75	Replace	
37			1					
38			1					
39			1					
40			1					
41			1					
42			1					
43			1					


44			1					
45			1					
47			1					
TOTAL MATERIALS \$ 26,435.00 \$ 19,994.25								

Yong Sing Estimate Repair

Vehicle Registration Number : GBH 9440M
 Make / Model : HIACE DX 2.8 AUTO
 Chassis No : GDH2011010737
 Year of Manufacture : 2016
 Registration Date : 1-Nov-18
 Type of Repair (TP/OD/WS) : TP
 Date/Time of Accident : 7 AUGUST 2019 / 09:25 hrs
 Rental Vehicle : Yes ☒ No
 Remark : TP

Case Ref. : YS/19/0069
 No.

The damages on the vehicle are as indicated in the following diagram :



	Yong Sing estimate breakdown cost	Adjusted by Surveyor, if applicable
Total Labour Cost	\$ 2,000.00	\$ 600.00
Total Spray Painting Cost	\$ 2,100.00	\$ 500.00
Total Spare Parts Cost	\$ 25,235.00	\$ 2,725.00
Other Charges	\$ 1,830.00	\$ 240.00
TOTAL	\$ 32,165.00	\$ 4,065.00

Lump Sum Repair, if any : _____

No. of Repair Days : [10] days [6] days

SURVEYOR'S Remark

6 DAYS
P/P REPAIR
BEFORE AND AFTER PAINT PHOTO
GUO QIANG - 82880282
16-8-19

Part 1 - Labour & Panel Beating Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO REMOVE & INSTALL ALL REPLACE ITEM, TO REPAIR RH PORTION	\$2,000.00	\$600.00
Total Labour Cost	\$2,000.00	\$600.00

Part 2 - Spray Painting Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO RESPRAY DOOR SUB-ASSY, SLIDE, RH	\$600.00	\$250.00
TO RESPRAY REAR PANEL RH	\$800.00	\$250.00
TO RESPRAY REAR BUMPER	\$800.00	\$0.00
TO RESPRAY SILLMEMBER RH	\$300.00	\$0.00
Total Spray Painting Cost	\$2,100.00	\$500.00

Part 3 - Other Costs - Accident Repair Related Expenses

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$150.00	\$40.00
TO TRANSFER DOOR MECHANISM RH	\$200.00	\$60.00
TO PROVIDE ANTI RUST COATING	\$250.00	\$50.00
TO CONDUCT WIRE CHECKING	\$100.00	\$0.00
TO VACCUMM AND CLEAN ON INTERIOR	\$80.00	\$0.00
TO CHECK WATER LEAKAGE ON INSTALLED PARTS	\$150.00	\$0.00
TO REMOVE AND REFIT BOTH GLASS WINDOW RH	\$300.00	\$60.00
TO DO 4 WHEEL ALIGNMENT TYRE BALANCING	\$200.00	\$30.00
TO REMOVE AND REFIT UNDERCARRIAGE COMPARTMENT	\$400.00	\$0.00
Total Other Costs	\$1,830.00	\$240.00

Part 4 - Spare Parts / Material Usage

Item	Part Name	Part No	Qty	List Price (\$)	Discount (25%)	Final Price (\$)	Repair @ Replace (/) (Yang Sing Request)	Repair @ Replace (/) (Surveyor Recommend)
1	DOOR SUB-ASSY, SLIDE, RH	67003-26340	1	\$ 2,500.00	25%	\$ 1,875.00	Replace	Replace
2	WEATHERSTRIP, REAR DOOR, RH	67871-26010	1	\$ 520.00	25%	\$ 390.00	Replace	Not Given
3	COVER, SLIDE DOOR SERVICE HOLE, NO.2 (TRIM)	6785126030	1	\$ 441.00	25%	\$ 330.75	Replace	Not Given
4	MOULDING, REAR DOOR TRIM, NO.2 RH	67745-26011	1	\$ 450.00	25%	\$ 337.50	Replace	Not Given
5	BOARD SUB-ASSY, REAR DOOR TRIM, RH	6761326080	1	\$ 620.00	25%	\$ 465.00	Replace	Not Given
6	HANDLE ASSY, REAR DOOR OUTSIDE, RH	6923026070	1	\$ 360.00	25%	\$ 195.00	Replace	Not Given
7	CASE, REAR DOOR OUTSIDE HANDLE, RH	6924126030	1	\$ 340.00	25%	\$ 255.00	Replace	Not Given
8	HANDLE SUB-ASSY, REAR DOOR INSIDE, RH	6920726010B1	1	\$ 380.00	25%	\$ 285.00	Replace	Not Given
9	LOCK ASSY, SLIDE DOOR, FRONT RH	6937026010	1	\$ 655.00	25%	\$ 491.25	Replace	Not Given
10	PLATE ASSY, SLIDE DOOR FRONT LOCK STRIKER	6944028050	1	\$ 120.00	25%	\$ 90.00	Replace	Not Given
11	PLATE ASSY, SLIDE DOOR LOCK STRIKER	6947028100	1	\$ 100.00	25%	\$ 75.00	Replace	Not Given
12	STRIKER, SLIDE DOOR OPEN, RH	6948526020	1	\$ 420.00	25%	\$ 315.00	Replace	Not Given
13	LOCK ASSY, SLIDE DOOR FULL OPEN STOP, RH	6905028011	1	\$ 499.00	25%	\$ 374.25	Replace	Not Given
14	ACTUATOR ASSY, REAR DOOR LOCK, RH	6913026020	1	\$ 550.00	25%	\$ 412.50	Replace	Not Given
15	CONTROL ASSY, SLIDE DOOR LOCK REMOTE, RH	6963026222	1	\$ 880.00	25%	\$ 660.00	Replace	Not Given
16	BASE SUB-ASSY, SLIDE DOOR LOWER ROLLER, RH	6802926070	1	\$ 367.00	25%	\$ 275.25	Replace	Not Given
17	ROLLER ASSY, SLIDE DOOR, LOWER RH	6835026080	1	\$ 380.00	25%	\$ 285.00	Replace	Not Given
18	PLATE, SLIDE DOOR LOWER RAIL, RH	6839426010	1	\$ 233.00	25%	\$ 174.75	Replace	Not Given
19	HINGE ASSY, SLIDE DOOR, CENTER RH	6838026030	1	\$ 210.00	25%	\$ 157.50	Replace	Not Given
20	ROLLER ASSY, SLIDE DOOR, UPPER RH	6831026051	1	\$ 180.00	25%	\$ 135.00	Replace	Not Given
21	ROLLER, SLIDE DOOR, RH	6833126071	1	\$ 266.00	25%	\$ 199.50	Replace	Not Given
22	PANEL, QUARTER, RH	6161126510	1	\$ 3,050.00	25%	\$ 2,287.50	Replace	Repair
23	WINDOW ASSY, SIDE, FRONT RH	6810326010	1	\$ 1,200.00	25%	\$ 900.00	Replace	Not Given
24	WINDOW ASSY, SIDE, REAR RH	6207326051	1	\$ 1,450.00	25%	\$ 1,087.50	Replace	Not Given
25	TYRE		1	\$ 100.00	0%	\$ 100.00	Replace	Replace
26	WHEEL, DISC	4261126180	1	\$ 1,200.00	25%	\$ 900.00	Replace	Not Given
27	CAP, WHEEL	4260226010	1	\$ 300.00	25%	\$ 225.00	Replace	Replace
28	CARRIER ASSY, DIFFERENTIAL, REAR	4111026432	1	\$ 3,420.00	25%	\$ 2,565.00	Replace	Not Given
29	SHAFT, REAR AXLE, RH	4231126310	1	\$ 1,700.00	25%	\$ 1,275.00	Replace	Not Given
30	ABSORBER ASSY, SHOCK, REAR RH	4853180725	1	\$ 270.00	25%	\$ 202.50	Replace	Not Given
31	SPRING ASSY, REAR RH	4821026A02	1	\$ 672.00	0%	\$ 672.00	Replace	Not Given
32	DRUM SUB-ASSY, REAR BRAKE	4243126200	1	\$ 855.00	25%	\$ 641.25	Replace	Not Given
33	COVER, REAR BUMPER	5215926490	1	\$ 700.00	25%	\$ 525.00	Replace	Replace
34	SUPPORT, REAR BUMPER SIDE, RH	5215526150	1	\$ 211.00	25%	\$ 158.25	Replace	Not Given
35	SUPPORT, REAR BUMPER SIDE, NO.2 RH	5215726010	1	\$ 211.00	25%	\$ 158.25	Replace	Not Given
36	PROTECTOR, SIDE MUDGUARD, FRONT RH	7692526050	1	\$ 525.00	25%	\$ 393.75	Replace	Not Given

TOTAL MATERIALS \$ 26,235.00 \$ 19,869.25 \$2,725.00								

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Thursday, 15 August 2019 3:36 PM
To: assignments
Cc: Vic (LKKAuto)
Subject: FW: New Assignment - Accident involving SJD5067K (OI) and GBH9440M (TP) on 10/08/2019 @ Sim Lim Tower Carpark - Oref: 19/19/19/VP05/022213 [External Confidential]
Attachments: GBH9440M CT(TP).pdf

4.06pm 15/8/19
person @ Mr. Phua
Vehicle not in

Hi Assignments,

Kindly arrange.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: KENNY LIM CHING GHEE <kennylim@lonpac.com>
Sent: Thursday, 15 August 2019 3:33 PM
To: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Shu Pei (LKKAuto) <shupe@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: New Assignment - Accident involving SJD5067K (OI) and GBH9440M (TP) on 10/08/2019 @ Sim Lim Tower Carpark - Oref: 19/19/19/VP05/022213 [External Confidential]

Lonpac External - Confidential

Dear Shu Pei

Please refer to the email below and we appreciate if you can arrange for a survey of the TP vehicle GBH9440M.

Kindly contact Mr Phua Zhi Yang/Yong Sing Motor Works to make arrangement for a pre-repair inspection on a without prejudice basis.

FYI, our Insured has yet to report the accident to us todate. Copy of T/P's GIA report is attached for your reference.

Best Regards

Kenny Lim
Asst. Claims Manager | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
DID: 6279 9256 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Zhi Yang Phua [<mailto:ZhiYangPHUA@yongsingmotor.com>]
Sent: Thursday, 15 August, 2019 3:23 PM
To: KENNY LIM CHING GHEE
Cc: MT_Claim_SG
Subject: RE: 3rd PARTY CLAIMS AGAINST YOUR INSURED VEHICLE SJD5067K [External Confidential]

Hi Kenny,

Thanks for your prompt reply.

We would like to choose Xing Guo Qiang to survey this vehicle

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: KENNY LIM CHING GHEE <kennylim@lonpac.com>
Sent: Thursday, August 15, 2019 2:37:48 PM
To: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: 3rd PARTY CLAIMS AGAINST YOUR INSURED VEHICLE SJD5067K [External Confidential]

Lonpac External - Confidential

Dear Zhi Yang

Please refer to our email to you yesterday (as attached).

Appreciate your reply soon.


Best Regards

Kenny Lim

Asst. Claims Manager | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

DID: 6279 9256 | Fax: (65) 6296 2706



From: Zhi Yang Phua [<mailto:ZhiYangPHUA@yongsingmotor.com>]
Sent: Thursday, 15 August, 2019 2:30 PM
To: MT_Claim_SG; GERALD POH WEE BIN
Subject: RE: 3rd PARTY CLAIMS AGAINST YOUR INSURED VEHICLE SJD5067K

Hi Both,

Please revert.

With Regards,

Phua Zhi Yang

Operation Supervisor
Mobile: 9101 7563 Fax: 6284 2798
No: 53, Defu Lane 12 Singapore 539144 (Head Office)
No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua
Sent: Wednesday, August 14, 2019 3:07:28 PM
To: mt_claim@lonpac.com <mt_claim@lonpac.com>; geraldpoh@lonpac.com <geraldpoh@lonpac.com>
Subject: 3rd PARTY CLAIMS AGAINST YOUR INSURED VEHICLE SJD5067K

Attention Motor Claims Department.

Our Ref: GBH9440M

DOA: 10/08/2019

Dear Sir/Mdm

RE: 3rd PARTY CLAIMS AGAINST YOUR INSURED VEHICLE SJD5067K

Kindly refer to attachment for our client's SAS report and our estimated cost of repair (based on our visual inspection only) for our client's vehicle, for your perusal.

We would like to check on liability and appreciate if you could confirm your agreement on direct settlement with us for COR and claim for LOU \$120 or rental \$150 .Number of days will be in accordance with your surveyor's recommendation.

Please provide a list of surveyors to choose from and you may then arrange to survey our client's vehicle to be survey at No. 53 Defu Lane 12, Singapore 539144

We thank you in advance for your assistance in this matter.

With Regards,

Phua Zhi Yang

Operation Supervisor
Mobile: 9101 7563 Fax: 6284 2798
No: 53, Defu Lane 12 Singapore 539144 (Head Office)
No: 10, Defu Lane 8 Singapore 539315



Mei Kwan (LKKAUTO)

From: KENNY LIM CHING GHEE <kennylim@lonpac.com>
Sent: Thursday, 22 August, 2019 5:49 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG; Asher Sng (LKKAUTO); CS A Team; Admin A
Subject: RE: New Assignment - Accident involving SJD5067K (OI) and GBH9440M (TP) on 10/08/2019 @ Sim LimTower Carpark - Oref: 19/19/19/VP05/022213 [External Confidential]
Attachments: SJD5067K GIA.PDF
Categories: HMK


Lonpac External - Confidential

Dear Mei Kwan

Please see attachment for our Insured's GIA report for your perusal.

Best Regards

Kenny Lim
Asst. Claims Manager | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
DID: 6279 9256 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: KENNY LIM CHING GHEE
Sent: Tuesday, 20 August, 2019 12:29 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG; Asher Sng (LKKAUTO); CS A Team; Admin A
Subject: RE: New Assignment - Accident involving SJD5067K (OI) and GBH9440M (TP) on 10/08/2019 @ Sim LimTower Carpark - Oref: 19/19/19/VP05/022213 [External Confidential]

Lonpac External - Confidential
Dear Mei Kwan

Insured will be making a report tomorrow. We will let you have it upon receipt of it.

Thank you.

Best Regards

Kenny Lim
Asst. Claims Manager | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
DID: 6279 9256 | Fax: (65) 6296 2706

Subject: RE: New Assignment - Accident involving SJD5067K (OI) and GBH9440M (TP) on 10/08/2019 @ Sim LimTower Carpark - Oref: 19/19/19/VP05/022213 [External Confidential]

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: KENNY LIM CHING GHEE <kennylim@lonpac.com>

Sent: Thursday, 15 August 2019 3:33 PM

To: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: New Assignment - Accident involving SJD5067K (OI) and GBH9440M (TP) on 10/08/2019 @ Sim LimTower Carpark - Oref: 19/19/19/VP05/022213 [External Confidential]

Lonpac External - Confidential

Dear Shu Pei

Please refer to the email below and we appreciate if you can arrange for a survey of the TP vehicle GBH9440M.

Kindly contact Mr Phua Zhi Yang/Yong Sing Motor Works to make arrangement for a pre-repair inspection on a without prejudice basis.

FYI, our Insured has yet to report the accident to us todate. Copy of T/P's GIA report is attached for your reference.

Best Regards

Kenny Lim

Asst. Claims Manager | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

DID: 6279 9256 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Zhi Yang Phua [<mailto:ZhiYangPHUA@yongsingmotor.com>]
Sent: Thursday, 15 August, 2019 2:30 PM
To: MT_Claim_SG; GERALD POH WEE BIN
Subject: RE: 3rd PARTY CLAIMS AGAINST YOUR INSURED VEHICLE SJD5067K

Hi Both,

Please revert.

With Regards,

Phua Zhi Yang
Operation Supervisor
Mobile: 9101 7563 Fax: 6284 2798
No: 53, Defu Lane 12 Singapore 539144 (Head Office)
No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua
Sent: Wednesday, August 14, 2019 3:07:28 PM
To: mt_claim@lonpac.com <mt_claim@lonpac.com>; geraldpoh@lonpac.com <geraldpoh@lonpac.com>
Subject: 3rd PARTY CLAIMS AGAINST YOUR INSURED VEHICLE SJD5067K

Attention Motor Claims Department.
Our Ref: GBH9440M
DOA: 10/08/2019
Dear Sir/Mdm

RE: 3rd PARTY CLAIMS AGAINST YOUR INSURED VEHICLE SJD5067K
Kindly refer to attachment for our client's SAS report and our estimated cost of repair (based on our visual inspection only) for our client's vehicle, for your perusal.

We would like to check on liability and appreciate if you could confirm your agreement on direct settlement with us for COR and claim for LOU \$120 or rental \$150. Number of days will be in accordance with your surveyor's recommendation.

Please provide a list of surveyors to choose from and you may then arrange to survey our client's vehicle to be survey at No. 53 Defu Lane 12, Singapore 539144

We thank you in advance for your assistance in this matter.

With Regards,

Phua Zhi Yang
Operation Supervisor
Mobile: 9101 7563 Fax: 6284 2798
No: 53, Defu Lane 12 Singapore 539144 (Head Office)
No: 10, Defu Lane 8 Singapore 539315



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19014235/Gea3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 06-01-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJD 5067K	Veh. Inspected	GBH 9440M
Policy No.		Coverage (\$)	0.00
Claim No.	19/19/19/VP05/022213	Excess (\$)	0.00
Assign From	KENNY	Assign Date	15/08/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE 2.8	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GDH2011010737	Colour	WHITE
Odometer	14141	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS

5. General Information

Accident Date	10/08/2019	Inspection Date	16/08/2019
Survey held at	53 DEFU LANE 12		
Repairer	YONG SING MOTOR WORKS		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 9440M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	DOOR SUB-ASSY, SLIDE, RH	BUCKLED	2,500.00	2,500.00
1	WEATHERSTRIP, REAR DOOR, RH	NOT NECESSARY	520.00	-
1	COVER, SLIDE DOOR SERVICE HOLE, NO.2 (TRIM)	NOT NECESSARY	441.00	-
1	MOULDING, REAR DOOR TRIM, NO.2 RH	NOT NECESSARY	450.00	-
1	BOARD SUB-ASSY, REAR DOOR TRIM, RH	NOT NECESSARY	620.00	-
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	NOT NECESSARY	260.00	-
1	CASE, REAR DOOR OUTSIDE HANDLE, RH	NOT NECESSARY	340.00	-
1	HANDLE SUB-ASSY, REAR DOOR INSIDE, RH	NOT NECESSARY	380.00	-
1	LOCK ASSY, SLIDE DOOR, FRONT RH	NOT NECESSARY	655.00	-
1	PLATE ASSY, SLIDE DOOR FRONT LOCK STRIKER	NOT NECESSARY	120.00	-
1	PLATE ASSY, SLIDE DOOR LOCK STRIKER	NOT NECESSARY	100.00	-
1	STRIKER, SLIDE DOOR OPEN, RH	NOT NECESSARY	420.00	-
1	LOCK ASSY, SLIDE DOOR FULL OPEN STOP, RH	NOT NECESSARY	499.00	-
1	ACTUATOR ASSY, REAR DOOR LOCK, RH	NOT NECESSARY	550.00	-
1	CONTROL ASSY, SLIDE DOOR LOCK REMOTE, RH	NOT NECESSARY	880.00	-
1	BASE SUB-ASSY, SLIDE DOOR LOWER ROLLER, RH	NOT NECESSARY	367.00	-
1	ROLLER ASSY, SLIDE DOOR, LOWER RH	NOT NECESSARY	380.00	-
1	PLATE, SLIDE DOOR LOWER RAIL, RH	NOT NECESSARY	233.00	-
1	HINGE ASSY, SLIDE DOOR, CENTER RH	NOT NECESSARY	210.00	-
1	ROLLER ASSY, SLIDE DOOR, UPPER RH	NOT NECESSARY	180.00	-
1	ROLLER, SLIDE DOOR, RH	NOT NECESSARY	266.00	-
1	PANEL, QUARTER, RH	TO REPAIR SEE LABOUR	3,050.00	-
1	WINDOW ASSY, SIDE, FRONT RH	NOT NECESSARY	1,200.00	-
1	WINDOW ASSY, SIDE, REAR RH	NOT NECESSARY	1,450.00	-
1	WHEEL, DISC	NOT NECESSARY	1,200.00	-
1	CAP, WHEEL	CUT	300.00	300.00
1	CARRIER ASSY, DIFFERENTIAL, REAR	NOT NECESSARY	3,420.00	-
1	SHAFT, REAR AXLE, RH	NOT NECESSARY	1,700.00	-
1	ABSORBER ASSY, SHOCK, REAR RH	NOT NECESSARY	270.00	-
1	SPRING ASSY, REAR RH	NOT NECESSARY	672.00	-

Report Ref No. CC4/LPC19014235/Gea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DRUM SUB-ASSY, REAR BRAKE	NOT NECESSARY	855.00	-
1	COVER, REAR BUMPER	CUT	700.00	700.00
1	SUPPORT, REAR BUMPER SIDE, RH	NOT NECESSARY	211.00	-
1	SUPPORT, REAR BUMPER SIDE, NO.2 RH	NOT NECESSARY	211.00	-
1	PROTECTOR, SIDE MUDGUARD, FRONT RH	NOT NECESSARY	525.00	-
	LESS 25% DISCOUNT		-	-875.00
			26,135.00	2,625.00
	SPECIAL NETT ITEMS			
1	TYRE (SN)	SCRATCHED	300.00	100.00
			300.00	100.00
	LABOUR			
	TO REMOVE & INSTALL ALL REPLACE ITEM, TO REPAIR RH PORTION. INCLUSIVE OF THE REPAIR OF PANEL, QUARTER, RH.		2,000.00	600.00
	TO RESPRAY DOOR SUB-ASSY, SLIDE, RH.		600.00	250.00
	TO RESPRAY REAR PANEL RH.		600.00	250.00
	TO RESPRAY REAR BUMPER.	NOT NECESSARY	600.00	-
	TO RESPRAY SILLMEMBER RH.	NOT NECESSARY	300.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		150.00	40.00
	TO TRANSFER DOOR MECHANISM RH.		200.00	60.00
	TO PROVIDE ANTI RUST COATING.		250.00	50.00
	TO CONDUCT WIRE CHECKING.	NOT NECESSARY	100.00	-
	TO VACUUM AND CLEAN ON INTERIOR.	NOT NECESSARY	80.00	-
	TO CHECK WATER LEAKAGE ON INSTALLED PARTS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT BOTH GLASS WINDOW RH.		300.00	60.00
	TO DO 4 WHEEL ALIGNMENT TYRE BALANCING.		200.00	30.00
	TO REMOVE AND REFIT UNDERCARRIAGE COMPARTMENT.	NOT NECESSARY	400.00	-
	-		-	-
	-		-	-
	-		-	-
			5,930.00	1,340.00
GRAND TOTAL			32,365.00	4,065.00

Report Ref No. CC4/LPC19014235/Gea3n2



RECOMMENDED COST OF REPAIRS			4,065.00
-----------------------------	--	--	----------

Report Ref No. CC4/LPC19014235/Gea3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.