


### Yong Sing Estimate Repair

Section A - To be completed by Claims Advisor

Vehicle Registration Number : GBH 9440M  
 Make / Model : HIACE DX 2.8 AUTO  
 Chassis No : GDH2011010737  
 Year of Manufacture : 2018  
 Registration Date : 1-Nov-18  
 Type of Repair (TP/OD/WS) : TP  
 Date/Time of Accident : 7 AUGUST 2019 / 09:25 hrs  
 Rental Vehicle : Yes ☐ No ☒  
 Remark : TP

Case Ref. : YS/19/0069  
 No. :

The damages on the vehicle are as indicated in the following diagram :



#### Yong Sing estimate breakdown cost

|                           |           |                  |
|---------------------------|-----------|------------------|
| Total Labour Cost         | \$        | 2,000.00         |
| Total Spray Painting Cost | \$        | 2,100.00         |
| Total Spare Parts Cost    | \$        | 26,435.00        |
| Other Charges             | \$        | 1,830.00         |
| <b>TOTAL</b>              | <b>\$</b> | <b>32,365.00</b> |

#### Adjusted by Surveyor, if applicable

|  |    |   |
|--|----|---|
|  | \$ | - |
|  | \$ | - |
|  | \$ | - |
|  | \$ | - |
|  | \$ | - |

Lump Sum Repair, if any :

No. of Repair Days : [ 10 ] days

### SURVEYOR'S Remark

6 Days.  
 P/P ~~Lump Sum~~ Repair.  
 before/after repair photos.  
 Gmo Qian - 82880282  
 16/8/19.

#### **UKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### Part 1 - Labour & Panel Beating Related Works

| Job Scope                                                  | Yong Sing Estimate | Surveyor Adjustment |
|------------------------------------------------------------|--------------------|---------------------|
| TO REMOVE & INSTALL ALL REPLACE ITEM, TO REPAIR RH PORTION | \$2,000.00         | 600                 |
|                                                            |                    |                     |
| <b>Total Labour Cost</b>                                   | \$2,000.00         | \$0.00              |

### Part 2 - Spray Painting Related Works

| Job Scope                           | Yong Sing Estimate | Surveyor Adjustment |
|-------------------------------------|--------------------|---------------------|
| TO RESPRAY DOOR SUB-ASSY, SLIDE, RH | \$600.00           | 250                 |
| TO RESPRAY REAR PANEL RH            | \$600.00           | 250                 |
| TO RESPRAY REAR BUMPER              | \$600.00           | X                   |
| TO RESPRAY SILLMEMBER RH            | \$300.00           | X                   |
|                                     |                    | NN                  |
| <b>Total Spray Painting Cost</b>    | \$2,100.00         | \$0.00              |

### Part 3 - Other Costs - Accident Repair Related Expenses

| Job Scope                                     | Yong Sing Estimate | Surveyor Adjustment |
|-----------------------------------------------|--------------------|---------------------|
| TO TEST AND REFIX REVERSE SENSOR SYSTEM       | \$150.00           | 40                  |
| TO TRANSFER DOOR MECHANISM RH                 | \$200.00           | 60                  |
| TO PROVIDE ANTI RUST COATING                  | \$250.00           | 50                  |
| TO CONDUCT WIRE CHECKING                      | \$100.00           | X                   |
| TO VACCUMM AND CLEAN ON INTERIOR              | \$80.00            | X                   |
| TO CHECK WATER LEAKAGE ON INSTALLED PARTS     | \$150.00           | X                   |
| TO REMOVE AND REFIT BOTH GLASS WINDOW RH      | \$300.00           | 60                  |
| TO DO 4 WHEEL ALIGNMENT TYRE BALANCING        | \$200.00           | 30                  |
| TO REMOVE AND REFIT UNDERCARRIAGE COMPARTMENT | \$400.00           | X                   |
|                                               |                    | NN                  |
| <b>Total Other Costs</b>                      | \$1,830.00         | \$0.00              |

**Part 4 - Spare Parts / Material Usage**

| Item | Part Name                                            | Part No              | Qty | List Price (\$) | Discount (25%) | Final Price (\$) | Repair @ Replace (/) (Yong Sing Request) | Repair @ Replace (/) (Surveyor Recommend) |
|------|------------------------------------------------------|----------------------|-----|-----------------|----------------|------------------|------------------------------------------|-------------------------------------------|
| 1    | DOOR SUB-ASSY, SLIDE, RH <i>Buc</i>                  | 67003-26340          | 1   | \$ 2,500.00     | 25%            | \$ 1,875.00      | Replace                                  |                                           |
| 2    | WEATHERSTRIP, REAR DOOR, RH <i>X</i>                 | 67871-26010          | 1   | \$ 520.00       | 25%            | \$ 390.00        | Replace                                  |                                           |
| 3    | COVER, SLIDE DOOR SERVICE HOLE, NO.2 (TRIM) <i>X</i> | 6785126030           | 1   | \$ 441.00       | 25%            | \$ 330.75        | Replace                                  |                                           |
| 4    | MOULDING, REAR DOOR TRIM, NO.2 RH <i>X</i>           | 67745-26011          | 1   | \$ 450.00       | 25%            | \$ 337.50        | Replace                                  |                                           |
| 5    | BOARD SUB-ASSY, REAR DOOR TRIM, RH <i>X</i>          | 6761326080 <i>NN</i> | 1   | \$ 620.00       | 25%            | \$ 465.00        | Replace                                  |                                           |
| 6    | HANDLE ASSY, REAR DOOR OUTSIDE, RH <i>X</i>          | 6923026070           | 1   | \$ 260.00       | 25%            | \$ 195.00        | Replace                                  |                                           |
| 7    | CASE, REAR DOOR OUTSIDE HANDLE, RH <i>X</i>          | 6924126030           | 1   | \$ 340.00       | 25%            | \$ 255.00        | Replace                                  |                                           |
| 8    | HANDLE SUB-ASSY, REAR DOOR INSIDE, RH <i>X</i>       | 6920726010B1         | 1   | \$ 380.00       | 25%            | \$ 285.00        | Replace                                  |                                           |
| 9    | LOCK ASSY, SLIDE DOOR, FRONT RH <i>X</i>             | 6937026010           | 1   | \$ 655.00       | 25%            | \$ 491.25        | Replace                                  |                                           |
| 10   | PLATE ASSY, SLIDE DOOR FRONT LOCK STRIKER <i>X</i>   | 6944028050           | 1   | \$ 120.00       | 25%            | \$ 90.00         | Replace                                  |                                           |
| 11   | PLATE ASSY, SLIDE DOOR LOCK STRIKER <i>X</i>         | 6947028100           | 1   | \$ 100.00       | 25%            | \$ 75.00         | Replace                                  |                                           |
| 12   | STRIKER, SLIDE DOOR OPEN, RH <i>X</i>                | 6948526020           | 1   | \$ 420.00       | 25%            | \$ 315.00        | Replace                                  |                                           |
| 13   | LOCK ASSY, SLIDE DOOR FULL OPEN STOP, RH <i>X</i>    | 6905026011           | 1   | \$ 499.00       | 25%            | \$ 374.25        | Replace                                  |                                           |
| 14   | ACTUATOR ASSY, REAR DOOR LOCK, RH <i>X</i>           | 6913026020           | 1   | \$ 550.00       | 25%            | \$ 412.50        | Replace                                  |                                           |
| 15   | CONTROL ASSY, SLIDE DOOR LOCK REMOTE, RH <i>X</i>    | 6963026222           | 1   | \$ 880.00       | 25%            | \$ 660.00        | Replace                                  |                                           |
| 16   | BASE SUB-ASSY, SLIDE DOOR LOWER ROLLER, RH <i>X</i>  | 6902926070           | 1   | \$ 367.00       | 25%            | \$ 275.25        | Replace                                  |                                           |
| 17   | ROLLER ASSY, SLIDE DOOR, LOWER RH <i>X</i>           | 6935026080           | 1   | \$ 380.00       | 25%            | \$ 285.00        | Replace                                  |                                           |
| 18   | PLATE, SLIDE DOOR LOWER RAIL, RH <i>X</i>            | 6939426010           | 1   | \$ 233.00       | 25%            | \$ 174.75        | Replace                                  |                                           |
| 19   | HINGE ASSY, SLIDE DOOR, CENTER RH <i>X</i>           | 6938026030           | 1   | \$ 210.00       | 25%            | \$ 157.50        | Replace                                  |                                           |
| 20   | ROLLER ASSY, SLIDE DOOR, UPPER RH <i>X</i>           | 6931026051           | 1   | \$ 180.00       | 25%            | \$ 135.00        | Replace                                  |                                           |
| 21   | ROLLER, SLIDE DOOR, RH <i>X</i>                      | 6933126071           | 1   | \$ 266.00       | 25%            | \$ 199.50        | Replace                                  |                                           |
| 22   | PANEL, QUARTER, RH <i>X Repair</i>                   | 6161126510           | 1   | \$ 3,050.00     | 25%            | \$ 2,287.50      | Replace                                  |                                           |
| 23   | WINDOW ASSY, SIDE, FRONT RH <i>X</i>                 | 69810326010          | 1   | \$ 1,200.00     | 25%            | \$ 900.00        | Replace                                  |                                           |
| 24   | WINDOW ASSY, SIDE, REAR RH <i>X</i>                  | 6207326051           | 1   | \$ 1,450.00     | 25%            | \$ 1,087.50      | Replace                                  |                                           |
| 25   | TYRE <i>/ Gca 1008 (SN)</i>                          |                      | 1   | \$ 300.00       | 25%            | \$ 225.00        | Replace                                  |                                           |
| 26   | WHEEL, DISC <i>X NN</i>                              | 4261126180           | 1   | \$ 1,200.00     | 25%            | \$ 900.00        | Replace                                  |                                           |
| 27   | CAP, WHEEL <i>/ Cut</i>                              | 4260226010           | 1   | \$ 300.00       | 25%            | \$ 225.00        | Replace                                  |                                           |
| 28   | CARRIER ASSY, DIFFERENTIAL, REAR <i>X</i>            | 4111026432           | 1   | \$ 3,420.00     | 25%            | \$ 2,565.00      | Replace                                  |                                           |
| 29   | SHAFT, REAR AXLE, RH <i>X</i>                        | 4231126310           | 1   | \$ 1,700.00     | 25%            | \$ 1,275.00      | Replace                                  |                                           |
| 30   | ABSORBER ASSY, SHOCK, REAR RH <i>X</i>               | 4853180725           | 1   | \$ 270.00       | 25%            | \$ 202.50        | Replace                                  |                                           |
| 31   | SPRING ASSY, REAR RH <i>X</i>                        | 4821026A02           | 1   | \$ 672.00       | 0%             | \$ 672.00        | Replace                                  |                                           |
| 32   | DRUM SUB-ASSY, REAR BRAKE <i>X</i>                   | 4243126200           | 1   | \$ 855.00       | 25%            | \$ 641.25        | Replace                                  |                                           |
| 33   | COVER, REAR BUMPER <i>/ Cut</i>                      | 5215926490           | 1   | \$ 700.00       | 25%            | \$ 525.00        | Replace                                  |                                           |
| 34   | SUPPORT, REAR BUMPER SIDE, RH <i>X</i>               | 5215526150           | 1   | \$ 211.00       | 25%            | \$ 158.25        | Replace                                  |                                           |
| 35   | SUPPORT, REAR BUMPER SIDE, NO.2 RH <i>X</i>          | 5215726010 <i>NN</i> | 1   | \$ 211.00       | 25%            | \$ 158.25        | Replace                                  |                                           |
| 36   | PROTECTOR, SIDE MUDGUARD, FRONT RH <i>X</i>          | 7692526050           | 1   | \$ 525.00       | 25%            | \$ 393.75        | Replace                                  |                                           |
| 37   |                                                      |                      | 1   |                 |                |                  |                                          |                                           |
| 38   |                                                      |                      | 1   |                 |                |                  |                                          |                                           |
| 39   |                                                      |                      | 1   |                 |                |                  |                                          |                                           |
| 40   |                                                      |                      | 1   |                 |                |                  |                                          |                                           |
| 41   |                                                      |                      | 1   |                 |                |                  |                                          |                                           |
| 42   |                                                      |                      | 1   |                 |                |                  |                                          |                                           |
| 43   |                                                      |                      | 1   |                 |                |                  |                                          |                                           |