



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
ZACK CHOY KUAN ZHEN	Cust No/Name LCV06630/ZACK CHOY KUAN ZHEN
BLK 271 TAMPINES STREET 21	Reg No/Reg Date SMF9225Z / 21/09/201
#03-85	Date In/Mileage / 0
SINGAPORE 520271	Chassis No KNAHU815VJ7208953
Contact No Mobile: 86123494	Engine No D4FDJH553274
	Make/Model KIA/CARENS 1.7 A-D SX FL DY6
	Colour/Trim ID CLEAR WHITE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	17/07/2019/ 18:12	Bod	261 / Edwin Calina	54257		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							550 2200.00
RENEW & RE-ALIGN FRT DAMAGED PORTION:							
-RENEW FRT BUMPER ✓							
-REPAIR FRT FENDER RH X							
E PNT98000							420 840.00
RESPRAY FRT BUMPER & FRT FENDER RH							
A 54900099							30 50.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM							✓ 200.00
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							X 120.00
APPLY ANTI CORROSION ON AFFECTED AREAS							
E PNT88000							60 120.00
REMOVE & REFIT FRT PARKING ASSIST SENSOR							
M SUNDRY							20 50.00
Sundries							
M	LAMP ASSY-HEAD,RH			1.00	1558.00	00.00	at 1558.00
M	EMBLEM-KIA			1.00	76.00	00.00	ner 76.00
M	COVER-FR BUMPER			1.00	695.00	00.00	de 695.00
M	GRILLE ASSY-RADIATOR			1.00	428.00	00.00	X 428.00
M	STRIP ASSY-FR BUMPER UPR			1.00	32.00	00.00	32.00
M	COVER-FR BUMPER FOG LAMP,RH			1.00	130.00	00.00	ent 130.00
M	LAMP ASSY-FRONT FOG,RH			1.00	206.00	00.00	ent 206.00
M	HOLDER-PARKING ASSIST SYSTEM N			1.00	17.00	00.00	17.00
M	HOLDER-PARKING ASSIST SYSTEM N			1.00	17.00	00.00	17.00
M	HOLDER-PARKING ASSIST SYSTEM N			1.00	17.00	00.00	17.00
M	HOLDER-PARKING ASSIST SYSTEM N			1.00	17.00	00.00	17.00
M	BRACKET-FR BUMPER SIDE,RH			1.00	12.00	00.00	? 12.00

To find damaged part(s) during resurvey WIP No

Parts/prices are subject to confirmation

261 / Edwin Calina 54257

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate

SURVEYOR NAME : Tanglim 97495744

SURVEYOR NAME: Tan Jiah 97895744

Confirm & accepted by

SURVEYOR SIGNATURE: [Signature]DATE: 14/8/19 3:25pmREMARKS: Resurvey before paint03 days sure (knauto.com)

Nett 6,785.00

7% GST on 6785.00 474.95

Total Payable 7,259.95

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.