



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : HR-8500111-X

ZACK CHOY KUAN ZHEN BLK 271 TAMPINES STREET 21 #03-85 SINGAPORE 520271 Contact No Mobile: 86123494	Cust No/Name	LCV06630/ZACK CHOY KUAN ZHEN
	Reg No/Reg Date	SMF9225Z / 21/09/201
	Date In/Mileage	/ 0
	Chassis No	KNAHU815VJ7208953
	Engine No	D4FDJH553274
	Model/Model	KIA/CARENG 1.7 A-D SX FL DY6
Work/Work 1. Repairs to damaged portion of the following: • To resurvey before/after spray painting		CLEAR WHITE / WK SATURN BLACK

CSM00081	Cash	17/07/2019/ 18:12	Bod	2617 EDWIN CHIA	54257		
E PNT88000 RENEW & RE-ALIGN FRT DAMAGED PORTION: -RENEW FRT BUMPER ✓ -REPAIR FRT FENDER RH X E PNT98000 RESPRAY FRT BUMPER & FRT FENDER RH X A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS E PNT88000 REMOVE & REFIT FRT PARKING ASSIST SENSOR M SUNDRY Sundries M LAMP ASSY-HEAD,RH M EMBLEM-KIA M COVER-FR BUMPER M GRILLE ASSY-RADIATOR M STRIP ASSY-FR BUMPER UPR M COVER-FR BUMPER FOG LAMP,RH M LAMP ASSY-FRONT FOG,RH M HOLDER-PARKING ASSIST SYSTEM N M HOLDER-PARKING ASSIST SYSTEM N M HOLDER-PARKING ASSIST SYSTEM N M HOLDER-PARKING ASSIST SYSTEM N M BRACKET-FR BUMPER SIDE,RH						• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	5502200.00 420 840.00 30 50.00 / 200.00 n x 120.00 60 120.00 20 50.00 at 1558.00 re 76.00 de 695.00 n x 428.00 n x 32.00 int 130.00 int 206.00 17.00 17.00 17.00 17.00 n x 12.00

SURVEYOR NAME : Tan Jiah 97495744

Confirm & accepted by

SURVEYOR SIGNATURE : [Signature]DATE : 19/8/19 3:25pmREMARKS : Resurvey before paint03 daysSure (handwritten)

Nett

6,785.00

GST on

474.95

Total Payable

7,259.95

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Surveyor : TAUFIKH LKK
 Claim : TP ERGO
 DOA : 16.07.2019
 Emailed : 24.09.2019 9.30am
 Date survey : 19.08.2019

VEHICLE NO : SMF 9225 Z
 MODEL : KIA CARENS 1.7 A D SX
 WIP : 54257

Material	:	\$	<u>2,733.00</u>
Labour	:	\$	<u>1,280.00</u>
Sub-Total	:	\$	<u>4,013.00</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>4,013.00</u>
GST 7%	:	\$	<u>280.91</u>
Grand Total	:	\$	<u>4,293.91</u>
Finalise By/Date	:		<u>LOI / 24/09/2019</u>

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 3 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 3

☒ TP claim GBF9346M

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ZACK CHOY KUAN ZHEN	Cust No/Name LCV06630/ZACK CHOY KUAN ZHEN
BLK 271 TAMPINES STREET 21	Reg No/Reg Date SMF9225Z / 21/09/2018
#03-85	Date In/Mileage 19/08/2019/ 22208
SINGAPORE 520271	Chassis/Package KNAHU815VJ7208953 /KC17P(F)
Contact No Mobile: 86123494	Engine No D4FDJH553274
27/08/	Make/Model KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim 1D CLEAR WHITE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	24/09/2019/ 08:32	TLE	260 / AiTing	54257

Description of Goods/Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 550.00
E PNT98000 RESPRAY ON FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 420.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK- USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 200.00
E PNT88000 REMOVE & REINSTALL FRONT PARKING ASSIST SENSOR				✓ 60.00
M SUNDRY SUNDRIES				✓ 20.00
X LAMP ASSY-HEAD,RH	1.00	✓ 1558.00	00.00	1558.00
X EMBLEM-KIA	1.00	✓ 76.00	00.00	76.00
X COVER-FR BUMPER	1.00	✓ 695.00	00.00	695.00
X COVER-FR BUMPER FOG LAMP,RH	1.00	✓ 130.00	00.00	130.00
X LAMP ASSY-FRONT FOG,RH	1.00	✓ 206.00	00.00	206.00
X HOLDER-PARKING ASSIST SYSTEM N	1.00	✓ 17.00	00.00	17.00
X HOLDER-PARKING ASSIST SYSTEM N	1.00	✓ 17.00	00.00	17.00
X HOLDER-PARKING ASSIST SYSTEM N	1.00	✓ 17.00	00.00	17.00
X HOLDER-PARKING ASSIST SYSTEM N	1.00	✓ 17.00	00.00	17.00
Z TEXT TP CLAIM ERGO GBF9346M DOA : 16.07.19 SURVEYOR TAUFIKH LKK 19.08.19 REPAIR 03 DAYS				

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	2,733.00	Nett	* 4,013.00
Labour	1,260.00	7% GST on	4013.00
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	4,293.91
Sundry/Others	20.00		
Total(w/o GST)	4,013.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.