| 22/03/2002 ASS. REC. BY: | REF: CS/AG1 190 | 14741/ N | + £300 pecial Instruction: |
|--|--|--------------|-----------------------------|
| Surveyor : NOZ | ASSIGNME | ENT (Office) | . Y |
| From (Person): Ivy Ray | HIIA of AG | 1 | Date/Time: 13.8 19 4.08 p.m |
| Estimated Cost: | | Bill to: | |
| OD / TP WS / TP RES / O To Inspect Vehicle No: | OD RESIEVAINVIMVIC SJK 2941U | S | Insured: SKN 72390 Odysse |
| at Workshop m/s Ryd | ir Auto | | Tel: 84848271 |
| of 2 karci Burat | AVI 2 #02-19 | | |
| Policy No: | | Claim No: | (10003752/JW |
| Sum Insured: | | Excess: | |
| Make of Veh: (Client's Record) | mp" | | D.O.A. 14.8.2019 |
| CA / REV / REP. / RE Date/Time: 154.19 5 | V 24 HRS -06 p. n Person Contacted: | June | H.O.D. Endorsement: |
| Date/Time Action/Instr | ruction (V) Estimate | | |
| 5JK 29 | 410-> | | |
| SKN F2 | 39 b - x | | |
| | * | | |
| | | | |
| | | | |
| | | | |

| ACCT | CININ | /E E7 | BUTTER |
|-----------------------|-------|-------|------------------|
| ASSI | (E) | | INT |
| St. St. Park Ton. Co. | | - | Name and Address |

| From: Date: 16/8/16 | Veh No: SJK 29414 | Yr Regn: 15 DUT 1208 |
|--|--|---------------------------------|
| Estimated Cost: | Type: M.Car J.M.Cycle / Bus / Van / Lorry / | 4.0 |
| OD (TP) WS / TP RES / OD RES / EVA / INV / MV | Truck / Trailer or | |
| To Inspect Vehicle No: SJK 29414 | Make: to yota wisit 1. | 8 A c.c 1,794 |
| at Workshop m/s Ryder Auto | | /C: (nsured / Std / NI / NA |
| of 2 kalki Bulkit Ne 2#02-10 | Colour ELRY A Sp.Reading 214,248 | /Radio: Insured / Std / NI / NA |
| Insured: Autohub | Eng/No: | |
| Policy No. | C/No: ITDER/2W/O | 3000526 |
| Claims No. | Gen. Cond: Good / Fair / Poor / Burnt | |
| Sum Insured: Excess: | Steering: (norder / Jammed / Leaked / Bur | nt or |
| (Client's Record) | Brake: norder / Jammed / Leaked / Bur | nt or |
| Make of Veh: | Modi: Nil / S/Rim / STD A/Rim or | |
| | Tyre Size: F: 195/63 | RIST |
| (Policy Condition) | R: 11 | |
| Remark: The veh had commenced its N/S | O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIO | OHTSU / PIR / SUMI / |
| repair at the time of inspection. | TOYO/YOKO or COUTINE | |
| Bal, or Market Value: | | Rear |
| IDAC Accident Rport: Consistent? : Yes or No | | R/Bal. 6 mm |
| GIA / PR Seen: Consistent? : Yes or No | | _/Bal. 6 mm |
| Est. Repairs: days Res.: Yes or No | | 0.0.1. (6/8/19 |
| Lum Sum: % 3 Val.: Yes or No | Survey held at PYDER AU | |
| CA / REV / REP. / 24 HRS 149 | Des. of Damages : Frt Rear / O/S / N/S | |
| Vehicle: | IN / OUT | |
| Date:Person Contacted: | The U/C / Chassis frame / Body Str | |
| Date / Time Action / Instruction | execus 1327 - 150 | AG1 CB |
| 19/8/19 FINALIZED umf sur | REPAIR \$3,350.00/5D | 1793 |
| Cla. 0704.014,6070) | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Date/Time, File Pass to? Preli. Report | Days Of Repair: 5 | |
| and Track | | Curvey Foo: 721 |
| 1) 24 18 LUN S : Final Report Date/Time, File Return to? | | Survey Fee: 350 |
| | Add Fee: Site Insp (\$ | Transportation:S + RSSI |
| 2) | : Interview (\$ | Photos |
| Elabert Found | : Tech. Invs (\$ | |
| Report Format: Lump(S)m / LBJ: (# 3350 - | | Others |
| FRIBERIUM PETE (# 22.2.2) | : Weetend (% | |
| | | TOTAL 350 |

Nivitha (LKK Auto)

From:

Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Sent:

Thursday, 15 August 2019 4:08 PM

sur@lkkauto.com; Julie Mangubat

To: Cc:

Admin-D (LKKAuto)

Subject:

FW: TPPD Survey: Claim ref:C10003752/JM || OI- SKN7239D (Silver) TP- SKN7239D ||

Est:0.00 | Ryder Auto

Attachments:

SJK2941U PRS NOTICE.pdf

Hi Team,

TP PRS for SKN7239D please.

Workshop has chosen Mr. Kenneth or Marcus to survey the vehicle.

Please confirm.

Regards,

Ivy Ratilla Executive, Claims Admin

T +65 6540 2185 F +65 6725 0853 E ivy.r@budgetdirect.com.sq



2019 feefo

Customer Care +65 6221 2111 Claims +65 6221 2199 Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01 Singapore Shopping Centre Singapore 239924 budgetdirect.com.sq

auto 🗳 general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget** Direct Insurance.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Ryder Auto workshop <ra description: Sent: Thursday, 15 August 2019 11:11 AM

To: Claims <claims@budgetdirect.com.sg>
Subject: Urgent: PRE-REPAIR INSPECTION: Your Vehicle SKN7239D; Our Vehicle SJK2941U Accident involving
SJK2941U & SKN7239D On 14 August 2019

Dear Sir,

We refer to the above matter.

Kindly find attached PRS for your necessary action.

For Direct Settlement cases, we only use your in-house surveyor. Kindly arrange your in-house surveyor.

Thank you.

Best regards
June

2 Kaki Bukit Ave 2, #02-19, 02-22 AutoHub @ Kaki Bukit, Singapore 417921

Tal: 67418277 Fax: 67468277

5 Tuas Ave 3 BS Logistics Hub Singapore 639405

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Fax: 64815390




2 Kaki Bukit Ave 2, #02-19/22, AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com Tel: 67418277 Fax: 67468277

Our Ref: SJK2941U

Date: 15 August 2019

Auto & General Insurance (S) Pte Ltd 190 Clemenceau Avenue, #03-01 Singapore Shopping Centre Singapore 239924



Dear Sir.

PROPERTY DAMAGE CLAIM

CLAIMANT

: WEE YING KONG

ACCIDENT INVOLVING

: SJK2941U & SKN7239D ALONG JURONG WEST AVE 4 SLIP ROAD TWDS JALAN BAHAR ON 14 AUGUST 2019

We act for WEE YING KONG, the owner of vehicle no. SJK2941U, which was involved in the aforesaid accident.

Kindly be notified that we are claiming against your insured motor vehicle no. SKN7239D for damages, costs and disbursements as a result of your insured driver's negligence. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at our workshop, 2 Kaki Bukit Ave 2, #02-19, Autohub @ Kaki Bukit, Singapore 417921.

Please arrange with the undersigned via mobile 97924673 Mr Chan. Kindly reply within the next two (2) working days or we shall proceed with our own necessary procedures and repairs.

This PRS is on a "Direct Settlement" basis, hence we shall be furnishing an estimate for your surveyor to finalise as soon as possible.

Kindly reply either via email, fax or mobile.

Thank you.

Yours faithfully,

Ryder Auto Pte Ltd

Chan San Choon

Director

DipEng, AAE MIMI, MSAE(Aust)









MSME19107029 / SME Motor Pte Ltd - Kaki Bukit ENTRY DATE & TIME: 15/08/2019 16:29 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.

| ACC | IDE | NT ST | ΓΑΤ | ΕV | ENT | |
|-----|-----|-------|-----|----|-----|--|
| | | | | | | |

Date Of Report 15/08/2019 16:29 Date Of Accident 14/08/2019 14:00

Exact Location Of Accident JURONG WEST AVE 4 SLIP RD TWDS JALAN BAHAR

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJK2941U

Insured/Policyholder

Name Of Registered Owner WEE YING KONG

NRIC No S2503443J Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-83556026 Alternative Phone No. OFFICE-97329511

Vehicle Particulars

Manufacturer TOYOTA WISH Model

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company LIBERTY INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number SI18V12236/VPE/R03

Cover Note Number

Driver:

Name of Driver WEE YING KONG

NRIC No S2503443J Date Of Birth 17/09/1953 Occupation INDOOR Date Of Driving Pass 23/07/1975

Driving Experience 44 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-83556026

Fax Number

Contact Number OFFICE-97329511

EMail Address NOEMAIL Address

BLK 732 JURONG WEST ST 73 #12-36

Postcode

640732

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Passenger 1

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

NAME:

: WONG SIEW GEOK

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG JURONG WEST AVE 4 SLIP ROAD TOWARDS JALAN BAHAR. VEHICLE AHEAD SLOWED DOWN AND STOPPED, I FOLLOWED SUIT. MOMENTS LATER, VEHICLE B REAR ENDED MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKN7239D

Vehicle Make/Model/Colour Details Of Properties

VEHICLE B

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

Sketch Plan #2 Pg. 1

SKETCH PLAN:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

| I WAS TRAVELLING ALONG JURONG WEST AVE 4 SLIP ROAD TOWARDS JALAN |
|--|
| BAHAR, VEHICLE AHEAD SLOWED DOWN AND STOPPED, I FOLLOWED SUIT. |
| MOMENTS LATER, VEHICLE B-REAR-ENDED MY-VEHICLE. |
| MOMENTO LITTLE, VEHICLE BREAK ENDED WIT VEHICLE. |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |

DECLARATION

I/ We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC / FIN No .:

> Back to OneMotoring

You may print this page for reference.

Enquire Transfer Fee

| Vehicle No.: | SJK2941U | | |
|---|--|---|--|
| Vehicle Type : | P11 - Passenger Station Wagon/Jeep/Land Rover | | |
| Vehicle Attachment 1: | No Attachment | | |
| Vehicle Scheme : | Normal | | |
| Vehicle Make : | TOYOTA | | |
| Vehicle Model : | WISH 1.8 AUTO | | |
| Chassis No.: | JTDER12W103000526 | | |
| Propellant: | Petrol | | |
| Engine No. : | 1ZZ3124322 | | |
| Engine Capacity: | 1794 cc | | |
| Maximum Power Output: | 97.0 kW (130 bhp) | | |
| Maximum Laden Weight: | 100 (100 m) 16 | | |
| Unladen Weight: | 1885 kg 1310 kg | | |
| Year Of Manufacture : | 2008 | | |
| Original Registration Date : | 15 Oct 2008 | | |
| Lifespan Expiry Date: | - | | |
| COE Category: | | | |
| PQP Paid: | B - Car (1601cc & above) \$32,279,00 | | |
| COE Expiry Date : | No partition of the control of the c | | |
| Road Tax Expiry Date : | 14 Oct 2028 | | |
| Inspection Due Date : | 14 Oct 2019 | | |
| Intended Transfer Date : | 14 Oct 2019 | | |
| CO2 Emission : | 19 Aug 2019 | | |
| CO2 Emission : | • | | |
| | • | | |
| HC Emission : | <u> </u> | | |
| NOx Emission : | • | | |
| PM Emission : | | | |
| The current road tax expiry is 14 Oc | ct 2019. You may renew the road tax from 15 Jul 2019 with | n all pre-requisite(s) fulfilled. If the road | tax is renewed after 14 Oct |
| Road tay including Over Payment (i | posed. Please use Enquire Road Tax Payable to check on the | ne late fee(s) payable. | |
| | | | 12. 14. |
| Amount Pavable (From 15 Oct | if any), of a vehicle will follow the vehicle to the new registe | ered owner when its ownership is being | transferred. |
| Amount Pavable (From 15 Oct. | 2019 to 14 Apr 2020) | | |
| Amount Pavable (From 15 Oct | 2019 to 14 Apr 2020) Amount Before GST | GST Amount | Amount After GS |
| Amount 2avable (Scome 500) | Amount Before GST (S\$) | GST Amount (S\$) | Amount After GS (S\$ |
| Amount Pavable (From 15 Oct.) Transfer Fee: | 2019 to 14 Apr 2020) Amount Before GST | GST Amount | Amount After GS (S\$ 25.0 |
| Amount Pavable (From 15 Oct.) Transfer Fee: Sub Total: | 2019 to 14 Apr 2020) Amount Before GST (S\$) 25.00 | GST Amount (S\$) | Amount After GS (S\$ 25.0 25.0 |
| Transfer Fee : Sub Total : Nett Road Tax Amount (After | Amount Before GST (S\$) | GST Amount (S\$) | |
| Amount Pavable (From 15 Oct.) Transfer Fee: Sub Total: | 2019 to 14 Apr 2020) Amount Before GST (S\$) 25.00 | GST Amount (S\$) | Amount After GS' (5\$ 25.00 25.00 584.00 |
| Amount Pavable (From 15 Oct Transfer Fee : Sub Total : Nett Road Tax Amount (After Offsetting Over Payment) : | 2019 to 14 Apr 2020) Amount Before GST (S\$) 25.00 | GST Amount (S\$) | Amount After GS (S\$ 25.0 25.0 |
| Amount Pavable (From 15 Oct Transfer Fee : Sub Total : Nett Road Tax Amount (After Offsetting Over Payment) : | 2019 to 14 Apr 2020) Amount Before GST (S\$) 25.00 584.00 2019 to 14 Oct 2020) Amount Before GST | GST Amount (S\$) | Amount After GS (53 25.0 25.0 584.0 |
| Amount Pavable (From 15 Oct.) Transfer Fee : Sub Total : Nett Road Tax Amount (After Offsetting Over Payment) : Total Amount Payable : Amount Payable (From 15 Oct.) | 2019 to 14 Apr 2020) Amount Before GST (S\$) 25.00 584.00 | GST Amount (S\$) - | Amount After GS (S\$ 25.0 25.0 584.0 |
| Amount Pavable (From 15 Oct.) Transfer Fee: Sub Total: Nett Road Tax Amount (After Offsetting Over Payment): Total Amount Payable: Amount Pavable (From 15 Oct.) | 2019 to 14 Apr 2020) Amount Before GST (S\$) 25.00 584.00 2019 to 14 Oct 2020) Amount Before GST | GST Amount (S\$) GST Amount | Amount After GS (58 25.0 25.0 584.0 609.0 |
| Transfer Fee : Sub Total : Nett Road Tax Amount (After Offsetting Over Payment) : Total Amount Payable : Amount Payable (From 15 Oct) Transfer Fee : Sub Total : | 2019 to 14 Apr 2020) Amount Before GST (S\$) 25.00 584.00 2019 to 14 Oct 2020) Amount Before GST (S\$) | GST Amount (S\$) GST Amount (S\$) | Amount After GS (58 25.0 25.0 584.0 609.0 Amount After GS (58 |
| Amount Pavable (From 15 Oct Transfer Fee : Sub Total : Nett Road Tax Amount (After Offsetting Over Payment) : | 2019 to 14 Apr 2020) Amount Before GST (S\$) 25.00 584.00 2019 to 14 Oct 2020) Amount Before GST (S\$) | GST Amount (S\$) GST Amount (S\$) | Amount After GS (5) 25.0 25.0 584.0 609.0 Amount After GS (5) 25.0 |

ОК

Print

'> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Owner ID Type: | Singapore NRIC |
|-------------------------------|--------------------------|
| Owner ID: | 443J |
| Vehicle Details | |
| Vehicle No.: | SJK2941U |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 19 Aug 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | WISH 1.8 AUTO |
| Primary Colour: | Grey |
| Manufacturing Year: | 2008 |
| Engine No.: | 1ZZ3124322 |
| Chassis No.: | JTDER12W103000526 |
| Maximum Power Output: | 97.0 kW (130 bhp) |
| Open Market Value: | \$18,803.00 |
| Original Registration Date: | 15 Oct 2008 |
| First Registration Date: | 15 Oct 2008 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$18,803.00 |
| Intended PARE Repair Details | |
| PARF Eligibility: | Forfeited |
| PARF Eligibility Expiry Date: | |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 14 Oct 2028 |
| COE Category: | B - Car (1601cc & above) |
| COE Period(Years): | 10 |
| PQP Paid: | \$32,279.00 |
| COE Rebate Amount: | \$29,540.00 |
| Total Rebate Amount: | \$29,540.00 |

The information contained herein is correct as at 19 Aug 2019

| | Make ▼ Model ▼ | Price | Depreciation | Ĉ Reg D: ▼ ‡ | Eng Cap | Mileage 🖨 | Veh Type | Status - |
|--|---|---------------------------------------|---|--|--|---|----------------|--------------|
| Search Selection | Toyota Wish | Any | Any | > 10 year(s) old | Any | Any | Any | Available |
| | ☐ Toyota Wish 1.8A (COE till 02/2021) | \$11,588 | \$7,650 /yr | 23-Feb-2006 | 1,794 cc | 350,000 km | MPV | Available |
| | HiFi, Car Camera. | | | | | | | DIRECT OWNER |
| Brazza | 1 Owner, Paper Value \$8.5k. Proted: 19-Aug-2019 Tags: 2006 Toyota | State State Control | The Phone Was a | | - k 11 - 17 4 | | | |
| | M March 1957/08-2019 Tags 2009 Toyota | Wish, 20% fayeta | yeost, toyout wisa, to | ACIDAL ACIDATIC THIS COLOR, THIS THE CA | CIARL STREAM FORWARD | | | |
| | ☐ Toyota Wish 1.8A X (COE till 07/2024) | \$41,800 | \$8,510 /yr | 17-Jul-2009 | 1,797 сс | 102,000 km | MPV | Available |
| 782 | Keyless Entry, Best Selling MPV And Well Maintained. Good For Comfort. 100% Loan Available. | Big Familie | s Or With Kid | ls. No Comprom | ise On Space | | rly | |
| | MS Carz | DES. 2000 (2004) | Int. Towns Miles and | | and the Driver | | | |
| | Posted: 19-Aug-2019 Tags: 2009 Toyon | Wish, 2009 toyota | wish, Ioyota Wish, to | yota wish, Toyota, Wish, v | vish, Ustil Toyota | | | |
| AND V | Toyota Wish 1.8A X (COE till 05/2029) | \$59,800 | \$6,110 /yr | 09-Jun-2009 | 1,797 cc | 110,000 km | MPV | Available |
| | 1 Owner, Low Mileage, Acciden | t Free. Bank | /In House Lo | an Available. Ch | eapest In Tl | ne Market. | | DIRECT OWNER |
| | Protect 19-Aug-2019 Tep: 2009 Toyota | Wish, 2005 toyota | wish Toyota With, to | nota wish, Toyota, Wish, a | erst. Load Tayota | | | |
| 0 | Toyota Wish 1.8A X Sunroof (COE till 05/2029) | \$67,800 | \$6,930 /yr | 26-Jun-2009 | 1,797 cc | - | MPV | Availabl |
| E | 1 Year In House Warranty, Full I Workshop, Price Stated Above Is | Actual Sel | ling Price, Our | Company Rene | w COE Car | Based On | | |
| | Condition Not On Ownership, N | ew Paintwo | rk, Fully Refu | rbished, Acciden | t Free, ST. | | | |
| | Carway Posted: 19-Aug-2019 Togs. 2009 Tayon | Wish, 2009 toyota | wiah, Toyota Wish, to | yota wish, Toyota, Wish, v | vish, Used Toyota | | | |
| GETYOUR | Is your COE expiring? Let us help you r | | | | | | | |
| RENEWAL | Getting your COE renewed is ea the cheapest loan in town and ar | isy, fast and approval in | affordable. W | ut effort! Enquire | e today. | E and get a loa | an for it. Gei | |
| LOAN | | | | | | | | |
| LOAN | ☐ Toyota Wish 1.8A (COE till 02/2021) | \$11,800 | \$7,700 /yr | 21-Mar-2006 | 1,794 cc | 1100,040,178 | MPV | Availabl |
| LOAN | ☐ Toyota Wish 1.8A (COE till 02/2021) Lowest In Market. Vehicle In De Coming. | | | | | t First Before | MPV | Available |
| LOAN | till 02/2021) Lowest In Market. Vehicle In De | cent Condit | ion. Please Ca | ll For Viewing A | appointmen | t First Before | MPV | Available |
| LOAN | till 02/2021) Lowest In Market. Vehicle In De Coming. Prested 19-Apg-2019 Tags: 2000 Toyot. Toyota Wish 1.8A X (COE | cent Condit | ion. Please Ca | ll For Viewing A | appointmen | t First Before | MPV | |
| EDAN STATE OF THE PARTY OF THE | till 02/2021) Lowest In Market. Vehicle In De Coming. Prosed 19-Apg-2019 Tags: 2006 Toyon. Toyota Wish 1.8A X (COE till 06/2029) Smooth Engine, Easy To Mainta Miss, Bank And In House Loan. | S65,800 in Unit, Imn | ion. Please Ca | II For Viewing A | Appointmen eash, Used Toyeta 1,797 cc on Is Even | 98,488 km Cheaper, Do N | MPV | |
| LOAN | till 02/2021) Lowest In Market. Vehicle In De Coming. Prosed 19-Apg-2019 Tags: 2006 Toyon Toyota Wish 1.8A X (COE till 06/2029) Smooth Engine, Easy To Mainta | \$65,800 in Unit, Imm | S6,680 /yr naculate Cond | Il For Viewing A | 1,797 cc on Is Even pointment I | 98,488 km Cheaper, Do N | MPV | |
| LOAN | till 02/2021) Lowest In Market. Vehicle In De Coming. Prested 19-Apg-2019 Tags: 2000 Toyota Wish 1.8A X (COE till 06/2029) Smooth Engine, Easy To Mainta Miss, Bank And In House Loan Now Before The Car Is Gone. Posted 19-Aug-2019 Tags: 2009 Toyota Toyota Wish 1.8A X (New | \$65,800 in Unit, Imm | S6,680 /yr naculate Cond | Ill For Viewing A cota wish, Toyota, Wish, v 26-Jun-2009 ition, Depreciatione. Call For Appropriate wish, Toyota, Wish, v | 1,797 cc on Is Even pointment I | 98,488 km Cheaper, Do N | MPV | Available |
| E CONTRACTOR OF THE CONTRACTOR | till 02/2021) Lowest In Market. Vehicle In De Coming. Presed 19-Apg-2019 Tags: 2000 Toyon Toyota Wish 1.8A X (COE till 06/2029) Smooth Engine, Easy To Mainta Miss, Bank And In House Loan. Now Before The Car Is Gone. Posted 19-Aug-2019 Tags: 2009 Toyota Ush 1.8A X (New 10-yr COE) 5 Years COE Renewal For \$42,8 Provide Lowest Interest Rate. Fl | \$65,800 in Unit, Imr Available! T | S6,680 /yr maculate Cond rade In Welco wish Toyota Wish, to \$6,080 /yr Cheap! Hurry! And High Tra | 26-Jun-2009 ition, Depreciatione. Call For Appropriate wish, Joysta, Wish, v. 26-Jun-2009 View Now. Up de In Are Availa | 1,797 cc on Is Even pointment I 1,797 cc To 100% F tble. Packag | 98,488 km Cheaper, Do N For A Test Driv | MPV fot ve MPV | Available |
| E CONTRACTOR OF THE CONTRACTOR | till 02/2021) Lowest In Market. Vehicle In De Coming. Product 19-Apg-2019 Tags: 2000 Toyota Wish 1.8A X (COE till 06/2029) Smooth Engine, Easy To Mainta Miss, Bank And In House Loan Now Before The Car Is Gone. Posted 19-Aug-2019 Tags: 2009 Toyota Wish 1.8A X (New 10-yr COE) 5 Years COE Renewal For \$42,8 Provide Lowest Interest Rate. Fl Warranty Complete With Certific | \$65,800 in Unit, Imr Available! T | S6,680 /yr maculate Cond rade In Welco wish Toyota Wish, to \$6,080 /yr Cheap! Hurry! And High Tra | 26-Jun-2009 ition, Depreciatione. Call For Appropriate wish, Joysta, Wish, v. 26-Jun-2009 View Now. Up de In Are Availa | 1,797 cc on Is Even pointment I 1,797 cc To 100% F tble. Packag | 98,488 km Cheaper, Do N For A Test Driv | MPV fot ve MPV | Available |
| CON CONTRACTOR OF THE PARTY OF | till 02/2021) Lowest In Market. Vehicle In De Coming. Presed 19-Apg-2019 Tags: 2000 Toyon Toyota Wish 1.8A X (COE till 06/2029) Smooth Engine, Easy To Mainta Miss, Bank And In House Loan. Now Before The Car Is Gone. Posted 19-Aug-2019 Tags: 2009 Toyota Ush 1.8A X (New 10-yr COE) 5 Years COE Renewal For \$42,8 Provide Lowest Interest Rate. Fl | \$65,800 in Unit, Imm Available! T | son. Please Ca \$6,680 /yr naculate Cond Trade In Welco wish Trigota Wish, to \$6,080 /yr Cheap! Hurry! And High Tra st Report. Che | 26-Jun-2009 ition, Depreciatione. Call For Appropriate wish, Toyota, Wish, or the wish, Toyota, Wish, or 26-Jun-2009 View Now. Up de In Are Availack Out Our New | 1,797 cc on Is Even pointment I 1,797 cc To 100% F 1,00% F 1,00% F 1,00% F 1,00% F 1,00% F | 98,488 km Cheaper, Do N For A Test Driv | MPV fot ve MPV | Available |
| EVAN STATE OF THE PARTY OF THE | till 02/2021) Lowest In Market. Vehicle In De Coming. Product 19-Apg-2019 Tags: 2000 Toyyob Toyota Wish 1.8A X (COE till 06/2029) Smooth Engine, Easy To Mainta Miss, Bank And In House Loan Now Before The Car Is Gone. Product 19-Aug-2019 Tags: 2009 Toyyob Toyota Wish 1.8A X (New 10-yr COE) Syears COE Renewal For \$42,8 Provide Lowest Interest Rate. Fl Warranty Complete With Certific Classic Credit Pte Ltd | \$65,800 in Unit, Imm Available! T | son. Please Ca \$6,680 /yr naculate Cond Trade In Welco wish Trigota Wish, to \$6,080 /yr Cheap! Hurry! And High Tra st Report. Che | 26-Jun-2009 ition, Depreciatione. Call For Appropriate wish, Toyota, Wish, or the wish, Toyota, Wish, or 26-Jun-2009 View Now. Up de In Are Availack Out Our New | 1,797 cc on Is Even pointment I 1,797 cc To 100% F 1,00% F 1,00% F 1,00% F 1,00% F 1,00% F | 98,488 km Cheaper, Do N For A Test Driv | MPV fot ve MPV | Availabl |



Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including Wee...

88 Motor Trading

Pastart 18-Aug-2019 Tags. 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, Joyota Wish, Joyota Wish, Joseph Used Toyota



Toyota Wish 1.8A X (OPC) \$40,500 \$8,090 /yr 19-Aug-2009 1,797 cc MPV Available OPC CONVERT! LOW MILLEAGE! \$0 Down Payment Scheme Available. Interest From 3.18%. Bank Loan And In House Loan Available. Lowest Monthly Installment \$701. Trade In Welcome.

Posted: 18-Aug-2019 Taga. 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, with, Used Toyota



Toyota Wish 1.8A X \$29,800 \$8,440 /yr 29-Feb-2008 1,794 cc 108,000 km MPV Available Limited (COE till 02/2023)

6 Months Warranty, Excellent Condition, Accident Free, Bank Loan/In House Loan Available, Trade In



Posted 18-Aug-2019 Ing. 2008 Toyon Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota Wish, work, Used Toyota



BlackVue DR750S Car Camera

Equipped with Sony Starvis CMOS Sensor, this blackvue full HD cloud camera gives you best image quality under any light condition. Find the list of the best cameras available, each with product information and user reviews.

Find out more!



Toyota Wish 1.8A X (New \$61,800 \$6,170 /yr 30-Jul-2009 1,797 cc MPV Available 10-yr COE)

Graded B by STR

3.18% Per Annum. \$688 Monthly. \$0 Admin Fees For All GV Purchase. STA Grade B. 2 Years Warranty For Engine And Gearbox. Inhouse Finance, inhouse Workshop And Paintshop All Under One Roof. Buy With Assurance. Warranty Booklet And STA Report Will Be Given.

GV Credit Ptc Ltd

Posted: 18-Aug-2019 Tags 2009 Toyora Wish, 2009 rovota wish. Toyota Wish, toyora wish, Toyora Wish, wish, Wish, wish, Used Toyota



Toyota Wish 1.8A X (COE \$40,800 \$8,290 /yr 20-Jul-2009 1.797 cc MPV Available till 07/2024)

PREMIUM AD

3.18% Per Annum. \$688 Monthly. \$0 Admin Fees For All GV Purchase. STA Grade B. 2 Years Warranty For Engine And Gearbox. Inhouse Finance, inhouse Workshop And Paintshop All Under One Roof. Buy With Assurance. Warranty Booklet And STA Report Will Be Given.

GV Credit Pte Ltd

Posted: 18-Aug-2019 Taga: 2009 Toyon: Wish, 2009 toyona wish, Toyona Wish, Toyona wish, Toyona Wish, wish, Used Toyona



☐ Toyota Wish 1.8A (COE \$16,800 \$9,860 /yr 03-May-2006 1,794 cc 165,000 km MPV Available

1st Owner, 1 Year In House Warranty, Free 2 x Servicing, Full Loan Available, Warranty Not By 3rd Party Workshop, Price Stated Above Is Actual Selling Price, No Gimmicks, Purchase Comes With Official Warranty Certificate For A Peace Of Mind, Accident Free, STA Or VICOM...

Posted: 18-Aug-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, Joyota Wish, Toyota Wish, Wish, Wish, Wish, Used Toyota



Toyota Wish 1.8A X (COE \$31,800 \$7,830 /yr 11-Sep-2008 1,794 cc MPV Available till 09/2023)

12 Months Warranty, Drive By A Retiree. Brand New Tyre, Most Sought After Mid Size MPV, Silver On Black Leather! Very Low Mileage! As Good As New Interior And Engine! Silky Smooth Gear Box! No Repair Needed! 100% Loan Available! Act Fast! Call Me Now Before It Is...

Posted: 18-Aug-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, Ioyota wish, Toyota, Wish, wish, Used Toyota



2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh#

: SJK2941U

Model:

TOYOTA WISH

Accident Date : 14/08/2019

(15/10/2008)

SKN7239D

Location

: JURONG WEST AVE 4 SLIP RD TOWARDS JALAN BAHAR

3P:

(AUTO & GENERAL INS)

| S/Nos. | <u>Qty</u> | Description | <u>List\$</u> | S/Nett \$ | Nett\$ |
|--------|------------|---|---------------|-----------|--------|
| 1 | 1 pc | Rear bumper / LR Y | 481.25 | - | |
| 2 | 8 pcs | Rear bumper clips / NEC | 24.00 | - | |
| 3 | 2 pcs | Rear bumper o/s & n/s stay | 141.70 | - | |
| 4 | 2 pcs | Rear bumper o/s & n/s reflector X SV C | 167.40 | - | |
| 5 | 2 pcs | Rear bumper o/s & n/s retainer X JV (| 144.70 | = | |
| 6 | 2 pcs | Rear bumper o/s & n/s corner clips ? X SV L | 242.20 | - | |
| 7 | 1 pc | Rear tail-gate | 981.40 | - | |
| 8 | 1 pc | Rear tail-gate weatherstrip | 190 289.90 | - | |
| 9 | 1 pc | Rear tail-gate emblem / Nh (| 61.70 | ÷ | |
| 10 | 1 pc | Rear tail-gate Borneo Motor emblem / NEC | 61.35 | - | |
| 11 | 1 pc | Rear tail-gate moulding (chrome) | 200 287.72 | - | |
| 12 | 2 pcs | Rear tail-gate moulding clips / NF (| 25.80 | - | |
| 13 | 1 pc | Rear tail-gate inner trim X SV | 591.75 | - | |
| 14 | 8 pcs | Rear tail-gate inner trim clips $\chi N N$ | 24.00 | - | |
| 15 | 1 pc | Rear tail-gate lock (upper) | 322.70 | - | |
| 16 | 1 pc | Rear tail-gate lock (lower) X SUL | 124.80 | - | |
| 17 | 1 pc | Rear tail-gate lower panel (outer) | 589.72 | - | |
| 18 | 1 pc | Rear tail-gate lower panel (inner) | 561.60 | - | |
| 19 | 1 pc | Rear tail-gate lower panel inner trim | 289.90 | - | |
| 20 | 4 pcs | Rear tail-gate lower panel inner trim clips メ ジゾン | 12.00 | - | |
| 21 | 1 pc | Rear boot floor panel XR | 1,789.00 | | |

| | | | | | / |
|----|-------|---|----------|-----------|--------|
| 22 | 1 pc | Rear windscreen sealant / NEC | - | 30.00 | / . |
| 23 | 1 set | Rear reverse sensor XSVL | - | 280.00 | |
| 24 | 1 pc | Rear reg. no. plate | - | 45.00 | 3,50 |
| 25 | 1 pc | Rear reg. no. plate bracket | - | 29.00 | 3 |
| | | Sub-Total: | 7,214.59 | 384.00 | 0.0 |
| | | | 25% | 0% | 09 |
| | | After Less %: | 5,410.94 | 384.00 | 0.0 |
| | | <u>Labour</u> | | | |
| 1 | | To dismantle rear portion | | 1,900.00 | 600 80 |
| 2 | | To spray painting | | | 800 |
| 3 | | To remove and refit rear windscreen | | 120.00 | |
| 4 | | To remove and replace rear reverse sensor | | ·100.00° | 30 |
| 5 | | To check wiring | | -120.00 | 30 |
| 6 | | To re-seal anti-rust | | 280.00 | 50 |
| | | Sub-Total: | | 4,320.00 | 1,830 |
| | | Total: | | 10,114.94 | |
| | | After Less 20%: | | 8,091.95 | |

Chan San Choon

Director

DipEng, AAE MIMI, MSAE (Aust)

NAZ UCIC 1618/19 1430

. 615

5 Days

AGTER REPOR PHOTOS

PARTS 3,046.82 LESS 25% \$2,285.11 SINETT \$ 80 LABOUR TOTAL LESS LISZO10 \$ 3,356.08

LIS TOTAL \$ 3,350.00 / 5 REPAIR DAYL






AL 8778 1999 24 hr accident call

Mobil 1 bisAFE.





- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref: CS/AGI19014241/Ntf3e2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE

Date: 10-09-2019



| | | NG CENTRESINGAPORE | Date: 10-09-2019 | | | |
|-----|----------------|---|------------------------|--------------------|--|--|
| 399 | 124 | | Code: AGI | | | |
| | | Policy Particula | ars :- THIRD PARTY CLA | IM | | |
| | Insured Veh. | SKN 7239D | Veh. Inspected | SJK 2941U | | |
| | Policy No. | | Coverage (\$) | 0.00 | | |
| | Claim No. | C10003752/JM | Excess (\$) | 0.00 | | |
| | Assign From | IVY RATILLA | Assign Date | 15/08/2019 | | |
| | 一般再是国际 | Vehicle Pa | articulars & Condition | | | |
| | Make & Model | TOYOTA WISH 1.8 A | c.c | 1794 | | |
| | Engine No. | HIDDEN | Year of Reg. | 2008 | | |
| | Chassis No. | JTDER12W103000526 | Colour | GREY | | |
| | Odometer | 214248 | Steering | IN ORDER | | |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | | |
| | General | FAIR | | | | |
| | | Con | ditions of Tyres | | | |
| | | Size | Make | Balance | | |
| | R/H Front Tyre | 195/65 R15 | CONTINENTAL | 6 mm | | |
| | L/H Front Tyre | 195/65 R15 | CONTINENTAL | 6 mm | | |
| | R/H Rear Tyre | 195/65 R15 | CONTINENTAL | 6 mm | | |
| | L/H Rear Tyre | 195/65 R15 | CONTINENTAL | 6 mm | | |
| | · 2000年1月1日 | Descri | ption of Damages | 在1867年 | | |
| | THE VEHICLE SU | STAINED DAMAGES AT THE | REAR PORTION. | | | |
| | DAMAGES SEE D | ETAILS. | | | | |
| i | | Gen | eral Information | SHEET STREET | | |
| | Accident Date | 14/08/2019 | Inspection Date | 16/08/2019 | | |
| | Survey held at | RYDER AUTO WORKSHOP | LLP | | | |
| | | 2 Kaki Bukit Ave 2# 02-19 KAKI BUKIT AUTOHUB SINGAPORE 417921 | | | | |
| ia. | | | Remarks | | | |
| | | ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS | | | | |
| b. | | Estima | ate Days of Repair | | | |
| | ESTIMATED NOR | MAL PERIOD FOR REPAIR: | 5 Working Da | ys | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 2941U

| REPLACEMENT OF PARTS | Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--|-----|---|---------------|------------------------------|-------------------|
| REAR BUMPER CLIPS | | REPLACEMENT OF PARTS | | | |
| 2 REAR BUMPER O/S & N/S STAY BENT 141.70 141.70 2 REAR BUMPER O/S & N/S REFLECTOR SERVICEABLE 167.40 - 2 REAR BUMPER O/S & N/S RETAINER SERVICEABLE 144.70 - 2 REAR BUMPER O/S & N/S CORNER CLIPS SERVICEABLE 242.20 - 1 REAR TAIL-GATE DENTED 981.40 981.40 1 REAR TAIL-GATE WEATHERSTRIP DEFORMED 289.90 190.00 1 REAR TAIL-GATE EMBLEM NECESSARY 61.70 61.70 1 REAR TAIL-GATE BORNEO MOTOR EMBLEM NECESSARY 61.35 61.35 1 REAR TAIL-GATE MOULDING (CHROME) CRACKED 287.72 200.00 2 REAR TAIL-GATE MOULDING CLIPS NECESSARY 25.80 25.80 3 REAR TAIL-GATE INNER TRIM SERVICEABLE 591.75 - 4 REAR TAIL-GATE LOCK (LOPER) SERVICEABLE 322.70 - 5 REAR TAIL-GATE LOCK (LOWER) SERVICEABLE 322.70 - 6 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE 561.60 - 6 REAR TAIL-GATE LOWER PANEL INNER TRIM CRACKED 289.90 289.90 7 REAR BOOT FLOOR PANEL | 1 | REAR BUMPER | CRACKED | 481.25 | 481.25 |
| 2 REAR BUMPER O/S & N/S REFLECTOR SERVICEABLE 167.40 - 2 REAR BUMPER O/S & N/S RETAINER SERVICEABLE 144.70 - 2 REAR BUMPER O/S & N/S CORNER CLIPS SERVICEABLE 242.20 - 1 REAR TAIL-GATE DENTED 981.40 981.40 1 REAR TAIL-GATE WEATHERSTRIP DEFORMED 289.90 190.00 1 REAR TAIL-GATE EMBLEM NECESSARY 61.70 61.70 1 REAR TAIL-GATE BORNEO MOTOR EMBLEM NECESSARY 61.35 61.35 1 REAR TAIL-GATE MOULDING (CHROME) CRACKED 287.72 200.00 2 REAR TAIL-GATE MOULDING CLIPS NECESSARY 25.80 25.80 1 REAR TAIL-GATE INNER TRIM SERVICEABLE 591.75 - 2 REAR TAIL-GATE INNER TRIM CLIPS NOT NECESSARY 24.00 - 3 REAR TAIL-GATE LOCK (UPPER) SERVICEABLE 322.70 - 4 REAR TAIL-GATE LOWER PANEL (OUTER) DENTED 599.72 599.72 5 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE LABOUR 1.789.00 - 4 REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS SERVICEABLE 1,789.00 - 5 RE | 8 | REAR BUMPER CLIPS | NECESSARY | 24.00 | 24.00 |
| 2 REAR BUMPER O/S & N/S RETAINER SERVICEABLE 144.70 - 2 REAR BUMPER O/S & N/S CORNER CLIPS SERVICEABLE 242.20 - 1 REAR TAIL-GATE DENTED 981.40 981.40 1 REAR TAIL-GATE WEATHERSTRIP DEFORMED 289.90 190.00 1 REAR TAIL-GATE EMBLEM NECESSARY 61.70 61.70 1 REAR TAIL-GATE BORNEO MOTOR EMBLEM NECESSARY 61.35 61.35 1 REAR TAIL-GATE MOULDING (CHROME) CRACKED 287.72 200.00 2 REAR TAIL-GATE MOULDING CLIPS NECESSARY 25.80 25.80 3 REAR TAIL-GATE INNER TRIM SERVICEABLE 591.75 - 4 REAR TAIL-GATE INNER TRIM CLIPS NOT NECESSARY 24.00 - 5 REAR TAIL-GATE LOCK (UPPER) SERVICEABLE 322.70 - 1 REAR TAIL-GATE LOWER PANEL (OUTER) DENTED 589.72 589.72 1 REAR TAIL-GATE LOWER PANEL INNER TRIM CRACKED 289.90 289.90 2 REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS SERVICEABLE 12.00 - 1 REAR BOOT FLOOR PANEL TO REPAIR SEE 1,789.00 - 1 REAR BOOT FLOOR PA | 2 | REAR BUMPER O/S & N/S STAY | BENT | 141.70 | 141.70 |
| 2 REAR BUMPER O/S & N/S CORNER CLIPS SERVICEABLE 242.20 - 1 REAR TAIL-GATE DENTED 981.40 981.40 1 REAR TAIL-GATE WEATHERSTRIP DEFORMED 289.90 190.00 1 REAR TAIL-GATE EMBLEM NECESSARY 61.70 61.70 1 REAR TAIL-GATE BORNEO MOTOR EMBLEM NECESSARY 61.35 61.35 1 REAR TAIL-GATE MOULDING (CHROME) CRACKED 287.72 200.00 2 REAR TAIL-GATE MOULDING CLIPS NECESSARY 25.80 25.80 3 REAR TAIL-GATE INNER TRIM SERVICEABLE 591.75 - 4 REAR TAIL-GATE INNER TRIM CLIPS NOT NECESSARY 24.00 - 5 REAR TAIL-GATE LOCK (LOWER) SERVICEABLE 322.70 - 6 REAR TAIL-GATE LOCK (LOWER) SERVICEABLE 124.80 - 7 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE LABOUR 561.60 - 8 REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS SERVICEABLE 12.00 - 9 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - 1 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - 1 REAR WINDSC | 2 | REAR BUMPER O/S & N/S REFLECTOR | SERVICEABLE | 167.40 | - |
| REAR TAIL-GATE DENTED 981.40 981.40 REAR TAIL-GATE WEATHERSTRIP DEFORMED 289.90 190.00 REAR TAIL-GATE EMBLEM NECESSARY 61.70 61.70 REAR TAIL-GATE BORNEO MOTOR EMBLEM NECESSARY 61.35 61.35 REAR TAIL-GATE MOULDING (CHROME) CRACKED 287.72 200.00 REAR TAIL-GATE MOULDING CLIPS NECESSARY 25.80 25.80 REAR TAIL-GATE INNER TRIM SERVICEABLE 591.75 - REAR TAIL-GATE INNER TRIM SERVICEABLE 322.70 - REAR TAIL-GATE LOCK (LOWER) SERVICEABLE 124.80 - REAR TAIL-GATE LOWER PANEL (OUTER) DENTED 589.72 589.72 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE LABOUR LABOUR REAR TAIL-GATE LOWER PANEL INNER TRIM CRACKED 289.90 289.90 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - LESS 25% DISCOUNT -1,803.65 -761.71 SPECIAL NETT ITEMS NECESSARY 30.00 30.00 SET REAR REVERSE SENSOR (SN) SERVICEABLE 280.00 - REAR REG. NO. PLATE BRACKET (SN) DENTED 45.00 50.00 REAR REG. NO. PLATE BRACKET (SN) DENTED 45.00 50.00 REAR REG. NO. PLATE BRACKET (SN) | 2 | REAR BUMPER O/S & N/S RETAINER | SERVICEABLE | 144.70 | - |
| REAR TAIL-GATE WEATHERSTRIP DEFORMED 289.90 190.00 REAR TAIL-GATE EMBLEM NECESSARY 61.70 61.70 REAR TAIL-GATE BORNEO MOTOR EMBLEM NECESSARY 61.35 61.35 REAR TAIL-GATE MOULDING (CHROME) CRACKED 287.72 200.00 REAR TAIL-GATE MOULDING CLIPS NECESSARY 25.80 25.80 REAR TAIL-GATE INNER TRIM SERVICEABLE 591.75 - | 2 | REAR BUMPER O/S & N/S CORNER CLIPS | SERVICEABLE | 242.20 | - |
| 1 REAR TAIL-GATE EMBLEM NECESSARY 61.70 61.70 1 REAR TAIL-GATE BORNEO MOTOR EMBLEM NECESSARY 61.35 61.35 1 REAR TAIL-GATE MOULDING (CHROME) CRACKED 287.72 200.00 2 REAR TAIL-GATE MOULDING CLIPS NECESSARY 25.80 25.80 1 REAR TAIL-GATE INNER TRIM SERVICEABLE 591.75 - 8 REAR TAIL-GATE INNER TRIM CLIPS NOT NECESSARY 24.00 - 1 REAR TAIL-GATE LOCK (UPPER) SERVICEABLE 322.70 - 1 REAR TAIL-GATE LOCK (LOWER) SERVICEABLE 124.80 - 1 REAR TAIL-GATE LOWER PANEL (OUTER) DENTED 589.72 589.72 1 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE 561.60 - 1 REAR TAIL-GATE LOWER PANEL INNER TRIM CRACKED 289.90 289.90 4 REAR BOOT FLOOR PANEL TO REPAIR SEE 1,789.00 - 1 REAR BOOT FLOOR PANEL TO REPAIR SEE 1,789.00 - 1 LESS 25% DISCOUNT -1,803.65 -761.71 5,410.94 2,285.11 SPECIAL NETT ITEMS 1 REAR REVERSE SENSOR (SN) SERVICEABLE 28. | 1 | REAR TAIL-GATE | DENTED | 981.40 | 981.40 |
| 1 REAR TAIL-GATE BORNEO MOTOR EMBLEM NECESSARY 61.35 61.35 1 REAR TAIL-GATE MOULDING (CHROME) CRACKED 287.72 200.00 2 REAR TAIL-GATE MOULDING CLIPS NECESSARY 25.80 25.80 1 REAR TAIL-GATE INNER TRIM SERVICEABLE 591.75 - 8 REAR TAIL-GATE INNER TRIM CLIPS NOT NECESSARY 24.00 - 1 REAR TAIL-GATE LOCK (UPPER) SERVICEABLE 322.70 - 1 REAR TAIL-GATE LOWER PANEL (OUTER) DENTED 589.72 589.72 1 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE 561.60 - 1 REAR TAIL-GATE LOWER PANEL INNER TRIM CRACKED 289.90 289.90 4 REAR BOOT FLOOR PANEL TO REPAIR SEE 1,789.00 - 1 REAR BOOT FLOOR PANEL TO REPAIR SEE 1,789.00 - 1 LABOUR -1,803.65 -761.71 -761.71 5 SPECIAL NETT ITEMS NECESSARY 30.00 30.00 1 REAR REVERSE SENSOR (SN) SERVICEABLE 280.00 - 1 REAR REG. NO. PLATE (SN) } DENTED 45.00 50.00 1 REAR REG. NO. PLATE BRACKET (SN) } | 1 | REAR TAIL-GATE WEATHERSTRIP | DEFORMED | 289.90 | 190.00 |
| 1 REAR TAIL-GATE MOULDING (CHROME) CRACKED 287.72 200.00 2 REAR TAIL-GATE MOULDING CLIPS NECESSARY 25.80 25.80 1 REAR TAIL-GATE INNER TRIM SERVICEABLE 591.75 - 8 REAR TAIL-GATE INNER TRIM CLIPS NOT NECESSARY 24.00 - 1 REAR TAIL-GATE LOCK (UPPER) SERVICEABLE 322.70 - 1 REAR TAIL-GATE LOWER PANEL (OUTER) DENTED 589.72 589.72 1 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE LABOUR 561.60 - 1 REAR TAIL-GATE LOWER PANEL INNER TRIM CRACKED 289.90 289.90 4 REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS SERVICEABLE 12.00 - 1 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - 1 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - 1 LESS 25% DISCOUNT -1,803.65 -761.71 5,410.94 2,285.11 SPECIAL NETT ITEMS 1 REAR REVERSE SENSOR (SN) NECESSARY 30.00 30.00 2 SERVICEABLE 280.00 - 3 REAR REG. NO. PLATE (SN) } DENTED 45.00 < | 1 | REAR TAIL-GATE EMBLEM | NECESSARY | 61.70 | 61.70 |
| 2 REAR TAIL-GATE MOULDING CLIPS NECESSARY 25.80 25.80 1 REAR TAIL-GATE INNER TRIM SERVICEABLE 591.75 - 8 REAR TAIL-GATE INNER TRIM CLIPS NOT NECESSARY 24.00 - 1 REAR TAIL-GATE LOCK (UPPER) SERVICEABLE 322.70 - 1 REAR TAIL-GATE LOCK (LOWER) SERVICEABLE 124.80 - 1 REAR TAIL-GATE LOWER PANEL (OUTER) DENTED 589.72 589.72 1 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE LABOUR 561.60 - 2 REAR TAIL-GATE LOWER PANEL INNER TRIM CRACKED 289.90 289.90 3 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - 4 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - 4 LESS 25% DISCOUNT -1,803.65 -761.71 -761.71 5 SPECIAL NETT ITEMS NECESSARY 30.00 30.00 1 REAR REVERSE SENSOR (SN) SERVICEABLE 280.00 - 1 REAR REG. NO. PLATE (SN) } DENTED 45.00 50.00 1 REAR REG. NO. PLATE BRACKET (SN) } DENTED -29.00 - | 1 | REAR TAIL-GATE BORNEO MOTOR EMBLEM | NECESSARY | 61.35 | 61.35 |
| REAR TAIL-GATE INNER TRIM SERVICEABLE 591.75 - | 1 | REAR TAIL-GATE MOULDING (CHROME) | CRACKED | 287.72 | 200.00 |
| 8 REAR TAIL-GATE INNER TRIM CLIPS NOT NECESSARY 24.00 - 1 REAR TAIL-GATE LOCK (UPPER) SERVICEABLE 322.70 - 1 REAR TAIL-GATE LOCK (LOWER) SERVICEABLE 124.80 - 1 REAR TAIL-GATE LOWER PANEL (OUTER) DENTED 589.72 589.72 1 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE LABOUR 561.60 - 2 REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS SERVICEABLE 12.00 - 1 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - 2 LESS 25% DISCOUNT -1,803.65 -761.71 -761.71 5 SPECIAL NETT ITEMS -1,803.65 -761.71 -761.71 5 SET REAR REVERSE SENSOR (SN) NECESSARY 30.00 30.00 1 REAR REG. NO. PLATE (SN)) SERVICEABLE 280.00 - 1 REAR REG. NO. PLATE BRACKET (SN) } DENTED 45.00 50.00 | 2 | REAR TAIL-GATE MOULDING CLIPS | NECESSARY | 25.80 | 25.80 |
| 1 REAR TAIL-GATE LOCK (UPPER) SERVICEABLE 322.70 - 1 REAR TAIL-GATE LOCK (LOWER) SERVICEABLE 124.80 - 1 REAR TAIL-GATE LOWER PANEL (OUTER) DENTED 589.72 589.72 1 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE LABOUR 561.60 - 1 REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS SERVICEABLE 12.00 - 1 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - 1 LESS 25% DISCOUNT TO REPAIR SEE LABOUR 1,789.00 - 1 REAR WINDSCREEN SEALANT (SN) NECESSARY 30.00 30.00 1 SET REAR REVERSE SENSOR (SN) SERVICEABLE 280.00 - 1 REAR REG. NO. PLATE (SN) } DENTED 45.00 50.00 1 REAR REG. NO. PLATE BRACKET (SN) } DENTED - - | 1 | REAR TAIL-GATE INNER TRIM | SERVICEABLE | 591.75 | - |
| 1 REAR TAIL-GATE LOCK (LOWER) SERVICEABLE 124.80 - 1 REAR TAIL-GATE LOWER PANEL (OUTER) DENTED 589.72 589.72 1 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE LABOUR 561.60 - 1 REAR TAIL-GATE LOWER PANEL INNER TRIM CRACKED 289.90 289.90 4 REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS SERVICEABLE 12.00 - 1 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - LESS 25% DISCOUNT -1,803.65 -761.71 5,410.94 2,285.11 SPECIAL NETT ITEMS 1 REAR WINDSCREEN SEALANT (SN) NECESSARY 30.00 30.00 1 SET REAR REVERSE SENSOR (SN) SERVICEABLE 280.00 - 1 REAR REG. NO. PLATE (SN) } DENTED 45.00 50.00 1 REAR REG. NO. PLATE BRACKET (SN) } - 29.00 - | 8 | REAR TAIL-GATE INNER TRIM CLIPS | NOT NECESSARY | 24.00 | - |
| 1 REAR TAIL-GATE LOWER PANEL (OUTER) DENTED 589.72 589.72 1 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE LABOUR 561.60 - 1 REAR TAIL-GATE LOWER PANEL INNER TRIM CRACKED 289.90 289.90 4 REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS SERVICEABLE 12.00 - 1 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - LESS 25% DISCOUNT -1,803.65 -761.71 -761.71 SPECIAL NETT ITEMS 1 REAR WINDSCREEN SEALANT (SN) NECESSARY 30.00 30.00 1 SET REAR REVERSE SENSOR (SN) SERVICEABLE 280.00 - 1 REAR REG. NO. PLATE (SN) } DENTED 45.00 50.00 1 REAR REG. NO. PLATE BRACKET (SN) } DENTED - - | 1 | REAR TAIL-GATE LOCK (UPPER) | SERVICEABLE | 322.70 | - |
| 1 REAR TAIL-GATE LOWER PANEL (INNER) TO REPAIR SEE LABOUR 561.60 - LABOUR 1 REAR TAIL-GATE LOWER PANEL INNER TRIM CRACKED 289.90 289.90 4 REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS SERVICEABLE 12.00 - TO REPAIR SEE LABOUR 1 REAR BOOT FLOOR PANEL TO REPAIR SEE LABOUR 1,789.00 - TO REPAIR SEE LABOUR LESS 25% DISCOUNT -1,803.65 -761.71 SPECIAL NETT ITEMS 1 REAR WINDSCREEN SEALANT (SN) NECESSARY 30.00 30.00 3 SET REAR REVERSE SENSOR (SN) SERVICEABLE 280.00 - 1 REAR REG. NO. PLATE (SN) } DENTED 45.00 50.00 1 REAR REG. NO. PLATE BRACKET (SN) } 29.00 - | 1 | REAR TAIL-GATE LOCK (LOWER) | SERVICEABLE | 124.80 | - |
| 1 REAR TAIL-GATE LOWER PANEL INNER TRIM CRACKED 289.90 2 | 1 | REAR TAIL-GATE LOWER PANEL (OUTER) | DENTED | 589.72 | 589.72 |
| 4 REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS 1 REAR BOOT FLOOR PANEL LESS 25% DISCOUNT 1 REAR WINDSCREEN SEALANT (SN) SET REAR REVERSE SENSOR (SN) 1 REAR REG. NO. PLATE (SN) } SET NO. PLATE BRACKET (SN) } SERVICEABLE 12.00 - TO REPAIR SEE 1,789.00 - 1,803.65 -761.71 5,410.94 2,285.11 NECESSARY 30.00 30.00 30.00 5ERVICEABLE 280.00 - DENTED 45.00 50.00 - 29.00 | 1 | REAR TAIL-GATE LOWER PANEL (INNER) | | 561.60 | - |
| 1 REAR BOOT FLOOR PANEL LESS 25% DISCOUNT SPECIAL NETT ITEMS 1 REAR WINDSCREEN SEALANT (SN) SET REAR REVERSE SENSOR (SN) REAR REG. NO. PLATE (SN) } REAR REG. NO. PLATE BRACKET (SN) } TO REPAIR SEE LABOUR 1,789.00 -1,803.65 -761.71 5,410.94 2,285.11 NECESSARY 30.00 30.00 SERVICEABLE 280.00 -1 DENTED 45.00 50.00 -1 | 1 | REAR TAIL-GATE LOWER PANEL INNER TRIM | CRACKED | 289.90 | 289.90 |
| LESS 25% DISCOUNT LESS 25% DISCOUNT -1,803.65 -761.71 5,410.94 2,285.11 SPECIAL NETT ITEMS REAR WINDSCREEN SEALANT (SN) SET REAR REVERSE SENSOR (SN) REAR REVERSE SENSOR (SN) REAR REG. NO. PLATE (SN) } DENTED LABOUR -1,803.65 -761.71 5,410.94 2,285.11 SPECIAL NETT ITEMS DENTED -1,803.65 -761.71 5,410.94 2,285.11 -1,803.65 -761.71 5,410.94 2,285.11 -1,803.65 -761.71 5,410.94 -1,803.65 -761.71 5,410.94 -1,803.65 -761.71 -761. | 4 | REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS | SERVICEABLE | 12.00 | - |
| 5,410.94 2,285.11 SPECIAL NETT ITEMS 1 REAR WINDSCREEN SEALANT (SN) NECESSARY 30.00 30.00 1 SET REAR REVERSE SENSOR (SN) SERVICEABLE 280.00 - 1 REAR REG. NO. PLATE (SN) } DENTED 45.00 50.00 1 REAR REG. NO. PLATE BRACKET (SN) } | 1 | REAR BOOT FLOOR PANEL | | 1,789.00 | - |
| SPECIAL NETT ITEMS 1 REAR WINDSCREEN SEALANT (SN) NECESSARY 30.00 30.00 1 SET REAR REVERSE SENSOR (SN) SERVICEABLE 280.00 - 1 REAR REG. NO. PLATE (SN) } DENTED 45.00 50.00 1 REAR REG. NO. PLATE BRACKET (SN) } 29.00 - | | LESS 25% DISCOUNT | | -1,803.65 | -761.71 |
| 1 REAR WINDSCREEN SEALANT (SN) NECESSARY 30.00 30.00 1 SET REAR REVERSE SENSOR (SN) SERVICEABLE 280.00 - 1 REAR REG. NO. PLATE (SN) } DENTED 45.00 50.00 1 REAR REG. NO. PLATE BRACKET (SN) } 29.00 - | | | | 5,410.94 | 2,285.11 |
| 1 SET REAR REVERSE SENSOR (SN) SERVICEABLE 280.00 - 1 REAR REG. NO. PLATE (SN) } 1 REAR REG. NO. PLATE BRACKET (SN) } 29.00 - | | SPECIAL NETT ITEMS | | | |
| 1 REAR REG. NO. PLATE (SN) } DENTED 45.00 50.00 1 REAR REG. NO. PLATE BRACKET (SN) } 29.00 - | 1 | REAR WINDSCREEN SEALANT (SN) | NECESSARY | 30.00 | 30.00 |
| 1 REAR REG. NO. PLATE BRACKET (SN) } | 1 | SET REAR REVERSE SENSOR (SN) | SERVICEABLE | 280.00 | - |
| | 1 | REAR REG. NO. PLATE (SN) } | DENTED | 45.00 | 50.00 |
| 384.00 80.00 | 1 | REAR REG. NO. PLATE BRACKET (SN) } | | 29.00 | _ |
| | | | | 384.00 | 80.00 |

Report Ref No. CS/AGI19014241/Ntf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

3,350.00

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|-----------|------------------------------|-------------------|
| | LABOUR | | | |
| | TO DISMANTLE REAR PORTION. INCLUSIVE OF THE REPAIR OF REAR TAIL-GATE LOWER PANEL (INNER) AND REAR BOOT FLOOR PANEL. | | 1,900.00 | 800.00 |
| | TO SPRAY PAINTING. | | 1,800.00 | 800.00 |
| | TO REMOVE AND REFIT REAR WINDSCREEN. | | 120.00 | 120.00 |
| | TO REMOVE AND REPLACE REAR REVERSE SENSOR. | | 100.00 | 30.00 |
| | TO CHECK WIRING. | | 120.00 | 30.00 |
| | TO RE-SEAL ANTI-RUST. | | 280.00 | 50.00 |
| | | | 4,320.00 | 1,830.00 |
| | GRAND TOTAL | | 10,114.94 | 4,195.11 |

Report Ref No. CS/AGI19014241/Ntf3e2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.