

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9922P**AAD1908-079***Not Notarised*
1/Sup &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

14 AUG 2019

SHD 9922P

VF1ABL15AUC277511

RENAULT

LATITUDE

8.8.19

AXA

5/6/2014

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>Div</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP RH	\$	<i>mj cm</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
1	TOW COVER FRT	\$	<i>Sn</i> 28.61
1	FRONT BRACE PANEL	\$	<i>R</i> 177.22
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	BONNET	\$	<i>R</i> 1,941.63
1	BONNET INSULATOR	\$	<i>Sn</i> 405.73
1	BONNET STRUT LH	\$	<i>Sn</i> 88.61
1	BONNET STRUT RH	\$	<i>Sn</i> 88.61
1	BONNET HINGE LH	\$	<i>R</i> 348.31

Trans-cab Auto Services Pte Ltd**AAD1908-079**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9922P

1	BONNET HINGE RH	\$	<i>M</i>	348.31	X
1	BONNET LOCK	\$	<i>M</i>	305.48	X
1	BONNET CABLE	\$	<i>Sn</i>	119.19	X
1	BONNET CABLE COVER	\$	<i>Sn</i>	161.03	X
1	BONNET SEAL OUTER	\$	<i>Sn</i>	92.36	X
1	BONNET SEAL INNER	\$	<i>Sn</i>	157.28	X
1	DOOR PANEL FRT RH	\$	<i>Rt</i>	2,844.66	✓
1	DOOR MIRROR ASSY RH	\$	<i>Sn</i>	1,483.40	} X
1	LOWER ARM RH L70Y	\$	<i>Sn</i>	685.76	
1	KNUCKLE ARM RH L70Y	\$	<i>Sn</i>	846.98	
1	ABSORBER FRT RH L70Y	\$	<i>Sn</i>	360.54	
1	DRIVESHAFT RH	\$	<i>M</i>	1,747.45	
1	STABILIZER BAR FRT	\$	<i>Sn</i>	604.65	
1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i>	270.06	
1	WIPER RESERVOIR	\$	<i>Sn</i>	348.25	
1	WIPER RESERVOIR NECK	\$	<i>Sn</i>	136.11	} X
1	DOOR HARNESS WIRE RH	\$	<i>Sn</i>	2,670.00	
TOTAL		\$		26,770.74	
10%		\$		2,677.07	
		\$		24,093.67	

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>M</i>	80.00	<i>60sm</i>
1	FRONT DOOR STICKER 'Classic'	\$	<i>M</i>	80.00	<i>15sm</i>
1	BUMPER CLIP FRT	\$	<i>M</i>	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>M</i>	12.00	} X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>M</i>	10.50	
1	BUMPER GRILLE LOWER CLIP	\$	<i>M</i>	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>M</i>	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>M</i>	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>M</i>	30.00	} X
1	WHEELARCH CLIP FRT RH	\$	<i>M</i>	30.50	
1	FRONT RIGHT TYRE	\$	<i>Sn</i>	300.00	} X
1	FRONT RIGHT TYRE RIM	\$	<i>Net</i>	380.00	
1SET	Front licence plate with holder	\$	<i>Sn</i>	80.00	X
1SET	RADIATOR GRILLE SCREW	\$	<i>Sn</i>	16.00	X

Trans-cab Auto Services Pte Ltd

AAD1908-079

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9922P

1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	} X
1	WINDSCREEN SEALANT	\$	nn	253.80	
1	FRONT WINDSCREEN MOULDING	\$	nn	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	
2	BONNET STRUT L70Y	\$	sn	88.61	
2	BONNET CABLE CLIP L70Y	\$	nn	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	
TOTAL		\$		1,882.88	
TOTAL PARTS		\$		25,976.54	

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	6601
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	5001
To transfer of front windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	n 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	n 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	n 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1908-079**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9922P

To rust-proofing of the affected areas.	\$	170.00	601
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	601
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
Towing Fees	\$	nn 150.00	X
TOTAL	\$	16,090.00	
Over All Total	\$	42,066.54	

LUMP SUM (REPAIR DAY)**20 DAYS****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: