



AMA Autocare Pte Ltd  
Enterprise Hub 36 Toh Guan Road East #01-36  
Singapore (608580)  
Co. Reg. No: 201735370W E: ama.claim@gmail.com  
T: 87783636

Page No. 1

Vehicle No. SKJ 8411 L TOYOTA ALTIS 1.6A

| QTY  | DESCRIPTION                              | CONDITION | REPAIRER'S ESTIMATE(\$\$) | ADJUSTMENT    |
|------|------------------------------------------|-----------|---------------------------|---------------|
|      | <b>PARTS (LIST ITEMS)</b>                |           |                           |               |
| 1    | Rear bootlid                             |           | 855.10 1478.00            | bt            |
| 1    | Rear bootlid centre chrome moulding      |           | 254.00                    | xnn           |
| 1    | Rear bootlid weatherstrip                |           | 214.00                    | wt            |
| 1    | Rear bootlid COROLLA emblem              |           | 108.00                    | nei           |
| 1    | Rear bootlid Altis emblem                |           | 82.00                     | nei           |
| 1    | Rear bootlid 1.6 E emblem                |           | 58.00                     | nei           |
| 1    | Rear bootlid VVT-I emblem                |           | 70.00                     | nei           |
| 1    | Rear bootlid Corolla badge               |           | 88.00                     | nei           |
| 1    | Rear bootlid "DUAL" badge                |           | 58.00                     | nei           |
| 1    | Rear bootlid Elegance badge              |           | 82.00                     | nei           |
| 1    | Rear bootlit lock assy                   |           | 285.20 480.00             | bt            |
| 1    | Rear bootlid reflector @\$572.40         | \$314     | 314 1144.80               | LH-X, RH-at   |
| 2    | Rear taillamp @\$780                     | 594.60    | 594.60 1560.00            | LH-xnn, RH-wt |
| 2    | Taillamp lower panel @214.50             |           | 429.00                    | Rx            |
| 1    | Rear end panel                           |           | 586.60 982.00             | bt            |
| 1    | Rear end panel top garnish               |           | 216.00                    | de            |
| 1    | Rear bumper                              |           | 596.50 1250.00            | de            |
| 1    | Rear bumper reinforcement                |           | 392.60 672.00             | bt            |
| 1    | Rear bumper foam                         |           | 163.80 310.00             | crn           |
| 1set | Rear bumper side retainer @98.00         |           | 98 196.00                 | LH-X, RH-ds   |
| 2    | RHS & LHS Rear fender @782.50            |           | 1565.00                   | Rx            |
| 1    | RHS & LHS Rear fender inner trim @272.40 |           | 544.80                    | xnn           |
| 1    | Rear spare tyre panel                    |           | 980.00                    | Ry            |
| 1    | Rear spare tyre top cover                |           | 288.00                    | crn           |
| 1    | Rear Exhaust silencer assembly           |           | 670.00                    | xRy           |
| 1    | Rear Exhaust silencer assembly mountings |           | 98.00                     | xnn           |
|      |                                          |           | 13877.60                  | 0.00          |
|      |                                          | less 25%  | 3469.40                   | 25% 0.00      |
|      |                                          |           | 10408.20                  | 0.00          |
|      | <b>SPECIAL NETT ITEMS</b>                |           |                           |               |
| 1set | Rear bumper clips                        |           | 80.00                     | 30            |
| 1set | Inner trim clips                         |           | 80.00                     | xnn           |
| 1set | Taillamp clips                           |           | 70.00                     | 30            |
| 1set | Rear bumper reverse sensor               |           | 220.00                    | 200AW         |
| 1    | Rear end panel sealant                   |           | 100.00                    | 40            |
| 1    | Rear number plate                        |           | 80.00                     | xnn           |
|      | <b>TOTAL PARTS</b>                       |           | 11038.20                  | 0.00          |

5150.40

3862.80

300



AMA Autocare Pte Ltd  
Enterprise Hub 36 Toh Guan Road East #01-36  
Singapore (608580)  
E: ama.claim@gmail.com  
T: 87783636

Page No. 2

Vehicle No. SKJ 8411 L TOYOTA ALTIS 1.6A

| S/N                     | DESCRIPTION                                                                                                  | REPAIRER'S ESTIMATE (S\$) | ADJUSTMENT |
|-------------------------|--------------------------------------------------------------------------------------------------------------|---------------------------|------------|
| <b>LABOUR</b>           |                                                                                                              |                           |            |
| 1                       | To remove the affected parts & fittings to commence repairs; replace damaged parts and components            | 1400.00 860               |            |
| 2                       | To supply paint materials, expandable items & putty, respray paint on parts replaced                         | 1400.00 800               |            |
| 3                       | To remove and re-fix wiring and check all electrical components at damaged areas for proper functions        | 200.00 30                 |            |
| 4                       | To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment | 250.00 60                 |            |
| 5                       | To remove and replace reverse sensors                                                                        | 150.00 30                 |            |
| 6                       | To provide anti-rust treatment on affected areas                                                             | 180.00 40                 |            |
| 7                       | To remove and replace rear exhaust silencer assy                                                             | 250.00 60                 |            |
| Labour Total :          |                                                                                                              | 3830.00                   |            |
| TOTAL (PARTS & LABOUR): |                                                                                                              | 14686.20                  |            |

3862.80

300

1760

5922.80

L/s \$ 4700  
6 days #

Tanjik 97495749  
"WP"

16/8/19 @ 445pm

6 days

Resurvey after repair

suu@lkkauto.com

tanjik@lkkauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: