

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5601Y

AAD1908-086

*Not Authorized
L1 Pay 85000.*

Vehicle No.:
 Chassis No.: 15 AUG 2019
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHC 5601Y
 VF1ABL15AUC279405
 RENAULT
 LATITUDE
 10.8.19
AIG
 30/9/2014

PART		LIST
1	BUMPER COVER FRT	\$ N 1,259.42
1	BUMPER SPOILER FRT	\$ S 181.75
1	BUMPER ABSORBER FRT	\$ S 394.68
1	BUMPER RETAINER FRT LH	\$ S 151.41
1	BUMPER SUPPORT FRT	\$ S 123.88
1	BUMPER UNDERTRAY FRT	\$ S 472.83
1	BUMPER GRILLE LOWER FRT	\$ S 266.80
1	BUMPER FOG LAMP GRILLE LH	\$ S 207.21
1	BUMPER BEAM FRT	\$ N 914.08
1	HEADLAMP LH	\$ S 1,184.43
1	HEADLAMP PANEL FRT LH	\$ N 152.15
1	FENDER PANEL FRT LH	\$ B 783.83
1	WHEELARCH FRT LH	\$ S 278.84
1	FENDER BRACKET LOWER LH	\$ S 15.79
1	FENDER INSULATOR LH	\$ S 130.84
1	FRONT BRACE PANEL	\$ N 177.22
1	RADIATOR GRILLE	\$ S 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$ S 225.36
1	RADIATOR GRILLE FRAME	\$ S 1,353.75
1	FRAME FULL SUPPORT PANEL	\$ S 615.90
1	FRAME FULL SUPPORT BRACKET	\$ N 89.79
1	BONNET	\$ N 1,941.63
1	BONNET INSULATOR	\$ S 405.73
1	BONNET STRUT LH	\$ S 88.61
1	BONNET STRUT RH	\$ S 88.61
1	BONNET HINGE LH	\$ N 348.31
1	BONNET HINGE RH	\$ N 348.31
1	BONNET LOCK	\$ N 305.48
1	BONNET CABLE	\$ S 119.19

X

X

Trans-cab Auto Services Pte Ltd

AAD1908-086

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5601Y

1	BONNET CABLE COVER	\$	Sh	161.03	X
1	BONNET SEAL OUTER	\$	Sh	92.36	X
1	BONNET SEAL INNER	\$	Sh	157.28	X
1	AIR CLEANER BOX	\$	Sh	464.20	X
1	AIR CLEANER HOSE	\$	Sh	175.85	X
1	AIR CLEANER LOWER	\$	Sh	271.26	X
1	DOOR PANEL FRT LH	\$	B	2,844.66	✓
1	DOOR HANDLE OUTER FRT LH	\$	Sh	477.76	X
1	DOOR HANDLE COVER FRT LH	\$	Sh	13.22	X
1	DOOR HANDLE MODULE FRT LH	\$	Sh	133.60	X
1	DOOR MIRROR ASSY LH	\$	Ad/100%	1,483.40	✓
1	DOOR HARNESS WIRE LH	\$	Sh	2,670.00	} X
1	ROCKER PANEL INNER GARNISH LH	\$	Sh	466.51	
1	ROCKER PANEL INNER LH	\$	n	1,024.79	
1	ROCKER PANEL OUTER LH	\$	n	1,184.99	
1	ROCKER PANEL CENTER LH	\$	n	990.25	
1	DOOR PANEL REAR LH	\$	n	2,844.66	
TOTAL		\$		29,789.42	
10%		\$		2,978.94	
		\$		26,810.48	

Special Nett

1	BUMPER CLIP FRT	\$	na	66.00	} X
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
1	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
1	WHEELARCH CLIP FRT LH	\$	na	30.50	
1	FRONT LEFT TYRE	\$	Sh	300.00	
1	FRONT LEFT TYRE RIM	\$	Sh	380.00	
1SET	Front licence plate with holder	\$	Sh	80.00	
1	WINDSCREEN SEALANT	\$	na	253.80	
1	FRONT WINDSCREEN MOULDING	\$	na	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
6	BONNET INSULATOR CLIP L70Y	\$	na	7.30	
2	BONNET STRUT L70Y	\$	Sh	88.61	

Trans-cab Auto Services Pte Ltd

AAD1908-086

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5601Y

2	BONNET CABLE CLIP L70Y	\$	na	6.31 X
2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85 X
1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00 X
1SET	RADIATOR GRILLE SCREW	\$	na	16.00 X
1	FRONT DOOR STICKER 'Trans-Cab'	\$	na	80.00 601M
1	FRONT DOOR STICKER 'Classic'	\$	na	80.00 155M
1	REAR DOOR STICKER "6555-3333"	\$	na	80.00 601M
TOTAL		\$		1,962.88
TOTAL PARTS		\$		28,773.35

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	500	6,000.00
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	na	380.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	↪	380.00 X
To transfer of front windscreen fittings and conduct water seepage test.	\$	↪	170.00 X
To check steering geometry and computer wheel alignment	\$	↪	220.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	na	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na	380.00 X

Trans-cab Auto Services Pte Ltd

AAD1908-086

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5601Y

Putty and spray painting of the affected portion.	\$	6,000.00	<i>800</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	<i>600</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>200</i>
To rust-proofing of the affected areas.	\$	170.00	<i>600</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
TOTAL	\$	15,940.00	
Over All Total	\$	44,713.35	

LUMP SUM (REPAIR DAY)

20 days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: