


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: NISSAN QASHQAI, 2.0 CVT ABS D/AIRBAG 2WD
 Engine/Chassis No.: SJNFBAJ11U1764484
 Date of accident:
 Damaged area: O/S Rear

Date: 01/07/2019
 Claim Type: TP
 VRN: SJJ808R



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate	1	\$ 2,937.00	\$ 2,937.00
2	Tailgate hinge	2	\$ 59.00	\$ 118.00
3	Tailgate damper	2	\$ 114.00	\$ 228.00
4	Tailgate emblem	1	\$ 61.00	\$ 61.00
5	Tailgate Qashqai logo	1	\$ 87.00	\$ 87.00
6	Taillamp o/s	1	\$ 747.00	\$ 747.00
7	Taillamp lower beam o/s	1	\$ 49.00	\$ 49.00
8	Rear bumper	1	\$ 1,017.00	\$ 1,017.00
9	Rear bumper side retainer	2	\$ 72.00	\$ 144.00
10	Rear bumper reflector o/s	1	\$ 89.00	\$ 89.00
11	Rear bumper lower	1	\$ 678.00	\$ 678.00
12	Rear bumper reinforcement	1	\$ 619.00	\$ 619.00
13	Rear bumper reinforcement bracket	2	\$ 126.00	\$ 252.00
14	Rear bumper sponge	1	\$ 137.00	\$ 137.00
15	Rear side panel o/s	1	\$ 483.00	\$ 483.00
16	Rear side panel air vent o/s	1	\$ 68.00	\$ 68.00
17	Rear fender wheel arch o/s	1	\$ 483.00	\$ 483.00
			Subtotal	\$ 8,197.00
			List discount	30.00%
			Total	\$ 5,737.90

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper clips	10	\$ 4.50	\$ 45.00
2	Rear bumper reverse sensor wire harness	1	\$ 150.00	\$ 150.00
3	Reverse sensor	1	\$ 280.00	\$ 280.00
4	Side panel sealant o/s	1	\$ 80.00	\$ 80.00
5	Rear fender wheel arch clips o/s	6	\$ 4.50	\$ 27.00
6	Sundries	1	\$ 50.00	\$ 50.00
			Total	\$ 632.00

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00
5	Supply spray paint material and necessary items to respray rear bumper, tailgate, o/s rear side panel and other affected area / panel.	5	\$ 1,000.00
6	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,400.00
Estimate Grand Total			\$ 8,769.90