ASS. REC. BY: SUIVA OY From (Person):		MS19	Date/Time: 16.8.19 1.2012.19
OD / TP WS / To Inspect Vehic	PRESIOD RESIEVATING SMD 73299 SK Aub noble		Insured: St. 5 22197 Tel: 81210478
Policy No: Sum Insured:	Bupit NR 4 #08-42 80468545	Claim No: Excess:	D.O.A. 14/8/19
Make of Veh: _ (Client's Record) CA / REV / Date/Time:	REP. / REV 24 HRS	natacted: xiong	Vehicle IN OUT
Date/Time	Action/Instruction (V) SMD 73299 - NBA/ MSO SKS 2497 - NBA/ MSO	Estimate 9 190 14179/ Y 1 190 14179/ Y	DOA-14/04/2017
19/19/19	Send preli revised	via merimen	al (Red 13, 185.44, 8

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Fievel Foo Wenyao

Date:

19 Aug 2019

Preliminary Advice

Insured Vehicle No : SKS2219T

TP Vehicle No

: SMD7329G

: SUBARU FORESTER

Accident Date

: 14/08/2019

Make

Assignment Date

: 16/08/2019

Date of Inspection

: 16/08/2019

Est. Duration of Repair

Inspection At

: 4.00

: SK AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4, #08-46 PREMIER @ KAKI BUKIT

SINGAPORE 415875

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,435.44
Revised Amount	:S\$	3,983.44
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,983.44
Lump Sum Renair	:S\$	

Total Loss Consideration

Lump Sum Repair

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

AIM SUBFO			Adt Assigned	Adj Rpt	Adi Subn	nitted	Ins Auth ed	Status	V-1000	
50000	4 Aug 2019	Est Submitted	16 Aug 2019 16:39 Edit Adj Rpt	Noj kat	Last:IA 19 Aug 2 10:23			Pending for Surve Report Cancel Case		iy
М	ain	Re	ference	CI	aim Details		Document	ts	Sh	ow All
CLATM SUP	FOLDER DE	TAILS	Personal Continues	IN PROPERTY AND IN SEC.		[Create	ed by insurer]			
Insured:	монама	D HERMI BIN YA	TIMAN, ID: S	7400034G						
Main Claimant:	WONG TZ					14/09/2	019 08:00 - :59			
Vehicle Reg. No.:	SMD73	29G			Date of Loss:	[11 Mor	oths and 14 Days F 45 (Comprehensive	rom LTA Re	eg Date (M	an Yr)]
Claim Type:	TP				Policy/Cover Note No.:	Coverag	ge: 27/03/2019 - 20	6/03/2020		
Vehicle Reg. No.	SKS2219	т			Policy No. (Claimant):					
(Insured):					Excess:		ens with Disk To	1. 0121 04	78	
Repairer:	Sk Autor	nobile Pte Ltd ()	8 Kaki Bukit Av	e 4, #08-46 Pr	emier @ Kaki E	Bukit, 415	875 Kaki Bukit - Te	11: 0121 04		
Handling Insurer:	MSIG In	surance (Singapo	ore) Pte. Ltd. (HQ) - Tel: +6	5 6827 7888	Handle	by Fievel Foo W	enyao - 60 nal Rpt c	ue 15/09	/2019]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Te	1: 6256-3561 .	[Handled by	AING GC	IO QIANG] [Fil			
Driver/Cust dian (Insured):	MOHAMA	D HERMI BIN YATI	MAN (45 / Male)) , NRIC: 57	400034G Email		0 0131	0470 Man	ial accion t	n I KK via
Adj Asg. Remarks:	on WP. (N email on	1anual Assign). Lia 16/08/2019.	b: 100%. Assig	n: LKK Auto Co	onsultants Pte L	td. Conta	act: Xiong @ 8121			
ASSOCIAT	ED MAIL R	ECEIVED						View All	Compose	Case Mail
There are n	o mail for th	s case.							100	
ALL ASSO	CIATED TA	SKS				View			New Task	Complete
Due Dat	e Priorit		Group Su	bject Han	dler Assig	ned By	Completed 0	n Cri	eated On	Done

Catherine Chong (LKK Auto)

From:

Crystal Lee <crystal_lee@sg.msig-asia.com>

Sent:

Friday, 16 August, 2019 1:20 PM

To:

Admin-D (LKKAuto); assignments

Cc:

Ong Zi Hui; Helene Phua

Subject:

Survey Request - Manual Assigned (Survey the vehicle by today)

Attachments:

SMD7329G GIA .pdf; SMD7329G ARRANGE.pdf

Importance:

High

Arrange surveyor for SMD7329G & Your Ref:SKS2219T

Manual Assigned

Dear LKK,

Refer to the email, please arrange survey the vehicle by today.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg









A Member of MS&AD INSURANCE GROUP

From: Motor Survey

Sent: Friday, 16 August, 2019 11:48 AM

To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Fievel Foo <Fievel_Foo@sg.msig-asia.com>; Low Yi Qian

<yiqian_low@sg.msig-asia.com>

Cc: Helene Phua <helene_phua@sg.msig-asia.com>

Subject: FW: Arrange surveyor for SMD7329G & Your Ref:SKS2219T

Importance: High

Hi Crystal

Please outsource this case today.

Have a nice day

Jason Sim

Manager, Claims Services (Motor)

Veron Chen (LKKAuto)

From:

Daniel Jude <danieljude@motorimage.net>

Sent:

Friday, 13 September 2019 3:11 PM

To:

Veron Chen (LKKAuto)

Subject:

FW: CHECK PARTS PRICES-SMD 7329G

Importance:

High

HI Veron,

Refer to trailing email as requested.

Thank You.

Best Regards

Daniel A Jude

Service Executive


Motor Image Enterprises Pte Ltd

HP: 8611 3195

Email: danieljude@motorimage.net

19 Lorong 8 Toa Payoh Singapore 319255

Website: www.tanchong.com: www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Ng Kok Seng

Sent: Friday, 13 September 2019 3:08 PM
To: Daniel Jude <danieljude@motorimage.net>
Cc: Simon Kam <simonkam@motorimage.net>
Subject: RE: CHECK PARTS PRICES-SMD 7329G

Price quoted, subject to GST

1)TCS-FJ8-RL-002/R BUMPER UNDER SPOILER-\$828.00 (Stock is available)

Ng

From: Daniel Jude < daniel jude @motorimage.net >

Sent: Friday, September 13, 2019 2:56 PM To: Ng Kok Seng <ng@motorimage.net>

Subject: FW: CHECK PARTS PRICES-SMD 7329G

Importance: High

Hi Ng,

Refer to trailing email

Thank You.

Best Regards

Daniel A Jude

Service Executive


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 13 September 2019 2:25 PM
To: Daniel Jude < danieljude@motorimage.net >
Subject: RE: CHECK PARTS PRICES-SMD 7329G

Dear Daniel,

MAKE-SUBARU FORESTER 2.0 2018,1995 cc CHASSIS -JF1SJ5KC5JG 111979

REAR BUMPER LOWER LIP

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Daniel Jude < danieljude@motorimage.net >

Sent: Friday, 13 September 2019 2:15 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Subject: FW: CHECK PARTS PRICES

Importance: High

Hi Veron,

Kindly refer to the trailing email.

Kindly provided as requested to get the quotation.

Thank You.

Best Regards

Daniel A Jude

Service Executive


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com: www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Ng Kok Seng

Sent: Friday, 13 September 2019 1:52 PM

To: Daniel Jude < daniel jude @motorimage.net >
Cc: Simon Kam < simonkam@motorimage.net >

Subject: RE: CHECK PARTS PRICES

We need your vehicle number or chassis number before we can quote.

Ng

From: Daniel Jude < danieljude@motorimage.net >

Sent: Friday, September 13, 2019 1:48 PM
To: Ng Kok Seng <ng@motorimage.net>
Subject: FW: CHECK PARTS PRICES

Importance: High

Hi Ng,

Kindly assist to check price as requested below

Thank You.

Best Regards

Daniel A Jude

Service Executive


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 13 September 2019 10:20 AM To: Daniel Jude < daniel jude @motorimage.net >

Subject: CHECK PARTS PRICES

Dear Daniel,

Kindly assist to check parts prices

MAKE-SUBARU FORESTER 2.0 2018,1995 cc

1) REAR BUMPER LOWER LIP

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

15

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From:

JING XIONG KHOO <xiongskauto@gmail.com>

Sent:

Saturday, 14 September 2019 3:32 PM

To:

Veron Chen (LKKAuto) SUR; Sk Automobile

Cc: Subject:

Re: SMD 7329G-DOA: 14/8/19

Attachments:

IMG_9508.JPG; IMG_9510.JPG; IMG_9509.JPG

hi,

we accept Lump Sum \$2,250/- @ 4 working days

Veron Chen (LKKAuto) < <u>veronchen@lkkauto.com</u>> 于2019年9月13日周五 下午3:44写道: Dear Xiong,

WITHOUT PREJUDICE

Offer Lump Sum \$2,250/- @ 4 working days

PARTS-\$1976.30 (less 20%)=\$1581.04 SN-\$430 LABOUR-\$840 TOTAL-\$2851.04 (less 20%)=\$2,280.83

Please check and confirm

Best Regards, Veron Chen | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :<u>sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	854A
Vehicle Details	
Vehicle No.:	SMD7329G
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Aug 2019
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.01-L CVT AWD SR
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	FB20YE38553
Chassis No.:	JF1SJ5KC5JG111979
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,451.00
Original Registration Date:	31 Aug 2018
First Registration Date:	31 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$13,451.00
Intended PARF Rebate Details	为最后,1944年,1944年,1944年,1944年,1944年,1944年,1944年,1944年,1944年,1944年,1944年,1944年,1944年,1944年,1944年,1944年,1944年,1944年
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2028
PARF Rebate Amount:	\$10,088.00
Intended COE Rebate Details	三年,李州时间发现到安徽等并由7点70万元,由19世界,自己是农业
COE Expiry Date:	30 Aug 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,429.00
COE Rebate Amount:	\$29,308.00
Total Rebate Amount:	\$39,396.00

The information contained herein is correct as at 16 Aug 2019

ОК

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties,
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	14/08/2019 19:53
Date Of Accident	14/08/2019 08:10
Exact Location Of Accident	COMMONWEALTH AVE TOWARD LENG KEE RD TRAFFIC LIGHT
Country/State of Loss	SINGAPORE

	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMD7329G	
Insured/Policyholder		
Name Of Registered Owner	WONG TZE YAU	
NRIC No	S8262854A	
Email Address	KENJIWTY@HOTMAIL.COM	
Mobile Phone No	(LOCAL) +65-82239269	
Alternative Phone No	OTHERS-82239269	
Vehicle Particulars		

Manufacturer SUBARU

Model FORESTER-2.0 I-L (SJ) (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken THIRD PARTY Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1800103872

Cover Note Number

Driver

Name of Driver WONG TZE YAU NRIC No S8262854A Date Of Birth 05/03/1982 Occupation **INDOOR** Date Of Driving Pass 06/05/2011

Driving Experience 8 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-82239269

Fax Number

Contact Number OTHERS-82239269

EMail Address KENJIWTY@HOTMAIL.COM

APT BLK 415B FERNVALE LINK Address

#06-56

Postcode 792415

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OWNER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Refer Sketch Plan

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKS2219T

Vehicle Make/Model/Colour

HONDA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MOHAMAD HERMI BIN YATIMAN

NRIC/Passport Number

S7400034G

Contact Number

97651944

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims fincluding the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's

Date & Time: 14/8/2019

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Co ntre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

 	HI AUDIT
	Phoneroon
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Commence of Branch Branch	
Commonwealth Ave	
+++++++++++++++++++++++++++++++++++++++	
SCRIBE CIRCUMSTANCES OF THE ACCIDENT	
on 44 Ang 2019, around \$:10 am, I was driving service centre for servicing appointment. Inn Leng kee Road. At the traffic light junction, I stopped at	red light.
At the traffic light punction, I stopped at	red light.
At the traffic light punction, I stopped at About I minute later I heard a brong on I stopped the car and went down to	red light. my our from behind. checke.
At the traffic light punction, I stopped at About I minute later I heard a brong on I stopped the car and went down to	red light. my our from behind. checke.
At the traffic light punction, I stopped at	red light. my our from behind. checke.
At the traffic light punction, I stopped at About I minute later I heard a brong on I stopped the car and went down to a A thould retrible hit the back of my a he dozed off and released the acceleration	red light. my our from behind. checke.
At the traffic light punction, I stopped at About I minute later I heard a brong on I stopped the car and went down to a A thould retrible hit the back of my a he dozed off and released the acceleration	red light. my our from behind. checke.
At the traffic light punction, I stopped at About I wing to later I heard a brong on I stopped the car and went down to a A ttenda vehicle hit the back of my a he dozed off and released the acceleration	red light. my our from behind. checke.
At the traffic light punction, I stopped at About I wing to later I heard a brong on I stopped the car and went down to a A ttenda vehicle hit the back of my a he dozed off and released the acceleration	red light. my our from behind. checke.
At the traffic light punction, I stopped at About I wing to later I heard a brong on I stopped the car and went down to a A ttenda vehicle hit the back of my a he dozed off and released the acceleration	red light. my our from behind. checke.
Af the traffic light junction, I stopped at though I minute later I heard a bring on I stopped the car and want down to a A though religie hit the back of my a he dozed off and released the acceleration. CON.	red light. my our from behind. checke. ar. The driver admitted or and finhequently but on
Af the fraffic light punction, I stopped at About I minute later, I heard a brong on I stopped the car and want down to a A though vehicle hit the back of my a he dozed off and released the acceleration. CON.	red light. my our from behind. checke.
Af the traffic light punction, I stopped at About I minute later I heard a brong on I stopped the car and want down to a A though religing hit the back of my a he dozed off and released the acceleration	red light. my car from behind. checke. ar. The driver admitted or and fubequently but on - Reporting Only

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature Date & Time Nyl 8/2019 4:15 pm

Driver's Signature

(if driver not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name:

Nric/Fin No.

SK Automobile Pte Ltd (Co Reg. No. 201500047H) 23 Kaki Bukit Ave 4, #03-01 Vicom Inspection Centre (\$415933)

Tel: 6789 5155 Fax: 6783 5155

TO

. .

: MSIG

DATE

: 15-Aug-19

ATTENTION

: MOTOR CLAIMS DEPT

JOB TYPE : T/P CLAIM

ESTIMATE REPORT

OWNER'S PARTICULAR

VEHICLE DETAILS

NAME

VEHICLE NO : SMD7329G

ADDRESS

OWNER'S INSURANCE:

ACCIDENT DETAILS

MODEL

LKK Auto Consultants hence notify

the Repairer of the following:

TEL. NO.

POLICY NO.

CHASSIS NO resurvey before/after spray pain

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) iş allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482

DATE : TIME :

Acknowledged by Repairer

Signature:

Date:

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE		TOTAL LIST PRICE	
1	TAIL GATE X Repair.	1	\$	1,584.00	\$	1,584.00
2	TAIL GATE LOGO	1	\$	112.00	\$	112.00
3	TAIL GATE EMBLEM" SUBARU"	1	\$	75.00	\$	75.00
4	TAIL GATE EMBLEM" AWD"	1	\$	57.00	\$	57.00
5	TAIL GATE EMBLEM "FORESTER"	1	\$	72.00	\$	72:00
6	TAIL GATE EMBLEM "SPORT"	1	\$	68.00	\$	68.00
7	TAIL GATE WEATHER STRIP / TW	1	\$	364.80	\$	364.80
8	TAIL GATE WINDSCREEN MOULDING X	MA	\$	214.00	\$	214.00
9	REAR BUMPER / BR	1	\$	689.00	\$	689.00
10	REAR BUMPER LOWER LIP / 6	1	\$	1,954.00	\$	1,954.00
11	REAR BUMPER REFELCTOR X /	2	\$	79.00	\$	158.00
12	REAR BUMPER SIDE RETAINER X	2	\$	71.00	\$	142.00
13	REAR BUMPER TOWING COVER X	W 1	s	58.00	\$	58.00
14	REAR BUMPER REINFORCEMENT X	1	\$	400.00	\$	400.00
15	REAR FENDER INNER COWLING 🗶	2	\$	257.00	\$	514.00
16	REAR FENDER INNER TRIM	2	\$	812.00	\$	1,624.00
17	TAIL LAMP ★	2	\$	589.00	\$	1,178.00
18	TAIL LAMP LOWER BRACKET 🗶	2	\$	54.00	\$	108.00

20% · 918 · 64

19	REAR END PANEL X	1	\$ 684.00	\$ 684.00
	REAR END PANEL TOP GARNISH X	1	\$ 369.00	\$ 369.00
_	REAR FLOOR PANEL TOP SIDE BOARD	2	\$ 128.00	\$ 256.00
-	REAR FLOOR PANEL TOP BOARD	MA	\$ 598.00	\$ 598.00
23	REAR TOOLS SIDE SPONGE	2	\$ 359.00	\$ 718.00
24	REAR SPARE TYRE LOWER SPOMGE X	1	\$ 512.00	\$ 512.00
25	REAR TOOLS CENTRE SPONGE	1	\$ 298.00	\$ 298.00

TOTAL PRICE LESS 20% SUB TOTAL PRICE \$ 12,806.80 \$ 2,561.36 \$ 10,245.44

S/N	DESCRIPTION	QTY	UNI	UNIT S/NETT		AL S/NETT
1	TAIL GATE INNER TRIM CLIP X NV	ា	\$	50.00	\$	50.00
2	REAR BUMPER CLIPS / 4L	1	\$	60.00	\$	60.00
3	REAR BUMPER CHROME / el.	1	\$	500.00	\$	500.00
4	REAR FENDER INNER TRIM CLIPS X	1	\$	60.00	\$	60,00
5	REAR FENDER INNER COWLING CLIPS X	1	\$	30.00	\$	30.00
6	REAR TAIL LAMP CLIPS SET	11	\$	30.00	\$	30.00
7	REAR END PANEL TOP GARNISH CLIPS	1	\$	30.00	\$	30.00
8	REAR END PANEL INSULATION SEAL 🗴	1	\$	150.00	\$	150.00
9	RAER WINDSCREEN SEALANT X	1	\$	60.00	\$	60.00
10	REAR WINDSCREEN INNER SEAL X	1	\$	60.00	\$	60.00
11	REVERSE SENSOR DA	1	\$	350.00	\$	350.00

TOTAL \$ 1,380.00

430

200

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION			
	WELD, KNOCK, OUT DENTS AND STRAIGHTEN ACCIDENT DAMAGED PARTS	\$1,600.00	400	
10000	TO PUTTY, SPRAY PAINT, POLISH AND WAX ADJACENT PANELS	\$1,400.00	400	
3	WIRING, BULB CHECKING	\$120.00	×	,
	REMOVE AND REFIX CUSHION/SEAT/ UPHOLSTERY TO FACILITATE REPAIR	\$250.00	×	/
5	REMOVE AND REFIX EXHAUST SYSTEM	\$200.00	Х	~~
6	REMOVE AND REFIX REAR WINDSCREEN	\$120.00	Х	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$120.00	40.	<i>i</i>

840

3,810.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,625.44 TOTAL LABOUR COST: \$ 3,810.00 TOTAL REPAIR COST : \$ 15,435,44

APPROVED DETAILS

EXCESS

NO. OF WORKINGDAYS :

RE-SURVEY

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

4 Pays. (28) lugsom After vepour photos. Come Giorg - 828801 62 16/8/19.

2588.64 20%: 2050

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19014287/GVF3N2

Date:

17/09/2019

REFERENCE

Handling

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

80468545

Claimant

Insurer:

SMD7329G

Insured Vehicle No:

SKS2219T

Vehicle No: Date of Loss:

14/08/2019

Nature of Claim:

TP

Claim No: 603023

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMD7329G

Make & Model:

SUBARU FORESTER, 2.0 i-L (SJ) (A)

Engine No:

FB20YE38553

19549 km

Reg. Date: Colour:

31/08/2018 (Man. Year: 2018)

Chassis No: Odometer:

JF1SJ5KC5JG111979

Engine Capacity:

Grey

Market Value/New Car

1995 cc N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

85.42

CONDITION OF TYRES

Front Tyre Size:

225/60R17

Rear Tyre Size:

225/60R17

Front Left Side: Front Right Side: Yokohama 6 mm

Rear Left Side: Rear Right Side:

Yokohama 6 mm Yokohama 6 mm

Yokohama 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,625.44	2.011.04	9,614.40	82.70
Miscellaneous Items	0.00	0.00	0.00	02.70
Labour	3,810.00	840.00	2,970.00	77.95
Paintwork Labour	0.00	0.00	0.00	11.50
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,435.44	2,851.04	12,584,40	81.53
Approved Total (Overridden) (S\$)		2,250.00	4285.244.2	01.00
(S\$)	15,435.44	2,250.00	13,185.44	85.42
+ GST 7.00/7.00% (S\$)	1,080.48	157.50	922.98	85.42
Nett Amount (S\$)	16,515.92	2,407.50	14.108.42	85 42

INSPECTION

Date of Assignment:

16/08/2019

Date Inspected:

16/08/2019 Inspected At:

Sk Automobile Pte Ltd

8 Kaki Bukit Ave 4, #08-46 Premier @

14,108.42

Kaki Bukit

Singapore 415875

Estimated Period of Repair:

4.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g... 17/9/2019

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Sep 2019) Parts:

SUBARU FORESTER 2.0 i-L (SJ) (A) (Catalogue:Merimen Singapore 1.0) M1-SUV Labour:

Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD7329G) Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

TAIL GATE EMBLEM SUBARU *TAIL GATE EMBLEM AWD *TAIL GATE EMBLEM FORESTOR *TAIL GATE EMBLEM FORESTOR *TAIL GATE EMBLEM FORESTOR *TAIL GATE EMBLEM SPORT *TAIL GATE EMBLEM SPORT *TAIL GATE EMBLEM SPORT *TAIL GATE WINDSCREEN MOULDING *TAIL GATE BUMPER SIDE RETAINER **NOT NOT NOT NOT NOT NOT NOT NOT NOT NOT	ondition	Repairer's	Amount
TAIL GATE LOGO *TAIL GATE EMBLEM SUBARU *TAIL GATE EMBLEM AWD *TAIL GATE EMBLEM AWD *TAIL GATE EMBLEM FORESTOR *TAIL GATE EMBLEM FORESTOR *TAIL GATE EMBLEM FORESTOR *TAIL GATE EMBLEM SPORT *TAIL GATE WINDSCREEN MOULDING *TAIL GATE BUMPER LOWER SPOCE *TAIL LAMP STAIL TOP SIDE BOARD *TAIL LAMP LOWER BRACKET *TAIL GATE WINDSCREEN MOULDING *TAIL LAMP LOWER BRACKET *TAIL GATE WINDSCREEN SPONGE *TAIL LAMP LOWER SPONGE *TAIL LAMP LOWER SPONGE *TAIL LAMP LOWER SPONGE *TAIL GATE WINDSCREEN SEAL NOT	epair	1,584.00 FI	_ *-F
TAIL GATE EMBLEM SUBARU *TAIL GATE EMBLEM AWD *TAIL GATE EMBLEM FORESTOR *TAIL GATE EMBLEM FORESTOR *TAIL GATE EMBLEM FORESTOR *TAIL GATE EMBLEM SPORT *TAIL GATE EMBLEM SPORT *TAIL GATE EMBLEM SPORT *TAIL GATE WINDSCREEN MOULDING *TAIL GATE WINDSCREEN TOP *TAIL GATE WINDSCREEN MOULDING *TAIL GATE WINDSCREEN SPONGE **NOT NOT NOT NOT NOT NOT NOT NOT NOT NOT	ecessary	112.00 FI	
TAIL GATE EMBLEM AWD **TAIL GATE EMBLEM FORESTOR **TAIL GATE EMBLEM FORESTOR **TAIL GATE EMBLEM SPORT **TAIL GATE EMBLEM SPORT **TAIL GATE EMBLEM SPORT **TAIL GATE WINDSCREEN MOULDING **TAIL GATE WINDSCREEN WINDSCREEN MOULDING **TAIL GATE WINDSCREEN MOULDING **TAIL GATE WINDSCREEN SPONGE **NOT NOT NOT NOT NOT NOT NOT NOT NOT NOT	ecessary	75.00 FI	
*TAIL GATE EMBLEM FORESTOR Nece *TAIL GATE EMBLEM SPORT Nece *TAIL GATE WINDSCREEN MOULDING Not	ecessary	57.00 FL	
*TAIL GATE EMBLEM SPORT Nece TAIL GATE WEATHER STRIP TORN TAIL GATE WINDSCREEN MOULDING TEAR BUMPER TORN TEAR BUMPER LOWER LIP TEAR BUMPER REFLECTOR TEAR BUMPER SIDE RETAINER TORN TEAR BUMPER TOWING COVER TORN TEAR BUMPER REINFORCEMENT TORN TORN TEAR FENDER INNER COWLING TORN TEAR FENDER INNER TRIM TORN TORN TORN TORN TORN TORN TEAR BUMPER BRACKET TORN TORN TEAR FENDER INNER TRIM TORN TORN TEAR FENDER BRACKET TORN TORN TORN TEAR FENDER BRACKET TORN TORN TEAR FENDER BRACKET TORN TORN TORN TORN TORN TORN TORN TOR	ecessary		
*TAIL GATE WEATHER STRIP *TAIL GATE WINDSCREEN MOULDING *REAR BUMPER *TAIL GATE WINDSCREEN MOULDING *REAR BUMPER *REAR BUMPER LOWER LIP *REAR BUMPER SIDE RETAINER *REAR BUMPER SIDE RETAINER *REAR BUMPER TOWING COVER *REAR BUMPER REINFORCEMENT *REAR BUMPER REINFORCEMENT *REAR BUMPER REINFORCEMENT *REAR BUMPER RINNER COWLING *REAR FENDER INNER COWLING *NOT N *REAR FENDER INNER TRIM *NOT N *REAR FENDER INNER TRIM *NOT N *REAR FENDER INNER TRIM *REAR SEAR FENDER INDER SEAR SEAR SEAR SEAR SEAR SEAR SEAR SE	ecessary	72.00 FL 68.00 FL	
*TAIL GATE WINDSCREEN MOULDING Not			00.001
REAR BUMPER	t Necessary	364.80 FL	
REAR BUMPER LOWER LIP **REAR BUMPER REFLECTOR** Not		214.00 FL	
REAR BUMPER REFLECTOR Not		689.00 FL	
REAR BUMPER SIDE RETAINER Not		1,954.00 FL	The second state of the second state of the second
**REAR BUMPER TOWING COVER Not	t Necessary	158.00 FL	10 0.1 <i>0</i>
REAR BUMPER REINFORCEMENT **REAR FENDER INNER COWLING** **REAR FENDER INNER TRIM** **REAR FENDER INNER TRIM** **REAR FENDER INNER TRIM** **Not N** **REAR FENDER INNER TRIM** **Not N** **REAR END PANEL** **TAIL LAMP LOWER BRACKET** **Not N** **REAR END PANEL TOP GARNISH** **Not N** **REAR FLOOR PANEL TOP SIDE BOARD** **Not N** **REAR FLOOR PANEL TOP BOARD** **Not N** **REAR FLOOR PANEL TOP BOARD** **Not N** **REAR TOOLS SIDE SPONGE** **Not N** **REAR SPARE TYRE LOWER SPONGE** **Not N** **REAR TOOLS CENTRE SPONGE** **Not N** **TAIL GATE INNER TRIM CLIP** **Not N** **REAR BUMPER CLIPS** **REAR BUMPER CLIPS** **REAR BUMPER CHROME** **PEAR BUMPER CHROME** **REAR FENDER INNER TRIM CLIPS** **Not N** **REAR FENDER INNER COWLING CLIPS** **Not N** **REAR FENDER INNER COWLING CLIPS** **Not N** **REAR FENDER INNER COWLING CLIPS** **Not N** **REAR END PANEL TOP GARNISH CLIPS** **Not N** **REAR END PANEL TOP GARNISH CLIPS** **Not N** **REAR END PANEL INSULATION SEAL** **Not N** **REAR WINDSCREEN INNER SEAL*	t Necessary	142.00 FL	
REAR FENDER INNER COWLING **REAR FENDER INNER TRIM** **Not N** **TAIL LAMP** **TAIL LAMP** **TAIL LAMP LOWER BRACKET** **Not N** **TEAR FLOOR PANEL TOP GARNISH** **TEAR FLOOR PANEL TOP SIDE BOARD** **Not N** **TEAR FLOOR PANEL TOP BOARD** **Not N** **TEAR FLOOR PANEL TOP BOARD** **Not N** **TEAR TOOLS SIDE SPONGE** **Not N** **TEAR SPARE TYRE LOWER SPONGE** **Not N** **TAIL GATE INNER TRIM CLIP** **TAIL GATE INNER TRIM CLIP** **TAIL GATE INNER TRIM CLIPS** **TAIL G	t Necessary	58.00 FL	23 Tab
REAR FENDER INNER TRIM **REAR FENDER INNER TRIM** **TAIL LAMP** **TAIL LAMP** **TAIL LAMP LOWER BRACKET** **Not N Not N N Not N N N N	t Necessary	400.00 FL	
*TAIL LAMP Not N *TAIL LAMP LOWER BRACKET Not N *TAIL LAMP LOWER BRACKET Not N *REAR END PANEL NOT N *REAR END PANEL TOP GARNISH NOT N *REAR END PANEL TOP SIDE BOARD NOT N *REAR FLOOR PANEL TOP BOARD NOT N *REAR FLOOR PANEL TOP BOARD NOT N *REAR TOOLS SIDE SPONGE NOT N *REAR SPARE TYRE LOWER SPONGE NOT N *REAR SPARE TYRE LOWER SPONGE NOT N *REAR TOOLS CENTRE SPONGE NOT N *TAIL GATE INNER TRIM CLIP NOT N *TAIL GATE INNER TRIM CLIP NOT N *REAR BUMPER CHROME DEFORM *REAR BUMPER CHROME DEFORM *REAR FENDER INNER TRIM CLIPS NOT N *REAR FENDER INNER COWLING CLIPS NOT N *REAR FENDER INNER COWLING CLIPS NOT N *REAR END PANEL TOP GARNISH CLIPS NOT N *REAR END PANEL INSULATION SEAL NOT N *REAR WINDSCREEN SEALANT NOT N *REAR WINDSCREEN INNER SEAL NOT N *REAR WINDSCREEN INNER SEAL NOT NE *TREAR WINDSCREEN INNER SEAL NOT NE *TREAR WINDSCREEN INNER SEAL NOT NE *TREAR SEVERSE SENSOR DAMAGE **FEAR SEVERSE SENSOR SUBBER **FEARCH SEAL SESPENSOR SEALANT NOT NE **TAIL LAMP CLIPS NOT	t Necessary	514.00 FL	1.10
*TAIL LAMP LOWER BRACKET Not	t Necessary	1,624.00 FL	*-Fl
REAR END PANEL **REAR END PANEL** **REAR END PANEL TOP GARNISH** **REAR END PANEL TOP SIDE BOARD** **REAR FLOOR PANEL TOP BOARD** **REAR FLOOR PANEL TOP BOARD** **REAR FLOOR PANEL TOP BOARD** **REAR TOOLS SIDE SPONGE** **REAR SPARE TYRE LOWER SPONGE** **Not N.* **REAR SPARE TYRE LOWER SPONGE** Not N.* **REAR TOOLS CENTRE SPONGE** **Not N.* **TAIL GATE INNER TRIM CLIP** **REAR BUMPER CLIPS** **REAR BUMPER CLIPS** **REAR BUMPER CHROME** **REAR BUMPER CHROME** **REAR FENDER INNER TRIM CLIPS** Not N.* **REAR FENDER INNER COWLING CLIPS** Not N.* **REAR FENDER INNER COWLING CLIPS** Not N.* **REAR END PANEL TOP GARNISH CLIPS** Not N.* **REAR END PANEL TOP GARNISH CLIPS** Not N.* **REAR END PANEL INSULATION SEAL** Not N.* **REAR END PANEL INSULATION SEAL** Not N.* **REAR WINDSCREEN SEALANT** Not N.* **REAR WINDSCREEN INNER SEAL** Not N.* **REAR WINDSCREEN INNER SEAL** Not N.* **REAR WINDSCREEN INNER SEAL** Not N.* **REVERSE SENSOR** **Franchise part. S=SpcNett. L=ListItemDisc.** **Sub**	t Necessary	1,178.00 FL	*-FL
REAR END PANEL TOP GARNISH Not	t Necessary	108.00 FL	*-FL
*REAR FLOOR PANEL TOP GARNISH Not	t Necessary	684.00 FL	*-FL
*REAR FLOOR PANEL TOP BOARD Not N REAR TOOLS SIDE SPONGE NOT N REAR SPARE TYRE LOWER SPONGE NOT N REAR SPARE TYRE LOWER SPONGE NOT N REAR TOOLS CENTRE SPONGE NOT N REAR BUMPER CLIPS NOT N REAR BUMPER CLIPS NOT N REAR BUMPER CHROME DEFORM REAR FENDER INNER TRIM CLIPS NOT N REAR FENDER INNER TRIM CLIPS NOT N REAR FENDER INNER COWLING CLIPS NOT N REAR FENDER INNER COWLING CLIPS NOT N REAR FENDER INSULATION SEAL NOT N REAR WINDSCREEN SEALANT NOT N REAR WINDSCREEN INNER SEAL NOT NER REAR WINDSCREEN INNER SEAL NER REAR WINDSCREEN SEAL NER REAR WINDSCREEN SEAL NER REAR WINDSCREEN SEAL NER REAR WINDSCREEN WINDSCREEN SEAL NER REAR WINDSCREEN SEAL NER R	t Necessary	369.00 FL	*-FL
*REAR TOOLS SIDE SPONGE Not N *REAR SPARE TYRE LOWER SPONGE Not N *REAR TOOLS CENTRE SPONGE NOT N *REAR TOOLS CENTRE SPONGE NOT N *TAIL GATE INNER TRIM CLIP NOT N *REAR BUMPER CLIPS NECES *REAR BUMPER CHROME DEFORM *REAR FENDER INNER TRIM CLIPS NOT N *REAR FENDER INNER TRIM CLIPS NOT N *REAR FENDER INNER COWLING CLIPS NOT N *REAR FENDER INNER COWLING CLIPS NOT N *SET REAR TAIL LAMP CLIPS NOT N *REAR END PANEL TOP GARNISH CLIPS NOT N *REAR END PANEL INSULATION SEAL NOT N *REAR WINDSCREEN SEALANT NOT N *TREAR WINDSCREEN INNER SEAL N *TREAR WINDSCREEN SEAL N *TREAR WINDSCRE	t Necessary	256.00 FL	*-FL
*REAR SPARE TYRE LOWER SPONGE Not N *REAR TOOLS CENTRE SPONGE Not N *TAIL GATE INNER TRIM CLIP Not N *REAR BUMPER CLIPS Necess *REAR BUMPER CHROME Deform *REAR FENDER INNER TRIM CLIPS NOT N *REAR FENDER INNER COWLING CLIPS NOT N *SET REAR TAIL LAMP CLIPS NOT N *SET REAR TAIL LAMP CLIPS NOT N *TEAR END PANEL TOP GARNISH CLIPS NOT N *TEAR END PANEL INSULATION SEAL NOT N *TEAR WINDSCREEN SEALANT NOT N *TEAR WINDSCREEN INNER SEAL N *TEAR WINDSCREEN INNER SEAL NOT N *TEAR WINDSCREEN INNER SEAL N *TEAR WINDSCREEN SEAL N *TEAR W *TEA	Necessary	598.00 FL	*-FL
*REAR SPARE TIRE LOWER SPONGE Not N *REAR TOOLS CENTRE SPONGE Not N *TAIL GATE INNER TRIM CLIP Not N *TAIL GATE INNER TRIM CLIP Not N *REAR BUMPER CHROME Deform *REAR FENDER INNER TRIM CLIPS NOT N *REAR FENDER INNER COWLING CLIPS NOT N *SET REAR TAIL LAMP CLIPS NOT N *SET REAR TAIL LAMP CLIPS NOT N *TREAR END PANEL TOP GARNISH CLIPS NOT N *TREAR END PANEL INSULATION SEAL NOT N *TREAR WINDSCREEN SEALANT NOT N *TREAR WINDSCREEN INNER SEAL N *TREAR WINDS	Necessary	718.00 FL	*-FL
*TAIL GATE INNER TRIM CLIP Not	Necessary	512.00 FL	*-FL
**REAR BUMPER CLIPS Neces Deform **REAR BUMPER CHROME Deform **REAR FENDER INNER TRIM CLIPS Not	Necessary	298.00 FL	*-FL
REAR BUMPER CHROME PAREAR FENDER INNER TRIM CLIPS Not	Necessary	50.00 FS	*-FS
*REAR FENDER INNER TRIM CLIPS Not	cessary	60.00 FS	
*REAR FENDER INNER COWLING CLIPS Not	ormed	500.00FS	*200.00 FS
Not New Year Company C	Necessary	60.00 FS	*-FS
Not	Necessary	30.00 FS	*-FS
REAR END PANEL TOP GARNISH CLIPS Not Ne REAR END PANEL INSULATION SEAL Not Ne REAR WINDSCREEN SEALANT Not Ne REAR WINDSCREEN INNER SEAL Not Ne REAR WINDSCREEN INNER SEAL Not Ne REVERSE SENSOR Damag	Necessary	30.00 FS	*-FS
TREAR END PANEL INSULATION SEAL 1 *REAR WINDSCREEN SEALANT 5 1 *REAR WINDSCREEN INNER SEAL Not Ne 5 1 *REVERSE SENSOR Franchise part. S=SpcNett. L=ListItemDisc. Sub	Necessary	30.00 FS	*-FS
Not Ne 1 *REAR WINDSCREEN SEALANT Not Ne 5 1 *REAR WINDSCREEN INNER SEAL Not Ne 5 1 *REVERSE SENSOR Damage Franchise part. S=SpcNett, L=ListItemDisc. Sub	Necessary	150.00 FS	*-FS
Franchise part. S=SpcNett. L=ListItemDisc.	Necessary	60.00 FS	*-FS
Franchise part. S=SpcNett. L=ListItemDisc.	Necessary	60.00 FS	*-FS
Sub		350.00 FS	*200.00 FS
Sub - List Item Discount on L Items 20.00/20	3-(00)		
- List item Discount on L Items 20.00/20	ub Total (S\$)	14,186.80	2,406.30
	/20.00% (S\$)	2,561.36	395.26
T-4-11	al Parts (S\$)	11,625.44	2,011.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	WELD,KNOCK,OUT DENTS AND STRAIGHTEN ACCIDENT DAMAGED PARTS	New	1,600.00	400.00
2	TO PUTTY,SPRAY PAINT,POLISH AND WAX ADJACENT PANELS	New	1,400.00	400.00
3	WIRING, BULB CHECKING	New	120.00	0.00
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY TO FACILITATE REPAIR	New	250.00	0.00
5	REMOVE AND REFIX EXHAUST SYSTEM	New	200.00	0.00
6	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	40.00
	Gross Labour Cost (S\$)		3,810.00	840.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >