

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 248L

AAD1908-089

NOT WITHHELD

L/By B

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

15 AUG 2019

SHD 248L
 VF1ABL15AUC282395
 RENAULT
 LATITUDE
 9.8.19
AXA
 3/11/2015

		PART		LIST	
1	1	BUMPER COVER REAR	\$	<i>B</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Bu</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47	✓
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1	BUMPER RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61	✓
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1	BUMPER BEAM REAR	\$	<i>B</i> 777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1	BOOT REAR	\$	<i>B</i> 2,872.68	✓
14	1	BOOT FINISHER	\$	<i>Sn</i> 470.06	X
15	1	BOOT WHEATERSTRIP	\$	<i>W</i> 323.05	<i>508.00</i>
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	✓
18	1	BOOT BADGE 'RENAULT'	\$	<i>nc</i> 225.36	—
19	1	BOOT BADGE	\$	<i>nc</i> 225.36	—
20	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08	} X
21	1	BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1	BOOT INNER TRIM	\$	<i>Sn</i> 586.45	
25	1	BOOT SWITCH	\$	<i>Sn</i> 168.13	
26	1	BOOT LOCK	\$	<i>R</i> 202.67	
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40	

Trans-cab Auto Services Pte Ltd

AAD1908-089

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 248L

28	2	LICENCE PLATE LAMP	\$	50.52	
29	2	BOOT RUBBER PLUG	\$	221.81	
30	1	FENDER PANEL INNER TRIM REAR RH	\$	671.45	
31	1	FENDER PANEL REAR RH	\$	3,299.13	
32	1	WHEELARCH REAR RH	\$	543.47	
33	1	FENDER PANEL REAR LH	\$	3,299.13	
34	1	FENDER PANEL INNER TRIM REAR LH	\$	671.45	
35	1	WHEELARCH REAR LH	\$	543.47	
36	1	TAILLAMP RH	\$	552.55	
37	1	TAILLAMP PANEL RH	\$	986.70	
38	1	TAILLAMP LH	\$	552.55	
39	1	TAILLAMP PANEL LH	\$	986.70	
40	1	OUTER PANEL REAR (End Panel)	\$	1,471.77	
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	404.56	
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	612.21	X
44	1	EXHAUST REAR	\$	7,489.05	X
45	1	EXHAUST CAP REAR	\$	230.49	X
46	1	FUEL FLAP	\$	343.57	X
TOTAL			\$	36,212.51	
10%			\$	3,621.25	
			\$	32,591.26	

Special Nett

1	1SET	PARKING AID	\$	700.00	400.00
2	1SET	REAR BUMPER CLIP	\$	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	
10	1	EXHAUST MOUNTING REAR	\$	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	30.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD1908-089

SHD 248L

13	1	BOOT STICKER "6555-3333"	\$	<i>nee</i>	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i>	35.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>su</i>	385.00	X
17	1	SPARE TYRE	\$	<i>su</i>	330.00	X
18	1	FENDER INNER TRIM CLIP RH	\$	<i>na</i>	28.00	X
19	1	TAILLAMP CLIP RH	\$	<i>nee</i>	5.00	✓
20	2	REAR WINDSCREEN SEALANT	\$	<i>na</i>	80.00	X
21	1	WINDSCREEN MOULDING	\$	<i>na</i>	100.00	X
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	X
23	1	TAILLAMP CLIP LH	\$	<i>nee</i>	5.00	✓
24	1	FENDER INNER TRIM CLIP LH	\$	<i>na</i>	28.00	} X
25	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i>	35.00	
26	1	Rear left tyre	\$	<i>su</i>	330.00	
27	1	Rear left tyre rim	\$	<i>su</i>	380.00	
28	1	Rear right tyre	\$	<i>su</i>	330.00	
29	1	Rear right tyre rim	\$	<i>su</i>	380.00	
30	1	Rear Bumper Protector	\$	<i>na</i>	100.00	
TOTAL			\$		3,745.02	

TOTAL PARTS \$ 36,336.28

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	<i>8801</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	<i>7001</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 248L**AAD1908-089**

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} <i>bol</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>bol</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>↪</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>↪</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>bol</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	<i>X</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>na</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>bol</i>

Trans-cab Auto Services Pte Ltd

AAD1908-089

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 248L

To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.

\$ *nn* 380.00 X

Towing Fees

\$ *nn* 150.00 X

TOTAL \$ **19,350.00**

Over All Total \$ **55,686.28**

(LUMP SUM) Repair Days

~~25~~ DAYS

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: