Acres Mirmo AS	SPENMENT
From: Date:	Veh No: SCQ9190A. Yr Regn: 2010 / Jan.
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD/TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Audi A4 c.c 1984
at Workshop m/s	Colour Black - A/C: Insured / Std / NI / NA
of	Sp.Reading 183862 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WAUZZZ8K3AAO7.3301
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: 800	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inproder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / string / STD A/Rim or
	Tyre Size: F: 245/40 R.18
(Potby Condition)	R: 245/40818.
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BSIDUNIEXNOVAIGYIFSILIZAIMICIOHTSUIPIRISUMII TOYOIYOKO or Continental
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. Q6 mm L/Bal. a6 mm
Est Repairs: days Res.: Yes or No	D.O.A. D.O.I. 16/08/15.
Lum Sum: / % 3 Val.: Yes or No	Survey held at ((PM))
CA / REV / REP. / 24 HRS	Des. of Damages Fit Rear O/S N/S U/C Rooftop or
Vehicle: IN / OUT Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
67 ACG.	
SCQ 990 A - 06/A19 120/20	982 /AbH292 DOA-23/06/2012
16/8- Devert via menmen 23/8-15:17 - Mandate appropri	al la saffac #10001
WA: 38K 3512 @ 5. MA	al my victor \$6000 -
PV: 22K.	process to report excess poor
Nett: 6K	
All In- \$6000 [repair	Sum (Red: 27508, 82%)
Date/Time, File Pass to? Date/Time, File Return to?	Part Prices Check: Survey Fee: Date:
1) 2/3 TUPIST 2)	IN OUT Basic & Add.
5)	S+RS,SI
Preli. Report.	Others
Final Report	TOTAL

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #08-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Date:

16 Aug 2019

Attn:

Preliminary Advice

Vehicle No

: SCQ9190A

Accident Date

: 12/08/2019

Make

: AUDI A4

Policy No.

: 2100188177-09

Excess

: \$\$0.00

Assignment Date

: 16/08/2019

Date of Inspection : 16/08/2019

Est. Duration of Repair

: 8.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,931.00
Revised Amount	:S\$	11,031.00
Check Items (Estimated)	:S\$	2,792.00
Total	:S\$	13,823.00

Lump Sum Repair

:S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	28,000.00
COE / PARF Rebate	:S\$	21,977.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,023.00

Remarks

()	The vehicle is repairable at our adjusted let us have your authorisation.	nount. We have also confirm	ned excess and polic	y coverage. Kindiy
-----	--	-----------------------------	----------------------	--------------------

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

Claim Audit

AUDIT TRAIL			Ву
lo. On	Audit	Remarks	[] Merimen Administrator
1 13 Aug 2019 16:40	Clm Veh Model Changed	2400188177.09 Acrt Date: 2019/08/12, Claim Typ	[I] Merimen Administrator
2 13 Aug 2019 16:40	Clm Created	e: SC. Insurer: AIG Asia Pacific Insurance rec. 23. (55) n. Created from SAS:MPA119105559	[] LEE SU
3 16 Aug 2019 15:13	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	THING [] LEE SU THING
4 16 Aug 2019 15:13	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[A] LEE SU THING
5 16 Aug 2019 15:13	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU
6 16 Aug 2019 15:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/27	[A] LEE SU
7 16 Aug 2019 15:13		Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU
8 16 Aug 2019 15:13	Modified	Rep:1137->200611.	[A] LEE SU
9 16 Aug 2019 15:13	Clm Veh Model Changed	(202487) AUDI A4 2.0 MU TFSI (8E) (A).	THING [A] LEE SU
10 16 Aug 2019 15:13	Adj Adjuster Assigned	[None] -> ADRIAN LING	THING [A] DENISE TAY KWEE
11 16 Aug 2019 16:32	Adj Rpt Initiated		CHENG [A] DENISE
12 16 Aug 2019 16:32	Insured Phone No Updated	[None] -> [+6597974825]	TAY KWEE CHENG [A] DENISE
13 16 Aug 201 16:32	Clm Dtl Modified	JPJ Reg. Date: -> 2019/08/16.	TAY KWEE CHENG [A] DENISE
14 16 Aug 201 14 16:32	⁹ Clm Details Notified		TAY KWEE CHENG
15 16 Aug 201 15 16:36	9 Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/08/27	[A] DENISE TAY KWEE CHENG [A] DENISE
16 Aug 201 16 16:44	9 Adj Mandate Request	Cur.Req:13823.00:DAMAGE CONSISTENT	TAY KWEE CHENG [I] Nadaraja
17 21 Aug 201	9 Clm Registration Modified	Init.Est.:->5,000 - 6,000.	Deeban
18 23 Aug 201	Houmen	Excess: -> 800.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Nadaraja Deeban
19 08:32 19 23 Aug 201	G.	(20226):Coverage Confirmed.	[A] Merimer Administrate
20 23 Aug 201 15:17	9 Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/27, Mandate Remarks: Repair limit \$6000. In only check with repairer if they are able to repair. Re-inspection to be done for darkage check and supplementary items / labour.	Victor-CK
21 23 Aug 20: 15:17	9 Adj Mandate Set	Approved:6000.00:Repair limit \$6000. Kindly check with repairer if they are able to repair. Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	0 [I] Koh, Victor-CK

Duto 1 to	
ACTIVITY	
No record	

erimen Billin	g for this case -	Fransaction H	istory				
Bill Ref No	Bill Date	Асс Туре	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2247756	16/08/2019 16:32	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SCQ9190A		11.77

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Friday, 23 August 2019 3:44 PM

To:

Claims Dept; 'Nadaraja, Deebanalnadaraja'; SUR

Cc:

nora.khai@premiumauto.com.sg; 'Lim, Sheng Yang'; 'Parthiban, Theerthan'

Subject:

RE: - AIG - OD / 1788924970SG / SCQ9190A - Request for undertaking and

interview form

Attachments:

estimates.pdf

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SCQ 9190A (Excess \$800/-). Repair limi at \$6000

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>

Sent: Friday, 23 August 2019 11:08 AM

To: 'Nadaraja, Deebanalnadaraja' <Deebanalnadaraja.Nadaraja@aig.com>; SUR <sur@lkkauto.com>; Denise Tay (LKKAuto) < denisetay@lkkauto.com>

Cc: nora.khai@premiumauto.com.sg; 'Lim, Sheng Yang' <ShengYang.Lim@aig.com>; 'Parthiban, Theerthan'

<Theerthan.Parthiban@aig.com>; 'Claims Dept' <claims@premiumauto.com.sg>

Subject: RE: - AIG - OD / 1788924970SG / SCQ9190A - Request for undertaking and interview form

Dear all,

Any update on repair approval?

Thank you.

Best Regards, Tony Foong Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

MPA119105559 / Premium Automobiles Pte Ltd - UBI ENTRY DATE & TIME: 13/08/2019 16:17 SUBMITTED BY: Khoo Zhen Wei

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCI	DEM	I STA	ини
AUU	DEN	DIA	

13/08/2019 16:17 Date Of Report 12/08/2019 16:00 Date Of Accident

UPPER THOMSON ROAD TOWARDS SLE Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SCQ9190A Vehicle Registration Number

Insured/Policyholder

GOH YONG KENG Name Of Registered Owner

S1216828D NRIC No NOEMAIL Email Address

(LOCAL) +65-97974285 Mobile Phone No

HOME-64590805 Alternative Phone No.

Vehicle Particulars

AUDI Manufacturer

A4 SEDAN 2.0 TFSI QU 8K206 Model

Exact Purpose for which vehicle was being used at PRIVATE USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

PRIVATE CAR Vehicle Category

Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

2100188177-09 Policy Number

Cover Note Number

Driver

GOH HUI YI Name of Driver S8851077A NRIC No 21/12/1988 Date Of Birth

INDOOR Occupation 09/07/2007 Date Of Driving Pass

12 YEARS AND 1 MONTH **Driving Experience**

FEMALE Gender

(LOCAL) +65-97974285 Mobile Number

Fax Number

EMail Address

Contact Number GOHHYI@GMAIL.COM

Page 1 of 32

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material. facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any faise reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - [ii] processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection. investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature Date & Time

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name: 73-4 Fast

NRIC/FIN No.:

6-2040147

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	Singapore NRIC
Owner ID:	828D
Vehicle Details	REALPHOOD AND AND AND AND AND AND AND AND AND AN
Vehicle No.:	SCQ9190A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Aug 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 2.0 TFSI QU S-TRONIC
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	CDN079210
Chassis No.:	WAUZZZ8K3AA073301
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$42,349.00
Original Registration Date:	29 Jan 2010
First Registration Date:	29 Jan 2010
Transfer Count:	0
Actual ARF Paid:	\$42,349.00
Intended PARF Reparte Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2020
PARF Rebate Amount:	\$21,174.00
Intended COE Repate Details	
COE Expiry Date:	28 Jan 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$17,889.00
COE Rebate Amount:	\$803.00
Total Rebate Amount:	\$21,977.00

The information contained herein is correct as at 16 Aug 2019

New Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Feel at home with our award-winning service Over 1,800 entertainment options Up to 30kg baggage al

SEARCH Audi A4

Price Range

▼ Depreciation

Year Reg

▼ Vehicle Type

Used Car Comparison

--- Comparing 3 Vehicles ---

Audi A4 2.0A TFSI Quattro S-tronic

Audi A4 2.0A TFSI Quattro S-tronic

Audi A4 2.0A TFSI Quattro 5-tronic



Clear All







Add all to Shortlist Back to search result	Add to Shortlist	Add to Shortfist	Add to Shortlist	to compare.
CAR DETAILS				
Price	\$27,000	\$31,555	\$31,800	
Instalment	\$6,347	\$7,418	\$2,529	1.4
Registration Date	11-Dec-2009	11-Dec-2009	25-May-2010	
Manufactured	2009	2009	2010	53.
Mileage	\$1	100,000 km	94,000 km	
Transmission	Auto	Auto	Auto	550
Engine Cap	1,984 cc	1,984 cc	1,984 cc	
Road Tax	\$1,194 /yr	\$1,194 /yr	\$1,194 /yr	
Power	155.0 kW (207 bhp)	155.0 kW (207 bhp)	155.0 kW (207 bhp)	•
Curb Weight	1,565 kg	1,565 kg	1,565 kg	888
Features	2.0L Turbocharged Engine Mated With 7 Speed Auto Transmission, Multi Function Steering, Comfort And Dynamic(Sports) Mode, Esp System.	2.0 TFSI Turbo Charged Engine, S- Tronic, Quattro, S-Line, 7 Speed Gearbox, 6 SRS Airbags, ABS, ESP, ASR, Auto Electronic Parking Brake, Paddle Shifts.	 TFSI Turbocharged Engine, 7 Speed S Tronic Gearbox, 6 SRS, ABS, ESP, ASR Electronic Parking Brake, Paddle Shift, AWD Quattro. S-Line. 	
Accessories	Sports Rims And Electric Memory Seat. Factory Fitted Interior,	Sports Rims, Cruise Control, Keyless Start/Stop. Audi MMI, Drive Select, Paddle Shifts, Factory Fitted Audio, System Parking Assist.	Cruise Control, MMI Interface Audio, Bluetooth, SD Card, Memory Seat, Dual Climate Control, LED Daytime Running Lights,	14
Description	Immaculate Condition, Well Maintained, Wear And Tear Repairs Done, Tyre, Front Upper And Lower Arm, Brake Pad, Coolant Tank + Cap, Radiator Fan, Gearbox Transmission All Changed! Trade In Available, Call Our Friendly Staff Now To Book An Appointment For This Reauty!	Well Maintained Audi 2.0T, Agent Unit.100% Accident Free! Low Mileage Done, Best Unit For Short Term Usage Or Option To Renew COE, High In House Loan And Bank Loans Are Available! Please Drop By To View And Test Drive.	Clean And Neat Interior/Exterior, Agent Service Till 61000km Thereafter Service At External Workshop. Clutch Plate Changed Mid 2018,	

COE

OMV

\$42,349

ARF Depreciation

No. of Owners

Type of Vehicle Category

Availability

3 Luxury

N.A.

\$18,002

\$42,349

PARE Car, Premium Ad Car

Available

N.A. 3

N.A.

\$43,589

\$43,589

PARF Car

Available

\$42,725

\$13,510 /yr

\$34,600

\$42,725

5

Luxury

PARF Car, Direct Owner Sale

Available



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: Goh Yong Keng

Period of Insurance

: 29 Jan 2019 To 28 Jan 2020

Engine No.

: CDN079210

Chassis No.

: WAUZZZ8K3AA073301

Vehicle No.

: SCQ9190A

Policy No.

Issued Date

: 2100188177-09

Endorsement No.

: 11 Jan 2019

ABOUT THE COVER

Make/Model

: AUDI A4 2.0 TFSI

Engine Capacity/Tonnage: 1,984.00 CC

: NA

Sum Insured : Market Value

First Year of Registration : 2010

Off Peak Car : No

Insuring with COE/PARF : Yes

Driver Restriction Person or Classes of Persons Entitled to Drive*:

b) Any other person who is driving on the Policyholder's order or with his/her permission. This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than

Age Condition

: All Age Condition

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Goh Yong Keng - \$800 (Own Damage), Goh Hui Yi - \$800 (Own Damage), Yeo Mui - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of gother

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

AIG Asia Pacific Insurance Pte. Ltd.

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

- To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
- Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
- 3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
- The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
- 5. Rental cars are strictly for use in Singapore only.
- 6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
- Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.





55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/0971/2019/NS

Date : 15-Aug-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR GOH YONG KENG
Address : 27 SPRINGSIDE WALK

Singapore 786620

 Telephone
 : Hp:+65 97974285

 Type of Claim
 : Own Damage Claims

 Policy No.
 : 2100188177-09

 Vehicle No
 : SCQ 9190 A

Model Code : Audi A4 2.0 TFSI QU

 Model / Year
 : Jan-10

 Engine No
 : CDN 079210

Chassis No : WAUZZZ8K3AA073301

Mileage : Date In :
Liability : Excess Cost : -

Estimated By : Allan Wu
Accident Date : 12-Aug-19

Place of Accident : UPPER THOMSON ROAD TOWARDS SLE

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCQ 9190 A

S/N	Nature of Jobs		j	Estimated Charges	SURVEYOR'S RECOMMENDATION
3/14	, included by the second secon				
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	
2	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$	1,200.00	
3	To dismantle and renew front bumper, lhs headlight and bonnet. Renew front lock carrier		\$	4,550.00	
4	To respray front bumper and bonnet.		\$	2,000,00	1100
5	To carry out diagnostic checks.	S/N	\$	192.00	/
	TOTAL LABOUR CHARGES	:	\$	8,302.00	- - 1

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn SCQ 9190 A

			Damage Pa	arts & Prices
	S/N	Parts Description	S/NETT	REMARKS
	1	FRONT BUT Pistoted	\$ 2,470.00	1976
	2	FRONT BUMPER FIXING PARTS 7	\$ 234.00	×
	3	FRONT BUMPER IMPACT BAR	\$ 802.00	+
	4	FRONT BUMPER BRACKET - LH	\$ 207.00	+
	5	FRONT BUMPER SUPPORT - LH / RH 2	\$ 52.00	1
	6	FRONT BUMPER GUIDE SECTION - LH	\$ 40.00	*
¥	7	FRONT BUMPER COVER and	\$ 116.00	92.40
Λ.	8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 177.00	+
	9	FRONT BUMPER SPOILER - LOWER	\$ 307.00	+
	10	FRONT BUMPER PULL STRAP - LOWER 2. 144 ~	\$ 47.00	
	11	FRONT BUMPER FOAM FILLER PIECE ton	\$ 113.00	- 90.40
	12	FRONT BUMPER VENT GRILLE - LH	\$ 123.00	4
*	13	FRONT BUMPER COVER ME reinforcement 192	\$ 89.00	1 07
	14	CAUTION SIGN 2 Blam NEC	\$ 13.00	
	15	AIRCON STICKER NEC	\$ 18.00	/ 14.00
	16	SIGNAL HORN - LH HIGH TONE 7	\$ 189.00	*
	17	SPRING SHACKLE - LH HIGH TONE 2	\$ 23.00	x
	18	RADIATOR GRILLE Could	\$ 644.00	- 515.60
	19	RADIATOR GRILLE COVER HE NE	\$ 53.00	J. X
	20	BONNET Dented Report	\$ 1,788.00	_ ×
		SUB TOTAL SPARE PARTS	\$ 7,505.00	_
				12

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle RegnSCQ 9190 A

	SECURE FOR WALL A APPRIATOR AND A REPORT OF THE APPLICATION AN				arts & Prices
S/N	Parts Description		S/NETT		REMARKS
-					
21	BONNET ATTACHMENT PARTS >~ ~~			2.00	1 00 00
22	BONNET EDGE PROTECTION ME	C	\$ 5	0.00	/ 39-84
23	BONNET CATCH HOOK 2		\$ 12	7.00	+
24	BONNET LID LOCK Me ~		\$ 19	6.00	*
25	LID LOCK CABLE		\$ 4	4.00	
26	MAIN BEAM HEADLIGHT MOUNT - LH		\$ 10	7.00	* 85.60
27	HEADLIGHT BRACKET - LH		\$ 7	1.00	+
28	GAS DISCHARGE LAMP HEADLIGHT - LH Area		\$ 1,98	9.00	2
29	HALOGEN FOG LAMP XXX XX		\$ 23	8.00	*
30	LIFT CYLINDER - LH / RH	2	\$ 38	34.00	*
31	LIFT CYLINDER HOSE XXX N		\$ 3	6.00	*
. 32	COOLANT RADIATOR LOCK CARRIER 714 NW		\$ 92	28.00	541.60
33	A/C CONDENSER Dest Distal		\$ 67	77.00	
34	PRESSURE RELIEF VALVE		5 0	18.00	
35	PRESSURE SENDER		\$ \J1	75.00	+ 140
36	CHARGE AIR COOLER MAN		\$ 53	13.00	
. 37	COOLANT RADIATOR LOCK CARRIER . Radiator		SCRA 1,24	46.00	? 996.89X
38	RUBBER BUSH - UPPER HERE GVIIL	2	\$	12.00	2
39	RADIATOR SUPPORT	2	\$	59.00	?
* 40	COOLANT-RADIATOR LOCK CARRIER No.	4	\$	84.00	1: 67.20
	SUB TOTAL SPARE PARTS		\$ 14,65	1.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle RegnSCQ 9190 A

			Damage Parts & Prices				
	S/N	Parts Description		S/NETT	REMARKS		
	41	TWIN FAN RING		\$ 237.00			
	42	RADATOR AIR GUIDE - LH / RH KLP W-	2	\$ 50.00	+ 19.60 XX CRA		
	43	RADIATOR SEALING STRIP		\$ 21.00	+		
K	44	RADIATOR FAN 2		\$ 779.00	+		
K	45	RADIATOR FAV		\$ 673.00	4-		
	46	RADIATOR FAN CONTROL UNIT And New		\$ 778.00	+		
	47	FRONT NO. PLATE	S/N	\$ 40.00			
	48	SUNDRIES Her.	-	\$ 400.00	34.56		
		TOTAL SPARE PARTS	:	\$ 25,134.00	17629		
		TOTAL LABOUR CHARGES	:	\$ 8,302.00	**************************************		
		GRAND TOTAL	:	\$ 33,436.00	25931		
		All charges are not inclusive of GST.			25987.324		

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

: Adrian him

Surveyed Date

Authorised Date

Excess Cost

Liability Remarks

: Ne Anthorsed, 06 Days With book Carrier.

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate Workshop Accident Repairs

Workshop Contact No Ubi Road 1 6366 2323

Fax No

6841 1183

Reference

PA/OD/0971/2019/NS

Date

15-Aug-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Hi Adrian 6 days - ok - jb - 25 Oct 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

MR GOH YONG KENG

Address

27 SPRINGSIDE WALK

Singapore 786620

Telephone

Hp: +65 97974285

Type of Claim

Own Damage Claims

Policy No.

2100188177-09

Vehicle No

SCQ 9190 A

..

Audi A4 2.0 TFSI QU

Model Code

Jan-10

Model / Year

CDN 079210

Engine No

: WAUZZZ8K3AA073301

Chassis No

Mileage Date In

.

Liability

.

Excess Cost

. ...

Estimated By

Allan Wu

Accident Date

: 12-Aug-19

Place of Accident

UPPER THOMSON ROAD TOWARDS SLE

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCQ 9190 A

S/N	Nature of Jobs		Estimated Charges		RVEYOR'S COMMENDATION
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$	360.00
2	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,200.00	S	1,200.00
3	To dismantle and renew front bumper, Ihs headlight and bonnet. Renew front lock carrier and align to		\$ 4,550.00	\$	2,250.00
4	To respray front bumper and bonnet.		\$ 2,000.00	\$	1,100.00
5	To carry out diagnostic checks.	S/N	\$ 192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 8,302.00	\$	5,102.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn SCQ 9190 A

				Damage Pa	rts &	Prices
S/N	Parts Description		S	NETT	REM	MARKS
			\$	2,470.00	S	1,976.00
1	FRONT BU		\$	234.00	*	
2	FRONT BUMPER FIXING PARTS		100	802.00		
3	FRONT BUMPER IMPACT BAR		\$			
4	FRONT BUMPER BRACKET - LH		\$	207.00		
5	FRONT BUMPER SUPPORT - LH / RH	2	\$	52.00		
6	FRONT BUMPER GUIDE SECTION - LH		\$	40.00		
7	FRONT BUMPER COVER		\$	116.00	\$	92.40
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Ε	\$	177.00		
9	FRONT BUMPER SPOILER - LOWER		\$	307.00		
10	FRONT BUMPER PULL STRAP - LOWER		\$	47.00		
11	FRONT BUMPER FOAM FILLER PIECE		\$	113.00	\$	90.40
12	FRONT BUMPER VENT GRILLE - LH		\$	123.00		
13	FRONT BUMPER COVER		\$	89.00		
14	CAUTION SIGN	NEC	\$	13.00	\$	9.76
15	AIRCON STICKER	NEC	\$	18.00	\$	14.00
16	SIGNAL HORN - LH HIGH TONE		\$	189.00		
17	SPRING SHACKLE - LH HIGH TONE	2	\$	23.00		
18	RADIATOR GRILLE		\$	644.00	\$	515.60
19	RADIATOR GRILLE COVER		\$	53.00		
20	BONNET		\$	1,788.00		
	SUB TOTAL SPARE PARTS	:	\$	7,505.00	\$	2,698.16
	1.50		_			

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle RegnSCQ 9190 A

			Damage Parts & Prices			
S/N	Parts Description		S	/NETT	REN	MARKS
O/II	Tanto Bosonphion	c/f			\$	2,698.16
21	BONNET ATTACHMENT PARTS		\$	152.00		
22	BONNET EDGE PROTECTION	NEC	\$	50.00	\$	39.84
23	BONNET CATCH HOOK		\$	127.00		
24	BONNET LID LOCK		\$	196.00		
25	LID LOCK CABLE		\$	44.00		
26	MAIN BEAM HEADLIGHT MOUNT - LH		\$	107.00	\$	85.60
27	HEADLIGHT BRACKET - LH		\$	71.00		
28	GAS DISCHARGE LAMP HEADLIGHT - LH		\$	1,989.00		
29	HALOGEN FOG LAMP		\$	238.00		
30	LIFT CYLINDER - LH / RH	2	\$	384.00		
31	LIFT CYLINDER HOSE		\$	36.00		
32	COOLANT RADIATOR LOCK CARRIER		\$	928.00		
33	A/C CONDENSER		\$	677.00	\$	541.60
34	PRESSURE RELIEF VALVE		\$	48.00	\$	37.76
35	PRESSURE SENDER		\$	175.00	\$	140.00
36	CHARGE AIR COOLER		\$	513.00		
37	COOLANT RADIATOR LOCK CARRIER		\$	1,246.00	\$	996.80
38	RUBBER BUSH - UPPER	2	\$	12.00		
39	RADIATOR SUPPORT	2	\$	69.00		
40	COOLANT RADIATOR LOCK CARRIER	4	\$	84.00	\$	67.20
	SUB TOTAL SPARE PARTS	1	\$	14,651.00	\$	4,606.96

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle RegnSCQ 9190 A

				Damage Pa	rts &	Prices
S/N	Parts Description		S	NETT	REN	IARKS
		c/f			\$	4,606.96
41	TWIN FAN RING		\$	237.00		
42	RADATOR AIR GUIDE - LH / RH	2	\$	50.00	\$	19.60
43	RADIATOR SEALING STRIP		\$	21.00		
44	RADIATOR FAN		\$	779.00		
45	RADIATOR FAV		\$	673.00		
46	RADIATOR FAN CONTROL UNIT		\$	778.00		
47	FRONT NO. PLATE	S/N	\$	40.00	\$	40.00
48	Added parts - see attached		\$	72.00	\$	56.32
49	SUNDRIES		\$	400.00	\$	34.56
	TOTAL SPARE PARTS	4	\$	25,206.00	\$	4,757.44
	TOTAL LABOUR CHARGES	:	\$	8,302.00	\$	5,102.00
	GRAND TOTAL	:	\$	33,508.00	\$	9,859.44

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

8 Shenton 07-16 AIG ingapore 0 ttn: Mr. Ac	Building	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0971/2019/NS 6-Sep-19 Glory Tan 1 of 1 SCQ 9190 A Audi A4 2.0 TFSI QU			Amount \$ 43.28 \$ 13.04 \$ 56.32	
Quantity	Description		Un	it Price	- 1	Amount	
Parts 1 2	Headlight securing element External temperature bracket	(anch.	\$	55.00 17.00	\$	43.28 13.04	
			\$	72.00	\$	56.32	
	1000 A A A A A A A A A A A A A A A A A A	TOTAL	\$	72.00	\$	56.32	

For Premium Automobiles Pte Ltd

Authorised Signature

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SCQ 9190 A Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept

25th February 2020

PA/OD/0971/2019/NH

from

Telephone +65-Telefax +65-

EMail

Our department Our Ref Your Ref

Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SCQ 9190 A, Audi A4 2.0 TFSU QU.

With reference to the above-mentioned vehicle, no. SCQ 9190 A, claimant, Mr. Goh Yong Keng, please find the related document per attached.

- 1. A copy of the Original invoice no. 85014889 S\$ 5,564.00.
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encl AIG - SCQ 9190 A Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore

Main Telefax 6471 3733

281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Alexandra Service Centre 281 Alexandra Road Singapore 159938

Main Telephone 6388 2223 Main Telefax 6475 1023 **Ubi Service Centre**

55 Ubi Road 1 Singapore 408699

Main Telephone 6388 2323 Main Telefax 6841 1183

Customer Service

Service Appointment 24-hour Breakdown Service

6366 2323 9828 1233

Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1

14:50

Company Reg. No. 199902271W

GST Reg.No.199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING 78 SHENTON WAY

#07-16

SINGAPORE 079120 079120

Invoice:

Date :

Order:

Term:

85014889 24/02/2020

SCQ9190A

Account : A0006

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY #07-16

SINGAPORE 079120

Regn No: SCQ9190A (V 11242)

Regn Date: 29/01/2010

30

Mileage: 183863

WIP No: 63805

Model: A4 2.0 TFSI QU 8K206Y

Chassis: WAUZZZ8K3AA073301

Engine: CDN 079210

DEPT: U

You have been assisted by:-UB-Tony Foong

(33)

		Details	Qty	Unit Price	Amount
S	SUBLET	To carry out contractual LIMIT repair basis as agreed	6,000.00	1.00	6,000.00
Q	EXC	Insurance Excess/Liability	-800.00	1.00	-800.00

0.00 Parts 0.00 Labour Sublet 6,000.00 0.00 Menus Lubricant 0.00

5,200.00 Sub-Total 364.00 7% GST

5,564.00 **Grand Total**

Received by

For & on behalf of Premium Automobiles Pte Ltd

Telefax

to AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Motor Claims Dept Yr Ref: SCQ9190A Norah Khai 6768 9828 6841 1183

Body Repair

from Telephone +65-

Telefax +65-

Mobile +65-

Our department Your Claim Ref

PA/OD/0971/2019/TF 2 September 2019 Our Ref Date

.

total pages

Showroom

9 Leng Kee Road Singapore 159090

55 Ubi Road 1 Singapore 408699

Premium Automobiles Pte Ltd

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres

Telephone (65) 6366 2323 Telefax (65) 6841 1183

RE: CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model

Audi A4 2.0 TFSI QU

Vehicle Chassis No. :

WAUZZZ8K3AA073301

Vehicle Regn No.

SCQ9190A

Vehicle Mileage

1 83863 KM

Vehicle Owner

Mr. Goh Yong Keng

Certificate No

2100188177-09

Own Damage Excess :

\$856.00.00 (Inclusive GST)

Accident Date

12/08/2019

Place

ss 5564.00

Repair Cost WIP No.

20

:

63805

Repairer's Name

Premium Automobiles Pte Ltd

Upper Thomson Road Towards SLE

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature

Time

:

:

Date

20/9/19

DISCHARGE VOUCHER- AIG - SCQ9190A

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Subr	mitted 1	ns Auth'ed	Status			
	16 Aug 2019 16:32		16 Aug 2019 15:13 Edit Adj Rpt	S\$6,000.00 Edit Estimate	200	\$\$6,000 View Rp	THE PROPERTY OF		Pending for Surve Report Cancel Case		/ey	
M	tain	Re	ference	C	laim [Details		Document	s] <u>s</u>	how All	
CLAIM SU	FOLDER DE	TAILS		and the Walter St.		ALCOHOLD DE	[Created	by insurer]	CONTRACTOR OF STREET	JACOBIA MANAGONIA	Call Confession	
Insured:	GOH YON	G KENG, ID: S1	216828D, Tel:	+6597974825	5							
Vehicle Reg. No.:	SCQ919	0A			Date	of Loss:	12/08/201 [114 Mont	9 16:00 - :59 hs and 14 Days I	From LTA	Reg Date	(Man Yr)]	
Claim Type:	OD / 17	88924970SG				y/Cover No.:	21001881	8177-09 (Comprehensive)				
	70				Exce		S\$800.00					
Repairer:	Premium	Automobiles Pte	Ltd (UBI) 55 L	Jbi Road 1, 40	8699	Ubi - Tel:	67689828/	9827/9911				
Handling Insurer:	Deebanair	Pacific Insuranc adaraja.Nadaraja(@aig.com									
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	. [Han	dled by	ADRIAN LI	NG] [Final R	pt due	27/08/20	019]	
Driver/Custo dian:	GOH HUI	YI (30 / Female) ,	NRIC: S88510	77A, Tel: +6	65979	74285 En	nail: GOHHY	/I@GMAIL.COM				
ASSOCIAT	ED MAIL RE	CEIVED							iew All	Compose	Case Mail	
AIG_SG AIG_SG	23/08/2019) 23/08/2019)	: Alert - Adj Man : SCQ9190A / OI	date Approved 0 / 12/08/201	(S\$6000.00 9 / Coverage) - SC e & Ex	Q9190A cess up	- Claim Ha date	ndler: Nadaraja	, D			
ALL ASSO	CIATED TAS	SKS [□]					View All	Search Tasks	Create N	ew Task	Complete	
Due Date	Priority	Type Task	Group Sub	ject Hand	ler	Assign	ed By	Completed On	Cre	ated On	Done	

Claim Documents

*SCQ9190A (1788924970SG)
OD
Aug 12 2019 4:00PM
[GOH YONG KENG]
Premium Automobiles Pte Ltd

Upl	load Documents Upk	ad Photos Compose New Letter Upload Video Upload Audio	View	View in Brow	
Ass	essment Reports		1 per	4	•
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/08/19 16:36	Adjuster Immediate Advice	0	Load HTM	
Pho	otos/Images		3 per	page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	and the latest department of the latest depart
1	16/08/19 16:13	General View	0	Load JPG	•
2	16/08/19 16:13	General View	0	Load JPG	•
3	16/08/19 16:13	General View	0	Load JPG	✓
4	16/08/19 16:13	General View	0	Load JPG	•
5	16/08/19 16:13	General View	0	Load JPG	•
6	16/08/19 16:13	General View	0	Load JPG	•
7	16/08/19 16:13	General View	0	Load JPG	•
8	16/08/19 16:13	General View	0	Load JPG	S
9	16/08/19 16:13	General View	0	Load JPG	•
10	16/08/19 16:13	General View	0	Load JPG	•
11	16/08/19 16:13	General View	0	Load JPG	•
12	16/08/19 16:13	General View	0	Load JPG	€
13	16/08/19 16:13	General View	0	Load JPG	•
14	16/08/19 16:13	General View	0	Load JPG	•
15	16/08/19 16:13	General View	0	Load JPG	
16	16/08/19 16:13	General View	0	Load JPG	•
17	16/08/19 16:13	General View	0	Load JPG	€
18	16/08/19 16:13	General View	0	Load JPG	•
19	16/08/19 16:13	General View	0	Load JPG	•
20	16/08/19 16:13	General View	0	Load JPG	V
21	16/08/19 16:13	General View	0	Load JPG	•
22	06/02/20 10:50	Reinspection Photo	0	Load JPG	•
23	06/02/20 10:50	Reinspection Photo	0	Load JPG	•
24	06/02/20 10:50	Reinspection Photo	0	Load JPG	•
25	06/02/20 10:50	Reinspection Photo	0	Load JPG	•
26	06/02/20 10:50	Reinspection Photo	0	Load JPG	•
27	06/02/20 10:50	Reinspection Photo	0	Load JPG	•
28	06/02/20 10:50	Reinspection Photo	0	Load JPG	•
29	06/02/20 10:50	Reinspection Photo	0	Load JPG	•
30	06/02/20 10:50	Reinspection Photo	0	Load JPG	•
31	06/02/20 10:50	Reinspection Photo	0	Load JPG	•
32	06/02/20 10:50	Reinspection Photo	0	Load JPG	•
33	06/02/20 10:50	Reinspection Photo	0	Load JPG	•

Asse	essment Reports		1 per page ▼	
Vo	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	ASSESSMENT OF THE PARTY NAMED IN
34	06/02/20 10:50	Reinspection Photo	■ Load JPG	€
35	06/02/20 10:50	Reinspection Photo	1 Load JPG	✓
36	06/02/20 10:50	Reinspection Photo	1 Load JPG	€
	(2-2 CO 10 C	Reinspection Photo	● Load JPG	•
37	06/02/20 10:50		1 Load JPG	•
38	06/02/20 10:50	Reinspection Photo	♠ Load JPG	•
39	06/02/20 10:50	Reinspection Photo	1 Load JPG	-
40	06/02/20 10:50	Reinspection Photo		2000
41	06/02/20 10:50	Reinspection Photo		
42	06/02/20 10:50	Reinspection Photo	1 Load JPG	3 6 6
43	06/02/20 10:50	Reinspection Photo	6 Load JPG	
44	06/02/20 10:50	Reinspection Photo	1 Load JPG	-
45	06/02/20 10:50	Reinspection Photo	1 Load JPG	
46	06/02/20 10:50	Reinspection Photo	♠ Load JPG	
47	06/02/20 10:50	Reinspection Photo	1 Load JPG	. 🗷
		Reinspection Photo	♠ Load JPG	· 🗷
48	06/02/20 10:50		● Load JPG	
49	06/02/20 10:50	Reinspection Photo	1 Load JPG	4000
50	06/02/20 10:50	Reinspection Photo	1 Load JPG	6790
51	06/02/20 10:50	Reinspection Photo		100
52	06/02/20 10:50	Reinspection Photo	① Load JPG	
53	06/02/20 10:50	Reinspection Photo	1 Load JPG	3 377
54	06/02/20 10:50	Reinspection Photo	1 Load JPG	
55	06/02/20 10:50	Reinspection Photo	1 Load JPG	
56	06/02/20 10:50	Reinspection Photo	1 Load JPG	9
57	06/02/20 10:50	Reinspection Photo	1 Load JPG	3
58	06/02/20 10:50	Reinspection Photo	1 Load JPG	i 🗹
59	06/02/20 10:50	Reinspection Photo	1 Load JPG	3
	_	Reinspection Photo	1 Load JPC	s 😢
60	06/02/20 10:50		⑥ Load JPC	G 🗹
61	06/02/20 10:50	Reinspection Photo	1 Load JPC	Comm.
62	06/02/20 10:50	Reinspection Photo		
63	06/02/20 10:50	Reinspection Photo		
64	06/02/20 10:50	Reinspection Photo	1 Load JPC	
65	06/02/20 10:50	Reinspection Photo	1 Load JPC	_
66	06/02/20 10:50	Reinspection Photo	1 Load JPC	20 10 100
67	06/02/20 10:50	Reinspection Photo	1 Load JPC	G 🗹
	- Addition		The state of the s	•
Do	cumentation		1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1 Load PD	
1	16/08/19 16:12	SG CAR MART LOG CARD	1 Load PD	-
2	16/08/19 16:12 16/08/19 16:12	Certificate of Insurance	1 Load PD	
4	16/08/19 16:12	Driver's Driving License	1 Load PD	F
5	16/08/19 16:12	Singapore Accident Statement	● Load PD	F
6	22/08/19 09:29	INTERVIEW FORM	0 Load PD	
7	22/08/19 09:29	UNDERTAKING LETTER	1 Load PD	_
8	23/08/19 14:27	ESTIMATE	1 Load PD	_
9	03/03/20 15:45	DISCHARGE VOUCHER	1 Load PD	-
10	03/03/20 15:45	SUPPLEMENTARY	6 Load PD	
11	03/03/20 15:45	WORKSHOP INVOICE	1 Load PD	

Linked Accident Report Documents

- -

)20		Mermen e-Claims	View	View in Brow	rser ▼
Ass	essment Reports		1 per	page 🔻	•
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	04/09/19 02:19	Accident Statement	0	Load HTM	
n	/*		3 per	page ▼	•
100000	tos/Images	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
No	Finalized On 13/08/19 16:28	Accident Photo	0	Load JPG	•
2	13/08/19 16:28	Accident Photo	0	Load JPG	•
3	13/08/19 16:28	Accident Photo	0	Load JPG	•
		Accident Photo	0	Load JPG	•
4	13/08/19 16:28	Accident Photo	0	Load JPG	•
5	13/08/19 16:28	Accident Photo	0	Load JPG	•
6	13/08/19 16:28		0	Load JPG	•
7	13/08/19 16:28	Accident Photo	0	Load JPG	•
8	13/08/19 16:28	Accident Photo	ő	Load JPG	Ø
9	13/08/19 16:28	Accident Photo	ő	Load JPG	•
10	13/08/19 16:28	Accident Photo	o	Load JPG	•
11	13/08/19 16:28	Accident Photo	ŏ	Load JPG	•
12	13/08/19 16:28	Accident Photo	0	Load JPG	•
13	13/08/19 16:28	Accident Photo	0	Load JPG	•
14	13/08/19 16:28	Accident Photo	o	Load JPG	•
15	13/08/19 16:28	Accident Photo	0	Load JPG	9
16	13/08/19 16:28	Accident Photo	0		2
17	13/08/19 16:28	Accident Photo		Load JPG	•
18	13/08/19 16:28	Accident Photo	0	Load JPG	-
19	13/08/19 16:28	Accident Photo	0	Load JPG	S
20	13/08/19 16:28	Accident Photo	0	Load JPG	2
21	13/08/19 16:28	Accident Photo	0	Load JPG	2
22	13/08/19 16:28	Accident Photo	0		€
23	13/08/19 16:28	Accident Photo	0	Load JPG	•
24	13/08/19 16:28	Accident Photo	0	_	8
25	13/08/19 16:28	Accident Photo	0	_	
26	13/08/19 16:28	Accident Photo	0		€
27	13/08/19 16:28	Accident Photo	0		€
28	13/08/19 16:28	Accident Photo	0	Load JPG	€
Do	cumentation		1 pe	rpage ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnai	-
1	13/08/19 16:39	Sketch Plan	0	Load JPG	•
2	13/08/19 16:39	Sketch Plan #2	0	Load JPG	•

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #08-16 Our File No:

CC3/AIG19014294/ATF3S2

Singapore 079120

Date:

03/03/2020

REFERENCE

Date of Loss:

Insured/Claimant:

GOH YONG KENG

12/08/2019

Policy No:

2100188177-09

Nature of Claim: OD

Claim No:

1788924970SG

WAUZZZ8K3AA073301

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SCQ9190A

Make & Model:

AUDI A4, 2.0 MU TFSI (8E) (A) 29/01/2010 (Man. Year: 2009)

Engine No: Chassis No: Odometer: CDN079210

183862 km

Reg. Date: Colour:

Black

Engine Capacity:

1984 cc

Market Value/New Car Price:

S\$28,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No Pre-accident Condition:

res

CONDITION OF TYRES

Front Tyre Size:

245/40 R18

Rear Tyre Size:

245/40 R18

Front Left Side: Front Right Side: Continental 6 mm Continental 6 mm Rear Left Side: Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,685.32	4,757.44	12,927.88	73.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,302.00	5,102.00	3,200.00	38.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,987.32	9,859.44	16,127.88	62.06
Approved Total (Overridden) (S\$)		6,000.00		
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	25,187.32	5,200.00	19,987.32	79.35
+ GST 7.00/7.00% (S\$)	1,763.11	364.00	1,399.11	79.35
Nett Amount (S\$)	26,950.43	5,564.00	21,386.43	79.35

INSPECTION

Date of Assignment:

16/08/2019

Premium Automobiles Pte Ltd (UBI)

Date Inspected:

16/08/2019

Inspected At:

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

6.0 days

Adjuster: ADRIAN LING

Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printrpt&caseid=854521&extid=313655&CFID=68082263&C... 1/5

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

No.	Qty Pa	nended Parts art No. Particulars	Condition	Repairer's	Amount
		*FRONT BUMPER	Distorted	2,470.00 FS	*1,976.00 FS
1	1	*FRONT BUMPER FIXING PARTS	Not Necessary	234.00 FS	*-FS
2	1	*FRONT BUMPER IMPACT BAR	Not Necessary	802.00 FS	*-FS
3	1	*FRONT BUMPER BRACKET - LH	Not Necessary	207.00 FS	*-FS
4	1	*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	52.00 FS	*-FS
5	2		Not Necessary	40.00 FS	*-FS
6	1	*FRONT BUMPER GUIDE SECTION - LH	Cracked	116.00 FS	*92.40 FS
7	1	*FRONT BUMPER COVER	Not Necessary	177.00 FS	*-FS
8	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	307.00 FS	*-FS
9	1	*FRONT BUMPER SPOILER - LOWER	Not Necessary	47.00 FS	*-FS
10	1	*FRONT BUMPER PULL STRAP - LOWER	Torn	113.00 FS	*90.40 FS
11	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*-FS
12	1	*FRONT BUMPER VENT GRILLE - LH		89.00 FS	*-FS
13	1	*REINFORCEMENT BEAM COVER	Not Necessary	13.00 FS	*9.76 FS
14	1	*CAUTION SIGN	Necessary	18.00 FS	*14.00 FS
15	1	*AIRCON STICKER	Necessary		*-FS
16	1	*SIGNAL HORN - LH HIGH TONE	Not Necessary	189.00 FS	*-FS
17	2	*SPRING SHACKLE - LH HIGH TONE	Not Necessary	23.00 FS	*515.60 FS
18	1	*RADIATOR GRILLE	Cracked	644.00 FS	
19	1	*RADIATOR GRILLE COVER	Not Necessary	53.00 FS	*-FS
20	1	*BONNET	Repair	1,788.00 FS	*-FS
21	1	*BONNET ATTACHMENT PARTS	Not Necessary	152.00 FS	*-FS
22	1	*BONNET EDGE PROTECTION	Necessary	50.00 FS	*39.84 FS
23	1	*BONNET CATCH HOOK	Not Necessary	127.00 FS	*- FS
24	1	*BONNET LID LOCK	Not Necessary	196.00 FS	*- FS
25	1	*LID LOCK CABLE	Not Necessary	44.00 FS	*-FS
26	1	*MAIN BEAM HEADLIGHT MOUNT - LH	Not Necessary	107.00 FS	*85.60 FS
27	1	*HEADLIGHT BRACKET - LH	Not Necessary	71.00 FS	
28	1	*GAS DISTANCE LAMP HEADLIGHT - LH	Not Necessary	1,989.00 FS	*-F8
29	1	*HALOGEN FOG LAMP	Not Necessary	238.00 FS	*-F8
30	2	*LIFT CYLINDER - LH / RH	Not Necessary	384.00 FS	*-F8
31	1	*LIFT CYLINDER HOSE	Not Necessary	36.00 FS	*-F8
32	1	*COOLANT RADIATOR LOCK CARRIER	Not Necessary	928.00 FS	*-F8
33	1	*A/C CONDENSER	Distorted	677.00 FS	*541.60 FS
34	1	*PRESSURE RELIEF VALVE	Damaged	48.00 FS	*37.76 FS
	39	*PRESSURE SENDER	Damaged	175.00 FS	*140.00 FS
35	1	*CHARGE AIR COOLER	Not Necessary	513.00 FS	
36	1	*RADIATOR GRILLE	Cracked	1,246.00 FS	
37	1	*RUBBER BUSH - UPPER	Not Necessary	12.00 FS	
38	2	*RADIATOR SUPPORT	Not Necessary	69.00 FS	
39	2	*COOLANT	Necessary	84.00 FS	
40	4		Not Necessary	237.00 FS	
41	1	*TWIN FAN RING	Cracked	50.00 FS	
42	2	*RADIATOR AIR GUIDE - LH / RH	Not Necessary	21.00 FS	
43	1	*RADIATOR SEALING STRIP	Not Necessary	779.00 FS	8 8 8 2 8
44	1	*RADIATOR FAN	Not Necessary	673.00 FS	
45	1	*RADIATOR FAV	Not Necessary	778.00 FS	it(1) Ei
46	1	*RADIATOR FAN CONTROL UNIT	•	40.00 FS	
47	1	*FRONT NO. PLATE	Necessary		
48	1	*SUNDRIES	Necessary	400.00 FS	
49	1	*HEADLIGHT SECURING ELEMENT	Cracked	43.28 FS	
50	1	*EXTERNAL TEMPERATURE BRACKET	Cracked	13.04 FS	*13.04 F

Report was unsubmitted during this print-out.

No. Qty Part No. Particulars

Condition

Repairer's

Amount

Total Parts (S\$)

17,685.32

4,757.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Re	commended Labour			
No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items		202.00	360.00
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	0.0000000000000000000000000000000000000
2	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New S.	1,200.00	1,200.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS HEADLIGHT AND BONNET, RENEW FRONT LOCK CARRIER.	New	4,550.00	2,250.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
	Gross Labor	ur Cost (S\$)	8,302.00	5,102.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >