

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 19 Aug 2019

Preliminary Advice

Vehicle No	: SLK2353T	Accident Date	: 15/08/2019
Make	: TOYOTA COROLLA ALTIS	Policy No.	: A28881428QMY
Assignment Date	: 16/08/2019	Excess	: S\$800.00
Date of Inspection	: 16/08/2019	Est. Duration of Repair	: -
Inspection At	: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 70,220.00
Revised Amount	:S\$ TOTAL LOSS
Check Items (Estimated)	:S\$ 0.00
Total	:S\$ TOTAL LOSS
 Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 74,000.00
COE / PARF Rebate	:S\$ 52,015.00
Salvage Value	:S\$
Margin for Repair	:S\$ 21,985.00

Remarks

- (X) The vehicle is not economical for repair. Vehicle recommended total loss due to uneconomical for repair.
- () The above survey was conducted on a 'without prejudice' basis.