

INS. CASE OWNER: LOH CHEE HENG

CC4/AIG19014303/Uha352

LKK:  
IDAC:

## ASSIGNMENT

Surveyor:

MARCUS

DOI: 16/08/2019

Date / Time: 16/08/2019

Registered in Merimen: 16/08/2019

Pre-assign / CCU / FTE



Insured Vehicle No.: SMJ 2236S

Claim No.: 8084555646SG

Name of Insured: SECK LING LING, MELISSA

Policy No.: 1900020109

Insured Tel No.: HP: +65-92785766

Make / Model:

Excess Sec II :S\$

D.O.A.: 09/06/2019 11:45

Place of Accident: CTE BEFORE BUKIT TIMAH EXIT

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L) YES / NO

Insured Liability: % Final ? Yes / No

FBE 3642C

INSRS:  
WSP: BAN HOCK HIN  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time		STAGE	DATE / PIC
	FBE 3642C - X	Non-Reporting ltr (1st):	
	SMJ 2236S - CC6/AIG19010141/Uhb3 : DOA: 09/6/19	Non-Reporting ltr (2nd):	
18/06/19	- JIMMY SPOKE TO OI. INFORMED OF TP CLAIM & NCD ISSUES.	Non-Reporting ltr (Final):	
	- VIDEO FOOTAGE UPLOADED IN ATTACHMENT	Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	21/08/19 - VIC
12/09/19	- AIG INSTRUCTED TO REPAIR TP CLAIM TO INSURER OF FENGHAT (MTC) UNDER BOLA 28(C).	Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/>
		Towing Invoice	<input type="checkbox"/>
		LTA / GIA:	<input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
22/10/19	- EMAIL TO TP TO INFORM THE CASE FILED IN. AGAINST OI	PIR: AGAINST OI	<input checked="" type="checkbox"/>
	- EMAIL TO AIG FOR INSTRUCTION	Mandate/Reject Instruction:	<input type="checkbox"/>
	- AIG MAINTAIN BOLA 28. REPAIR TP CLAIM.	LOD	<input type="checkbox"/>
	- TP LOD IN. FINAL RECD.	Payment Breakdown Form:	<input type="checkbox"/>
09/08/2020	- TP WITHDRAWN CLAIM. OWNER PAY CASH.	Post-Repair Photos:	<input type="checkbox"/>
	- EMAIL TO AIG TO CLOSE & EVENT WP REPORT	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time:

Sent By:

## FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: L/S

S\$ 2,500.00 ( 4 days) Reduction: %

Email ☐ Call ☐

## FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

—

COI COMPLETED TO TP

Loss of Rental (LOR):

S\$

—

( days)

Loss of Use (LOU):

S\$

—

(\$ x days)

Loss of Income (LOI):

S\$

—

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOU ☐

(Tick only one)

GIA/LTA Search

S\$

—

Medical:

S\$

—

1) Claim status: Normal/Reject/Private Settle

Disbursement:

S\$

—

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

S\$

—

3) Survey fee:

\$290.00

Total:

S\$

—

Global Sum S\$:

## FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

—

Name 1:

—

Payee 2: (Strike if N.A.)

S\$

—

Name 2:

—

Payee 3: (Strike if N.A.)

S\$

—

Name 3:

—

COPY SENT  
9/3/2020



### Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBE3642C		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	SUZUKI		
Vehicle Model :	GSR400 M		
Chassis No. :	GK7DA103050		
Propellant :	Petrol		
Engine No. :	K719103084		
Engine Capacity :	398 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	320 kg		
Unladen Weight :	210 kg		
Year Of Manufacture :	2008		
Original Registration Date :	12 Mar 2010		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$1,001.00		
COE Expiry Date :	11 Mar 2020		
Road Tax Expiry Date :	11 Mar 2020		
Inspection Due Date :	11 Mar 2020		
Intended Transfer Date :	09 Jul 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	579I
<b>Vehicle Details</b>	
Vehicle No.:	FBE3642C
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Aug 2019
Vehicle Make:	SUZUKI
Vehicle Model:	GSR400 M
Primary Colour:	Blue
Secondary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	K719103084
Chassis No.:	GK7DA103050
Maximum Power Output:	-
Open Market Value:	\$10,629.00
Original Registration Date:	12 Mar 2010
First Registration Date:	12 Mar 2010
Transfer Count:	1
Actual ARF Paid:	\$1,595.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	11 Mar 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,001.00
COE Rebate Amount:	\$56.00
<b>Total Rebate Amount:</b>	<b>\$56.00</b>

The information contained herein is correct as at 16 Aug 2019

OK



**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

NO. : 34395

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120  
Motor Claims Dept

DATE : 08/07/2019  
CLAIM NO : 11375  
POLICY NO :

FROM : RAYMOND

VEHICLE NO : FBE3642C  
MAKE/MODEL : SUZ / GSR400M

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE REAR	REPLACE	1.00	\$147.00	147.00 X
2	BALANCER	REPLACE	1.00	\$42.00	42.00
3	BALANCER HANDLE P/N: 40721	REPLACE	1.00	\$122.00	122.00 X
4	BAR HANDLE P/N: 40104	REPLACE	1.00	\$138.00	138.00
5	BAR PILLION FOOTREST LH P/N: 54144	REPLACE	1.00	\$48.00	48.00 X
6	BEARING STEERING CONE P/N: 44475	REPLACE	2.00	\$84.00	168.00
7	BOLT LEVER PIVOT	REPLACE	1.00	\$14.00	14.00
8	BOLT TANK SENSOR P/N: 44458	REPLACE	1.00	\$9.00	9.00 X
9	BRACKET FOOTREST LH P/N: 51651	REPLACE	1.00	\$475.00	475.00
10	BRACKET HEADLAMP P/N: 51640	REPLACE	1.00	\$178.00 X	178.00 X
11	BRACKET REAR	REPLACE	1.00	\$21.00	21.00
12	BRACKET UNDER	REPLACE	1.00	\$600.00	600.00 X
13	BUSH SWINGARM P/N: 58506	REPLACE	2.00	\$38.00	76.00 X



biSAFE<sub>3</sub>



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 200214093  
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	CABLE CLUTCH P/N: 58513	REPLACE	1.00	\$48.00	48.00 X
15	COVER METER LOWER	REPLACE	1.00	\$80.00	80.00
16	COVER MUFFLER RH	REPLACE	1.00	\$143.00	143.00 X
17	COVER SPEEDOMETER	REPLACE	1.00	\$105.00	105.00
18	COVER STEERING CONE	REPLACE	1.00	\$28.00	28.00
19	COVER TAIL ASSY	REPLACE	1.00	\$625.00	625.00 ✓
20	COVER TANK SIDE LH(SILVER)	REPLACE	1.00	\$220.00	220.00 X
21	EMBLEM ABS	REPLACE	2.00	\$14.00	28.00
22	EMBLEM GSR	REPLACE	2.00	\$28.00	56.00
23	EMBLEM SUZUKI	REPLACE	1.00	\$14.00	14.00
24	ENGINE GUARD HEPKO & BECKER	REPLACE	1.00	\$553.00	553.00 X
25	FENDER REAR	REPLACE	1.00	\$118.00	118.00
26	FORK FRONT ASSY LH P/N: 51634	REPLACE	1.00	\$1,388.00	1,388.00 X
27	FORK FRONT ASSY LH P/N: 51632	REPLACE	1.00	\$1,388.00	1,388.00 X
28	FRAME COMPARTMENT	REPLACE	1.00	\$2,286.00	2,286.00 X
29	FRONT MUDGUARD	REPLACE	1.00	\$223.00	223.00
30	HEADLAMP ASSY	REPLACE	1.00	\$476.00	476.00 X
31	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	Supply/Install	32.00	\$35.00	1,120.00
32	LAMP LICENSE PLATE	REPLACE	1.00	\$72.00	72.00
33	LAMP SIGNAL FRONT RH	REPLACE	1.00	\$91.00	91.00 X
34	LAMP SIGNAL REAR LH	REPLACE	1.00	\$112.00	112.00 X

bizSAFE<sub>3</sub>



S/N	Description	Action	Qty	Unit Price	Amount
35	LAMP SIGNAL REAR RH	REPLACE	1.00	\$112.00	112.00
36	LEVER CLUTCH	REPLACE	1.00	\$48.00	48.00
37	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$200.00	200.00
38	MIRROR BLACK SET	REPLACE	1.00	\$48.00	48.00
39	NUT AXLE	REPLACE	1.00	\$20.00	20.00
40	PIN P/N: 54145	REPLACE	1.00	\$5.00	5.00
41	PROTECTOR REAR	REPLACE	1.00	\$165.00	165.00
42	REFLECTOR ASSY	REPLACE	1.00	\$21.00	21.00
43	RUBBER FOOTREST P/N: 44469	REPLACE	1.00	\$34.00	34.00
44	SEAL STEERING UPPER DUST P/N: 44470	REPLACE	2.00	\$12.00	24.00
45	SWING ARM ASSY	REPLACE	1.00	\$2,902.00	2,902.00
46	TAIL LAMP ASSY	REPLACE	1.00	\$356.00	356.00
47	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A P/N: 45835 - TOW BACK BIKE TO WORKSHOP	★	1.00	\$69.00	69.00

SUB TOTAL

\$15,216.00

GST @ 7 %

\$1,065.12

GRAND TOTAL

\$16,281.12

50% deposit required before ordering of parts.

Validity: 30 days

For &amp; on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge &amp; Accepted By

P-2805  
15245  
29555  
2367

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE<sub>3</sub>

Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002 1-0381  
ISO 9001:2015



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K  
MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

NO. : 34395

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120  
Motor Claims Dept

*not added  
sum  
TOTAL 1055?  
16/8/19  
MV \$2500?*

DATE : 08/07/2019  
CLAIM NO. : 11375  
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBE3642C  
MAKE/MODEL : SUZ / GSR400M

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE REAR	REPLACE	1.00	\$147.00	147.00 ?
2	BALANCER	REPLACE	1.00	\$42.00	scr 42.00
3	BALANCER HANDLE P/N: 40721	REPLACE	1.00	\$122.00	scr 122.00
4	BAR HANDLE P/N: 40104	REPLACE	1.00	\$138.00	scr 138.00
5	BAR PILLION FOOTREST LH P/N: 54144	REPLACE	1.00	\$48.00	scr 48.00
6	BEARING STEERING CONE P/N: 44475	REPLACE	2.00	\$84.00	scr 168.00
7	BOLT LEVER PIVOT	REPLACE	1.00	\$14.00	scr 14.00
8	BOLT TANK SENSOR P/N: 44458	REPLACE	1.00	\$9.00	9.00 ?
9	BRACKET FOOTREST LH P/N: 51651	REPLACE	1.00	\$475.00	scr 475.00
10	BRACKET HEADLAMP P/N: 51640	REPLACE	1.00	\$178.00	178.00 X
11	BRACKET REAR	REPLACE	1.00	\$21.00	scr 21.00
12	BRACKET UNDER	REPLACE	1.00	\$600.00	scr 600.00
13	BUSH SWINGARM P/N: 58506	REPLACE	2.00	\$38.00	scr 76.00



*bizSAFE<sub>3</sub>*



Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0380  
ISO 9001: 2015



S/N	Description	Action	Qty	Unit Price	Amount
14	CABLE CLUTCH P/N: 58513	REPLACE	1.00	\$48.00	48.00 X
15	COVER METER LOWER	REPLACE	1.00	\$80.00	80.00
16	COVER MUFFLER RH	REPLACE	1.00	\$143.00	143.00 X
17	COVER SPEEDOMETER	REPLACE	1.00	\$105.00	105.00
18	COVER STEERING CONE	REPLACE	1.00	\$28.00	28.00
19	COVER TAIL ASSY	REPLACE	1.00	\$625.00	625.00
20	COVER TANK SIDE LH(SILVER)	REPLACE	1.00	\$220.00	220.00 ?
21	EMBLEM ABS	REPLACE	2.00	\$14.00	28.00
22	EMBLEM GSR	REPLACE	2.00	\$28.00	56.00
23	EMBLEM SUZUKI	REPLACE	1.00	\$14.00	14.00
24	ENGINE GUARD HEPKO & BECKER	REPLACE	1.00	\$553.00	553.00
25	FENDER REAR	REPLACE	1.00	\$118.00	118.00
26	FORK FRONT ASSY LH P/N: 51634	REPLACE	1.00	\$1,388.00	1,388.00
27	FORK FRONT ASSY LH P/N: 51632	REPLACE	1.00	\$1,388.00	1,388.00 X
28	FRAME COMPARTMENT	REPLACE	1.00	\$2,286.00	2,286.00 ?
29	FRONT MUDGUARD	REPLACE	1.00	\$223.00	223.00
30	HEADLAMP ASSY	REPLACE	1.00	\$476.00	476.00
31	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	Supply/Install	32.00	\$35.00	1,120.00
32	LAMP LICENSE PLATE	REPLACE	1.00	\$72.00	72.00
33	LAMP SIGNAL FRONT RH	REPLACE	1.00	\$91.00	91.00
34	LAMP SIGNAL REAR LH	REPLACE	1.00	\$112.00	112.00

bizSAFE<sub>3</sub>

S/N	Description	Action	Qty	Unit Price	Amount
35	LAMP SIGNAL REAR RH	REPLACE	1.00	\$112.00	112.00 <i>cm</i>
36	LEVER CLUTCH	REPLACE	1.00	\$48.00	48.00 <i>cu7</i>
37	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$200.00	200.00 <i>cu7</i> <i>775.00</i>
38	MIRROR BLACK SET	REPLACE	1.00	\$48.00	48.00 <i>cu7</i>
39	NUT AXLE	REPLACE	1.00	\$20.00	20.00 ?
40	PIN P/N: 54145	REPLACE	1.00	\$5.00	5.00 ?
41	PROTECTOR REAR	REPLACE	1.00	\$165.00	165.00 ?
42	REFLECTOR ASSY	REPLACE	1.00	\$21.00	21.00 <i>320</i>
43	RUBBER FOOTREST P/N: 44469	REPLACE	1.00	\$34.00	34.00 <i>7100</i>
44	SEAL STEERING UPPER DUST P/N: 44470	REPLACE	2.00	\$12.00	24.00 ?
45	SWING ARM ASSY	REPLACE	1.00	\$2,902.00	2,902.00 ?
46	TAIL LAMP ASSY	REPLACE	1.00	\$356.00	356.00 <i>320</i>
47	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A P/N: 45835 - TOW BACK BIKE TO WORKSHOP		1.00	\$69.00	69.00 <i>35</i>

SUB TOTAL

\$15,216.00

GST @ 7 %

\$1,065.12

GRAND TOTAL

\$16,281.12

**50% deposit required before ordering of parts.**

Validity: 30 days

For &amp; on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge &amp; Accepted By

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE<sub>3</sub>

ADDENDUM Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
6 Raffles Quay #18-00 Singapore 048580  
Tel (65) 6224 0010 Fax (65) 6224 0030  
Operating Hours : Monday to Friday, 09:00 – 17:00  
UTN: S65500206 / GST Reg. No.: M400017735

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

**ADDENDUM**

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : MBHH19076325 Vehicle Registration No: FBE3642C  
Name (as shown in NRIC) : HIEW YOKE KONG, MELVIN NRIC/FIN/Passport No : S8036579I  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : \_\_\_\_\_ Singapore ( )  
Contact (Tel) : \_\_\_\_\_ Mobile No. : 96153492  
Email Address : ANGELASHLEY08@HOTMAIL.COM  
Date of Accident : 09/06/2019 Time of Accident : 1145HRS  
Place of Accident : CTE TO AYE  
Insurance Company : DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

AMEND FROM REPORTING ONLY TO 3RD PARTY CLAIM

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

\_\_\_\_\_  
Policyholder / Driver's Signature  
Date:

Joanne Tham  
Reporting Centre Personnel's Signature  
Name: Joanne Tham  
NRIC/FIN No.:  
Date: 19 JUNE 2019

**PRE-REPAIR INSPECTION REQUEST – FBE3642C vs SMJ2236S (OI) on D.O.A.: 09/06/2019**

From: Hor, Yinnul  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni  
Sent: 8/16/2019 1:33:37 PM  
Attachments:  WhatsApp Video 2019-08-02 at 12.31.57 mod  11375 Claim File-1.pdf

Hi,

Please refer to the enclosed request from Ban Hock Hin Co., Pte Ltd.

Claim no : 8084555646SG007  
Case Owner : Loh Chee Heng

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Singapore FNOL | Claims Operations – Auto

[Yinnul.Hor@aig.com](mailto:Yinnul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

4:13pm @ 16/8/19  
vehicle in  
Pasong Raymond  
SRA @ Merus.

---

**From:** raymond@bhh.com.sg [mailto:raymond@bhh.com.sg]  
**Sent:** Friday, August 16, 2019 11:24 AM  
**To:** Hor, Yinnul  
**Cc:** Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Parthiban, Theerthan; Tong, Wahxin; raymond@bhh.com.sg  
**Subject:** RE: PRE-REPAIR INSPECTION - Accident Involving FBE3642C), FBN9445T, GBC9511T), SMJ2236S & SHC242H along CTE twds AYE before Balestier

Dear Viviane,

We are claiming against SMJ2236S.

Thanks & Regards,

Raymond Tan

Ban Hock Hin Co. Pte Ltd

---

**From:** Hor, Yinnul  
**Sent:** Fri, 16 Aug 2019 03:16:49 +0000  
**To:** raymond@bhh.com.sg  
**Cc:** Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Parthiban, Theerthan, Tong, Wahxin  
**Subject:** RE: PRE-REPAIR INSPECTION - Accident Involving FBE3642C), FBN9445T, GBC9511T), SMJ2236S & SHC242H along CTE twds AYE before Balestier

Hi Raymond,

Thank you for the notice of the accident. Noticed that this is a chain-collision accident.  
Kindly advise which vehicle you're claiming against to.

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Singapore FNOL | Claims Operations – Auto

[Yinnul.Hor@aig.com](mailto:Yinnul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Raymond [mailto:raymond@bhh.com.sg]  
**Sent:** Friday, August 16, 2019 10:33 AM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] Accident Involving FBE3642C), FBN9445T, GBC9511T), SMJ2236S & SHC242H along CTE twds AYE before Balestier

This message is from an external sender; be cautious with links and attachments.

Dear Sir / Madam,

We attached the third party claim documents and video footage from the taxi (SHC242H) for your perusal.

Appreciate for you to arrange LKK Auto Consultants Pte Ltd for the pre-repair survey.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



No. 6 Defu Lane 4, Singapore 539410

[www.bhh.com.sg](http://www.bhh.com.sg) / [facebook.com/bhhsg](https://facebook.com/bhhsg)



MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES



#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

FW: PRE-REPAIR INSPECTION - Accident Involving FBE3642C), FBN9445T, GBC9511T), SMJ2236S & SHC242H along CTE twds AYE before Balestier

From: Hor, Yinnul  
To: 'assignments@kkauto.com', Admin A (admin-a@kkauto.com)  
Cc: raymond@bhh.com.sg  
Sent: Tuesday, 20 August, 2019 4:05:11 PM

Dear LKK,

AIG VRN: SMJ2236S  
TP VRN: FBE3642C

TP workshop is requesting liability status.  
Kindly assist on this and revert back to Mr Raymond.

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.  
Tel: 8001206558 | Ext: 1002208  
[Yinnul.Hor@aig.com](mailto:Yinnul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

10:20am @ 21/8/2019  
vehicle in  
person @ Raymond  
SR @ menus

From: raymond@bhh.com.sg [mailto:raymond@bhh.com.sg]

Sent: Tuesday, August 20, 2019 3:58 PM

To: raymond@bhh.com.sg; Hor, Yinnul

Cc: Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Parthiban, Theerthan; Tong, Wahxin

Subject: RE: PRE-REPAIR INSPECTION - Accident Involving FBE3642C), FBN9445T, GBC9511T), SMJ2236S & SHC242H along CTE twds AYE before Balestier

Dear Viviane,

Appreciate for you to advise your insured liability for direct settlement.

Thanks & Regards,

Raymond

From: raymond@bhh.com.sg

Sent: Fri, 16 Aug 2019 03:24:20 +0000

To: Yinnul.Hor@aig.com

Cc: NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashni.Subramaniam@aig.com, Theerthan.Parthiban@aig.com, Wahxin.Tong@aig.com, raymond@bhh.com.sg

Subject: RE: PRE-REPAIR INSPECTION - Accident Involving FBE3642C), FBN9445T, GBC9511T), SMJ2236S & SHC242H along CTE twds AYE before Balestier

Dear Viviane,

We are claiming against SMJ2236S.

Thanks & Regards,

Raymond Tan



Ban Hock Hin Co. Pte Ltd

**From:** Hor, Yinrul  
**Sent:** Fri, 16 Aug 2019 03:16:49 +0000  
**To:** raymond@bhh.com.sg  
**Cc:** Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Parthiban, Theerthan, Tong, Wahxin  
**Subject:** RE: PRE-REPAIR INSPECTION - Accident Involving FBE3642C), FBN9445T, GBC9511T), SMJ2236S & SHC242H along CTE twds AYE before Balestier

Hi Raymond,

Thank you for the notice of the accident. Noticed that this is a chain-collision accident.  
 Kindly advise which vehicle you're claiming against to.

Thanks & Regards,

Hor Yin Rul (Viviane)  
 AIG  
 FNOL Adjuster I  
 Singapore FNOL | Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

**From:** Raymond [mailto:raymond@bhh.com.sg]  
**Sent:** Friday, August 16, 2019 10:33 AM  
**To:** AIG SGP, Claims-Survey  
**Subject:** [EXTERNAL] Accident Involving FBE3642C), FBN9445T, GBC9511T), SMJ2236S & SHC242H along CTE twds AYE before Balestier

This message is from an external sender; be cautious with links and attachments.

Dear Sir / Madam,

We attached the third party claim documents and video footage from the taxi (SHC242H) for your perusal.

Appreciate for you to arrange LKK Auto Consultants Pte Ltd for the pre-repair survey.

Thanks

Best Regards,  
 Raymond  
 Ban Hock Hin Co., Pte Ltd  
 Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969  
 Visit us at <http://www.bhh.com.sg>  
 Facebook: <http://www.facebook.com/bhhsg>



No. 6 Defu Lane 4, Singapore 539410

[www.bhh.com.sg](http://www.bhh.com.sg) / [facebook.com/bhhsg](https://www.facebook.com/bhhsg)



MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES



#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## LETTER OF AUTHORISATION

Your Ref : SMJ2236S  
Our Ref : TP/11375/FBE3642C/SMJ2236S

BY FAX & HAND

**AIG Asia Pacific Insurance Pte Ltd**  
**Chartis Building**  
**78 Shenton Way**  
**#07-16**  
**Singapore 079120**

**ATTN : Motor Claims Dept**

Dear Sir/Madam,

**Accident Involving FBE3642C, FBN9445T, GBC9511T, SMJ2236S & SHC242H  
along CTE towards AYE before Balestier on 09/06/2019**

### AUTHORIZATION LETTER

I / We refer to the above-mentioned matter.

I / We, Hiew Yoke Kong, Melvin hereby irrevocably authorize Ban Hock Hin Co Pte Ltd to act on our behalf to file a 3<sup>rd</sup> Party Claim against your insured SMJ2236S.

I / We further authorize M/s **AIG Asia Pacific Insurance Pte Ltd** to release the claim and payment to M/s Ban Hock Hin Co., Pte Ltd in consideration of their allowing me to take possession of my motorcycle FBE3642C upon completion of repairs.

If you need any verification from us, kindly direct all enquiries and correspondences to M/s Ban Hock Hin Co., Pte Ltd.

Yours faithfully

Witness

.....  
Claimant (Signature & Company Stamp)

.....  
Witness Signature

Hiew Yoke Kong, Melvin / S8036579I

Tan Chok Lok / G7715235R

.....  
Name & NRIC No

.....  
Name & NRIC No

6

**RELEASE VOUCHER**  
**(AIG Express Third Party Claim)**

"We/I, Ban Hock Hin Co. Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 2,461.00 (Repair Cost), S\$ 80.00 (Loss of rental/use), S\$ - (Disbursement), for vehicle no. FBE3642C that was damaged pursuant to the accident which occurred on 09/06/2019 (date) along CTE TO AYE (location) involving vehicle no/s SMJ 22366.  
This is pursuant to the inspection conducted on \_\_\_\_\_ (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Hiew Yoke Kong, Melvin ("the third party claimant") of vehicle no. FBE 3642C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to FBE 3642C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10<sup>th</sup> (day) of October (month) 2019 (year)

\_\_\_\_\_  
Signed by appointed surveyor

  
Signed by "the workshop" (with chop)



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## TAX INVOICE

GST Reg No. : M2-0010542-7

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120  
Motor Claims Dept

Invoice No. : **DLCR40102105-I11375**  
Invoice Date : 07/10/2019  
Payment Due Date : 06/11/2019

CLAIM NO. : 11375  
POLICY NO. :  
VEHICLE NO. : FBE3642C  
MAKE/MODEL : SUZ / GSR400M

S/N	Description	Amount
1	LUMPSUM REPAIR	\$2,300.00
SUB TOTAL		\$2,300.00
GST @ 7 %		\$161.00
GRAND TOTAL		<b>\$2,461.00</b>

Validity: 30 days

For & on Behalf of

**BAN HOCK HIN CO PTE LTD**

Printed by : RAYMOND

*bizSAFE<sub>3</sub>*



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jun 2019 <a href="#">Edit Reg</a>		16 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	<b>SECK LING LING, MELISSA</b> , Co. Reg. No.: -		
Main Claimant:	<b>HIEW YOKE KONG, MELVIN</b> , ID: S80365791		
Vehicle Reg. No.:	<b>FBE3642C</b>	Date of Loss:	09/06/2019 11:00 - :59 [110 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 8084555646SG</b>	Policy/Cover Note No.:	1900020109 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SMJ2236S</b>	Policy No. (Claimant):	MC/00607756
		Excess:	
Repairer:	<b>Ban Hock Hin Co. Pte Ltd (HQ)</b> No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	<b>Direct Asia Insurance (Singapore) Pte Ltd (HQ)</b> - Tel: 65322888		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 27/08/2019]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





## Claim Documents

**\*FBE3642C (8084555646SG)**  
**[SMJ2236S]**

**TP**
















































**HIEW YOKE KONG, MELVIN**

**Jun 9 2019 11:00AM**

**[SECK LING LING, MELISSA]**

**Ban Hock Hin Co. Pte Ltd**

<a href="#">Upload Documents</a>			<a href="#">Upload Photos</a>			<a href="#">Compose New Letter</a>			<a href="#">Upload Video</a>			<a href="#">Upload Audio</a>			<b>View</b>			<a href="#">View in Browser</a> ▼		
<b>Video</b>															1 per page ▼			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print			
1	16/08/19 16:06		Video - Accident														Load MP4			
<b>Assessment Reports</b>															1 per page ▼			<input checked="" type="checkbox"/>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail			Print			
1	19/08/19 14:24		Accident Statement From:OD - Reg. No: SMJ2236S, Claimant: SECK LING LING, MELISSA														Load HTM			
<b>Photos/Images</b>															3 per page ▼			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print			
1	16/08/19 18:52		Chassis Number														Load JPG <input checked="" type="checkbox"/>			
2	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
3	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
4	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
5	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
6	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
7	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
8	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
9	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
10	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
11	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
12	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
13	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
14	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
15	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
16	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
17	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
18	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
19	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
20	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
21	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
22	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
23	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
24	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
25	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
26	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
27	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			
28	16/08/19 18:55		General View														Load JPG <input checked="" type="checkbox"/>			

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
30	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
31	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
32	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
33	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
34	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
35	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
36	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
37	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
38	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
39	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
40	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
43	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
44	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
46	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
47	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
48	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
49	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
50	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
51	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
52	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
53	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
54	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
55	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
56	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
57	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
58	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
59	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
60	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
61	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
62	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
63	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
64	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
65	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
66	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
67	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
68	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
69	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
70	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
71	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
72	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
73	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
74	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
75	16/08/19 18:55	General View	 Load JPG	<input checked="" type="checkbox"/>
76	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
77	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>
78	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>
79	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>
80	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>
81	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>
82	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>
83	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>
84	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>
85	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>
86	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>
87	16/08/19 18:55	General View	Load JPG	<input checked="" type="checkbox"/>
88	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
89	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
90	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
91	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
92	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
93	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
94	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
95	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
96	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
97	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
98	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
99	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
100	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
101	04/10/19 15:55	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/08/19 16:01	EMAIL FROM AIG DD 16.08.2019	Load PDF	
2	16/08/19 16:06	TP GIA REPORT	Load PDF	
3	16/08/19 16:06	TP POLICE REPORT	Load PDF	
4	21/08/19 15:38	TP ESTIMATE - MARKED	Load PDF	
5	21/08/19 16:01	EMAIL TO OI	Load PDF	
6	21/08/19 16:01	LETTER TO OI	Load PDF	
7	12/09/19 09:36	EMAIL FROM AIG	Load PDF	
8	22/10/19 11:30	PIR - AGAINST OI	Load PDF	
9	23/10/19 10:40	EMAIL FROM AIG	Load PDF	
10	23/10/19 10:48	EMAIL TO TP	Load PDF	
11	03/04/20 11:48	EMAIL	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19014303/UHA3S2

Date: 03/04/2020

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1900020109

Claimant Vehicle  
No : FBE3642C

Insured Vehicle No : SMJ2236S

Date of Loss: 09/06/2019

Nature of Claim: TP

Claim No: 8084555646SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBE3642C

Make &amp; Model: SUZUKI GSR400M, 398cc

Engine No: K719103084

Reg. Date: 12/03/2010 (Man. Year: 2008)

Chassis No: GK7DA103050

Colour: Blue

Odometer: 0 km

Engine Capacity: 398 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 120/70ZR17

Rear Tyre Size:

180/55ZR17

Front Left Side: Metzeler 6 mm

Rear Left Side:

Metric 6 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,027.00	2,524.50	11,502.50	82.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,189.00	435.00	754.00	63.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,216.00</b>	<b>2,959.50</b>	<b>12,256.50</b>	<b>80.55</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,300.00</b>		
<b>(S\$)</b>	15,216.00	2,300.00	12,916.00	84.88
<b>+ GST 7.00/7.00% (S\$)</b>	1,065.12	161.00	904.12	84.88
<b>Nett Amount (S\$)</b>	<b>16,281.12</b>	<b>2,461.00</b>	<b>13,820.12</b>	<b>84.88</b>

## INSPECTION

Date of Assignment: 16/08/2019

Date Inspected: 16/08/2019

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

[https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\\_print&caseid=856087&extid=313668&CFID=69603712&C...](https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_print&caseid=856087&extid=313668&CFID=69603712&C...) 1/4



*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AXLE REAR	Not Necessary	147.00 F	*- FL
2	1		*BALANCER	Scratched	42.00 F	*42.00 FL
3	1		*BALANCER HANDLE	Serviceable	122.00 F	*- FL
4	1		*BAR HANDLE	Bent	138.00 F	*138.00 FL
5	1		*BAR PILLION FOOTREST LH	Serviceable	48.00 F	*- FL
6	2		*BEARING STEERING CONE	Necessary	168.00 F	*168.00 FL
7	1		*BOLT LEVER PIVOT	Cut	14.00 F	*14.00 FL
8	1		*BOLT TANK SENSOR	Not Necessary	9.00 F	*- FL
9	1		*BRACKET FOOTREST LH	Bent	475.00 F	*475.00 FL
10	1		*BRACKET HEADLAMP	Not Necessary	178.00 F	*- FL
11	1		*BRACKET REAR	Bent	21.00 F	*21.00 FL
12	1		*BRACKET UNDER	Serviceable	600.00 F	*- FL
13	1		*BUSH SWINGARM	Serviceable	76.00 F	*- FL
14	1		*CABLE CLUTCH	Not Necessary	48.00 F	*- FL
15	1		*COVER METER LOWER	Cut	80.00 F	*80.00 FL
16	1		*COVER MUFFLER RH	Repair	143.00 F	*- FL
17	1		*COVER SPEEDOMETER	Cut	105.00 F	*105.00 FL
18	1		*COVER STEERING CONE	Cut	28.00 F	*28.00 FL
19	1		*COVER TAIL ASSY	Cracked	625.00 F	*625.00 FL
20	1		*COVER TANK SIDE LH (SILVER)	Not Necessary	220.00 F	*- FL
21	2		*EMBLEM ABS	Necessary	28.00 F	*28.00 FL
22	2		*EMBLEM GSR	Necessary	56.00 F	*56.00 FL
23	1		*EMBLEM SUZUKI	Necessary	14.00 F	*14.00 FL
24	1		*ENGINE GUARD HEPKO & BECKER	Serviceable	553.00 F	*- FL
25	1		*FENDER BAR	Cracked	118.00 F	*118.00 FL
26	1		*FORK FRONT ASSY LH	Serviceable	1,388.00 F	*- FL
27	1		*FORK FRONT ASSY LH	Repeated	1,388.00 F	*- FL
28	1		*FRAME COMPARTMENT	Serviceable	2,286.00 F	*- FL
29	1		*FRONT MUDGUARD	Broken	223.00 F	*223.00 FL
30	1		*HEADLAMP ASSY	Serviceable	476.00 F	*- FL
31	1		*LAMP LICENCE PLATE	Cracked	72.00 F	*72.00 FL
32	1		*LAMP SIGNAL FRONT RH	Not Necessary	91.00 F	*- FL
33	1		*LAMP SIGNAL REAR LH	Serviceable	112.00 F	*- FL
34	1		*LAMP SIGNAL REAR RH	Cracked	112.00 F	*112.00 FL
35	1		*LEVER CLUTCH	Cut	48.00 F	*48.00 FL
36	1		*METER IU (12V) NEW MODEL	Serviceable	200.00 F	*- FL
37	1		*SET MIRROR BLACK	Cut	48.00 F	*48.00 FL
38	1		*NUT AXLE	Not Necessary	20.00 F	*- FL
39	1		*PIN	Not Necessary	5.00 F	*- FL
40	1		*PROTECTOR REAR	Not Necessary	165.00 F	*- FL
41	1		*REFLECTOR ASSY	Not Necessary	21.00 F	*- FL
42	1		*RUBBER FOOTREST	Torn	34.00 F	*34.00 FL
43	2		*SEAL STEERING UPPER DUST	Not Necessary	24.00 F	*- FL
44	1		*SWING ARM ASSY	Serviceable	2,902.00 F	*- FL
45	1		*TAIL LAMP ASSY	Broken	356.00 F	*356.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,027.00</b>	<b>2,805.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>280.50</b>
<b>Total Parts (\$\$)</b>	<b>14,027.00</b>	<b>2,524.50</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR- DISMANTLE AND ASSEMBLING OF PARTS QUOTED.	New	1,120.00	400.00
2	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A - TOW BACK BIKE TO WORKSHOP.	New	69.00	35.00
Gross Labour Cost (S\$)			1,189.00	435.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >