

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBE3642C		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	SUZUKI		
Vehicle Model :	GSR400 M		
Chassis No. :	GK7DA103050		
Propellant :	Petrol		
Engine No. :	K719103084		
Engine Capacity :	398 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	320 kg		
Unladen Weight :	210 kg		
Year Of Manufacture :	2008		
Original Registration Date :	12 Mar 2010		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$1,001.00		
COE Expiry Date :	11 Mar 2020		
Road Tax Expiry Date :	11 Mar 2020		
Inspection Due Date :	11 Mar 2020		
Intended Transfer Date :	09 Jul 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34395

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
Motor Claims Dept

DATE : 08/07/2019
CLAIM NO. : 11375
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBE3642C
MAKE/MODEL : SUZ / GSR400M

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE REAR	REPLACE	1.00	\$147.00	147.00
2	BALANCER	REPLACE	1.00	\$42.00	42.00
3	BALANCER HANDLE P/N: 40721	REPLACE	1.00	\$122.00	122.00
4	BAR HANDLE P/N: 40104	REPLACE	1.00	\$138.00	138.00
5	BAR PILLION FOOTREST LH P/N: 54144	REPLACE	1.00	\$48.00	48.00
6	BEARING STEERING CONE P/N: 44475	REPLACE	2.00	\$84.00	168.00
7	BOLT LEVER PIVOT	REPLACE	1.00	\$14.00	14.00
8	BOLT TANK SENSOR P/N: 44458	REPLACE	1.00	\$9.00	9.00
9	BRACKET FOOTREST LH P/N: 51651	REPLACE	1.00	\$475.00	475.00
10	BRACKET HEADLAMP P/N: 51640	REPLACE	1.00	\$178.00	178.00
11	BRACKET REAR	REPLACE	1.00	\$21.00	21.00
12	BRACKET UNDER	REPLACE	1.00	\$600.00	600.00
13	BUSH SWINGARM P/N: 58506	REPLACE	2.00	\$38.00	76.00




bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 1001:2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
14	CABLE CLUTCH P/N: 58513	REPLACE	1.00	\$48.00	48.00
15	COVER METER LOWER	REPLACE	1.00	\$80.00	80.00
16	COVER MUFFLER RH	REPLACE	1.00	\$143.00	143.00
17	COVER SPEEDOMETER	REPLACE	1.00	\$105.00	105.00
18	COVER STEERING CONE	REPLACE	1.00	\$28.00	28.00
19	COVER TAIL ASSY	REPLACE	1.00	\$625.00	625.00
20	COVER TANK SIDE LH(SILVER)	REPLACE	1.00	\$220.00	220.00
21	EMBLEM ABS	REPLACE	2.00	\$14.00	28.00
22	EMBLEM GSR	REPLACE	2.00	\$28.00	56.00
23	EMBLEM SUZUKI	REPLACE	1.00	\$14.00	14.00
24	ENGINE GUARD HEPKO & BECKER	REPLACE	1.00	\$553.00	553.00
25	FENDER REAR	REPLACE	1.00	\$118.00	118.00
26	FORK FRONT ASSY LH P/N: 51634	REPLACE	1.00	\$1,388.00	1,388.00
27	FORK FRONT ASSY LH P/N: 51632	REPLACE	1.00	\$1,388.00	1,388.00
28	FRAME COMPARTMENT	REPLACE	1.00	\$2,286.00	2,286.00
29	FRONT MUDGUARD	REPLACE	1.00	\$223.00	223.00
30	HEADLAMP ASSY	REPLACE	1.00	\$476.00	476.00
31	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	Supply/Install	32.00	\$35.00	1,120.00
32	LAMP LICENSE PLATE	REPLACE	1.00	\$72.00	72.00
33	LAMP SIGNAL FRONT RH	REPLACE	1.00	\$91.00	91.00
34	LAMP SIGNAL REAR LH	REPLACE	1.00	\$112.00	112.00



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
35	LAMP SIGNAL REAR RH	REPLACE	1.00	\$112.00	112.00
36	LEVER CLUTCH	REPLACE	1.00	\$48.00	48.00
37	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$200.00	200.00
38	MIRROR BLACK SET	REPLACE	1.00	\$48.00	48.00
39	NUT AXLE	REPLACE	1.00	\$20.00	20.00
40	PIN P/N: 54145	REPLACE	1.00	\$5.00	5.00
41	PROTECTOR REAR	REPLACE	1.00	\$165.00	165.00
42	REFLECTOR ASSY	REPLACE	1.00	\$21.00	21.00
43	RUBBER FOOTREST P/N: 44469	REPLACE	1.00	\$34.00	34.00
44	SEAL STEERING UPPER DUST P/N: 44470	REPLACE	2.00	\$12.00	24.00
45	SWING ARM ASSY	REPLACE	1.00	\$2,902.00	2,902.00
46	TAIL LAMP ASSY	REPLACE	1.00	\$356.00	356.00
47	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A P/N: 45835 - TOW BACK BIKE TO WORKSHOP		1.00	\$69.00	69.00
SUB TOTAL					\$15,216.00
GST @ 7 %					\$1,065.12
GRAND TOTAL					\$16,281.12

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

