

AES. REC. BY:

REF:

09/FCI19014304/Eyd302

Special Instruction:

Surveyor: Steve

WS

ASSIGNMENT (Office)

From (Person):

Sorene Tan

of

FCI

Date/Time:

3:10pm 16/8/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 9257A

Insured:

8HC 8469T

at Workshop n/s

Keh Motor

Tel:

8286302

of

6A Mandur Estate

Policy No:

Claim No:

D19005301MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/08/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

3 Bpm 16/8/19

Person Contacted:

Anikka

Vehicle

IN/OUT

Date/Time

Action/Instruction

Ishtimal ✓

SKZ 9257A - X

SHC 8469T - NS/INC/8010746/Klvbn2

Don 11/6/2018

19/8/19 sent Preli Revise by email

MOTOR SURVEY ASSIGNMENT

Date	15-08-2019	Our Ref No. D19005301MFSH
Accident Date	14-08-2019	Claim Type. Third Party
Insured Vehicle	SHC8469T	Third Party Vehicle. SKZ9257A
Survey Location	6A MANDAI ESTATE BODY REPAIR & PAINT CENTRE	
Contact Person.	ANIKKA LAI	
Contact No.	65145248/ 82886302	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO. SDN. BHD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Steve Chen (LKK Auto)

From: Steve Chen (LKK Auto)
Sent: Friday, August 30, 2019 9:58 AM
To: Anikka Lai
Cc: Yvonne Wong (LKK Auto)
Subject: SKZ9257A - FINALIZATION

Dear Anikka,

We confirm the finalize \$10,970.34 (P/P, before GST). 9 repair days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai [<mailto:anikkalai@honda.com.sg>]
Sent: Thursday, August 29, 2019 6:54 PM
To: Steve Chen (LKK Auto); SUR
Subject: SKZ9257A - FINALIZATION
Importance: High

Dear Steve,

We enclosed the total final repair costs for,

Vehicle No.	SKZ9257A
Final Repair Costs (exclude GST)	\$ 10,970.34
Repair Period* (Days)	9 days

**Note: Repair period does include Sunday and Public Holiday.*

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you.

Warmest regards
Anikka Lai



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005301mfsh
Our Ref: CS/FCI19014304/Eyd3

Date: 19 Aug 2019

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKZ 9257A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/08/2019 at the premises of M/s KAH MOTOR CO SDN BHD, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>15,678.58</u> .
Revised Estimate Amount	: S\$ <u>8,563.05</u> .
"Check" Items Amount	: S\$ <u>2,121.85</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the o/s portion.



Yours faithfully

Steve
Automotive Assessor

Yvonne Wong (LKK Auto)

From: Anikka Lai <anikkalai@honda.com.sg>
Sent: Thursday, August 29, 2019 6:54 PM
To: Steve Chen (LKK Auto); SUR
Subject: SKZ9257A - FINALIZATION
Attachments: 1304_001.pdf; Resurvey B4 Paint & Item _ SKZ 9257 A
Importance: High

Dear Steve,

We enclosed the total final repair costs for,

Vehicle No.	SKZ9257A
Final Repair Costs (exclude GST)	\$ 10,970.34
Repair Period* (Days)	9 days

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you.

Warmest regards
Anikka Lai
6A Mandai Estate
Singapore 729903
DID : 65145248 HP: 82886302
Email add: anikkalai@honda.com.sg

From: Printer Service <printservice@honda.com.sg>
Sent: Thursday, 29 August 2019 6:42 PM
To: Anikka Lai <anikkalai@honda.com.sg>
Subject: Attached Image



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/08/2019 15:28
Date Of Accident	14/08/2019 21:10
Exact Location Of Accident	X JUNCTION IN SENGKANG HOSPITAL PREMISES
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ9257A
Insured/Policyholder	
Name Of Registered Owner	YIP SHU MIN
NRIC No	S8230773G
Email Address	TIFFANYYSM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96990074
Alternative Phone No	OFFICE-96990074

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	YIP SHU MIN
NRIC No	S8230773G
Date Of Birth	20/09/1982
Occupation	INDOOR
Date Of Driving Pass	01/02/2010
Driving Experience	9 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96990074
Fax Number	
Contact Number	OFFICE-96990074
EMail Address	TIFFANYYSM@GMAIL.COM

Address	-
Postcode	-
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS ANNEX D&E

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SHC8469T
Vehicle Make/Model/Colour	HYUNDAI / BLUE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	HOI CHEE WENG
NRIC/Passport Number	S7936107J
Contact Number	91276115
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Vehicle Number: SKZ 9257A


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: 15/8/2019
13:05

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Vehicle Number: SKZ 9257A

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/8/2019 @ about 0910 pm, my vehicle (A) was stopped at the basement carpark exit of Sengkang Hospital to give way to a vehicle which coming from front and make a right turn. After confirming the traffic was clear, my vehicle slowly proceed to go straight with the speed about 20km/hr. As my vehicle reaching the middle of the junction. I saw vehicle B turned out from a side road with a speedy manner, and it did not slows down and continued to made a sharp right turn, as my vehicle was ~~reaching~~ entering to the opposite lane. As such, vehicle B hit onto my vehicle right front portion with a great impact to cause the damages to both vehicles.

I have no passenger on board as well as Veh B.
No injury involved.

*Statement recorded in English language by driver.

*Own Damage (OD) Claim submission must be proceeded within 14 Days from Date of Accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	773G
Vehicle Details	
Vehicle No.:	SKZ9257A
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	L15B31020646
Chassis No.:	JHMGK5850GX201691
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$15,527.00
Original Registration Date:	15 Feb 2016
First Registration Date:	15 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$10,527.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Feb 2026
PARF Rebate Amount:	\$7,895.00
Intended COE Rebate Details	
COE Expiry Date:	14 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,301.00
COE Rebate Amount:	\$33,338.00
Total Rebate Amount:	\$41,233.00

The information contained herein is correct as at 16 Aug 2019

OK

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SKZ9257A

Chassis No : JHMGK5850GX201691

Model : JAZZ 1.5VTIR CVT 16YM

Owner's Name : YIP SHU MIN (YE SHUMIN)

Ins Policy No. :

Date of Accident : 14/8/2019

Document No. : SQT19003555 **Page** 1

Date : 14. Aug 2019

Customer No. : WZF002

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B31020646

Date | Time : 14. Aug 2019 4:41:51 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: YIP SHU MIN OWNER INSURER: LIBERTY ACC DATE: 15/08/2019 SURVEYED BY: DATE: REF NO: TP INSURER: MS FCL TP VEH: SHC8469T						
04711-T5A-000ZZ	FACE,FR.BUMPER / DR	1	504.60 /	25	378.45	26.49	404.94
71193-T5A-000	SPACERR.FR.BUMPER / DR	1	10.40 /	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER / DR	1	10.40 /	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER / DR	19	2.30	25	32.77	2.29	35.06
71120-TAS-003	GRILLE ASSYFR. / DR	1	294.70 /	25	221.02	15.47	236.49
75700-TA0-A00	EMBLEMFR. / DR	1	26.70 /	25	20.02	1.40	21.42
90301-ST0-003	NUTPUSH 3MM / DR	2	2.10	25	3.15	0.22	3.37
71130-T5A-000ZZ	BEAM COMPFR.BUMPER X NM	1	223.80 X	25	167.85	11.75	179.60
71140-T5A-000	BRACKETR.HEADLIGHT / DR	1	24.10 /	25	18.07	1.26	19.33
33100-T5A-J21	HEADLIGHT ASSY,R. / DR	1	1140.90 /	25	855.67	59.90	915.57
33130-T1G-E01	ADJUSTER UNITHEADLIGHT ? X NAI	1	285.20 ?	25	213.90	14.97	228.87
60211-T5R-A00ZZ	PANELR.FR.FENDER / DR	1	398.60 /	25	298.95	20.93	319.88
74100-T5A-000	FENDER ASSYR.FRINNER / DR	1	73.30 /	25	54.97	3.85	58.82
74105-T5A-J00	ENCLOSURE,R.FR. ? X NM	1	17.60 ?	25	13.20	0.92	14.12
60640-T5A-300ZZ	BRACKET,COMP R.FR.FENDER ? X NAI	1	43.90 ?	25	32.92	2.30	35.22
74165-T5A-010	GUARDL.FR.SPLASH ? X NAI	1	23.40 ?	25	17.55	1.23	18.78
74110-T5B-900	COVER ASSY,ENG UNIT X NAI	1	184.30 X	25	138.22	9.68	147.90
60400-T5B-310ZZ	BULKHEAD COMPFR. X R	1	381.70 X	25	286.27	20.04	306.31
04674-T5A-300ZZ	EXTENSION SETR.FR. ? X NM	1	94.40 ?	25	70.80	4.96	75.76

Printed on 15/8/2019 4:43:37 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SKZ9257A

Chassis No : JHMGK5850GX201691

Model : JAZZ 1.5VTIR CVT 16YM

Owner's Name : YIP SHU MIN (YE SHUMIN)

Ins Policy No. :

Date of Accident : 14/8/2019

Document No. : SQT19003555

Date : 14. Aug 2019

Customer No. : WZF002

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B31020646

Date | Time : 14. Aug 2019 4:41:51 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
60610-T5A-310ZZ	MEMBER COMPR.FR.WHEELHOUSE ? X NAI	1	94.90 ?	25	71.17	4.98	76.15
60812-T5A-300ZZ	PLATER.FR.BACK ? X NAI	1	107.50 ?	25	80.62	5.64	86.26
60844-T5A-300ZZ	PLATE,R.SIDE FRAME ? X NAI	1	30.80 ?	25	23.10	1.62	24.72
60845-T5A-300ZZ	GUSSETR.FR.SIDE ? X NAI	1	46.10 ?	25	34.57	2.42	36.99
71800-T5B-003ZB	GARNISH ASSY,R.SIDE X NAI	1	370.80 X	25	278.10	19.47	297.57
67010-T5A-N10ZZ	PANEL COMP,R.FR.DOOR X R	1	772.30 X	25	579.22	40.55	619.77
72324-T5A-003	SUB SEALR.FR.DOOR X NAI	1	4.40 X	25	3.30	0.23	3.53
67324-T5A-003	TAPE SETR.FR.DOOR X NAI	1	33.60 X	25	25.20	1.76	26.96
72326-T5A-003	SEALFR.DOOR LOWER X NAI	1	19.70 X	25	14.77	1.03	15.80
72410-TD4-003	MOLDING ASSYR.FR.DOOR X APC	1	43.00 /	25	32.25	2.26	34.51
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J / CAT	1	836.00 /	25	627.00	43.89	670.89
44305-TE3-000	DRIVESHAFT ASSY,R. X NAI	1	1033.40 X	25	775.05	54.25	829.30
51211-T5A-J11	KNUCKLER.FR. ? / BT	1	110.60 ?	25	82.95	5.81	88.76
51306-T5A-J21	BUSHSTABILIZER HOLDER X NAI	1	7.30 X	25	5.47	0.38	5.85
51320-T5A-003	LINK COMPR.FR.STABILIZER X / BT	1	44.40 X	25	33.30	2.33	35.63
51350-T5A-J02	ARM ASSY,R.FR.LOWER ? / BT	1	166.80 ?	25	125.10	8.76	133.86
57450-T5A-013	SENSOR ASSYR.FR. ? NAI	1	158.60 ?	25	118.95	8.33	127.28
51611-T5A-J14	DAMPER UNITR.FR. ? / BT	1	298.40 ?	25	223.80	15.67	239.47
51686-SAA-E02	SLEEVE FR DUST COVER X NAI	1	25.20 X	25	18.90	1.32	20.22
51722-T5A-J02	RUBBERFR.BUMPER STOPPER X NAI	1	12.40 X	25	9.30	0.65	9.95
51726-SFA-005	BEARINGDAMPER MT ? X NAI	1	17.60 ?	25	13.20	0.92	14.12
60100-T5A-000ZZ	HOOD COMP X R	1	537.50 X	25	403.12	28.22	431.34
60120-TAR-000ZZ	HINGE COMP,R.HOOD X NAI	1	25.70 X	25	19.27	1.35	20.62
60170-TAR-000ZZ	HINGE COMPLHOOD X NAI	1	25.70 X	25	19.27	1.35	20.62
74120-T5A-003	LOCK ASSYHOOD X NAI	1	89.50 X	25	67.12	4.70	71.82
19043-PLA-E00	LABELCOOLANT INFORMATION X NAI	1	5.00 /	25	3.75	0.26	4.01
80050-SP0-000	LABELAIR CONDITIONER CAUTION X NAI	1	1.80 /	25	1.35	0.09	1.44

885-80 Sum Item **6528.58** **457.00** **6,985.58**
664.75

Printed on 15/8/2019 4:43:37 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SKZ9257A

Chassis No : JHMGK5850GX201691

Model : JAZZ 1.5VTIR CVT 16YM

Owner's Name : YIP SHU MIN (YE SHUMIN)

Ins Policy No. :

Date of Accident : 14/8/2019

Document No. : SQT19003555

Date : 14. Aug 2019

Customer No. : WZF002

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B31020646

Date | Time : 14. Aug 2019 4:41:51 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
Sum Ext. Service					<u>180.00</u>	<u>12.60</u>	<u>192.60</u>
BO-TOW	TOWING SERVICES (MBBS)	1	100.00		100.00	7.00	107.00
BOSUN	SUNDRIES	1	100.00	50	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	120.00		120.00	8.40	128.40
BPBODY - MINOR	RENEW RIM WITH TYRE.	1	100.00	50	100.00	7.00	107.00
BMU12R	REMOVE & REPLACE FR R UNDERCARRIAGE PARTS. (N)	1	600.00	50	600.00	42.00	642.00
BKOT00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	1	1000.00	? X	1000.00	70.00	1070.00
BMC01D	REMOVE & REFIX RADIATOR TO ASSIST WORKLOAD.	1	200.00	X	200.00	14.00	214.00
BMA01D	REMOVE & REFIX A/C CONDENSER TO ASSIST WORKLOAD.	1	250.00	X	250.00	17.50	267.50
BKBH01R	REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS	1	3500.00	2240	3500.00	245.00	3745.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00	2700	3000.00	210.00	3210.00
Sum Labor					<u>8970.00</u>	<u>627.90</u>	<u>9,597.90</u>

Survey By

Date & Time

Excess

Status

Signature

Store (LKK) 83228813

with repair 16/8/19, 4.00 pm

9 # days

P/P

Ry # Def spy

12629.85

Total Amount 15,678.58 1,097.50 16,776.08

Total (Inclusive of GST) 16,776.08

Printed on 15/8/2019 4:43:37 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co

Acknowledged by Repairer

Signature:

Date:



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0120505 / MS FIRST CAPITAL
Chassis No: JHMGK5850GX201691
License No: SKZ9257A
Mileage: 45042
Engine No: L15B31020646

Document No: SVO19053589
Printed By: ANIKKALAI
Order Date: 21. August 2019
Order Time: 11:52:37 AM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: YIP SHU MIN OWNER INSURER: LIBERTY ACC DATE: 15/08/2019 SURVEYED BY: STEVE / LKK DATE: 16/08/2019 REF NO: TP INSURER: MS FCL TP VEH: SHC8469T						
04711-T5A-000ZZ	FACE,FR.BUMPER	1	504.60	25	378.45	26.49	404.94
71193-T5A-000	SPACERR.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER	19	2.30	25	32.77	2.29	35.06
71120-TAS-003	GRILLE ASSYFR.	1	294.70	25	221.02	15.47	236.49
75700-TA0-A00	EMBLEMFR.	1	26.70	25	20.02	1.40	21.42
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
71140-T5A-000	BRACKETR.HEADLIGHT	1	24.10	25	18.07	1.26	19.33
33100-T5A-J21	HEADLIGHT ASSY,R.	1	1,140.90	25	855.67	59.90	915.57
60211-T5R-A00ZZ	PANELR.FR.FENDER	1	398.60	25	298.95	20.93	319.88
74100-T5A-000	FENDER ASSYR.FR INNER	1	73.30	25	54.97	3.85	58.82
72410-TD4-003	MOLDING ASSYR.FR.DOOR	1	43.00	25	32.25	2.26	34.51
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J	1	836.00	25	627.00	43.89	670.89
51211-T5A-J11	KNUCKLER.FR.	1	110.60	25	82.95	5.81	88.76
51320-T5A-003	LINK COMPR.FR.STABILIZER	1	44.40	25	33.30	2.33	35.63
51350-T5A-J02	ARM ASSY,R.FR.LOWER	1	166.80	25	125.10	8.76	133.86
51611-T5A-J14	DAMPER UNTR.FR.	1	298.40	25	223.80	15.67	239.47
90682-SEA-003	CLIP ABUMPER	2	2.60	25	3.90	0.27	4.17
91501-TR0-003	CLIP,INNER FENDER	11	2.80	25	23.10	1.62	24.72
33900-TY0-003	LIGHT ASSY, R. FR.FOG	1	267.10	25	200.32	14.02	214.34
44300-T9C-T61	BEARING ASSY,FR.HUB	1	114.90	25	86.17	6.03	92.20
44600-T5B-J00	HUB ASSYFR.	1	138.30	25	103.72	7.26	110.98
51920-SCC-015	RUBBER COMPFR.SHOCK ABS MTG	1	40.30	25	30.22	2.12	32.34
53400-TAR-T01	BOX ASSYSTEERING GEAR	1	1,171.70	25	878.77	61.51	940.28
53540-T5A-003	END COMPTIE ROD	1	73.30	25	54.97	3.85	58.82
50200-T5A-J03	SUB FRAME COMP	1	754.80	25	566.10	39.63	605.73
	SUM PARTS:				4,970.34	347.94	5,318.28
BO-TOW	TOWING SERVICES (MBBS)	1	100.00		100.00	7.00	107.00
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	120.00		120.00	8.40	128.40
BPBODY - MINOR	RENEW RIM WITH TYRE.	1	50.00		50.00	3.50	53.50
BMU12R	1438 REMOVE & REPLACE FR R UNDERCARRIAGE PARTS.(N)	1	560.00		560.00	39.20	599.20



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0120505 / MS FIRST CAPITAL
Chassis No: JHMGK5850GX201691
License No: SKZ9257A
Mileage: 45042
Engine No: L15B31020646

Document No: SVO19053589
Printed By: ANIKKALAI
Order Date: 21. August 2019
Order Time: 11:52:37 AM
Service Advisor: ANIKKA LAI SWEE KAM

BKBH01R	1729 REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS INCLUDING FITTING ON ATTACHMENT ITEMS	1	2,240.00 /	2,240.00	156.80	2,396.80
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,700.00 /	2,700.00	189.00	2,889.00
		SUM LABOUR:		5,820.00	407.40	6,227.40
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00 /	180.00	12.60	192.60
		SUM EXT SERVICE:		180.00	12.60	192.60
		TOTAL SGD		10,970.34 /	767.94	11,738.28
		Total Payable (SGD)		11,738.28		

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0120505 / YIP SHU MIN (YE
Chassis No: JHMGK5850GX201691
License No: SKZ9257A
Mileage: 45042
Engine No: L15B31020646

Document No: SVO19053589
Printed By: ANIKKALAI
Order Date: 21. August 2019
Order Time: 11:52:37 AM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
SUPPLEMENTARY PARTS:							
90682-SEA-003	CLIP ABUMPER / <i>APC</i>	2	2.60	25	3.90	0.27	4.17
91501-TR0-003	CLIP, INNER FENDER / <i>APC</i>	11	2.80	25	23.10	1.62	24.72
33900-TY0-003	LIGHT ASSY, R. FR.FOG / <i>APC</i>	1	267.10	25	200.32	14.02	214.34
44300-T9C-T61	BEARING ASSY, FR.HUB / <i>APC</i>	1	114.90	25	86.17	6.03	92.20
44600-T5B-J00	HUB ASSYFR. / <i>APC</i>	1	138.30	25	103.72	7.26	110.98
51920-SCC-015	RUBBER COMPFR.SHOCK ABS MTG / <i>CR4</i>	1	40.30	25	30.22	2.12	32.34
53400-TAR-T01	BOX ASSYSTEERING GEAR / <i>BT</i>	1	1,171.70	25	878.77	61.51	940.28
53540-T5A-003	END COMPTIE ROD / <i>BT</i>	1	73.30	25	54.97	3.85	58.82
50200-T5A-J03	SUB FRAME COMP / <i>BT</i>	1	754.80	25	566.10	39.63	605.73
SUM PARTS:					1,947.27	136.31	2,083.58
TOTAL SGD					1,947.27	136.31	2,083.58

Total Payable (SGD)

2,083.58

GST Amount is calculated from individual line(s)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19014304/Eyd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8469T	Veh. Inspected	SKZ 9257A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005301MFSH	Excess (\$)	0.00	
Assign From	SERENE TAN	Assign Date	16/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMGK5850GX201691	Colour	RED	
Odometer	45034	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	DUNLOP	5 mm	
L/H Front Tyre	185/55 R16	DUNLOP	5 mm	
R/H Rear Tyre	185/55 R16	DUNLOP	5 mm	
L/H Rear Tyre	185/55 R16	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/08/2019	Inspection Date	16/08/2019	
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 9257A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FACE,FR.BUMPER (SN)	BROKEN	378.45	378.45
1	SPACERR.FR.BUMPER (SN)	BROKEN	7.80	7.80
1	SPACERL.FR.BUMPER (SN)	BROKEN	7.80	7.80
19	CLIP,BUMPER (SN)	NECESSARY	32.77	32.77
1	GRILLE ASSYFR. (SN)	BROKEN	221.02	221.02
1	EMBLEMFR. (SN)	NECESSARY	20.02	20.02
2	NUTPUSH 3MM (SN)	NECESSARY	3.15	3.15
1	BEAM COMPFR.BUMPER (SN)	NOT NECESSARY	167.85	-
1	BRACKETR.HEADLIGHT (SN)	BROKEN	18.07	18.07
1	HEADLIGHT ASSY,R. (SN)	BROKEN	855.67	855.67
1	ADJUSTER UNITHEADLIGHT (SN)	NOT NECESSARY	213.90	-
1	PANELR.FR.FENDER (SN)	DENTED	298.95	298.95
1	FENDER ASSYR.FR.INNER (SN)	CRUSHED	54.97	54.97
1	ENCLOSURE,R.FR (SN)	NOT NECESSARY	13.20	-
1	BRACKET,COMP R.FR.FENDER (SN)	NOT NECESSARY	32.92	-
1	GUARDL.FR.SPLASH (SN)	NOT NECESSARY	17.55	-
1	COVER ASSY,ENG UNIT (SN)	NOT NECESSARY	138.22	-
1	BULKHEAD COMPFR. (SN)	TO REPAIR SEE LABOUR	286.27	-
1	EXTENSION SETR.FR. (SN)	NOT NECESSARY	70.80	-
1	MEMBER COMPR.FR.WHEELHOUSE (SN)	NOT NECESSARY	71.17	-
1	PLATER.FR.BACK (SN)	NOT NECESSARY	80.62	-
1	PLATE,R.SIDE FRAME (SN)	NOT NECESSARY	23.10	-
1	GUSSETR.FR.SIDE (SN)	NOT NECESSARY	34.57	-
1	GARNISH ASSY,R.SIDE (SN)	NOT NECESSARY	278.10	-
1	PANEL COMP,R.FR.DOOR (SN)	TO REPAIR SEE LABOUR	579.22	-
1	SUB SEALR.FR.DOOR (SN)	NOT NECESSARY	3.30	-
1	TAPE SETR.FR.DOOR (SN)	NOT NECESSARY	25.20	-
1	SEALFR.DOOR LOWER (SN)	NOT NECESSARY	14.77	-
1	MOLDING ASSYR.FR.DOOR (SN)	NECESSARY	32.25	32.25

Report Ref No. CS/FCI19014304/Eyd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DISKALUMINIUM WHEEL 16X6J (SN)	CUT	627.00	627.00
1	DRIVESHAFT ASSY,R. (SN)	NOT NECESSARY	775.05	-
1	KNUCKLER.FR (SN)	BENT	82.95	82.95
1	BUSHSTABILIZER HOLDER (SN)	NOT NECESSARY	5.47	-
1	LINK COMPR.FR.STABILIZER (SN)	BENT	33.30	33.30
1	ARM ASSY,R.FR.LOWER (SN)	BENT	125.10	125.10
1	SENSOR ASSYR.FR. (SN)	NOT NECESSARY	118.95	-
1	DAMPER UNITR.FR. (SN)	BENT	223.80	223.80
1	SLEEVE FR DUST COVER (SN)	NOT NECESSARY	18.90	-
1	RUBBERFR.BUMPER STOPPER (SN)	NOT NECESSARY	9.30	-
1	BEARINGDAMPER MT (SN)	NOT NECESSARY	13.20	-
1	HOOD COMP (SN)	TO REPAIR SEE LABOUR	403.12	-
1	HINGE COMP,R.HOOD (SN)	NOT NECESSARY	19.27	-
1	HINGE COMPL.HOOD (SN)	NOT NECESSARY	19.27	-
1	LOCK ASSYHOOD (SN)	NOT NECESSARY	67.12	-
1	LABELCOOLANT INFORMATION (SN)	NOT NECESSARY	3.75	-
1	LABELAIR CONDITIONER CAUTION (SN)	NOT NECESSARY	1.35	-
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
2	CLIP ABUMPER (SN) (ADDITIONAL)	NECESSARY	3.90	3.90
11	CLIP, INNER FENDER (SN) (ADDITIONAL)	NECESSARY	23.10	23.10
1	LIGHT ASSY,R.FR FOG (SN) (ADDITIONAL)	BROKEN	200.32	200.32
1	BEARING ASSY,FR.HUB (SN) (ADDITIONAL)	NECESSARY	86.17	86.17
1	HUB ASSYFR. (SN) (ADDITIONAL)	NECESSARY	103.72	103.72
1	RUBBER COMPFR.SHOCK ABS MTG (SN) (ADDITIONAL)	CRUSHED	30.22	30.22
1	BOX ASSYSTEERING GEAR (SN) (ADDITIONAL)	BENT	878.77	878.77
1	END COMPTIE ROD (SN) (ADDITIONAL)	BENT	54.97	54.97
1	SUB FRAME COMP (SN) (ADDITIONAL)	BENT	566.10	566.10
			8,575.85	5,020.34
	LABOUR			
	WHEEL ALIGNMENT X4.		180.00	180.00
	TOWING SERVICES (MBBS).		100.00	100.00
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		120.00	120.00

Report Ref No. CS/FCI19014304/Eyd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RENEW RIM WITH TYRE.		100.00	50.00
	REMOVE & REPLACE FR R UNDERCARRIAGE PARTS.		600.00	560.00
	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT.	NOT NECESSARY	1,000.00	-
	REMOVE & REFIX RADIATOR TO ASSIST WORKLOAD.	NOT NECESSARY	200.00	-
	REMOVE & REFIX A/C CONDENSER TO ASSIST WORKLOAD.	NOT NECESSARY	250.00	-
	REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF BULKHEAD COMPFR., PANEL COMP,R.FR.DOOR AND HOOD COMP.		3,500.00	2,240.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)		3,000.00	2,700.00
			9,050.00	5,950.00
GRAND TOTAL			17,625.85	10,970.34

RECOMMENDED COST OF REPAIRS				10,970.34
-----------------------------	--	--	--	-----------

Report Ref No. CS/FCI19014304/Eyd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.