

Celina

TO :
ESTIMATE REPORT 1ST Quotation

FAX NO:
 16/08/2019 10:59
 JOB-NO: 50111933

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet) CONTACT: 65533880
 ADDRESS: 383 SIN MING DRIVE SINGAPORE 575717 0 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHB2120T TRANS: AUTO CHASSIS: KMHC851CVKU165085
 MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI ENGINE: G4LEKU299284
 OWNER'S INSURER: MS First Capital Insurance Limited
 JOB-CODE: TP SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 CHECK WIRING SYS	1.00	120.00	0.00	120.00	Y		30
2 DIAGNOSTIC & REPROGRAMMED ELECTRICAL SYS	1.00	200.00	0.00	200.00	Y		100
3 TRANSFER BOOT LID PART	1.00	200.00	0.00	200.00	Y		80
4 R&R REAR W/SCREEN GLASS	1.00	200.00	0.00	200.00	Y		120
5 R&R REAR W/SCREEN GLASS CTR	1.00	150.00	0.00	150.00	Y		80
6 R&R REAR SEAT & INNER CARPET	1.00	200.00	0.00	200.00	Y		60
7 STRIAHTEN,PANEL BEAT REAR PORTION & ACCIDENT AREA.	1.00	1,200.00	0.00	1,200.00	Y		700
8 SPRAY BOOT LID	1.00	250.00	0.00	250.00	Y		200
9 SPRAY BOOT LID SPOILER	1.00	250.00	0.00	250.00	Y		150
10 SPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		200
11 SPRAY REAR END PANEL	1.00	250.00	0.00	250.00	Y		200
12 CLEAR UP REAR W/SCREEN GLASS CLIPS	1.00	80.00	0.00	80.00	Y		X 1^
TOTAL:		3,350.00	0.00	3,350.00			

1920

MATERIALS

1 BOOT LID <i>bt</i>	1.00	2,580.40	516.08	2,064.32	L	Y	
2 BOOT LID SPOILER <i>de</i>	1.00	685.40	137.08	548.32	L	Y	
3 BOOT LID CTR W/SCREEN GLASS <i>bro</i>	1.00	428.90	85.78	343.12	L	Y	
4 BOOT LID W/STRIP <i>pe</i>	1.00	155.40	31.08	124.32	L	Y	
5 BOOT LID LOCK <i>x su</i>	1.00	284.44	56.89	227.55	L	Y	
6 BOOT LID OUTER HANDLE <i>x su</i>	1.00	77.30	15.46	61.84	L	Y	
7 BOOT LID REVERSE CAMERA <i>x su</i>	1.00	486.86	97.37	389.49	L	Y	
8 BOOT LID INNER COVER <i>at</i>	1.00	259.40	51.88	207.52	L	Y	
9 BOOT LID LOGO <i>no</i>	1.00	68.20	13.64	54.56	L	Y	
10 BOOT LID HYBRID EMBLEM <i>no</i>	1.00	36.60	7.32	29.28	L	Y	
11 BOOT LID IONIQ EMBLEM <i>no</i>	1.00	34.60	6.92	27.68	L	Y	
12 REAR BUMPER <i>de</i>	1.00	759.40	151.88	607.52	L	Y	
13 REAR BUMPER RETAINER RHS <i>x su</i>	1.00	42.89	8.58	34.31	L	Y	
14 REAR BUMPER RETAINER LHS <i>no</i>	1.00	42.89	8.58	34.31	L	Y	
15 REAR BUMPER LOWER MOULDING <i>x su</i>	1.00	137.85	27.57	110.28	L	Y	
16 REAR BUMPER CTR MOULDING (BLACK) <i>ca</i>	1.00	486.86	97.37	389.49	L	Y	
17 REAR BUMPER REINFORCEMENT <i>bra</i>	1.00	424.28	84.86	339.42	L	Y	
18 REAR BUMPER REINFORCEMENT ARMS RHS <i>x su</i>	1.00	171.91	34.38	137.53	L	Y	
19 REAR BUMPER REINFORCEMENT ARMS LHS <i>bt</i>	1.00	171.91	34.38	137.53	L	Y	✓
20 REAR BUMPER TOW COVER <i>sc</i>	1.00	39.63	7.93	31.70	L	Y	
21 REAR END PANEL <i>repair</i>	1.00	632.20	126.44	505.76	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
22 REAR BUMPER LOWER SIDE COVER LHS <i>7/20</i>	1.00	58.70	11.74	46.96	L	Y	<i>✓</i>
23 BOOT LID TAIL LAMP RHS <i>f su</i>	1.00	733.20	146.64	586.56	L	Y	
24 BOOT LID TAIL LAMP LHS <i>sea cm</i>	1.00	733.20	146.64	586.56	L	Y	
25 TAIL LAMP OUTER RHS <i>X su</i>	1.00	957.44	191.49	765.95	L	Y	
26 TAIL LAMP OUTER LHS <i>su</i>	1.00	957.44	191.49	765.95	L	Y	
27 REAR 3RD BRAKE LAMP <i>cm</i>	1.00	268.88	53.78	215.10	L	Y	
28 REVERSE LAMP <i>X su</i>	1.00	268.20	53.64	214.56	L	Y	
29 REAR N/PLATE LAMP <i>X su</i>	2.00	153.76	30.75	123.01	L	Y	
30 REAR BUMPER REFLECTOR RHS <i>X su</i>	1.00	38.88	7.74	30.94	L	Y	
31 REAR BUMPER REFLECTOR LHS <i>X su</i>	1.00	38.88	7.74	30.94	L	Y	
32 BOOT LID STICKER <i>no</i>	1.00	150.00	0.00	150.00/100	S	Y	
33 REAR BUMPER CLIPS <i>no</i>	1.00	100.00	0.00	100.00/50	S	Y	
34 REAR BUMPER TOP PADDING <i>ad</i>	1.00	150.00	0.00	150.00/80	S	Y	
35 REVERSE SENSOR <i>no</i>	1.00	200.00	0.00	200.00	S	Y	
36 REAR N/PLATE <i>cm</i>	1.00	50.00	0.00	50.00/35	S	Y	
37 W/SCREEN SEALANT <i>no</i>	1.00	80.00	0.00	80.00/80	S	Y	
38 END PANEL SEALANT <i>X su</i>	1.00	80.00	0.00	80.00 <i>X su</i>	Y		
TOTAL:		13,025.50	443.12	10,582.38			

TOTAL PARTS & LABOUR : 16,375.50 2,443.12 13,932.38

EXCESS/LOADING:\$ 0.00

No. Of Day: 7 days 14,040.94#

RE-SURVEY BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: 16 / 08 / 19 @ 1420

SURVEYED BY: Rasul

CONTACT NO: 90000000 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL: _____ FAX: _____