



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2120T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID (CONSISTENT)	BENT	2,580.40	2,580.40
1	BOOT LID SPOILER (CONSISTENT)	DEFORMED	685.40	685.40
1	BOOT LID CTR W/SCREEN GLASS (CONSISTENT)	BROKEN	428.90	428.90
1	BOOT LID W/STRIP (CONSISTENT)	NECESSARY	155.40	155.40
1	BOOT LID LOCK (CONSISTENT)	SERVICEABLE	284.44	-
1	BOOT LID OUTER HANDLE (CONSISTENT)	SERVICEABLE	77.30	-
1	BOOT LID REVERSE CAMERA (CONSISTENT)	SERVICEABLE	486.86	-
1	BOOT LID INNER COVER (CONSISTENT)	CUT	259.40	259.40
1	BOOT LID LOGO (CONSISTENT)	NECESSARY	68.20	68.20
1	BOOT LID HYBRID EMBLEM (CONSISTENT)	NECESSARY	36.60	36.60
1	BOOT LID IONIQ EMBLEM (CONSISTENT)	NECESSARY	34.60	34.60
1	REAR BUMPER (CONSISTENT)	DEFORMED	759.40	759.40
1	REAR BUMPER RETAINER RHS (CONSISTENT)	SERVICEABLE	42.89	-
1	REAR BUMPER RETAINER LHS (CONSISTENT)	NECESSARY	42.89	42.89
1	REAR BUMPER LOWER MOULDING (CONSISTENT)	SERVICEABLE	137.85	-
1	REAR BUMPER CTR MOULDING (BLACK) (CONSISTENT)	CRACKED	486.86	486.86
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	CRACKED	424.28	424.28
1	REAR BUMPER REINFORCEMENT ARMS RHS (CONSISTENT)	SERVICEABLE	171.91	-
1	REAR BUMPER REINFORCEMENT ARMS LHS (CONSISTENT)	BENT	171.91	171.91
1	REAR BUMPER TOW COVER (CONSISTENT)	SCRATCHED	39.63	39.63
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	632.20	-
1	REAR BUMPER LOWER SIDE COVER LHS (CONSISTENT)	CRACKED	58.70	58.70
1	BOOT LID TAIL LAMP RHS (CONSISTENT)	SERVICEABLE	733.20	-
1	BOOT LID TAIL LAMP LHS (CONSISTENT)	CRACKED	733.20	733.20
1	TAIL LAMP OUTER RHS (CONSISTENT)	SERVICEABLE	957.44	-
1	TAIL LAMP OUTER LHS (CONSISTENT)	SCRATCHED	957.44	957.44
1	REAR 3RD BRAKE LAMP (CONSISTENT)	CRACKED	268.88	268.88
1	REVERSE LAMP (CONSISTENT)	SERVICEABLE	268.20	-
2	REAR N/PLATE LAMP (CONSISTENT)	SERVICEABLE	153.76	-

Report Ref No. CC4/ASM19014308/R1ga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER REFLECTOR RHS (CONSISTENT)	SERVICEABLE	38.68	-
1	REAR BUMPER REFLECTOR LHS (CONSISTENT)	SERVICEABLE	38.68	-
1	REAR BUMPER SMART KEY ANTENNA (ADDITIONAL)	CRACKED	135.68	135.68
	LESS 20% DISCOUNT		-2,470.24	-1,665.57
			9,880.94	6,662.20
	<u>SPECIAL NETT ITEMS</u>			
1	BOOT LID STICKER (SN) (CONSISTENT)	NECESSARY	150.00	100.00
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	100.00	50.00
1	REAR BUMPER TOP PADDING (SN) (CONSISTENT)	CUT	150.00	80.00
1	REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	200.00	200.00
1	REAR N/ PLATE (SN) (CONSISTENT)	CRACKED	50.00	35.00
1	W/SCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
1	END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
			810.00	505.00
	<u>LABOUR</u>			
	CHECK WIRING SYSTEM.		120.00	30.00
	DIAGNOSTIC & REPROGRAMMED ELECTRICAL SYSTEM.		200.00	100.00
	TRANSFER BOOT LID PART.		200.00	80.00
	R&R REAR W/SCREEN GLASS.		200.00	120.00
	R&R REAR W/SCREEN GLASS CTR.		150.00	80.00
	R&R REAR SEAT & INNER CARPET.		200.00	60.00
	STRAIGHTEN, PANEL BEAT REAR PORTION & ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,200.00	700.00
	SPRAY BOOT LID.		250.00	200.00
	SPRAY BOOT LID SPOILER.		250.00	150.00
	SPRAY REAR BUMPER.		250.00	200.00
	SPRAY REAR END PANEL.		250.00	200.00
	CLEAR UP REAR W/SCREEN GLASS CLIPS.	NOT NECESSARY	80.00	-
			3,350.00	1,920.00
GRAND TOTAL			14,040.94	9,087.20
RECOMMENDED COST OF REPAIRS				9,087.20

Report Ref No. CC4/ASM19014308/R1ga3s2



Report Ref No. CC4/ASM19014308/R1ga3s2

A handwritten signature in black ink, appearing to read 'MRB'.

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

A handwritten signature in black ink, appearing to read 'Ho Leong Chuan'.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.