

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

16/08/2019 10:59

JOB-NO: 50111933

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHB2120T TRANS: AUTO
MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: KMHC851CVKU165085
ENGINE: G4LEKU299284

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 CHECK WIRING SYS	1.00	120.00	0.00	120.00		Y	30
2 DIAGNOSTIC & REPROGRAMMED ELECTRICAL SYS	1.00	200.00	0.00	200.00		Y	100
3 TRANSFER BOOT LID PART	1.00	200.00	0.00	200.00		Y	80
4 R&R REAR W/SCREEN GLASS	1.00	200.00	0.00	200.00		Y	120
5 R&R REAR W/SCREEN GLASS CTR	1.00	150.00	0.00	150.00		Y	80
6 R&R REAR SEAT & INNER CARPET	1.00	200.00	0.00	200.00		Y	60
7 STRIAIGHTEN,PANEL BEAT REAR PORTION & ACCIDENT AREA.	1.00	1,200.00	0.00	1,200.00		Y	700
8 SPRAY BOOT LID	1.00	250.00	0.00	250.00		Y	200
9 SPRAY BOOT LID SPOILER	1.00	250.00	0.00	250.00		Y	150
10 SPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
11 SPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	200
12 CLEAR UP REAR W/SCREEN GLASS CLIPS	1.00	80.00	0.00	80.00		Y	X
TOTAL:		3,350.00	0.00	3,350.00			

MATERIALS

1 BOOT LID <i>bt</i>	1.00	2,580.40	516.08	2,064.32	L	Y	
2 BOOT LID SPOILER <i>de</i>	1.00	685.40	137.08	548.32	L	Y	
3 BOOT LID CTR W/SCREEN GLASS <i>bro</i>	1.00	428.90	85.78	343.12	L	Y	
4 BOOT LID W/STRIP <i>re</i>	1.00	155.40	31.08	124.32	L	Y	
5 BOOT LID LOCK <i>X</i>	1.00	284.44	56.89	227.55	L	Y	
6 BOOT LID OUTER HANDLE <i>X</i>	1.00	77.30	15.46	61.84	L	Y	
7 BOOT LID REVERSE CAMERA <i>X</i>	1.00	486.86	97.37	389.49	L	Y	
8 BOOT LID INNER COVER <i>cut</i>	1.00	259.40	51.88	207.52	L	Y	
9 BOOT LID LOGO <i>re</i>	1.00	68.20	13.64	54.56	L	Y	
10 BOOT LID HYBRID EMBLEM <i>re</i>	1.00	36.60	7.32	29.28	L	Y	
11 BOOT LID IONIQ EMBLEM <i>re</i>	1.00	34.60	6.92	27.68	L	Y	
12 REAR BUMPER <i>de</i>	1.00	759.40	151.88	607.52	L	Y	
13 REAR BUMPER RETAINER RHS <i>X</i>	1.00	42.89	8.58	34.31	L	Y	
14 REAR BUMPER RETAINER LHS <i>re</i>	1.00	42.89	8.58	34.31	L	Y	
15 REAR BUMPER LOWER MOULDING <i>?</i>	1.00	137.85	27.57	110.28	L	Y	
16 REAR BUMPER CTR MOULDING (BLACK) <i>re</i>	1.00	486.86	97.37	389.49	L	Y	
17 REAR BUMPER REINFORCEMENT <i>re</i>	1.00	424.28	84.86	339.42	L	Y	
18 REAR BUMPER REINFORCEMENT ARMS RHS <i>?</i>	1.00	171.91	34.38	137.53	L	Y	
19 REAR BUMPER REINFORCEMENT ARMS LHS <i>?</i>	1.00	171.91	34.38	137.53	L	Y	
20 REAR BUMPER TOW COVER <i>re</i>	1.00	39.63	7.93	31.70	L	Y	
21 REAR END PANEL <i>repair</i>	1.00	632.20	126.44	505.76	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
22 REAR BUMPER LOWER SIDE COVER LHS ?	1.00	58.70	11.74	46.96	L	Y	_____
23 BOOT LID TAIL LAMP RHS X	1.00	733.20	146.64	586.56	L	Y	_____
24 BOOT LID TAIL LAMP LHS sea cm -	1.00	733.20	146.64	586.56	L	Y	_____
25 TAIL LAMP OUTER RHS X	1.00	957.44	191.49	765.95	L	Y	_____
26 TAIL LAMP OUTER LHS sur -	1.00	957.44	191.49	765.95	L	Y	_____
27 REAR 3RD BRAKE LAMP cm -	1.00	268.88	53.78	215.10	L	Y	_____
28 REVERSE LAMP	1.00	268.20	53.64	214.56	L	Y	_____
29 REAR N/PLATE LAMP ?	2.00	153.76	30.75	123.01	L	Y	_____
30 REAR BUMPER REFLECTOR RHS X	1.00	38.68	7.74	30.94	L	Y	_____
31 REAR BUMPER REFLECTOR LHS X	1.00	38.68	7.74	30.94	L	Y	_____
32 BOOT LID STICKER ne -	1.00	150.00	0.00	150.00 100	S	Y	_____
33 REAR BUMPER CLIPS ne -	1.00	100.00	0.00	100.00 50	S	Y	_____
34 REAR BUMPER TOP PADDING ad -	1.00	150.00	0.00	150.00 80	S	Y	_____
35 REVERSE SENSOR ne -	1.00	200.00	0.00	200.00	S	Y	_____
36 REAR N/PLATE cm -	1.00	50.00	0.00	50.00 35	S	Y	_____
37 W/SCREEN SEALANT ne -	1.00	80.00	0.00	80.00 40	S	Y	_____
38 END PANEL SEALANT X	1.00	80.00	0.00	80.00 60 X?	S	Y	_____
TOTAL:		13,025.50	443.12	10,582.38			_____
TOTAL PARTS & LABOUR :		16,375.50	2,443.12	13,932.38			_____

EXCESS/LOADING:\$ 0.00

No. Of Day: 7 days

RE-SURVEY BEFORE AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$ \$ _____

DATE OF SURVEY: 16 / 08 / 19 @ 1420

SURVEYED BY: RSM

CONTACT NO: 9000068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002
Ding Auto User 2

ESTIMATOR
STA AUTOCENTRE
TEL: _____ FAX: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____