

INS. CASE OWNER:

TEO Kitty

CC4/ASM19014311/1 ga3

LKK:

IDAC:

131627

Surveyor:

Taufikn

DOI:

ASSIGNMENT

4/9/2019

Date / Time : 16/08/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SJY 1655D

Claim No. : S9M01WTK

Name of Insured : URBAN CAR RENTAL & LIMOUSINE SERVICES

Policy No. : GA409493

Insured Tel No. : HP:

Make / Model :

Excess Sec II : \$

D.O.A : 11/08/2019 14:30

Place of Accident : PIE (BEFORE STEVEN RD) TO JURONG

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age : MUHAMMAD AFIQ BIN SANI

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : +65-98267204

(V/L: YES / NO)

Insured Liability :

%

Final ? Yes / No

SKQ 1012P

INSRS:
WSP: WEARNES
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	SKQ 1012P - X	SJY 1655D - X	STAGE	DATE / PIC
17/8/19	- to req AVP from TP as per AXA instruction.		Non-Reporting ltr (1st):	
20/8	- Pending AXA reply on the need of taking AVP from TP.		Non-Reporting ltr (2nd):	
24/8	- TP AVP in. Liability clear send TP.		Non-Reporting ltr (Final):	
8/10	- File pass Taufikn to fill up parts condition on supp 107 & checked item & confirm final amt of \$17,863.01 for CR.		Notification ltr (if non-pickup):	
11/10	- To seek mandat.		Call OI:	
15/10	- Pending mandate approval		After call ltr to OI:	
25/10	- offer \$20,969.42 (pending acceptance)		Documentation Check List:	
11/11	- TP reject offer. counter propose @ LOD amt 107 full. seek AXA instruction.		Notification ltr (if non-pickup)	
24/12	- offer \$21,149.42 (pending acceptance).		After call ltr to OI:	
10/1	- TP reject offer. propose 9 days LOR. seek AXA instruction.		Authorisation To Act:	
10/1	- Re-offer & settle @ \$21,256.42 as proposed. TP send.		Release Voucher:	
			Final Repair Bill:	
			Car Rental Invoice:	
			Towing Invoice	
			LTA / GIA :	
			Medical Bill:	
			PIR:	
			Mandate/Reject Instruction:	
			LOD	
			Payment Breakdown Form:	
			Post-Repair Photos:	
			Others:	
PRELIMINARY ADVICE Date/Time: Sent By:				
FINALIZATION Date/Time: 8/10/19 Confirm with: Michelle. Confirm by: Taufikn				
Repair Cost: R/P	\$S 17,863.01	(7 days) Reduction: \$5071.52 % 22.	Email ☐	Call ☐
FINAL SETTLEMENT Date/Time: 19/1/2020 Confirm with: Suhaimi Email ☐ Call ☐				
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 22	If NO or B 28, Ass. Lia :	
Repair Cost: (w/ass)	\$S 19,113.42			
Loss of Rental (LOR):	\$S 963.00	(9 days) x \$107 (w/ass)		
Loss of Use (LOU):	\$S -	(\$ x days)		
Loss of Income (LOI):	\$S -	(\$ x days)		
LOR only ☐	LOU only ☐	LOR + LOU ☐	[Tick only one]	
GIA/LTA Search	\$S -			
Medical:	\$S -			
Disbursement:	\$S 1,180.00.	(e.g. Tow/Independent)	1) Claim status: Normal/Reject/Private Settle	
Legal Cost	\$S -		2) Report Format: TP	
Total:	\$S 21,256.42	Global Sum \$S: -	3) Survey fee: \$350.	
FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐				
Payee 1:	\$S 21,256.42.	Name 1: Wearnes Automotive Pte Ltd		
Payee 2: (Strike if N.A.)	\$S -	Name 2: -		
Payee 3: (Strike if N.A.)	\$S -	Name 3: -		

COPY SENT

✓ GIA

ASS. REQ. BY:

Tanjun

REF:

ASM(CAXA)

14311/T1(2)

ASSIGNMENT

From:

Date:

4/9/2019

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SKQ 1012P

at Workshop m/s Wearnes Auto

of 249 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10am - 12pm

Michelle

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

994K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

100%

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN/OUT

Michelle

Veh No:

SKQ 1012P

Yr Regn:

2018, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Grand Scenic

c.c.

1461

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

22496

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VFIRFA00059238184

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

4/9/19 21050

Survey held at

Wearnes Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P \$17,863.01 / - (Red - \$5031.52 / 22%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

Lump Sum / L&L: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

SERVICE ESTIMATE

97039 - C00001 SL: SERVICE SALES - PC

Mr Kenneth Aaron Leong Chong Mun
BLK 922 Jurong West Street 92
#06-35

Singapore 640922

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 15/08/2019

WIP No. : 30808

Veh.In/Out:

*Tel.No. : Mobile: 91805004

Reg.No. : SKQ1012P

Reg.date : 07/06/2018

Mileage : 0

Chassis No: VF1RFA00059238184

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Kenneth Aaron Leo

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BOOT LID, REAR EMBLEM, REAR BUMPER, REAR BRACKET REAR LOWER SPOILER, REAR SENSOR, REAR END PANEL, ETC	0	1	3150.00	0		3,150.00 S	
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR END PANEL, ETC	0	1	1600.00	0		1,600.00 S	
802	TO TRANSFER REAR BOOT LID PART	0	1	250.00	0		250.00 S	
802	TO REPLACE REAR WINDSCREEN	0	1	450.00	0		450.00 S	
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	1	900.00	0		900.00 S	
0080	TO INSTALL REAR WINDSCREEN FIL	0	1	280.00	0		280.00 S	
R06	TO INSTALL REAR NUMBER PLATE	0	1	60.00	0		60.00 S	
INCLUDE HOLDER								
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	1	360.00	0		360.00 S	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Repair party agrees on a "Without Prejudice" basis
- To sign the repair order and
- To sign the repair order and

Signature: _____
Date: _____

Tan Jiah 97415749

4/9/19 1050

Repair before paint

07 days

snv@lkkauto.com

SERVICE ESTIMATE

97039 - C00001 SL: SERVICE SALES - PC

Mr Kenneth Aaron Leong Chong Mun
BLK 922 Jurong West Street 92
#06-35

Singapore 640922

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 15/08/2019

WIP No. : 30808

Veh.In/Out:

*Tel.No. : Mobile: 91805004

Reg.No. : SKQ1012P

Reg.date. : 07/06/2018

Mileage : 0

Chassis No: VF1RFA00059238184

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Kenneth Aaron Leo

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	------	-----	-------	-------	-----	--------	---

BUMPER REAR GS4 BOSS	1.0	EA	883.40	de	883.40	S	795.06 /	
TOWING COVER REAR BU	1.0	EA	49.50	de	49.50	S	44.55 /	
BUMPER REAR PAD GS4	1.0	EA	392.30	de	392.30	S	353.07 /	
BUMPER MOUDLING CLIP	10.0	EA	3.50	re	35.00	S	31.50 /	
BUMPER REAR LOWER MO	1.0	EA	559.20	de	559.20	S	503.28 /	
R850457145R/BUMPER R	1.0	EA	275.60	?	275.60	S	X NN	
BUMPER REAR CENTER B	1.0	EA	265.60	de	265.60	S	239.04 /	
BUMPER REAR LH SUPPO	1.0	EA	84.60	dis	84.60	S	76.14 /	
BUMNER REAR RH SUPP	1.0	EA	84.60	?	84.60	S	X NN	
BUMPER REAR BRACKET	1.0	EA	94.80	re	94.80	S	85.32 /	
BUMPER REAR BRACKET	1.0	EA	94.80	re	94.80	S	85.32 /	
BUMPER PAD SUPPORT B	1.0	EA	64.80	de	64.80	S	116.64 /	
BUMPER RR CENTER UND	1.0	EA	304.50	?	304.50	S	3 X NN	
BUMPER RR RH UNDER C	1.0	EA	174.80	?	174.80	S	159.32 /	
BUMPER RR LH UNDER C	1.0	EA	174.80	de	174.80	S	159.32 /	
TAILGATE ASSY GS4	1.0	EA	1873.10	dis	1,873.10	S	pho 1685.79 /	
TAILGATE OUTER PANEL	1.0	EA	624.40	dis	624.40	S	561.96 /	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval by insurance Company

Acknowledged by Repairer

Signature:

Date:

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X

SERVICE ESTIMATE

97039 - C00001 SL: SERVICE SALES - PC

Mr Kenneth Aaron Leong Chong Mun
BLK 922 Jurong West Street 92
#06-35

Singapore 640922

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date. : 15/08/2019

WIP No. : 30808

Veh.In/Out:

*Tel.No. : Mobile: 91805004

Reg.No. : SKQ1012P

Reg.date. : 07/06/2018

Mileage : 0

Chassis No: VF1RFA00059238184

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Kenneth Aaron Leo

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	TAILGATE OUTER PANEL	1.0 EA	344.50			344.50 S	310.05
	RIVET FIX P	5.0 EA	6.50			32.50 S	29.25
	LOGO REAR "DIAMOND"	1.0 EA	123.50			123.50 S	111.15
	EMBLEM "SCENIC" GS4	1.0 EA	97.70			97.70 S	87.93
	"RENAULT" EMBLEM REA	1.0 EA	112.80			112.80 S	101.52
	WINDSCREEN REAR GS4	1.0 EA	375.20			375.20 S	337.68
	PRIMER	1.0 EA	176.60			176.60 S	158.94
	BODY PANEL SEALANT X	1.0 EA	883.20			883.20 S	794.88
	ADHESIVE SEALER FL2	1.0 EA	669.10			669.10 S	602.19
	PARKING SENSOR FRT/B	4.0 EA	199.80			799.20 S	X NN

Gross Total. 16,700.10

Labour Total 7,050.00
Parts Total 9,650.10
Package Total 0.00

Net..... 16,700.10
GST @ 7.0% 1,169.01
Total..... 17,869.10
Paid..... 0.00
Please Pay.. 17,869.10

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Supplementary List

SERVICE ESTIMATE

O - A00005 SL: AXA INSURANCE PTE LTD
 AXA INSURANCE PTE LTD
 8 SHENTON WAY,
 #27-01 AXA TOWER,
 SINGAPORE 068811

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 24/09/2019
 WIP No. . : 30808
 Veh.In/Out: 04/09/2019 20/09/2019
 *Tel.No. . : 6338 7288
 Reg.No. . : SKQ1012P
 Reg.date . : 07/06/2018
 Mileage . . : 22,496
 Chassis No: VF1RFA00059238184

Closed by : Michelle Ong Siew Be
 Svc Consultant : ACC
 Remarks : Mr Kenneth Aaron Leo

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE SPARE TYRE PANEL,		0	1350.00	0		1,350.00	S ✓
END PANEL,								
802	TO REPLACE EXHAUST		0	450.00	0		450.00	S ✓
	BOOT SILL PLATE "G/S	1.0	EA	309.70	10	bt	278.73	S ✓
	BUMPER HARNESS REAR	1.0	EA	133.20	10	tn	119.88	S ✓
	BLIND SPOT SENSOR GS	1.0	EA	341.00	10	nw	306.90	S ✓
	RIVET BLACK, BUMPER	10.0	EA	6.70	10	nei	60.30	S ✓
	RIVET SILVER, REAR B	20.0	EA	0.60	10	nei	10.80	S ✓
	CLIP INDEXA	10.0	EA	5.60	10	nei	50.40	S ✓
	WINDSCREEN SEALANT	2.0	EA	112.10	10	nei	201.78	S ✓
	BUMPER REAR REINFORC	1.0	EA	511.10	10	bt	459.99	S ✓
	REINFORCEMENT REAR P	1.0	EA	651.70	10	bt	586.53	S ✓
	EXHAUST PIPE REAR SI	1.0	EA	593.10	10	bt	533.79	S ✓
	EXHAUST CLAMP X50 M4	1.0	EA	62.40	10	bt	56.16	S ✓
	SPARE TYPE PANEL GS4	1.0	EA	955.80	10	bt	860.22	S ✓
	BUMPER BOLT 10 SILVE	10.0	EA	3.20	10	nei	28.80	S ✓
	HEAT SHIELD REAR END	1.0	EA	192.10	10	bt	172.89	S ✓

\$22894.53

Supplementary List

SERVICE ESTIMATE

O - A00005 SL: AXA INSURANCE PTE LTD
 AXA INSURANCE PTE LTD GST Reg.No:M28920628X
 8 SHENTON WAY, Inv.No. . : B&P 0 Page 2
 #27-01 AXA TOWER, Inv.date. : 24/09/2019
 SINGAPORE 068811 WIP No. . : 30808
 Veh.In/Out: 04/09/2019 20/09/2019
 *Tel.No. . : 6338 7288
 Reg.No. . : SKQ1012P
 Closed by : Michelle Ong Siew Be Reg.date. : 07/06/2018
 Svc Consultant : ACC Mileage . : 22,496
 Remarks : Mr Kenneth Aaron Leo Chassis No: VF1RFA00059238184

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER REAR LH PAD (	1.0 EA	393.90	10	de ✓	354.51	S ✓
	STORAGE REAR BOARD T	1.0 EA	200.70	10	de ✓	180.63	S ✓
	TAILGATE BODY SEAL G	1.0 EA	146.80	10	de ✓	132.12	S ✓

			Gross Total.	6,194.43
Labour Total	1,800.00	Net.....	6,194.43	
Parts Total	4,394.43	GST @ 7.0%	433.61	
Package Total	0.00	Total.....	6,628.04	
		Paid.....	0.00	
		Please Pay..	6,628.04	

GST: S=StdRated; O=OutOfScope; Z=ZeroRated