

Singer: NazASSIGNMENT (Office)From (Person): Crystal Lee of MSL Date/Time: 15/8/19 @ 4:54pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 4200 E Insured: SKM 64785at Workshop m/s Premier Automotive Tel: 65446682of 23 Changi South Avenue 2 # 01-02

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13/8/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 10:18am @ 16/8/19 Person Contacted: Vineet Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>Tahany /</u>
	<u>SLC 4200 E - X</u>
	<u>SKM 64785 - CS/MSG 17009057/ u21422</u>
	<u>D.O.A. - 04/04/2017</u>
	<u>Part by part \$3099.94. (Red: 60.00; 20%)</u>

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Thursday, 15 August 2019 4:54 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned

TP SLC4200E DOA: 13/08/19 SKM6478S

Manual Assigned

Dear LKK,

Refer to the email, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

-----Original Message-----

From: Helene Phua

Sent: Thursday, 15 August, 2019 11:50 AM

To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>

Subject: FW: TP SLC4200E DOA: 13/08/19 SKM6478S CAR IN?

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220
9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

-----Original Message-----

From: Helene Phua

Sent: Thursday, 15 August, 2019 11:49 AM

To: Goh Wee Dek <weedek.goh@premiertaxi.com>

Cc: Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>; Vincent Chua <vincent.chua@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>; Monica Chung <Monica_Chung@sg.msig-asia.com>

Subject: RE: TP SLC4200E DOA: 13/08/19 SKM6478S CAR IN?

Hi Wee Dek ,

Thank you for your selection.

We will proceed to assign LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

-----Original Message-----

From: Goh Wee Dek [mailto:weedek.goh@premiertaxi.com]

Sent: Wednesday, 14 August, 2019 5:51 PM

To: Winnie Chua <pingping_chua@sg.msig-asia.com>

Cc: Helene Phua <helene_phua@sg.msig-asia.com>; Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>; Vincent Chua <vincent.chua@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>

Subject: RE: TP SLC4200E DOA: 13/08/19 SKM6478S CAR IN?

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Winnie

We prefer LKK Auto.

please arrange. Thanks

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511 Visit us at:
<https://protect2.fireeye.com/url?k=332a4636-6f39dea0-332d4a63-0cc47a6d1990-7ddd6a2484248387&q=1&u=http%3A%2F%2Fwww.premiertaxi.com.sg%2F>

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

☐ Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION ☐

-----Original Message-----

From: Winnie Chua [mailto:pingping_chua@sg.msig-asia.com]
Sent: Wednesday, 14 August, 2019 5:48 PM
To: Vincent Chua; Goh Wee Dek; Liew Hai Leong
Cc: Helene Phua; Nabilah Rasol
Subject: FW: TP SLC4200E DOA: 13/08/19 SKM6478S CAR IN?

Hi,

We refer to your email/faxed dated 14/08/19.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) MSIG In-House Surveyors (Appointment is full on 15.08.19)

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

- 1) Kalvin Ang 6) Frankie Pang
- 2) Kenneth Kong 7) Ng You Han
- 3) Marcus Chua 8) Gary Soon
- 4) Henry Ng 9) Chow Bo Xiong
- 5) Lau Kwok Kwong 10) Axel Lee

NB:

(a) *Fast lane settlement is not applicable for cases that liability is in dispute* (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey) Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 19 Aug 2019

Preliminary Advice

Insured Vehicle No	: SKM6478S	Accident Date	: 13/08/2019
TP Vehicle No	: SLC4200E	Assignment Date	: 19/08/2019
Make	: HONDA VEZEL	Est. Duration of Repair	: 6.00
Date of Inspection	: 16/08/2019		
Inspection At	: PREMIER AUTOMOTIVE SERVICES PTE LTD (HQ) 23 CHANGI SOUTH AVE 2, #01-02 SINGAPORE 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,066.77 (Labour Only)
Revised Amount	:S\$	931.77
Check Items (Estimated)	:S\$	0.00
Total	:S\$	931.77

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.


(x) The above survey was conducted on a 'without prejudice' basis.

Denise Tay (LKKAuto)


From: Goh Wee Dek <weedek.goh@premiertaxi.com>
Sent: Saturday, 12 October 2019 10:06 AM
To: Denise Tay (LKKAuto)
Subject: RE: SLC 4200E / TP / DOA: 13/8/2019

Dear Denise

3167 & 3168 Both are the tailgate moulding and rear window seal is the lower moulding.
Total 3 moulding for this model.



The lower tailgate is referring to the rear under cover in the invoice.



Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Friday, 11 October, 2019 5:23 PM
To: Goh Wee Dek
Subject: RE: SLC 4200E / TP / DOA: 13/8/2019

Dear Wee Dek,

Naz is asking 3167. L/R Window Seal & 3168. R/R Window Seal is not necessary as the fender R&L is not change.

Secondly the 4981. Lower Tail gate \$65 is not found in the invoice.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh Wee Dek <weedek.goh@premiertaxi.com>
Sent: Thursday, 3 October 2019 1:28 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: FW: SLC 4200E / TP / DOA: 13/8/2019

Hi Denise

Any outcome to this finalize?

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Goh Wee Dek
Sent: Wednesday, 18 September, 2019 2:01 PM
To: 'Denise Tay (LKKAuto)'
Subject: RE: SLC 4200E / TP / DOA: 13/8/2019

Already sent to Naz for finalization.

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Denise Tay (LKKAuto) [<mailto:denisetay@lkkauto.com>]
Sent: Wednesday, 18 September, 2019 1:51 PM
To: Goh Wee Dek
Subject: SLC 4200E / TP / DOA: 13/8/2019

Dear Wee Dek,

Can finalized?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/08/2019 09:21
Date Of Accident	13/08/2019 19:40
Exact Location Of Accident	SLE - WOODLANDS (AFTER THOMSON EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC4200E
Insured/Policyholder	
Name Of Registered Owner	NG YAN LIN
NRIC No	S8521898J
Email Address	NGYANLIN01@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91735876
Alternative Phone No	OTHERS-91735876

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5080205880-03
Cover Note Number	

Driver

Name of Driver	NG YAN LIN
NRIC No	S8521898J
Date Of Birth	11/07/1985
Occupation	OUTDOOR
Date Of Driving Pass	28/06/2007
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91735876
Fax Number	
Contact Number	OTHERS-91735876
Email Address	NGYANLIN01@GMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 14/8/19 12:27H

Driver's Signature

(if driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 1940H, I was driving at SLE ~~towards~~ towards Woodlands. A car stopped suddenly in front of me. I stopped and the car behind rear-ended me. I felt my neck and back slightly stiff and will consult a doctor.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 14/8/19 0025H


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 14/8/19 0025H

14 AUG 2019


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SLC4200E

Version: 1810

Date calculated: 16/08/2019 11:09 AM

Full Report

Registration: SLC4200E

Printed: 16/08/2019 11:10 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Holdings (Asia) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	13/08/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	HONDA
Model:	VEZEL/HR-V RU1/5
Sub Model:	BASE MODEL
Model Sheet Number:	35 VE 01
Registration:	SLC4200E
VIN number:	
Odometer:	

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SLC4200E

Version: 1810

Date calculated: 16/08/2019 11:09 AM

Full Report

Registration: SLC4200E

Printed: 16/08/2019 11:10 AM

Vehicle Condition

Vehicle Status


Pre-Accident Damage:

Date of Inspection:

Damage Areas

All

Underbody

☐☐

Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
7141A0	R + R LEFT OUTER TAILLAMP		XNN 1.0	5.00
8131A8	R + R LEFT REAR WHEELHOUSE SHELL		XNN 3.0	15.00
7141A5	R + R RIGHT OUTER TAILLAMP		XNN 1.0	5.00
8131A9	R + R RIGHT REAR WHEELHOUSE SHELL		XNN 3.0	15.00
8111A5	RENEW REAR BUMPER		7.0	35.00
	INCLUDES: REMOVE AND REFIT REAR BUMPER, BUMPER CORNERS AND REQUIRED ATTACHED PARTS.			
823100	RENEW TAILGATE		32.0	160.00
	INCLUDES: R + R TAILGATE, CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
8231C2)	R + R MANUFACTURER BADGE		1.0	5.00
NO NUMBER	RENEW REAR PANEL		? ✓ 42.0	210.00
8131B2	R + R LOWER COVER		2.0	10.00
8571C8)	R + R L/R SIDE PANEL TRIM		XNN 2.0	10.00

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SLC4200E

Version: 1810

Date calculated: 16/08/2019 11:09 AM

Full Report

Registration: SLC4200E

Printed: 16/08/2019 11:10 AM

Material Cost - Paint

New Part Painting	63.36
New Part Painting - Plastic K1R	14.66
Surface-/Blend Paint	21.65
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	126.77

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Supplier	Price SGD	
2583	REAR BUMPER	71501T8NT00	CRK	180	0.00
2587	L/R BUMPER CORNER	71507T7JH00ZZ	X R	X	0.00
2588	R/R BUMPER CORNER	71502T7JH00ZZ	X R	X	0.00
2711	REAR PANEL	66100T8NT00ZZ	? / DD	270	0.00
2931	BOOTLID/TAILGATE	68100T8PU00ZZ	BD	650	0.00
2944	BOOT/TAILGATE SEAL	74440T7A003	NEC	45	0.00
2973	REAR LOCK STRIKER	74813T5A003	X SVC	X	0.00
2977	BOOT/TAILGATE LOCK	74800T7AJ02	JAM	65	0.00
2997	L/TAILGATE DAMPER	74870T7JH01	X SVC	X	0.00
2998	R/TAILGATE DAMPER	74820T7JH01	X SVC	X	0.00
3015	MANUFACTURER BADGE	75701T5A000	NBC	X	0.00
3017	BADGE MODEL	75722T7WA01	NBC	X	0.00
3161	LWR REAR SCREEN SEAL	73226SZW000	NBC	15	0.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS	NH XNN		
3165	UPP R-SCREEN SEAL	SEE GUIDE NO. 3161	NBC	15	
3170	CHECK	91502S70003			0.00
3171	CHECK	91501S70003			0.00
3173	CHECK	91536SS0J01			0.00
3281	L/R OUTER LAMP	33552T7AJ01	X SVC	240 / CRK	0.00
3283	L/R INNER LAMP	34155T7SA01	X SVC		0.00
4907	INNER TAILGATE TRIM	84431T8NT01ZA	X SVC		0.00
4909	L/INN TALGATE COVER	84485T8NT01ZA	X SVC		0.00
4910	R/INN TAILGATE COVER	84435T8NT01ZA	X SVC		0.00
4981	LOWER TAILGATE	74646T7MH00	? DEF	65	0.00
4985	END PANEL TRIM	84640T8NT01ZA	? / DEF	38	0.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				
u: Used parts	Total				0.00

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SLC4200E

Version: 1810

Date calculated: 16/08/2019 11:09 AM

Full Report

Registration: SLC4200E

Printed: 16/08/2019 11:10 AM

Final Calculation

	SGD	SGD
Labour Time Base 10 WU/h		
Total 116.0 WU X 50.00 SGD/h	580.00	580.00
Total of Labour		
Paint Work Time Base 10 WU/h		
Labour Cost 72.0 WU X 50.00 SGD/h	360.00	360.00
Material Cost	126.77	126.77
Total Paint Including Material		486.77
Repair Cost Excludes GST		1,066.77
GST (+7.0%)		74.67
Repair Cost Included GST		1,141.44

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

NAZ LUK
16/8/19 1730
LIS 6 Days
CHECK ITEMS PHOTO
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SLC4200E

Version: 1810

Date calculated: 16/08/2019 11:09 AM

Full Report

Registration: SLC4200E

Printed: 16/08/2019 11:10 AM

Code	Description		WU	Price SGD
8571C9)	R + R R/R SIDE PANEL TRIM	XNN	2.0	10.00
3900	FRONT BOOT FLOOR REPAIR	10	20.0*	100.00
Labour Cost				
	Panel / Mechanical Labour	Hrs	WU	
		11.60	116.0	580.00
Total of Labour				580.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR PANEL NEW PART PAINTING	?	17.0	19
	BOOTLID/TAILGATE NEW PART PAINTING		18.0	19
	L/R BUMPER CORNER NEW PART PAINT K1R	XNN	4.0	
	R/R BUMPER CORNER NEW PART PAINT K1R	XNN	4.0	
	FRONT BOOT FLOOR SURFACE PAINT		9.0	18

Paint Material Per Part

Code	Description		Price SGD
2711	REAR PANEL NEW PART PAINTING	20.90	16.61
2931	BOOTLID/TAILGATE NEW PART PAINTING	59.86	46.75
2587	L/R BUMPER CORNER NEW PART PAINT K1R	XNN	7.33
2588	R/R BUMPER CORNER NEW PART PAINT K1R	XNN	7.33
3900	FRONT BOOT FLOOR SURFACE PAINT	30.43	21.65

Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			52.0	
	Preparation Main Work Metal		1.70	17.0	85.00
	Preparation Comp. Work Plastic		0.30	3.0	15.00
Total		10 WU/h	7.20	72.0	360.00

Premier Automotive Services Pte Ltd
#01-02, 23 Changi Sth Ave 2
486443

Insurer Reference:
Repairer Reference: SLC4200E
Date calculated: 04/09/2019 2:51 PM

Full Report
Registration: SLC4200E
Printed: 10/09/2019 3:48 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Holdings (Asia) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	13/08/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle
Manufacturer: HONDA
Model: VEZEL/HR-V RU1/5
Sub Model: BASE MODEL
Model Sheet Number: 35 VE 01
Registration: SLC4200E
VIN number:
Odometer:
Model Specs
PREPARE OFF VEHICLE BASECOAT CLEAR

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Premier Automotive Services Pte Ltd
#01-02, 23 Changi Sth Ave 2
486443

Insurer Reference:
Repairer Reference: SLC4200E
Date calculated: 04/09/2019 2:51 PM

Full Report
Registration: SLC4200E
Printed: 10/09/2019 3:48 PM

Code	Description	WU	Price SGD
7141A0	R + R LEFT OUTER TAILLAMP	1.0	5.00
8131A8	R + R LEFT REAR WHEELHOUSE SHELL	3.0	15.00
7141A5	R + R RIGHT OUTER TAILLAMP	1.0	5.00
8131A9	R + R RIGHT REAR WHEELHOUSE SHELL	3.0	15.00
8111A5	RENEW REAR BUMPER INCLUDES: REMOVE AND REFIT REAR BUMPER, BUMPER CORNERS AND REQUIRED ATTACHED PARTS.	7.0	35.00
823100	RENEW TAILGATE INCLUDES: R + R TAILGATE, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	32.0	160.00
8231C2)	R + R MANUFACTURER BADGE	1.0	5.00
NO NUMBER	RENEW REAR PANEL	42.0	210.00
8131B2	R + R LOWER COVER	2.0	10.00
8571C8)	R + R L/R SIDE PANEL TRIM	2.0	10.00
8571C9)	R + R R/R SIDE PANEL TRIM	2.0	10.00
3900	FRONT BOOT FLOOR REPAIR	10.0*	50.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		10.60	106.0
Total of Labour			530.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - BASECOAT CLEAR	WU Price SGD
	REAR PANEL NEW PART PAINTING	19.0
	BOOTLID/TAILGATE NEW PART PAINTING	19.0
	FRONT BOOT FLOOR SURFACE PAINT	10.0

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	20.90
2931	BOOTLID/TAILGATE NEW PART PAINTING	59.86
3900	FRONT BOOT FLOOR SURFACE PAINT	30.63

Premier Automotive Services Pte Ltd
#01-02, 23 Changi Sth Ave 2
486443

Insurer Reference:
 Repairer Reference: SLC4200E
 Date calculated: 04/09/2019 2:51 PM

Full Report
 Registration: SLC4200E
 Printed: 10/09/2019 3:48 PM

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	50.00 SGD/h		
Time Paint		48.0	
Preparation Main Work Metal	2.50	25.0	125.00
Total	10 WU/h	73.0	365.00

Material Cost - Paint	Price SGD
New Part Painting	80.76
Surface-/Blend Paint	30.63
Material-constant Metal Preparation	28.60
Total	139.99

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	71501T8NT00	/ CRK	180.00
2711	REAR PANEL	66100T8NT00ZZ	- DO	270.00
2931	BOOTLID/TAILGATE	68100T8PU00ZZ	- DO	650.00
2944	BOOT/TAILGATE SEAL	74440T7A003	- NEL	45.00
2977	BOOT/TAILGATE LOCK	74800T7AJ02	- TAM	65.00
3161	LWR REAR SCREEN SEAL	73226SZW000	- NEL	15.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS	/ NEL	
3165	UPP R-SCREEN SEAL	SEE GUIDE NO. 3161	/ NEL	15.00
3167	L/R WINDOW SEAL	73254T7JH01	/ NEL	15.00
3168	R/R WINDOW SEAL	73214T7JH01	/ NEL	15.00
3170	CHECK	91502S70003		0.00
3171	CHECK	91501S70003		0.00
3173	CHECK	91536SS0J01		0.00
3281	L/R OUTER LAMP	33552T7AJ01	/ CRK	240.00
4981	LOWER TAILGATE	74646T7MH00	- DEF	65.00
4985	END PANEL TRIM	84640T8NT01ZA	- DEF	38.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,613.00
u: Used parts	Addition(+15.00%)			241.95
	Total			1,854.95

Extras

Code	Description	Price SGD
1000	REAR BUMPER CLIPS - NEL 3(A)	30.00*
1001	REVERSE SENSOR - MIS	180.00*
	Total Extras	210.00

Premier Automotive Services Pte Ltd
#01-02, 23 Changi Sth Ave 2
486443

Insurer Reference:
Repairer Reference: SLC4200E
Date calculated: 04/09/2019 2:51 PM

Full Report
Registration: SLC4200E
Printed: 10/09/2019 3:48 PM

Code	Description	Price SGD
------	-------------	-----------

Final Calculation

	SGD	SGD
Parts	1,613.00	
Addition(+15.00%)	241.95	
Total Parts		1,854.95
Labour Time Base 10 WU/h		
Total 106.0 WU X 50.00 SGD/h	530.00	
Total of Labour		530.00
Total Of Extras		210.00
Paint Work Time Base 10 WU/h		
Labour Cost 73.0 WU X 50.00 SGD/h	365.00	
Material Cost	139.99	
Total Paint Including Material		504.99
Repair Cost Excludes GST		3,099.94
GST (+7.0%)		217.00
Repair Cost Included GST		3,316.94

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 728672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 6417 9791 / 6745 9835

Dept Direct: 6305 9610

Dept Direct: 6303 9011

Dept Direct: 6417 9792

Dept Direct: 6417 9793

Dept Direct: 6417 9790

Dept Direct: 6417 9791

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PREMIER AUTOMOTIVE SERVICES PTE LTD
23 CHANGI SOUTH AVE 2
#01-02

SINGAPORE 486443
TEL: 6303 4743 FAX: 6466 3050
ATTN: TING TING / LAILENG

SEND Street 71 Woodland Ave 10, #04-07 Woodlands Industrial
Exchange, Singapore 737743

TAX INVOICE : AR201908-07941
DATE : 19/08/2019
CUSTOMER ID : PRE008
VEH REG. NO. : SLC4200E
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H71501-T8N-T10ZZ RU1 15	RR BUMPER(W/O HOLE)	CC C16-B2-1	1	180.00	180.00
2	H66100-T7A-300ZZ RU1	PANEL RR	CC C17-R1-03B	1	270.00	270.00
3	H74646-T7M-H00 RU1	REAR UNDER COVER	CC C17-A1-4S	1	65.00	65.00
4	H33552-T7A-J01 RU1	TAIL LAMP UNIT LH	CC C16-D1-2C	1	240.00	240.00
5	H74440-T7A-003	W/STRIP, TAILGATE	CC C16-F1-1AC	1	45.00	45.00

Inventory
Accident Repairs
Routine Maintenance
Preventive Maintenance
Surveyor Fees
Other Expenses

PU 128/119

Auto-1909011706

Parts

Pls specify : _____

Checked by : _____

on : _____

Approved by : _____

on : _____

SUB-TOTAL : 800.00
ADD GST 7.00 % 56.00

TOTAL AMOUNT S\$: 856.00

[P] 19/08/2019 15:00:09

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 19/08/2019 2:51:42PM

JAE Auto/Pte. Ltd.

Sales Executive: CHEN

This is computer generated document.

No signature is required.



* AR201908-07941 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 9417 9794

Dept Direct: 9417 9796

Dept Direct: 9417 9798

Dept Direct: 9417 9799

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PREMIER AUTOMOTIVE SERVICES PTE LTD
23 CHANGI SOUTH AVE 2
#01-02

SINGAPORE 486443
TEL: 6303 4743 FAX: 6466 3050
ATTN: TING TING / LAI LENG

SEND Street 71 Woodland Ave 10, #04-07 Woodlands Industrial
Exchange, Singapore 737743

TAX INVOICE : AR201908-07944
DATE : 19/08/2019
CUSTOMER ID : PRE008
VEH REG. NO. : SLC4200E
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	H84640-T8N-T01ZA	LINING, RR PANEL	PA PL1-M1-09A	1	38.00	38.00
2.	H74800-T7A-J01/J02	BOOT LOCK	PA PL1-L1-05I	1	65.00	65.00
3.	H73226-SZW-000	RR GLASS TOP MLD	PA PL1-P1-10A	2	15.00	30.00
	RUI GK8					
	GK3 FIT / RC1 ODY 14"/RM3					

Inventory *PV 13/8/19*

Accident Repairs

Routine Maintenance

Preventive Maintenance

Surveyor Fees *PAUTU-190901710*

Other Expenses

Pls specify : *Parts*

Checked by : *WPP 12/11*

on : *3/9/19*

Approved by : *Lawrence Ong*

on : *4/9/19*

SUB-TOTAL : 133.00
ADD GST 7.00 % 9.31

E. & O.E

TOTAL AMOUNT S\$: 142.31

[P] 19/08/2019 15:00:33

[E] 19/08/2019 2:53:18PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: CHEN

This is computer generated document.
No signature is required.



* AR201908-07944 *

ORIGINAL

Goods Received in Good Order

a

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PREMIER AUTOMOTIVE SERVICES PTE LTD
23 CHANGI SOUTH AVE 2
#01-02

SINGAPORE 486443

TEL: 6303 4743 FAX: 6466 3050

A1 : TING TING / LAI LENG 90611218

382ND Street 71 Woodland Ave 10, #04-07 Woodlands Industrial
Exchange, Singapore 737743

TAX INVOICE : AR201908-07948
DATE : 19/08/2019
CUSTOMER ID : PRE008
VEH REG. NO. : SLC4200E
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1 H73214-T7J-H01	73215-T7A-003/73226-T8C-003 R/RH SEAL	MO	1	15.00	15.00
	RUI VEZEL 14"	1A62			
2 H73254-T7J-H01	73265-T7A-003/73276-T8C-003 R/LH SEAL	MO	1	15.00	15.00
	RUI VEZEL 14"	1A62			

Inventory
Accident Repairs
Routine Maintenance
Preventive Maintenance
Surveyor Fees
Other Expenses

Pls specify : _____

Checked by : _____
on : _____

Approved by : _____
on : _____

SUB-TOTAL : 30.00
ADD GST 7.00 % 2.10

E. & O.E

TOTAL AMOUNT S\$: 32.10

P] 19/08/2019 2:57:01PM

[E] 19/08/2019 2:56:37PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

AE Auto Pte. Ltd.

Sales Executive : CHEN

This is computer generated document.

No signature is required.



* A R 2 0 1 9 0 8 - 0 7 9 4 8 *

Goods Received in Good Order

(Signature)

Signature / Co Stamp / Date

for GMA AUTOMOTIVE SERVICES

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2019		19 Aug 2019 10:49 Edit Adj Rpt	S\$3,099.94 Edit Estimates	S\$3,099.94 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	PREMIER RENT A CAR PTE LTD , Co. Reg. No.: 200612929E								
Main Claimant:	NG YAN LIN , ID: S85218981								
Vehicle Reg. No.:	SLC4200E	Date of Loss:	13/08/2019 19:00 - :59 [39 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 602823	Policy/Cover Note No.:	29123112 (Third Party Only) Coverage: 01/05/2019 - 30/04/2020						
Vehicle Reg. No. (Insured):	SKM64785	Policy No. (Claimant):							
		Excess:							
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazri Bin Abdullah] ... [Final Rpt due 18/09/2019]								
Driver/Custodian (Insured):	ONG KIAN HOW (), NRIC: S78716021, Tel: +6596849006 Email:								
Adj Asg. Remarks:	on WP. (Manual Assign). Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Wee Dek @ 6544 6682 / 6214 8880 ext 068. Manual assign to LKK via email on 15/08/2019.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC4200E (602823)
[SKM64785]
TP
NG YAN LIN
Aug 13 2019 7:00PM
[PREMIER RENT A CAR PTE LTD]
Premier Automotive Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports						1 per page 1	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print
1	19/08/19 10:35	Accident Statement From: SC - Reg. No: SKM64785, Claimant: PREMIER RENT A CAR PTE LTD				 Load HTM	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	19/08/19 17:43	Adjuster Immediate Advice				 Load HTM	Print
Photos/Images						3 per page 3	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	19/08/19 15:07	General View				 Load JPG	☒
2	19/08/19 15:07	General View				 Load JPG	☒
3	19/08/19 15:07	General View				 Load JPG	☒
4	19/08/19 15:07	General View				 Load JPG	☒
5	19/08/19 15:07	General View				 Load JPG	☒
6	19/08/19 15:07	General View				 Load JPG	☒
7	19/08/19 15:07	General View				 Load JPG	☒
8	19/08/19 15:07	General View				 Load JPG	☒
9	19/08/19 15:07	General View				 Load JPG	☒
10	19/08/19 15:07	General View				 Load JPG	☒
11	19/08/19 15:07	General View				 Load JPG	☒
12	19/08/19 15:07	General View				 Load JPG	☒
13	19/08/19 15:07	General View				 Load JPG	☒
14	19/08/19 15:07	General View				 Load JPG	☒
15	19/08/19 15:07	General View				 Load JPG	☒
16	19/08/19 15:07	General View				 Load JPG	☒
17	19/08/19 15:07	General View				 Load JPG	☒
18	19/08/19 15:07	General View				 Load JPG	☒
19	19/08/19 15:07	General View				 Load JPG	☒
20	19/08/19 15:07	General View				 Load JPG	☒
21	19/08/19 15:07	General View				 Load JPG	☒
22	19/08/19 15:07	General View				 Load JPG	☒
23	19/08/19 15:07	General View				 Load JPG	☒
24	18/10/19 17:38	Reinspection Photo				 Load JPG	☒
25	18/10/19 17:38	Reinspection Photo				 Load JPG	☒
26	18/10/19 17:38	Reinspection Photo				 Load JPG	☒
27	18/10/19 17:38	Reinspection Photo				 Load JPG	☒
28	18/10/19 17:38	Reinspection Photo				 Load JPG	☒
29	18/10/19 17:38	Reinspection Photo				 Load JPG	☒
30	18/10/19 17:38	Reinspection Photo				 Load JPG	☒
31	18/10/19 17:38	Reinspection Photo				 Load JPG	☒
32	18/10/19 17:38	Reinspection Photo				 Load JPG	☒
33	18/10/19 17:38	Reinspection Photo				 Load JPG	☒
34	18/10/19 17:38	Reinspection Photo				 Load JPG	☒
35	18/10/19 17:39	Before Repair Photo				 Load JPG	☒
36	18/10/19 17:39	Before Repair Photo				 Load JPG	☒
Documentation						1 per page 1	

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
					☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	19/08/19 10:35	PRI Notification	1	Load PDF	
2	19/08/19 10:36	SLC4200E GIA Rpt	1	Load PDF	
3	19/08/19 10:46	Agree on SJE	1	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	19/08/19 10:46	Survey Request - Manual Assigned	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/11/19 09:01	Parts Invoice	1	Load PDF	
2	12/11/19 09:05	Supplementary	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014313/NTF3E2

Date: 12/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29123112

Claimant

Vehicle No : SLC4200E

Insured Vehicle No : SKM6478S

Date of Loss: 13/08/2019

Nature of Claim: TP

Claim No: 602823

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC4200E

Make & Model: HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD
5DR (A)

Engine No: L15B4032169

Reg. Date: 13/05/2016 (Man. Year: 2015)

Chassis No: RU11112164

Colour: White

Odometer: 77591 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Maxxis 6 mm

Rear Left Side:

Maxxis 6 mm

Front Right Side: Maxxis 6 mm

Rear Right Side:

Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,064.95	2,064.95	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,084.99	1,034.99	50.00	4.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,149.94	3,099.94	50.00	1.59
+ GST 7.00/7.00% (S\$)	220.50	217.00	3.50	1.59
Nett Amount (S\$)	3,370.44	3,316.94	53.50	1.59

INSPECTION

Date of Assignment: 19/08/2019

Date Inspected: 16/08/2019 Inspected At:

Premier Automotive Services Pte Ltd
(HQ)23 Changi South Ave 2, #01-02
Singapore 486443

Estimated Period of Repair: 6.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2019)
Parts:	144	HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC4200E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Cracked	180.00 F	*180.00 F
2	1		*L/R BUMPER CORNER (NPA)	Repair	0.00 F	*- F
3	1		*R/R BUMPER CORNER (NPA)	Repair	0.00 F	*- F
4	1		*REAR PANEL (WCP)	Dented	270.00 F	*270.00 F
5	1		*BOOTLID / TAILGATE (WCP)	Dented	650.00 F	*650.00 F
6	1		*BOOT / TAILGATE SEAL (WCP)	Necessary	45.00 F	*45.00 F
7	1		*REAR LOCK STRIKER (NPA)	Serviceable	0.00 F	*- F
8	1		*BOOT / TAILGATE LOCK (WCP)	Jammed	65.00 F	*65.00 F
9	1		*L/TAIlgATE DAMPER (NPA)	Serviceable	0.00 F	*- F
10	1		*R/TAIlgATE DAMPER (NPA)	Serviceable	0.00 F	*- F
11	1		*MANUFACTURER BADGE (NPA)	Necessary	0.00 F	*- F
12	1		*BADGE MODEL (NPA)	Necessary	0.00 F	*- F
13	1		*LWR REAR SCREEN SEAL (WCP)	Necessary	15.00 F	*15.00 F
14	1		*SET REAR SCREEN FIX (NPA)	Not Necessary	0.00 F	*- F
15	1		*UPP R-SCREEN SEAL (WCP)	Necessary	15.00 F	*15.00 F
16	1		*L/R OUTER LAMP (WCP)	Cracked	240.00 F	*240.00 F
17	1		*L/R INNER LAMP (NPA)	Serviceable	0.00 F	*- F
18	1		*INNER TAILGATE TRIM (NPA)	Serviceable	0.00 F	*- F
19	1		*L/INN TAILGATE COVER (NPA)	Serviceable	0.00 F	*- F
20	1		*R/INN TAILGATE COVER (NPA)	Serviceable	0.00 F	*- F
21	1		*LOWER TAILGATE (WCP)	Deformed	65.00 F	*65.00 F
22	1		*END PANEL TRIM (WCP)	Deformed	38.00 F	*38.00 F
23	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
24	1		*REVERSE SENSOR	Missing	180.00 FS	*180.00 FS
25	1		*L/R WINDOW SEAL (WCP)	Necessary	15.00 F	*15.00 F
26	1		*R/R WINDOW SEAL (WCP)	Necessary	15.00 F	*15.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	1,823.00	1,823.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	241.95	241.95
Total Parts (\$\$)	2,064.95	2,064.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	116.0 WU X 50.00 SGD/H	New	580.00	530.00
2	LABOUR COST 72.0 WU X 50.00 SGD/H	New	365.00	365.00
3	MATERIAL COST	New	139.99	139.99
Gross Labour Cost (S\$)			1,084.99	1,034.99

Report was unsubmitted during this print-out.

< END OF ESTIMATES >