

Premier Automotive Services Pte Ltd
#01-02, 23 Changi Sth Ave 2
486443

Insurer Reference:
 Repairer Reference: SLC4200E
 Date calculated: 04/09/2019 2:51 PM

Full Report
 Registration: SLC4200E
 Printed: 10/09/2019 3:48 PM

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	50.00 SGD/h		
Time Paint		48.0	
Preparation Main Work Metal	2.50	25.0	125.00
Total	10 WU/h	73.0	365.00

Material Cost - Paint	Price SGD
New Part Painting	80.76
Surface-/Blend Paint	30.63
Material-constant Metal Preparation	28.60
Total	139.99

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
2583	REAR BUMPER	71501T8NT00	✓ CRK		180.00
2711	REAR PANEL	66100T8NT00ZZ	✓ DD		270.00
2931	BOOTLID/TAILGATE	68100T8PU00ZZ	✓ DD		650.00
2944	BOOT/TAILGATE SEAL	74440T7A003	✓ NEL		45.00
2977	BOOT/TAILGATE LOCK	74800T7AJ02	✓ JAM		65.00
3161	LWR REAR SCREEN SEAL	73226SZW000	✓ NEL		15.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS	✓ NEL		
3165	UPP R-SCREEN SEAL	SEE GUIDE NO. 3161	✓ NEL		15.00
3167	L/R WINDOW SEAL	73254T7JH01	3 jam X CRK ✓ NEL		15.00
3168	R/R WINDOW SEAL	73214T7JH01	X CRK ✓ NEL		15.00
3170	CHECK	91502S70003			0.00
3171	CHECK	91501S70003			0.00
3173	CHECK	91536SS0J01			0.00
3281	L/R OUTER LAMP	33552T7AJ01	✓ CRK		240.00
4981	LOWER TAILGATE	74646T7MH00	2 - DEF		65.00
4985	END PANEL TRIM	84640T8NT01ZA	- DEF		38.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				1,613.00
u: Used parts	Addition(+15.00%)				241.95
	Total				1,854.95

Extras

Code	Description	Price SGD
1000	REAR BUMPER CLIPS - NEL 3 (A)	30.00*
1001	REVERSE SENSOR - MIS	180.00*
	Total Extras	210.00