

ASS. REC. BY:

REF: CS/MSG 19014321/1013

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Pauline Tham

of MSG

Date/Time: 16.8.19 16.11p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLF 5726H

Insured: SKH 2016U

at Workshop m/s Estren Performance

Tel: 8799 0066

of BLK 5033 PMK Ind park 2 #01-259

Policy No: A2883564 QMX

Claim No: 602888

Sum Insured:

Excess:

Make of Veh:

D.O.A. 10.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 16.8.19 4.23p.m

Person Contacted: Jenny

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLF 5726H-X
	SKH 2016U-X
20/8/19 @ 2.07pm	visited to Pauline Tham for Meiman.
1/10	83486.72 emol & confirmed (led to 7624.16, 69%.)

meiman

Surveyor

REF: MSIG

ASSIGNMENT

From:

Date:

19.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLF 5726H

at Workshop m/s

Esteem Performance

of

BIC 5033 Amt Ind Part 2 + 01-259

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLF 5726H

Yr Regn:

08, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda CX5

c.c

2488

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

38964

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMKEL1032140389993

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

10/8/19

D.O.I.

19/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 04 OCT 2019

3/10/2019

Date/Time, File Pass to?



Preli. Report

1) 4/10/19



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

200
11

211

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

3486.72

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 20 Aug 2019

Preliminary Advice

Insured Vehicle No	: SKH2016U	Accident Date	: 10/08/2019
TP Vehicle No	: SLF5726H	Assignment Date	: 16/08/2019
Make	: MAZDA CX-5	Est. Duration of Repair	: 4.00
Date of Inspection	: 19/08/2019		
Inspection At	: ESTEEM PERFORMANCE PTE LTD (HQ) BLK 5033 ANG MO KIO IND PARK 2, #01-259 SINGAPORE 569536		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,374.00
Revised Amount	:S\$	2,533.84
Check Items (Estimated)	:S\$	868.64
Total	:S\$	3,402.48

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Aug 2019 15:52		16 Aug 2019 16:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	KHOO SANE ROY, ID: S8856791I		
Main Claimant:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D		
Vehicle Reg. No.:	SLF5726H	Date of Loss:	10/08/2019 12:00 - :59 [35 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 602888	Policy/Cover Note No.:	A28835664QMX (Comprehensive) Coverage: 12/10/2018 - 11/10/2019
Vehicle Reg. No. (Insured):	SKH2016U	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/08/2019]		
Driver/Custodian (Insured):	KHOO SANE ROY (), NRIC: S8856791I Email:		
Adj Asg. Remarks:	on WP. Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Jenny @ 6484 1221.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	651D
Vehicle Details	
Vehicle No.:	SLF5726H
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2019
Vehicle Make:	MAZDA
Vehicle Model:	CX-5 SKYACTIV-G 2.5 SP.6EAT 2WD LED S/R
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	PY30533831
Chassis No.:	JM6KE1032H0389993
Maximum Power Output:	141.0 kW (189 bhp)
Open Market Value:	\$29,414.00
Original Registration Date:	31 Aug 2016
First Registration Date:	31 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$33,180.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2026
PARF Rebate Amount:	\$24,885.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,500.00
COE Rebate Amount:	\$39,701.00
Total Rebate Amount:	\$64,586.00

The information contained herein is correct as at 20 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/08/2019 15:19
Date Of Accident	10/08/2019 13:30
Exact Location Of Accident	EXIT SLIP RD FROM BKE/NORTHBOUND TO DAIRY FARM RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF5726H
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66039399

Vehicle Particulars

Manufacturer	MAZDA
Model	CX5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994316
Cover Note Number	

Driver

Name of Driver	HERBERT MICHAEL LAWRENCE
Passport No/FIN	F5624440U
Date Of Birth	20/08/1961
Occupation	INDOOR
Date Of Driving Pass	27/12/2002
Driving Experience	16 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96369508
Fax Number	
Contact Number	
Email Address	MIKEHERBERT4WORK@HOTMAIL.COM

Address	45 HILLVIEW AVENUE #01-01 HILLINGTON GREEN CONDO
Postcode	669613
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKH2016U
Vehicle Make/Model/Colour	LEXUS G250 WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KHOO SANE ROY
NRIC/Passport Number	S8856791I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

KEY PLAN

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorized Driver.

3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Traffic Police Department for investigation.

6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the lodgement of this report to the Insurer, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/ law firms, the Monetary Authority of Singapore and any relevant government agency/authorities (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, receipts or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/paenall packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/ law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/ can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/ law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Page 3 of 17


Describe Circumstance of the Accident *

I WAS EXITING THE GIVE NORTHBOUND AT DAIRY FARM ROAD EXIT. AT THE
END OF THE EXIT SUPERROAD I STOPPED AT THE GIVE-WAY LINE TO ALLOW
TRAFFIC ON DAIRY FARM ROAD TO PASS BY (WIMBURY A. MOTORCYCLE), SINCE
DAIRY FARM ROAD TRAFFIC HAS PRIORITY OVER TRAFFIC ON THE GIVE EXIT
SUPERROAD. ~~WHILE I WAS STOPPED~~ WHILE STATIONARY, THE OTHER DRIVER DROVE
INTO THE REAR OF MY VEHICLE. WHILE WE EXCHANGED DETAILS, HE
STATED THAT HE WAS WATCHING TRAFFIC ON DAIRY FARM ROAD.

Declaration

(We declare the foregoing particulars are true in every respect.)


14 AUG 2019


Driver's Signature (if driver is not the police officer) / Date
& Time 13/8/19 - 1.20pm


Witnessed by Responding Constable Personnel
[Signature]

CERTIFICATE OF INSURANCE Pg. 1



HOTLINE TEL: (65) 6419-3000

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 185)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.Z.400

Comprehensive Commercial Motor		(The below excess is subject to GST)	
CERTIFICATE NO.	999994316	POLICY EXCESS	S\$1,200.00 ** (I)
		WINDSCREEN EXCESS	S\$100.00
		SUM INSURED	Market Value
		INSURING WITH COE/PARF	Yes
1) VEHICLE REGISTRATION NO.		SLF5726H	
2) NAME OF POLICYHOLDER		Goldbell Car Rental Pte Ltd	
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT		01 January 2019	
4) DATE OF EXPIRY OF INSURANCE		31 March 2020	
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*	<p>Any person who is driving on the Insured's order or with their permission.</p> <p>Additional Excess of \$1000 applies to all claims for Drivers below 23 years old and/or with Driving Experience less than 12 months</p> <p>Additional excess of \$500 applies to all claims for accident outside Singapore</p> <p>** Policy Excess vary according to Vehicle Usage. Refer to Policy for more details.</p>		
<p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p>			
6) LIMITATION AS TO USE*	<p>1) Use for social, domestic, pleasure purposes and business purposes of Insured</p> <p>2) Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.</p> <p>The Policy does not cover:</p> <p>1) Use for racing, pace-making, reliability trial or speed testing.</p> <p>2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.</p> <p>3) Use for the carriage of passengers for hire or reward by any person to whom the Vehicle is hired.</p> <p>4) Use for any purpose in connection with Motor Trade.</p>		
LOSS OF USE	Not Included		
HIRE PURCHASE COMPANY	DBS Bank Ltd		
<p>*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 185) and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</p>			

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 185) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 18 Jan 2019

AIG Asia Pacific Insurance Pte. Ltd.

030123-000
Acorn International Network Pte Ltd
48 Changi South St 1 Level 3
SINGAPORE 486130

ORIGINAL

AUTHORISED REPRESENTATIVE

SSPKWJ

DRIVER'S EMPLOYMENT PASS + DRIVING LICENCE Pg. 1

REPUBLIC OF SINGAPORE DRIVING LICENCE



HERBERT MICHAEL LAWRENCE

20 Aug 1961
20 Jan 2018
25/01/2020

002765615H

PERSONALISED EMPLOYMENT PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
THIS PERSON IS A PERSONALISED EMPLOYMENT PASS HOLDER

Name
HERBERT MICHAEL LAWRENCE
Occupation

FIN
F5524440J

Date of Application
13-06-2017
Date of Issue
07-11-2017
Date of Expiry
07-11-2020



18432505

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
Class 3	Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	27 Dec 2002

NP 428A

Licence No. F5524440J

VISIT PASS
Immigration Regulations

Name
HERBERT MICHAEL LAWRENCE

Date of Birth
20-08-1961

Sex
M

Nationality
BRITISH

FIN
F5524440J

Date of Issue
07-11-2017

Date of Expiry
07-11-2020

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLF 5726 H

Not Authorized

*Resurvey After Paint
6 Days @ ?*

Parts	(a) Cost / List Price Items	\$	9,117.50
	Plus/Less 20%	\$	1,823.50
	Total of Cost / List	\$	7,294.00
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	50.00
Total Parts Cost		\$	7,344.00
Labour		\$	3,030.00
Total		\$	10,374.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

11110.88

Name of Surveyor

Kennerth

Company

LKK

Survey conducted on

19/8/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : *04* day(s)

(c) Resurvey : Required / Not Required *Not Required*

(d) Excess : \$

(e) Signature of surveyor

Le

Date:

19/8/19

Repair Estimates

SLF 5726 H

Parts (a) Cost / List Price Items

Finalised 2383.40
\$ ~~2179.80~~ 9,117.50

Plus/Less 20%

\$ 435.46 1,823.50

Total of Cost / List

\$ 1743.74 7,294.00 1906.72

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

\$ 50.00

Total Parts Cost

\$ 7,344.00

Labour

\$ ~~1700.00~~ 3,030.00 1580

Total

\$ ~~3523.74~~ 10,374.00 3486.72

The above total will be subjected to 7% G.S.T.

Not authorized
Resurvey after Repair
6th May @ 7
PBP

Name of Surveyor

:

Kennerth

Company

:

KKK

Survey conducted on

:

19/8/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess

:

\$

(e) Signature of surveyor

:

Pe

Date:

19/8/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLF 5726 H**
Make & Model : **MAZDA CX5**
Chassis No : **JM6KE1032H0389993**

Submit By : **JENNY**
Year Manufacture : **2016**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	N/A		
2	Rear windscreen sealant	1	\$50.00	S.N	X
3	Reverse sensor	1	\$814.40		203.60
4	Rear bumper	1	\$1,278.90		—
5	Rear bumper clip	10	\$30.00		—
6	Rear bumper side retainer LH	1	N/A		X
7	Rear bumper side retainer RH	1	N/A		✓
8	Rear bumper bracket LH	1	\$34.10		X
9	Rear bumper bracket RH	1	\$34.10		X
10	Rear bumper sponge	1	N/A		X
11	Rear bumper reinforcement	1	\$520.00		2
12	Rear bumper lower skirt	1	N/A		
13	Rear bumper reflector LH	1	\$106.30		X
14	Rear bumper reflector RH	1	\$106.30		X
15	Rear bumper tow cover LH	1	\$2.70		X
16	Rear bumper tow cover RH	1	\$2.70		—
17	Tail door	1	\$1,387.50		X
18	Tail door lock	1	\$269.30		X
19	Tail door emblem	1	\$54.30		—
20	Wording "CX-5"	1	\$47.60		—
21	Wording "SKYACTIV"	1	\$75.20		—
22	Tail end panel	1	\$497.60		X
23	Tail end panel garnish	1	\$78.20		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLF 5726 H**
Make & Model : **MAZDA CX5**
Chassis No : **JM6KE1032H0389993**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish clip <i>nn</i>	10	\$30.00		X
25	Boot weatherstrip <i>sn</i>	1	\$183.30		X
26	Tail lamp LH <i>sn</i>	1	\$1,261.10		X
27	Tail lamp RH <i>sn</i>	1	\$1,261.10		X
28	Tail lamp clip <i>nn</i>	4	\$62.80		X
29	Tail Door reflector LH <i>sn</i>	1	\$490.00		X
30	Tail door reflector RH <i>sn</i>	1	\$490.00		X
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLF 5726 H** Submit By : **Carmen Lim**
Make & Model : **MAZDA CX5** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,000.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	600
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	60
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	X
6	To remove & refit rear windscreen.	\$120.00	X
7	To tuff coat.	\$150.00	X
8	To transfer boot mechanism to new boot	\$120.00	X
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare PartsVehicle No. :
Make & Model :
Chassis No. :**SLF 5726 H**

MAZDA CX5

JM6KE1032H0389993

Submit By :
Year Manufacture :
Engine No. :
Cost / List**CARMEN LIM**
2016**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear antenna sensor <i>cm</i>	1	\$111.10	✓	
2	Rear bumper reinforcement bracket <i>P.S</i>	2	\$60.00	✓	
3		1			
4	Labour : <i>20%</i>	1			
5	To repair & respray rear fender LH & RH	1	\$600.00		<i>400%</i>
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

171.10

600.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014321/KQF3N2

Date: 08/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28835664QMX
 Claimant Vehicle No: SLF5726H Insured Vehicle No: SKH2016U
 Date of Loss: 10/08/2019 Nature of Claim: TP Claim No: 602888

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF5726H Engine No: PY30533831
 Make & Model: MAZDA CX-5, 2.5 (A) Chassis No: JM6KE1032H0389993
 Reg. Date: 31/08/2016 (Man. Year: 2016) Odometer: 38964 km
 Colour: Metallic Grey
 Engine Capacity: 2488 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R19 Rear Tyre Size: 225/55 R19
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,480.88	1,906.72	5,574.16	74.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	1,580.00	2,050.00	56.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,110.88	3,486.72	7,624.16	68.62
+ GST 7.00/7.00% (\$\$)	777.76	244.07	533.69	68.62
Nett Amount (\$\$)	11,888.64	3,730.79	8,157.85	68.62

INSPECTION

Date of Assignment: 16/08/2019
 Date Inspected: 19/08/2019 Inspected At: Esteem Performance Pte Ltd (HQ)
 Blk 5033 Ang Mo Kio Ind Park 2, #01-259
 Singapore 569536

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2019)	
Parts: M1-SUV	MAZDA CX-5 2.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLF5726H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REVERSE SENSOR (4 Pcs)	Shorted (1 Pc only)	814.40 FL	*203.60 FL
2	1	*REAR BUMPER	Bent/Cracked	1,278.90 FL	*1,278.90 FL
3	10	*REAR BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
4	1	*REAR BUMPER SIDE RETAINER LH (NPA)	Serviceable	0.00 FL	*- FL
5	1	*REAR BUMPER SIDE RETAINER RH (NPA)	Distorted	0.00 FL	*- FL
6	1	*REAR BUMPER BRACKET LH	Repair	34.10 FL	*- FL
7	1	*REAR BUMPER BRACKET RH	Repair	34.10 FL	*- FL
8	1	*REAR BUMPER SPONGE (NPA)	Serviceable	0.00 FL	*- FL
9	1	*REAR BUMPER REINFORCEMENT	Bent	520.00 FL	*520.00 FL
10	1	*REAR BUMPER REFLECTOR LH	Serviceable	106.30 FL	*- FL
11	1	*REAR BUMPER REFLECTOR RH	Serviceable	106.30 FL	*- FL
12	1	*REAR BUMPER TOW COVER LH	Serviceable	2.70 FL	*- FL
13	1	*REAR BUMPER TOW COVER RH	Missing	2.70 FL	*2.70 FL
14	1	*TAIL DOOR	Repair	1,387.50 FL	*- FL
15	1	*TAIL DOOR LOCK	Repair	269.30 FL	*- FL
16	1	*TAIL DOOR EMBLEM	Necessary	54.30 FL	*54.30 FL
17	1	*WORDING CX-5	Necessary	47.60 FL	*47.60 FL
18	1	*WORDING SKYACTIV	Necessary	75.20 FL	*75.20 FL
19	1	*TAIL END PANEL	Repair	497.60 FL	*- FL
20	1	*TAIL END PANEL GARNISH	Serviceable	78.20 FL	*- FL
21	10	*TAIL END PANEL GARNISH CLIP	Not Necessary	30.00 FL	*- FL
22	1	*BOOT WEATHERSTRIP	Serviceable	183.30 FL	*- FL
23	1	*TAIL LAMP LH	Serviceable	1,261.10 FL	*- FL
24	1	*TAIL LAMP RH	Serviceable	1,261.10 FL	*- FL
25	4	*TAIL LAMP CLIP	Not Necessary	62.80 FL	*- FL
26	1	*TAIL DOOR REFLECTOR LH	Serviceable	490.00 FL	*- FL
27	1	*TAIL DOOR REFLECTOR RH	Serviceable	490.00 FL	*- FL
28	1	*REAR ANTENNA SENSOR	Cracked	111.10 FL	*111.10 FL
29	2	*REAR BUMPER REINFORCEMENT BRACKET	Distorted	60.00 FL	*60.00 FL
30	1	*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,338.60	2,383.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,857.72	476.68
Total Parts (\$\$)	7,480.88	1,906.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR & RESPRAY REAR FENDER LH & RH	New	600.00	400.00
2	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,TAIL DOOR,END PANEL,SPARE TYRE WELL PANEL)	New	1,000.00	500.00
3	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,TAIL DOOR,END PANEL,SPARE TYRE WELL PANEL)	New	1,200.00	600.00
4	TO CHECK WIRING	New	50.00	20.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	60.00
6	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	0.00
7	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
8	TO TUFF COAT	New	150.00	0.00
9	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	0.00
10	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	0.00
Gross Labour Cost (S\$)			3,630.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >