

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

SLF 5726 H

Make & Model :

MAZDA CX5

Chassis No. :

JM6KE1032H0389993

Submit By :

CARMEN LIM

Year Manufacture :

2016

Engine No. :

Cost / List**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear antenna sensor <i>CM</i>	1	\$111.10	✓	
2	Rear bumper reinforcement bracket <i>P.S</i>	2	\$60.00	✓	
3		1			
4	Labour : <i>20%</i>	1			
5	To repair & respray rear fender LH & RH	1	\$600.00		<i>400</i>
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

171.10
600.00