

22/03/2003

ASS. REC. BY:

REF: 08/MSG19014324/MSD3021

Special Instruction:

Surety: NAZ

ASSIGNMENT (Office)

From (Person): Crystal Lee

of

MSL

Date/Time:

15/8/19 @ 4:26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 4063 L

Insured:

GBC 97684

at Workshop m/s

comfort delgro

Tel:

62148355

of

Sq Loyang Drive

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:07am @ 16/8/19

Person Contacted:

Mr. Jim

Vehicle: IN/OUT

Date/Time	Action/Instruction	Signature
	SHB 4063 L - NS/INC/7011060/High 3k2	DA: 5/6/2017
	GBC 97684 - CC41.ASM/7015500/19/1pb3y2	DA: 5/8/17
19/03/19	@ 18:34 pm revised PA to Crystal Lee via memo.	

ASS. REC. BY: NAZ

REF: MS19

CCE

ASSIGNMENT

From: Date: 16/8/2019

Veh No: SHB 4063L Yr Regn: 21 MAY 2015

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SHB 4063L

Make: HYUNDAI 140 c.c. 1,605

at Workshop m/s: comfort delgro

Colour: BLUE A/C: Insured / Std / NI / NA

of: SQ LOYANG DRIVE

Sp. Reading: 516,788 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: 1CMHLBY1UMFU069168

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STDA/Rim or

(Policy Condition)

N/S	O/S
X	X
X	X

Tyre Size: F: 205/60 R16

R: 11

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKE

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 5 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 5 mm

Est. Repairs: 2 days Res.: Yes or No

D.O.A. 14/8/19 D.O.I. 16/8/19

Lum Sum: % 3 Val.: Yes or No

Survey held at COGE LOYANG

CA / REV / REP. / 24 HRS (up)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction MS19 LIS

NAZ, pls see my remarks.

21/08/19 Confirmed HS @ 1,400/- @ 2 days with NAZ.

( \$ 6,435.68 red - 82% )

RECEIVED 27 AUG 2019

21/8/2019

Date/Time, File Pass to?

27/08/19

[ ] : Prel. Report

Days Of Repair: 2

1) Typ: 34

[x] : Final Report

Resurvey No. of Trip: 2

Survey Fee:

150

Date/Time, File Return to?

Transportation:

2)

Add Fee: [ ] : Site Insp (\$)

S+RS: SI

[ ] : Interview (\$)

Photos

[ ] : Tech. Insp (\$)

Others

[ ] : Weekend (\$)

Report Format :

Lump Sum / N.B. (\$ 1,400/- HS)

TOTAL

161

## Nivitha (LKK Auto)

---

**From:** Crystal Lee <crystal\_lee@sg.msig-asia.com>  
**Sent:** Thursday, 15 August 2019 4:26 PM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Ong Zi Hui; Helene Phua; Nabilah Rasol  
**Subject:** Survey Request - Manual Assigned  
**Attachments:** img-815090027-0001.pdf

**Importance:** High

### SHB4063L with your insured GBC9768U (MSIG) (NR case)

#### Manual Assigned

Dear LKK,

Refer to the email and attachment, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,  
Crystal Lee  
Admin Officer, Claims Services (In-House Survey)  
D: +65 6594 2535 | F: +65 6643 1349 | [crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Lim Kwok Eng [<mailto:limke@cdge.com.sg>]  
**Sent:** Thursday, 15 August, 2019 9:06 AM  
**To:** Motor Survey <[motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)>  
**Cc:** Ng Nyuk Phin <[ngnp@cdge.com.sg](mailto:ngnp@cdge.com.sg)>; Roger How Keen Meng <[rogerhow@cdge.com.sg](mailto:rogerhow@cdge.com.sg)>  
**Subject:** SHB4063L with your insured GBC9768U

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

To Officer In Charge

Pls arrange surveyor, refer attachments

**Best Regards**

**Lim Kwok Eng**

**Taxi Crash Repairs / ComfortDelgro Engineering Pte Ltd**

**Tel. 6214-8355 / 6214-8156**

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

---

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Team: ARC Repair TP(CLSO)1

**JOB CARD**

Sales Order:

JC NO.: 305324900

OMER  
 S  
 COMFORT TRANSPORTATION PTE LTD  
 7010045  
 OMER NO. 383 SIN MING DRIVE  
 ESS Singapore SINGAPORE 575717  
 65508755  
 (R) (O)  
 (P)

*MSIG*


REGN NO: SHB4063L	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 14.08.2019 14:05
YR OF MANU 21.05.2015	TARGET DATE
CHASSIS CODE KMH41UMFU069168	COMPLETION DATE/TIME

IDENTIFICATION CARD NO.

JOB DESCRIPTION

Accident Date: 14.08.2019  
 NATURE: 3P 14.08.2019

S/NO                      LABOR CODE                      DESCRIPTION



CHECKED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
 SERVICE ADVISOR

\_\_\_\_\_  
 CUSTOMER'S SIGNATURE

Checklist / Acknowledgement Slip  
 No.: SHB4063L                      LKE  
 \_\_\_\_\_  
 Signature/Date  
 Returned to Service Reception upon collection

Exit Pass  
 Vehicle No.: SHB4063L  
 \_\_\_\_\_  
 Name of Service Advisor                      Date  
 To be kept by Security Guard

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 19 Aug 2019

## Preliminary Advice

Insured Vehicle No	: GBC9768U	Accident Date	: 14/08/2019
TP Vehicle No	: SHB4063L	Assignment Date	: 19/08/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 2 days
Date of Inspection	: 16/08/2019		
Inspection At	: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,807.20
Revised Amount	:S\$	1,308.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,308.24

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/08/2019 16:33
Date Of Accident	14/08/2019 11:35
Exact Location Of Accident	CTE TWDS TUAS.
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB4063L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD (COMPANY)
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	CHNG MOOK CHEONG
NRIC No	S1508850H
Date Of Birth	07/01/1961
Occupation	OUTDOOR
Date Of Driving Pass	31/08/1978
Driving Experience	40 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97113986
Fax Number	
Contact Number	
E Mail Address	CHNG2002RW@GMAIL.COM

Address	273 12-158 BANGKIT ROAD
Postcode	670273
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	GBC9768U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	PETER TENG POH PUAY.
NRIC/Passport Number	S1577783D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT & REAR

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	GBG5311J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HOSSSAIN AZMIR
NRIC/Passport Number	G2177537X
Contact Number	981687598
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/8/2019 at about 1135 hrs, I Vehicle A was driving my taxi along CTE toward TWD in the middle lane. As a car in front of me applied emergency brake and stop, I also follow the car in front. A few second later I hear bang from my taxi back. Then another bang is hear. No one was injured at that time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE. LTD.  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

*[Handwritten Signature]*

Driver's Signature  
(If driver is not the policyholder)

14/8/19  
Jackson Heng  
CSG

*[Handwritten Signature]*

Reporting Centre Personnel's Signature  
Name:

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO 199303421R




14/8/19


Jackson Heng  
CSO

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHB 4063L

DATE 14/8/2019 17:20

MAKE :

MODEL : HYUNDAI i40

LKK/Naz

Lke

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid			\$ 2,174.90	X SVL
	Boot Lid Lock Upper			\$ 102.60	XSVL
	Boot Lid Lock Lower			\$ 31.70	XSVL
	Boot Lid 'H' Emblem			\$ 28.70	XNN
	Boot Lid CRDI Plate			\$ 27.90	XNN
	Boot Lid Lamp (LH)			\$ 565.60	X SVL
	Bootlid Moulding			\$ 85.00	XSVL
	Bootlid i40 Emblem			\$ 27.90	XSVL
	Bootlid Lower Garnish			\$ 227.90	X SVL
	Rear Bumper			\$ 553.00	X R
	Rear Bumper Clip 10 pcs			\$ 22.00	XNN
	Tail Lamp (LH)			\$ 697.80	/CRK
	Rear Fender (LH)			\$ 2,171.40	R XSVL
	Rear Fender Inner Lining (RH)			\$ 169.30	XSVL
	Rear Windscreen Moulding			\$ 28.30	XNN
	<b>SUB TOTAL</b>			<b>\$ 6,914.00</b>	
	<b>LESS 20%</b>			<b>\$ 1,382.80</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 5,531.20</b>	
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00	Nett XNN
	Boot Lid Advertisement Logo			\$ 100.00	Nett XNN
	Rear Bumper Advertisement Logo			\$ 50.00	Nett / NNN
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett / NNN
	Rear Windscreen Sealant			\$ 46.00	Nett XNN
				<b>\$ 426.00</b>	
	<b>Labour Charge</b>				
	Panel Beating			\$ 800.00	200
	Spray Painting Charge			\$ 600.00	200
	Wiring Charge			\$ 50.00	30
	Tuff Kote			\$ 50.00	40
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	8NN
	Remove/Refix Rear Windscreen Glass			\$ 120.00	XNN
	Remove/Refix Reverse Sensor			\$ 80.00	30
	<b>TOTAL LABOUR</b>			<b>\$ 1,850.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 7,807.20</b>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date:

24/8/19

NAZ LKK  
16/8/19 1615  
.. LIS  
20NN

APRIL REPAIR PHOTOS

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHB 4063L

DATE 14/8/2019 17:20

MAKE :

MODEL : HYUNDAI i40

LKK/NAZ  
 Lke

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid		XSVL	\$ 2,174.90
	Boot Lid Lock Upper			\$ 102.60
	Boot Lid Lock Lower			\$ 31.70
	Boot Lid 'H' Emblem			\$ 28.70
	Boot Lid CRDI Plate			\$ 27.90
	Boot Lid Lamp (LH)			\$ 565.60
	Bootlid Moulding			\$ 85.00
	Bootlid i40 Emblem			\$ 27.90
	Bootlid Lower Garnish			\$ 227.90
	Rear Bumper		CRK	\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	Tail Lamp (LH)			\$ 697.80
	Rear Fender (LH)			\$ 2,171.40
	Rear Fender Inner Lining (RH)			\$ 169.30
	Rear Windscreen Moulding			\$ 28.30
	Rear Bumper Side Bracket LH		CRK	\$ 35.60
	<b>SUB TOTAL</b>		697.80	\$ 6,914.00
	<b>LESS 20%</b>		553.00	\$ 1,382.80
	<b>DISCOUNTED TOTAL</b>		35.60	\$ 5,531.20
	Boot Lid Comfort Logo & Tel No. Sticker		1,286.40 -20%	\$ 30.00
	Boot Lid Advertisement Logo		1,029.12	\$ 100.00
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
	Rear Windscreen Sealant		250	\$ 46.00
				\$ 426.00
	<b>Labour Charge</b>			\$ 800.00
	Panel Beating			\$ 600.00
	Spray Painting Charge		500	\$ 50.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 150.00
	Remove/Refix Cushion & Upholstery Rear			\$ 120.00
	Remove/Refix Rear Windscreen Glass			\$ 80.00
	Remove/Refix Reverse Sensor			\$ 80.00
	<b>TOTAL LABOUR</b>		1,779.12 -20%	\$ 1,423.29
	<b>ESTIMATE TOTAL</b>			\$ 7,897.20
				7835.14

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK  
 16/8/19 1615  
 .. LIS \$1,400  
 20ms  
 APPRE REPAIR PHOTOS

X SVL ?  
 XSVL  
 XSVL  
 XNN  
 XNN  
 X SVL  
 XSVL  
 X SVL  
 X SVL  
 X SVL  
 X R part total  
 XNN  
 CRK  
 X SVL  
 X SVL  
 X NN  
 Nett X NN  
 200  
 200  
 30  
 40  
 8ms  
 X NN  
 30



# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305324900  
Date : 20.08.19

## FINALIZATION FORM

To : LKK Fax : \_\_\_\_\_  
Attn : Mr NAZ  
Vehicle Reg No. SHB4063L CTPL 14.08.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: MSIG --- GBC9768U
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \_\_\_\_\_
  - (c) Lumpsum Repair (if applicable)
 

Total for Lumpsum repair cost after Less:	<u>20%</u>	<u>\$1,400.00</u>
<b>Final Lumpsum Repair cost</b>		<b><u>\$1,400.00</u></b>
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM KWOK ENG  
Tel : 62148316  
Fax : 65468156

Signature :   
Name : NAZ LKK  
Date : 20/8/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Aug 2019		19 Aug 2019 15:34 <a href="#">Edit Adj Rpt</a>	<b>S\$1,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	<b>SEASPIRE INTERNATIONAL PTE LTD</b> , Co. Reg. No.: 200510328K	
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R	
Vehicle Reg. No.:	<b>SHB4063L</b>	Date of Loss: 14/08/2019 00:00 - :59 [50 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 603818</b>	Policy/Cover Note No.: 29120240MKC Coverage: 11/04/2019 - 10/04/2020
Vehicle Reg. No. (Insured):	<b>GBC9768U</b>	Policy No. (Claimant): Excess:
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300	
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]	
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Muhammad Nazril Bin Abdullah</b> ] ... [Final Rpt due 18/09/2019]	
Adj Asg. Remarks:	on WP. (Manual Assign). Liab: Dispute(NR). Assign: LKK Auto Consultants Pte Ltd. Contact: Lim Kwok Eng @ 6214 8355 / 9824 0811. Manual assign to LKK via email on 15/08/2019.	

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS		<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHB4063L (603818)  
[GBC9768U]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Aug 14 2019 12:00AM  
[SEASPIRE INTERNATIONAL PTE LTD]  
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
<b>Assessment Reports</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	19/08/19 18:34	Adjuster Immediate Advice					Load HTM			
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
2	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
3	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
4	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
5	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
6	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
7	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
8	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
9	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
10	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
11	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
12	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
13	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
14	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
15	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
16	20/08/19 17:11	General View					Load JPG	<input checked="" type="checkbox"/>		
17	20/08/19 17:12	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>		
18	20/08/19 17:12	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>		
19	20/08/19 17:12	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>		
20	20/08/19 17:12	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>		
21	20/08/19 17:12	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>		
22	20/08/19 17:12	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>		
23	20/08/19 17:12	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>		
24	20/08/19 17:12	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>		
25	20/08/19 17:12	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>		
26	20/08/19 17:12	Dismantled Parts					Load JPG	<input checked="" type="checkbox"/>		
27	20/08/19 17:12	After Repair Photo					Load JPG	<input checked="" type="checkbox"/>		
28	20/08/19 17:12	After Repair Photo					Load JPG	<input checked="" type="checkbox"/>		
29	20/08/19 17:12	After Repair Photo					Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print		
1	19/08/19 15:20	PRI & Estimate					Load PDF			
2	19/08/19 15:21	SHB4063L GIA Rpt					Load PDF			
3	19/08/19 15:21	GBC9768U GIA Rpt					Load PDF			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
4	19/08/19 15:26	Manual Assign to LKK		Load PDF
5	28/08/19 09:34	Status of Driving Licence - valid		Load PDF
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail Print
1	19/08/19 15:32	Survey Request - Manual Assigned		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG19014324/NSD3E2

**Date:** 28/08/2019

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29120240MKC
<b>Claimant Vehicle No :</b> SHB4063L	<b>Insured Vehicle No :</b>	GBC9768U
Date of Loss: 14/08/2019	Nature of Claim:	TP <span style="float: right;">Claim No: 603818</span>

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB4063L</b>	
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Engine No: D4DFDU502965
Reg. Date:	21/05/2015 (Man. Year: 2015)	Chassis No: KMHLB41UMFU069168
Colour:	Blue	Odometer: 516788 km
Engine Capacity:	1685 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,985.68	1,279.12	4,706.56	78.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	500.00	1,350.00	72.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,835.68</b>	<b>1,779.12</b>	<b>6,056.56</b>	<b>77.29</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,400.00</b>		
(S\$)	7,835.68	1,400.00	6,435.68	82.13
<b>+ GST 7.00/7.00% (S\$)</b>	548.50	98.00	450.50	82.13
<b>Nett Amount (S\$)</b>	<b>8,384.18</b>	<b>1,498.00</b>	<b>6,886.18</b>	<b>82.13</b>

#### INSPECTION

Date of Assignment:	19/08/2019	
Date Inspected:	16/08/2019 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

---

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS**

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2019)	
<b>Parts:</b> 143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB4063L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BOOT LID	Serviceable	2,174.90 FL	*- FL	
2	1		*BOOT LID LOCK UPPER	Serviceable	102.60 FL	*- FL	
3	1		*BOOT LID LOCK LOWER	Serviceable	31.70 FL	*- FL	
4	1		*BOOT LID H EMBLEM	Not Necessary	28.70 FL	*- FL	
5	1		*BOOT LID CRDI PLATE	Not Necessary	27.90 FL	*- FL	
6	1		*BOOT LID LAMP (LH)	Serviceable	565.60 FL	*- FL	
7	1		*BOOTLID MOULDING	Serviceable	85.00 FL	*- FL	
8	1		*BOOTLID I40 EMBLEM	Serviceable	27.90 FL	*- FL	
9	1		*BOOTLID LOWER GARNISH	Serviceable	227.90 FL	*- FL	
10	1		*REAR BUMPER	Cracked	553.00 FL	*553.00 FL	
11	10		*REAR BUMPER CLIP	Not Necessary	22.00 FL	*- FL	
12	1		*TAIL LAMP (LH)	Cracked	697.80 FL	*697.80 FL	
13	1		*REAR FENDER (LH)	Serviceable	2,171.40 FL	*- FL	
14	1		*REAR FENDER INNER LINING (RH)	Serviceable	169.30 FL	*- FL	
15	1		*REAR WINDSCREEN MOULDING	Not Necessary	28.30 FL	*- FL	
16	1		*REAR BUMPER SIDE BRACKET LH	Cracked	35.60 FL	*35.60 FL	
17	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Not Necessary	30.00 FS	*- FS	
18	1		*BOOT LID ADVERTISEMENT LOGO	Not Necessary	100.00 FS	*- FS	
19	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS	
20	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS	
21	1		*REAR WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS	
					<b>Sub Total (S\$)</b>	<b>7,375.60</b>	<b>1,536.40</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>1,389.92</b>	<b>257.28</b>
					<b>Total Parts (S\$)</b>	<b>5,985.68</b>	<b>1,279.12</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	200.00
2	SPRAY PAINTING CHARGE	New	600.00	200.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
5	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	0.00
6	REMOVE / REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
7	REMOVE / REFIX REVERSE SENSOR	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,850.00</b>	<b>500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >