



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
REPAIR PERFORMA INVOICE

INDIA INTERNATIONAL INSURANCE

Vehicle number	SGF588G
Make / Model	TOYOTA/ALTIS
Chassis number	MRO53REH104548436
Accident date	08.08.19
Reference	1908-20

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER ✓ BR	582.00
1	FRONT BUMPER BRACKET R/H ?	182.40
2	FRONT BUMPER RETAINER ✓ DD	204.00
1	FRONT BUMPER REINFORCMENT ? - photo	458.20
1	FRONT BUMPER LOWER GRILLE X	186.00
1	FRONT GRILLE ASSY ✓ CRA	678.00
1	FRONT FOG LAMP R/H ?	390.00
1	FRONT FOG LAMP COVER R/H ✓ m/s	114.00
1	FRONT GRILLE EMBLEM ✓ nec	81.60
1	FRONT BRACE PANEL R	186.00
1	FRONT SUPPORT PANEL ? - photo	1186.80
1	FRONT SUPPORT PANEL TOP GARNISH' X	78.00
1	FRONT RH HEADLAMP ✓ CRA	2795.00
1	FRONT RH FENDER R	937.20
1	FRONT RH FENDER EMBLEM ✓ nec	89.10
1	FRONT FENDER INNER SHIELD ✓ CRA	240.00
1	BONNET R	1244.40
1	BONNET INSULATOR X	342.00
1	BONNET HINGE R	180.00
1	FRONT RH SHOCK ABSORBER X	559.10
1	FRONT RH KUNCKLE ARM X	501.30
1	FRONT RH KUNCKLE ARM BEARING X	211.50
1	FRONT RH LOWER ARM X	339.60
		11766.20
	Less 25%	2941.55
	Subtotal	8824.65
	Balance C/F	8824.65
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	8824.65
1 SET	FRONT BUMPER CLIP ✓ nec	50.00 \$20
1 SET	SUPPORT PANEL TOP GARNISH CLIP X	80.00
1 SET	FRONT GRILLE CLIP ✓ nec	80.00 \$20
	Subtotal	210.00
	Balance C/F	9034.65
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	9034.65

S/No	LABOUR AND MISCELLANEOUS CHARGES		Balance B/F
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	50.00	\$ 20
3	CHECK FRONT WHEEL ALIGNMENT → Alignment report)	200.00	\$ 50
4	PANEL BEATING ON AFFECTED AREAS	1000.00	\$ 600
6	SPRAY PAINTING ON AFFECTED AREAS (peach white) 4ps	1000.00	\$ 800
7	APPLY ANTI RUST ON AFFECTED AREAS	100.00	\$ 20
	Subtotal	2350.00	
	Grand total	11384.65	

→ repair
support
panel / \$700 →
replace
support
panel

L/S repair
Hock Ann
85311883
5.35pm 20/8/19
resurvey after paint
without prejudice
Hock Ann@lkkauto.com
5 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H

INDIA INTERNATIONAL INSURANCE

Vehicle number	SGF588G
Make / Model	TOYOTA/ALTIS
Chassis number	MRO53REH104548436
Accident date	08.08.19
Reference	1908-20

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER SPONGE ✓ C.R.A	199.20
1		199.20
	Less 25%	49.80
	Subtotal	149.40
	Balance C/F	149.40