

ASS REC BY:

REF: CS/MSG 190/4353/G9f3n2

Special Instruction:

Surveilor: GQ

ASSIGNMENT (Office)

From (Person): Christina Wong of MS1G Date/Time: 16.8.19 16.18 p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR 3502L Insured: SLH 5187C

at Workshop m/s Modern Automotive Tel: 6748 4422

of B1C 3023n ubi road 1 #01-61

Policy No: A80445118QMY Claim No: 60 2626

Sum Insured: Excess:

Make of Veh: D.O.A. 11.8.2019

(Client's Record) 19.8.19 2.4pm/weekday

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 19.8.19 9.28am Person Contacted: ms chin Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SLR 3502L - X
	SLH 5187C - X
10/8/19 @ 1.53pm	revised to Christina Wong via Maimen.

Surveyor

Cal.

REF: ms19

355H

ASSIGNMENT

From: Date: 19-8-2019

Estimated Cost:

ODV / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 3502 L
at Workshop m/s Modern Automotive
of Blk 3023A ubi road 1 701-61

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: 200p.m owner making

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

ms19

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLR3502L Yr Regn: 11 Aug 2017

Type: M.Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda vezel c.c. 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 42013 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU11207596

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 19-08-19

Survey held at w/s 2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

03/10 Finalized \$ 2379.12 with Grace.
(Red to 4196.48, 64%)

4/10/2019

RECEIVED 07 OCT 2019

Date/Time, File Pass to?

☐ : Preli. Report

1) 07/10 1455

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: MER-TP

Lump Sum / I.B.I. (\$ 2379.12)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 20 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLH5187C	Accident Date	: 11/08/2019
TP Vehicle No	: SLR3502L	Assignment Date	: 16/08/2019
Make	: HONDA VEZEL	Est. Duration of Repair	: 4.00
Date of Inspection	: 19/08/2019		
Inspection At	: MODERN AUTOMOTIVE PTE LTD (HQ) BLK 3023A UBI ROAD 1, #01-61 & #01-58 SINGAPORE 408717		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,825.60
Revised Amount	:S\$	1,805.60
Check Items (Estimated)	:S\$	328.00
Total	:S\$	2,133.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Aug 2019		16 Aug 2019 16:18 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	LU YOUYOU, ID: S6984924E, Tel: +6590935096, Email: LUYOUYOU@GMAIL.COM		[Created by insurer]
Main Claimant:	WANG LIANG CHENG, ID: S1484355H		
Vehicle Reg. No.:	SLR3502L	Date of Loss:	11/08/2019 14:00 - :59 [24 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 602626	Policy/Cover Note No.:	A80445118QMY (Comprehensive) Coverage: 08/11/2018 - 07/11/2019
Vehicle Reg. No. (Insured):	SLH5187C	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/08/2019]		
Driver/Custodian (Insured):	LU YOUYOU (49 / Male), NRIC: S6984924E, Tel: +6590935096 Email: LUYOUYOU@GMAIL.COM		
Adj Asg. Remarks:	Car in 19/08/19, survey after 2pm. Selected LKK (Adrain Lim) to survey. Liab: 100%. Agree on SJE. Contact: Grace @ 6748 4422.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	355H
Vehicle No.:	SLR3502L
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	L15B4407599
Chassis No.:	RU11207596
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,975.00
Original Registration Date:	11 Aug 2017
First Registration Date:	11 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$12,765.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Aug 2027
PARF Rebate Amount:	\$9,573.00
COE Expiry Date:	10 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,778.00
COE Rebate Amount:	\$37,309.00
Total Rebate Amount:	\$46,882.00

The information contained herein is correct as at 19 Aug 2019

OK

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MSIG INSURANCE (SINGAPORE) PTE LTD

4 Shenton Way # 21 - 01

SGX Centre 2

Singapore 068807

Hot line : 6827 - 7660

Fax : 6225- 7402 (CLAIM)

Quotation

DATE : 16.08.2019

VEH NO : SLR3502L

MODEL : Honda Vezel

D O A : 11.08.2019

YR REF : SLH5187C

Attn : Motor Claim Dept

(pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLR3502L (HONDA VEZEL)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Door - RH X NN	1	998.00
2	Rear Door - RH Q / Blue	1	977.00 ✓
3	Rear Door Glass Outer Moulding - RH X	1	63.00
4	Rear Door Weatherstripe - RH X	1	44.00
5	Rear Door Lock - RH X	1	221.00
6	Rear Door Hinges - RH (upper / lower) X	2	88.00
7	Rear Door Checker - RH X	1	47.00
8	Rear Door Glass Regulator & Motor - RH X	1 set	410.00
9	Rear Fender - RH X repair.	1	978.00
10	Rear Fender Lower Garnish - RH / Cut.	1	150.90 205.00 ✓
11	Rocker Panel Garnish - RH X / Cut	1	396.00 ✓
12	Rear Door Pillar - RH X NN	1	980.00
			\$ 5,407.00
Less 20%			(1,081.40)
			\$ 4,325.60
Total parts			
			\$ 4,325.60

LABOUR CHARGE

1	To knocking & pull out RH side portion & renew above parts	\$	700.00 400
2	To putty and spray up paint works	\$	600.00 400
3	To check wiring system	\$	20.00 X
4	To underseal	\$	30.00 X } NN

RE : ESTIMATE FOR ACCIDENT REPAIR SLR3502L (HONDA VEZEL)

5	To transfer door fittings	\$	150.00	60
		\$	1,500.00	

GRAND TOTAL	\$	5,825.60
-------------	----	----------

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

4 Days. *[Signature]* 20/8/19

Lumpsum Repair.

After repair photos.

Give Receipt - 82880282

19/8/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6575.60

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MSIG INSURANCE (SINGAPORE) PTE LTD

4 Shenton Way # 21 - 01

SGX Centre 2

Singapore 068807

Hot line : 6827 - 7660

Fax : 6225- 7402 (CLAIM)

Quotation

DATE : 16.08.2019

VEH NO : SLR3502L

MODEL : Honda Vezel

D O A : 11.08.2019

YR REF : SLH5187C

Attn : Motor Claim Dept

(pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLR3502L (HONDA VEZEL)

Item	Description	Qty	Amt
<u>NO</u>	<u>LIST ITEMS</u>		
1	Front Door - RH X	1	998.00
2	Rear Door - RH Q / Blue	1	977.00 ✓
3	Rear Door Glass Outer Moulding - RH X	1	63.00
4	Rear Door Weatherstripe - RH X	1	44.00
5	Rear Door Lock - RH X	1	221.00
6	Rear Door Hinges - RH (upper / lower) X	2	88.00
7	Rear Door Checker - RH X	1	47.00
8	Rear Door Glass Regulator & Motor - RH ?	1 set	410.00
9	Rear Fender - RH X repair.	1	978.00
10	Rear Fender Lower Garnish - RH - Cut.	1	150.9 205.00 ✓
11	Rocker Panel Garnish - RH Q ✓	1	396.00 ✓
12	Rear Door Pillar - RH X	1	980.00
13	REAR R.H SPORT RIM / Cut.	1	750 ✓ (M) 300(SN)
			\$ 5,407.00
	Less 20%		(1,081.40)
			\$ 4,325.60
	Total parts		\$ 4,325.60 1219.12

LABOUR CHARGE

1	To knocking & pull out RH side portion & renew above parts	\$	700.00 400
2	To putty and spray up paint works	\$	600.00 400
3	To check wiring system	\$	20.00 X
4	To underseal	\$	30.00 X

RE : ESTIMATE FOR ACCIDENT REPAIR SLR3502L (HONDA VEZEL)

5 To transfer door fittings

\$ 150.00

60

\$ 1,500.00

GRAND TOTAL

\$ 5,825.60

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

4 Days.

Lumpsum Repair.

After repair photos.

Quo Quip - 82880282

19/8/19.

2379.12

20%: 1900

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014353/GQF3N2
Date: 09/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80445118QMY
Claimant Vehicle No :	SLR3502L	Insured Vehicle No :	SLH5187C
Date of Loss:	11/08/2019	Nature of Claim:	TP
			Claim No: 602626

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR3502L	Engine No:	L15B4407599
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11207596
Reg. Date:	11/08/2017 (Man. Year: 2017)	Odometer:	42013 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,075.60	1,519.12	3,556.48	70.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	860.00	640.00	42.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,575.60	2,379.12	4,196.48	63.82
+ GST 7.00/7.00% (\$\$)	460.29	166.54	293.75	63.82
Nett Amount (\$\$)	7,035.89	2,545.66	4,490.23	63.82

INSPECTION

Date of Assignment:	16/08/2019	
Date Inspected:	19/08/2019	Inspected At:
		Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLR3502L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR-RH	Not Necessary	998.00 FL	*- FL
2	1	*REAR DOOR-RH	Buckled	977.00 FL	*977.00 FL
3	1	*REAR DOOR GLASS OUTER MOULDING-RH	Not Necessary	63.00 FL	*- FL
4	1	*REAR DOOR WEATHERSTRIPE-RH	Not Necessary	44.00 FL	*- FL
5	1	*REAR DOOR LOCK-RH	Not Necessary	221.00 FL	*- FL
6	2	*REAR DOOR HINGES-RH (UPPER/LOWER)	Not Necessary	88.00 FL	*- FL
7	1	*REAR DOOR CHECKER-RH	Not Necessary	47.00 FL	*- FL
8	1	*SET REAR DOOR GLASS REGULATOR & MOTOR-RH	Not Necessary	410.00 FL	*- FL
9	1	*REAR FENDER-RH	Repair	978.00 FL	*- FL
10	1	*REAR FENDER LOWER GARNISH-RH	Cut	205.00 FL	*150.90 FL
11	1	*ROCKER PANEL GARNISH-RH	Cut	396.00 FL	*396.00 FL
12	1	*REAR DOOR PILLAR-RH	Not Necessary	980.00 FL	*- FL
13	1	*REAR RH SPORT RIM	Cut	750.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,157.00	1,823.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,081.40	304.78
Total Parts (\$\$)	5,075.60	1,519.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT RH SIDE PORTION & RENEW ABOVE PARTS	New	700.00	400.00
2	TO PUTTY AND SPRAY UP PAINT WORKS	New	600.00	400.00
3	TO CHECK WIRING SYSTEM	New	20.00	0.00
4	TO UNDERSEAL	New	30.00	0.00
5	TO TRANSFER DOOR FITTINGS	New	150.00	60.00
Gross Labour Cost (S\$)			1,500.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >