

ASS. REC. BY:

REF: CF/MSG 19014356/Caf302 Special Instruction:

Singer: simu1

ASSIGNMENT (Office)From (Person): Meximen Koh Ming Shao of MSLU Date/Time: 14/8/19 @ 4:31pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR 8112X Insured: SLU 2619Aat Workshop m/s Twineer Automotive Tel: 68420051of 2 Kaki Bukit Ave 2 # 01-17Policy No: 2911 4756MKF Claim No: 598525

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 30/06/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 19.8.19 11:09am Person Contacted: zi Ting H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>SLR 8112X - <</u>
	<u>SLU 2619A - X</u>

* No re-survey photos. — 9/9.

20/9/19 @ 4.53pm confirmed with Mr Yeo LS \$5700, 5 days.

(Red \$ 4654.80, 45%)

RECEIVED 23 SEP 2019



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msg.com.sg

Executive
Claims Services

Inspection Report

Type of Survey:

OD - Excess	☐
TP Without Prejudice	☒

Vehicle Details:

Vehicle Reg No
Make
Model
Passenger capacity
Paint colour & code
Paint type

SLR 8112x
Toyota
Prius Alpha
07
Silver

Vehicle Extras:

In-built camera
Modification

Yes/No
Yes/No

Vehicle Data:

Odometer reading
Engine No
VIN No
Engine capacity
Engine modification

140999 km

Vehicle Condition:

Seviceable Yes / No

Handbrake
Footbrake
Steering
Body
Paint

Tyre Condition:

Front right
Front left
Rear left
Rear right

Tread mm	Size	Condition
5	Habilead 205/60/16	
5	"	
4	"	
4	"	

General Data:

Date of accident
Date of inspection
Date of assignment
Inspection location

30-06-19
04-07-19
03-07-19
Twincar

Painting Process:

Prepare off vehicle
Painting off vehicle
Neither (default)

Cost Details:

Parts
Supplementary
Miscellaneous
Body Labour
Paint labour
Paint material
TOTAL
Towing
Excess
Total less excess
Estimated days for repair

Repairer	Adjuster

Body Panel Repair:

Panel repair calculator used
Yes / No

Remarks:

Lump / Global Sum

--

Reason(s)

Margin Repair / Fast-line

Others:

Repair Authorised

Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2019 11:09		14 Aug 2019 16:31 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	DARWIN-51 CAR RENTAL PTE LTD, Co. Reg. No.: 201407909C		
Vehicle Reg. No.:	SLR8112X	Date of Loss:	30/06/2019 10:00 - :59 [22 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 598525	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLU2619A	Policy No. (Claimant):	
		Excess:	
Repairer:	Twincar Automotive Pte Ltd (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17, 417921 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Koh Ming Shao - 6594 2546]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]		
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. OI: grab. Liab: 100%. Contact: Zi Ting @ 6842 0051 / 6744 0510		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Yeo Poh Kheng <yeopk@n51.com.sg>
Sent: Friday, 20 September 2019 4:53 PM
To: Shiau Chan (LKKAUTO)
Subject: Re: Finalise

Dear Shiau Chan

SMD7470E L/S \$10700.00 7 days confirm

SLR8112X L/S \$5700.00 5 days confirm

Thanks

On Thu, 19 Sep 2019 at 2:54 PM, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Mr Yeo,

WITHOUT PREJUDICE

Offer of below vehicles:

- | | |
|-------------|-----------------------------------|
| 1. SKE7231Y | L/S \$ 4,300.00 and 5 repair days |
| 2. SMD7470E | L/S \$10,700.00 and 7 repair days |
| 3. SLR8112X | L/S \$ 5,700.00 and 5 repair days |

Kindly check and confirm.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: Yeo Poh Kheng <yeopk@n51.com.sg>
Sent: Saturday, 31 August 2019 11:06 AM
To: SUR
Cc: Shiau Chan (LKKAuto)
Subject: Finalise

Dear Shiau Chan

Can finalise below vehicles

SKE7231Y L/S \$ 7900.00 6 days

SMD7470E L/S limit \$11500.00 8 days

SLR8112X L/S \$ 5700.00 5 days


Pls check and let me know

Thanks

--

Regards,

Yeo Poh Kheng
N-51 Automotive Pte Ltd
Mobile : 8823 5151
Office : 6842 0051
www.n51.com.sg




MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Koh Ming Shao

Date: 08 Jul 2019

Preliminary Advice

Insured Vehicle No	: SLU2619A	Accident Date	: 30/06/2019
TP Vehicle No	: SLR8112X	Assignment Date	: 03/07/2019
Make	: TOYOTA PRIUS ALPHA HYBRID	Est. Duration of Repair	: 5.00
Date of Inspection	: 04/07/2019		
Inspection At	: TWINCAR AUTOMOTIVE PTE LTD (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17 SINGAPORE 417921		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front left portion.

Repairer's Estimate (Gross)	:S\$	10,354.80
Revised Amount	:S\$	7,737.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	

Lump Sum Repair	:S\$	5,800
-----------------	------	-------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,800
COE / PARF Rebate	:S\$	48,343
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- (X) The vehicle is economical/~~not economical~~ for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	909C
Vehicle Details	
Vehicle No.:	SLR8112X
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS ALPHA HYBRID 1.8S CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR1974960
Chassis No.:	ZVW400025720
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$30,981.00
Original Registration Date:	29 Aug 2017
First Registration Date:	29 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,374.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Aug 2027
PARF Rebate Amount:	\$4,030.00
Intended COE Rebate Details	
COE Expiry Date:	28 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,405.00
COE Rebate Amount:	\$43,143.00
Total Rebate Amount:	\$47,173.00

The information contained herein is correct as at 23 Sep 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
SLR8112X

Make / Model
TOYOTA / PRIUS ALPHA HYBRID 1.8S CVT

Vehicle Type :
Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover

Vehicle Attachment 1 :
No Attachment

Vehicle Scheme :
Normal

Chassis No. :
ZVW400025720

Propellant :
Petrol-Electric

Engine No. :
2ZR1974960

Motor No. :
317E03926

Engine Capacity :
1797 cc

Power Rating :
60.0 kW

 Maximum Power Output :
100.0 kW (134 bhp)

Maximum Laden Weight :

1845 kg

Unladen Weight :

1460 kg

Year Of Manufacture :

2017

Original Registration Date :

29 Aug 2017

Lifespan Expiry Date :

-

COE Category :

B - Car above 1600cc or 97kW (130bhp)

Quota Premium :

\$54,405.00

COE Expiry Date :

28 Aug 2027

Road Tax Expiry Date :

29 Feb 2020

PARF Eligibility Expiry Date :

28 Aug 2027

Inspection Due Date :

28 Aug 2020

Intended Transfer Date :

23 Sep 2019

CO2 Emission :

94.00 (g/km)

CEV/VES Rebate Utilised Amount :

\$30,000.00

CO Emission :

-

HC Emission :

-



NOx Emission :

PM Emission :

-

Fees To Be Paid For Transfer

Transfer Fees

\$25.00

Print

OK →

Save as PDF

Copy as Text





MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____
Date : _____

Policy No : _____
Claim No : _____


Insured Vehicle No : SLU 2619A Date of Accident : 30-06-19
TP Vehicle No : SLR 8112X Place of Survey : Twincar
Make & Model : Toyota Prius Alpha Date of Survey : 04-07-19

Point of Impact / Damages :

Front Left

Recommended Reserve :

Repairer's Estimate : \$ 10354.80
Interim Adjustment : \$ 7737.20
Check Items : \$ -



Proposed : Part by Part / Lump Sum Repair \$5800/- Excess : \$ -

Estimate Repair Period : 05 days

Pre-accident Market Value (for total loss consideration) : \$ 98800/-

COE / PARF to owner : \$ 48343/-

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐

OD Claim
Excess : \$ _____
(Authorised / Revert)

☒

TP Claim
(Without Prejudice)

Vehicle No. SLR 8112X

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 05

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 04-07-19

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

DARWIN-51 CAR RENTAL PTE LTD

2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT

AUTOHUB

SINGAPORE 417921

Contact : 88215151 87848443

ESTIMATE

Repair Code : CLM14604

Date in : 01/07/2019

Vehicle Num. : SLR8112X

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025720/2ZR1974960

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER / cracked	1	781.10	781.10
FRONT BUMPER AIR DUCT GARNISH LH / cracked	1	177.20	177.20
FRONT BUMPER DAYLIGHT LH / cracked	1	972.85	972.85
FRONT BUMPER SIDE BRACKET LH / cracked	1	171.10	171.10
FRONT BUMPER SIDE RETAINER L/R / cracked	2	132.25	264.50
FRONT BUMPER UPPER SEAL RUBBER / new	1	174.45	174.45
FRONT LH BALL JOINT X nn	1	173.00	173.00
FRONT LH FENDER / Deformed	1	721.30	721.30
FRONT LH FENDER 'HYBRID' EMBLEM / new	1	123.05	123.05
FRONT LH FENDER INNER SHIELD X nn	1	259.45	259.45
FRONT LH HEADLAMP / cracked	1	2721.10	2,721.10
FRONT LH KNUCKLE ARM / Dented	1	485.00	485.00
FRONT LH KNUCKLE ARM BEARING / Dented	1	517.00	517.00
FRONT LH LOWER ARM X nn	1	435.00	435.00
FRONT LH SHOCK ABSORBER / Dented	1	375.00	375.00
FRONT LH SHOCK ABSORBER TOP MOUNTING X nn	1	151.00	151.00
FRONT LH SPORT RIM X repair	1	1555.00	1,555.00
FRONT LH STABILIZER LINK X nn	1	117.00	117.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

DARWIN-51 CAR RENTAL PTE LTD
2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 88215151 87848443

ESTIMATE

Repair Code : CLM14604

Date in : 01/07/2019

Vehicle Num. : SLR8112X

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025720/2ZR1974960

FRONT LH TIE ROD END <i>X wn</i>	1	93.00	93.00
FRONT LH WHEEL CAP <i>/ Brozed / Cut</i>	1	379.30	379.30
Subtotal before discount			10,646.40
Percentage discount 25%			2,661.60
Sub-total 1			7,984.80
FRONT BUMPER CLIPS - SET <i>/ rec</i>	1	80.00	80.00 30
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>/ rec</i>	1	50.00	50.00 20
FRONT LH TYRE 205/60R16 <i>X wn</i>	1	450.00	450.00 X
Subtotal before discount			580.00
Percentage discount 0%			0.00
Sub-total 2			580.00
Parts-total			8,564.80

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

~~80.00~~ 50

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

~~350.00~~ 200

To road test driving, check and resetting wheel alignments system.

~~140.00~~ 80

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

~~600.00~~ 500

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~500.00~~ 400

To apply anti-rust chemical on repaired and replaced panel.

~~120.00~~ 60

Labour Total

1,790.00

Parts & Labour Total

10,354.80

*** This is a computer-generated document which requires no signature.***

05 days.
05/07/19 @ 1530
Victor - Seng @ 99- msig-asia-com
8784 701
L/S After paint

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2019 11:09		14 Aug 2019 16:31 Edit Adj Rpt	S\$5,700.00 Edit Estimates	S\$5,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	DARWIN-51 CAR RENTAL PTE LTD, Co. Reg. No.: 201407909C								
Vehicle Reg. No.:	SLR8112X	Date of Loss:	30/06/2019 10:00 - :59 [22 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 598525	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLU2619A	Policy No. (Claimant):							
		Excess:							
Repairer:	Twincar Automotive Pte Ltd (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17, 417921 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Koh Ming Shao - 6594 2546]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by SIMON HO LEONG CHUAN] ... [Imm.Advice due 15/08/2019]								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. OI: grab. Liab: 100%. Contact: Zi Ting @ 6842 0051 / 6744 0510								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR8112X (598525)
[SLU2619A]
TP
DARWIN-51 CAR RENTAL PTE LTD
Jun 30 2019 10:00AM
[GRAB RENTALS PTE LTD]
Twincar Automotive Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print	
1	08/07/19 11:04	Adjuster Immediate Advice	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print	
1	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
2	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
3	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
4	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
5	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
6	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
7	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
8	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
9	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
10	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
11	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
12	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
13	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
14	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
15	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
16	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
17	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
18	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
19	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
20	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
21	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
22	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
23	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
24	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
25	05/07/19 00:06	SURVEY PHOTO	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	03/07/19 11:10	Email - PRI	 Load PDF		
2	03/07/19 11:11	SLU2619A GIA Rpt	 Load PDF		
3	03/07/19 11:11	SLR8112X GIA Rpt	 Load PDF		
4	03/07/19 12:25	Agree on SJE - workshop details	 Load PDF		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print	
1	08/07/19 11:56	Preliminary Loss Advise	 Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014356/CQF3E2

Date: 24/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29114756MKF
Claimant
Vehicle No : SLR8112X **Insured Vehicle No :** SLU2619A
Date of Loss: 30/06/2019 **Nature of Claim:** TP **Claim No:** 598525

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR8112X
Make & Model: TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A) **Engine No:** 2ZR1974960
Reg. Date: 29/08/2017 (Man. Year: 2017) **Chassis No:** ZVW400025720
Colour: Silver **Odometer:** 140999 km
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 **Rear Tyre Size:** 205/60 R16
Front Left Side: Hablead 5 mm **Rear Left Side:** Hablead 4 mm
Front Right Side: Hablead 5 mm **Rear Right Side:** Hablead 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,564.80	5,848.02	2,716.78	31.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	1,290.00	500.00	27.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,354.80	7,138.02	3,216.78	31.07
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	10,354.80	5,700.00	4,654.80	44.95
+ GST 7.00/7.00% (S\$)	724.84	399.00	325.84	44.95
Nett Amount (S\$)	11,079.64	6,099.00	4,980.64	44.95

INSPECTION

Date of Assignment: 14/08/2019
Date Inspected: 04/07/2019 **Inspected At:** Twincar Automotive Pte Ltd (HQ)
 2 KAKI BUKIT AVEUNE 2 #01-17
 Singapore 417921
Estimated Period of Repair: 5.0 days

Adjuster: SIMON HO LEONG CHUAN**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2019)
Parts:	144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR8112X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	781.10 FL	*781.10 FL
2	1		*FRONT BUMPER AIR DUCT GARNISH LH	Cracked	177.20 FL	*177.20 FL
3	1		*FRONT BUMPER DAYLIGHT LH	Cracked	972.85 FL	*972.85 FL
4	1		*FRONT BUMPER SIDE BRACKET LH	Cracked	171.10 FL	*171.10 FL
5	1		*FRONT BUMPER SIDE RETAINER L/R	N/S Cracked	264.50 FL	*132.25 FL
6	1		*FRONT BUMPER UPPER SEAL RUBBER	Necessary	174.45 FL	*174.45 FL
7	1		*FRONT LH BALL JOINT	Not Necessary	173.00 FL	*- FL
8	1		*FRONT LH FENDER	Deformed	721.30 FL	*721.30 FL
9	1		*FRONT LH FENDER HYBRID EMBLEM	Necessary	123.05 FL	*123.05 FL
10	1		*FRONT LH FENDER INNER SHIELD	Not Necessary	259.45 FL	*- FL
11	1		*FRONT LH HEADLAMP	Cracked	2,721.10 FL	*2,721.10 FL
12	1		*FRONT LH KNUCKLE ARM	Dented	485.00 FL	*485.00 FL
13	1		*FRONT LH KNUCKLE ARM BEARING	Dented	517.00 FL	*517.00 FL
14	1		*FRONT LH LOWER ARM	Not Necessary	435.00 FL	*- FL
15	1		*FRONT LH SHOCK ABSORBER	Dented	375.00 FL	*375.00 FL
16	1		*FRONT LH SHOCK ABSORBER TOP MOUNTING	Not Necessary	151.00 FL	*- FL
17	1		*FRONT LH SPORT RIM	Repair	1,555.00 FL	*- FL
18	1		*FRONT LH STABILIZER LINK	Not Necessary	117.00 FL	*- FL
19	1		*FRONT LH TIE ROD END	Not Necessary	93.00 FL	*- FL
20	1		*FRONT LH WHEEL CAP	Grazed / Cut	379.30 FL	*379.30 FL
21	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*20.00 FS
23	1		*FRONT LH TYRE 205/60R16	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,226.40	7,780.70
- List Item Discount on L Items 25.00/25.00% (S\$)	2,661.60	1,932.68
Total Parts (S\$)	8,564.80	5,848.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING (TO FR)	New	80.00	50.00
2	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	New	350.00	200.00
3	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	140.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	600.00	500.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	500.00	400.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
Gross Labour Cost (\$\$)			1,790.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >