

32/03/2002

ASS. REC. BY:

REF: CP/MSG 19014263/ D1F3

Special Instruction:

Survivor: Simon

ASSIGNMENT (Office)

From (Person): Ng Chun How

of

MSG

Date/Time: 13.8.19 18.24P.M.

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKG 7231Y

Insured:

SML 55985

at Workshop m/s

Twin car Automotive

Tel:

67440570

of BIC 2 Kaki Bukit, #01-17

Policy No: D29114746MCP

Claim No: 600804

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23.7.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 14.8.19 10.400.m

Person Contacted:

zi ting

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKG 7231Y - CS/ AXA 14005222/ 616d1 DOA - 12/03/2014
	SML 55985 - X
	Unconfirmed - US 84850, 5 days.

RECEIVED 4 OCT 2019

Nuriman



MSIG Insurance (Singapore Pte. Ltd)

(Co. Reg. No 200412212G)

4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

www.msig.com.sg

Executive
Claims Services**Inspection Report****Type of Survey:**

OD - Excess	
TP Without Prejudice	✓

Vehicle Details:

Vehicle Reg No
Make
Model
Passenger capacity
Paint colour & code
Paint type

5KE 72314
VW
Golf GTi 2.0
05
Grey

Vehicle Extras:

In-built camera
Modification

Yes / No

Yes / No

Vehicle Data:

Odometer reading
Engine No
VIN No
Engine capacity
Engine modification

255122 km

Vehicle Condition:

Seviceable

Yes / No

Handbrake
Footbrake
Steering
Body
Paint

Tyre Condition:

Tread mm

Size

Condition

Front right
Front left
Rear left
Rear right

5	Bridgestone	225 / 40 / 18	
5	"	"	
4	"	"	
4	"	"	

General Data:

Date of accident
Date of inspection
Date of assignment
Inspection location

23-07-19
26-07-19
26-07-19
N-51

Painting Process:

Prepare off vehicle
Painting off vehicle
Neither (default)

Cost Details:

Repairer

Adjuster

Parts
Supplementary
Miscellaneous
Body Labour
Paint labour
Paint material
TOTAL
Towing
Excess
Total less excess
Estimated days for repair

Body Panel Repair:

Panel repair calculator used
Yes / No

--

Remarks:

Lump / Global Sum

--

Reason(s)

Margin Repair / Fast-line

Others:

Repair Authorised

Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jul 2019 10:21		13 Aug 2019 18:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	LEE CHIU LAU, ID: S1327125I								
Vehicle Reg. No.:	SKE7231Y	Date of Loss:	23/07/2019 16:00 - :59 [145 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 600804	Policy/Cover Note No.:	D29114745MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SML5598S	Policy No. (Claimant):							
		Excess:							
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/08/2019]								
Driver/Custodian (Insured):	IAN TAY ZHIWEN (), NRIC: S8118074A Email:								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. OI: Grab. Liab: 100%. Agree on IHS. Contact: 6842 0051/ 6744 0510 (Zi Ting)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Yeo Poh Kheng <yeopk@n51.com.sg>
Sent: Monday, 30 September 2019 1:31 PM
To: Shiau Chan (LKKAUTO)
Subject: Re: SKE7231Y Estimate

Dear Shiau Chan

I can't accept this amount
Too low

On Thu, 26 Sep 2019 at 4:02 PM, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Mr Yeo,

WITHOUT PREJUDICE

Re-offer Lump Sum \$4,850.00 before GST and 5 repair days.

Kindly check.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yeo Poh Kheng <yeopk@n51.com.sg>
Sent: Friday, 20 September 2019 4:48 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: SKE7231Y Estimate

Shiau Chan (LKKAuto)

From: Yeo Poh Kheng <yeopk@n51.com.sg>
Sent: Saturday, 31 August 2019 11:06 AM
To: SUR
Cc: Shiau Chan (LKKAuto)
Subject: Finalise

Dear Shiau Chan

Can finalise below vehicles

SKE7231Y L/S \$ 7900.00 6 days


SMD7470E L/S limit \$11500.00 8 days

SLR8112X L/S \$ 5700.00 5 days

Pls check and let me know
Thanks

Regards,

Yeo Poh Kheng
N-51 Automotive Pte Ltd
Mobile : 8823 5151
Office : 6842 0051
www.n51.com.sg





MSIG

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____
Date : _____

Policy No : _____
Claim No : _____


Insured Vehicle No : SML5598 S. Date of Accident : 23-07-19.
TP Vehicle No : SKE 7231 Y Place of Survey : Twin car.
Make & Model : VW Golf GTI Date of Survey : 26-07-19.

Point of Impact / Damages :

Side Left.

Recommended Reserve :

Repairer's Estimate : \$ 17091.44
Interim Adjustment : \$ 7358.44
Check Items : \$ 3333.47



Proposed : Part by Part / Lump Sum Repair \$8500 Excess : \$ -

Estimate Repair Period : 06 days

Pre-accident Market Value (for total loss consideration) : \$ 50000.00

COE / PARF to owner : \$ 40349.00

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐

OD Claim
Excess : \$ _____
(Authorised / Revert)

☒

TP Claim
(Without Prejudice)

Vehicle No. SKE 7231 Y

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 06

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 26-07-19.

Victor - Seng @ sg.msig-asia.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	125I
Vehicle Details	
Vehicle No.:	SKE7231Y
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF GTI 2.0 A
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	AXX049809
Chassis No.:	WVWZZZ1KZ6W042326
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$27,008.00
Original Registration Date:	28 May 2007
First Registration Date:	28 May 2007
Transfer Count:	3
Actual ARF Paid:	\$29,709.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$52,008.00
COE Rebate Amount:	\$39,526.00
Total Rebate Amount:	\$39,526.00

The information contained herein is correct as at 24 Sep 2019

OK

> [Back to OneMotoring](#)

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
SKE7231Y

Make / Model
VOLKSWAGEN / GOLF GTI 2.0 A

Vehicle Type :
P10 - Passenger Motor Car

Vehicle Attachment 1 :
With Sun Roof

Vehicle Scheme :
Normal

Chassis No. :
WVWZZZ1KZ6W042326

Propellant :
Petrol

Engine No. :
AXX049809

Motor No. :
-

Engine Capacity :
1984 cc

Power Rating :



Maximum Power Output :
147.0 kW (197 bhp)

Maximum Laden Weight :

1920 kg

Unladen Weight :

1391 kg

Year Of Manufacture :

2006

Original Registration Date :

28 May 2007

Lifespan Expiry Date :

-

COE Category :

B - Car (1601cc & above)

PQP Paid :

\$52,008.00

COE Expiry Date :

30 Apr 2027

Road Tax Expiry Date :

27 Nov 2019

PARF Eligibility Expiry Date :

-

Inspection Due Date :

27 May 2020

Intended Transfer Date :

24 Sep 2019

CO2 Emission :

-

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

-



NOx Emission :

PM Emission :

-

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (28 Nov 2019 to 27 May 2020)	\$777.00
Road Tax Renewal - 12 months (28 Nov 2019 to 27 Nov 2020)	\$1,612.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees.

Any road tax that has been paid for the vehicle will be transferred to the next owner.

Print

OK →

Save as PDF

Copy as Text



TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR LEE CHIU LAU
BLK 101 BEDOK NORTH AVE 4 #13-1950
SINGAPORE 460101

Contact : 97672147

ESTIMATE

Repair Code : CLM14635

Date in : 24/07/2019

Vehicle Num. : SKE7231Y

Model : VOLKSWAGEN GOLF GTI 2.0 A

Chassis/Eng# : WVWZZZ1KZ6W042326/AXX049809

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER / <i>cracked</i>	1	<i>1703.75</i> 1896.00	1,896.00
FRONT BUMPER SIDE RETAINER LH / <i>cracked</i>	1	160.31	160.31
FRONT LH DOOR <i>X repair</i>	1	2285.29	2,285.29
FRONT LH DOOR PROTECTOR <i>X</i>	1	258.95	258.95
<i>front</i> FRONT LH DOOR SIDE MIRROR / <i>Graced X R Ding</i>	1	<i>914.32</i> 1294.76 <i>? X</i>	1,294.76
FRONT LH DOOR SIDE MIRROR SIDE LAMP / <i>Graced</i>	1	90.23	90.23
FRONT LH FENDER / <i>Dented</i>	1	600.71	600.71
FRONT LH FENDER INNER SHIELD <i>CRA</i>	1	233.96	233.96
FRONT LH KNUCKLE ARM <i>distorted</i>	1	<i>607.90</i> 897.70	897.70
FRONT LH KNUCKLE ARM BEARING <i>BT</i>	1	<i>543.60</i> 600.31	600.31
FRONT LH LOWER ARM	1	689.89	689.89
FRONT LH SHOCK ABSORBER	1	488.96	488.96
FRONT LH SHOCK ABSORBER TOP MOUNTING	1	233.70	233.70
FRONT LH STABILIZER LINK	1	123.05	123.05
FRONT LH TIE ROD END	1	65.90	65.90
REAR LH DOOR <i>X repair</i>	1	2285.29	2,285.29
ROCKER GARNISH LH / <i>Graced X NN</i>	1	416.43	416.43

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR. LEE CHIU LAU
BLK 101 BEDOK NORTH AVE 4 #13-1950
SINGAPORE 460101

Contact : 97672147

ESTIMATE

Repair Code : CLM14635
Date in : 24/07/2019
Vehicle Num. : SKE7231Y
Model : VOLKSWAGEN GOLF GTI 2.0 A
Chassis/Eng# : WVWZZZ1KZ6W042326/AXX049809

Subtotal before discount 12,621.44

Percentage discount 0%

0.00

Sub-total 1

12,621.44

FRONT LH FENDER INNER SHIELD CLIPS - SET *1000*

1

50.00

30 ~~50.00~~

FRONT LH SPORT RIM *Gravel*

1

940.00

550 ~~940.00~~

FRONT LH TYRE 225/40R18 *X XH*

1

500.00

500.00

ROCKER GARNISH CLIPS LH - SET *XHn*

1

50.00

20 ~~50.00~~

Subtotal before discount

1,540.00

Percentage discount 0%

0.00

Sub-total 2

1,540.00

Parts-total

14,161.44

LABOUR

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

Labour Total

2,930.00

Parts & Labour Total

17,091.44

*** This is a computer-generated document which requires no signature.***

page 2

06 days
26/07/19 @ 1500hrs
Victor_Seng @ sg.msia-asia.com
87747011
w/o pre-judice
L1s check item? / After paint

5 days

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR LEE CHIU LAU
BLK 101 BEDOK NORTH AVE 4 #13-1950
SINGAPORE 460101

Contact : 97672147

ESTIMATE

Repair Code : CLM14635

Date in : 24/07/2019

Vehicle Num. : SKE7231Y

Model : VOLKSWAGEN GOLF GTI 2.0 A

Chassis/Eng# : WVWZZZ1KZ6W042326/AXX049809

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER / <i>cracked</i>	1	1896.00	1,896.00
FRONT BUMPER SIDE RETAINER LH / <i>cracked</i>	1	160.31	160.31
FRONT LH DOOR X <i>repair</i>	1	2285.29	2,285.29 X
FRONT LH DOOR PROTECTOR X	1	258.95	258.95 X
FRONT LH DOOR SIDE MIRROR / <i>Graced</i>	1	1294.76 ?	1,294.76
FRONT LH DOOR SIDE MIRROR SIDE LAMP / <i>Graced</i>	1	90.23	90.23
FRONT LH FENDER / <i>Dented</i>	1	600.71	600.71
FRONT LH FENDER INNER SHIELD 3/ <i>cracked</i>	1	233.96	233.96
FRONT LH KNUCKLE ARM / <i>Dented</i>	1	897.70	897.70
FRONT LH KNUCKLE ARM BEARING / <i>Dented</i>	1	600.31	600.31
FRONT LH LOWER ARM / <i>Dented</i>	1	689.89	689.89
FRONT LH SHOCK ABSORBER X	1	488.96	488.96 X
FRONT LH SHOCK ABSORBER TOP MOUNTING X	1	233.70	233.70
FRONT LH STABILIZER LINK / <i>Dented</i>	1	123.05	123.05
FRONT LH TIE ROD END / <i>Dented</i>	1	65.90	65.90
REAR LH DOOR X <i>repair</i>	1	2285.29	2,285.29 X
ROCKER GARNISH LH / <i>Graced</i>	1	416.43	416.43

*** This is a computer-generated document which requires no signature.***

page 1

Re - survey
29/07/19 @ 1500hrs
Vicki

7302.95
- 5% 365.14
6937.80

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR. LEE CHIU LAU
BLK 101 BEDOK NORTH AVE 4 #13-1950
SINGAPORE 460101

Contact : 97672147

ESTIMATE

Repair Code : CLM14635

Date in : 24/07/2019

Vehicle Num. : SKE7231Y

Model : VOLKSWAGEN GOLF GTI 2.0 A

Chassis/Eng# : WVWZZZ1KZ6W042326/AXX049809

	Subtotal before discount	12,621.44
Percentage discount 0%		0.00
	Sub-total 1	12,621.44
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>1000</i>	1	50.00 <i>30 50.00</i>
FRONT LH SPORT RIM <i>1000</i>	1	940.00 940.00
FRONT LH TYRE 225/40R18 <i>X</i>	1	500.00 500.00 <i>X</i>
ROCKER GARNISH CLIPS LH - SET <i>1000</i>	1	50.00 <i>20 50.00</i>
	Subtotal before discount	1,540.00
Percentage discount 0%		0.00
	Sub-total 2	1,540.00
	Parts-total	14,161.44

LABOUR

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

Labour Total	2,930.00
Parts & Labour Total	17,091.44

*** This is a computer-generated document which requires no signature.***

06 days
26/07/19 @ 1500hrs
Victor_Seng @ sg.msig-asia.com
8774 7011
w/o pre-incident
After paint

6937.80
950.00
2010.00
9897.80
1979.56
7918.24

The insurer has given adjuster a maximum mandate of S\$25,000.00 to authorize directly on their behalf, but the adjuster has disabled direct offer mode.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014363/DQF3
Date: 08/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: D29114745MKF

Claimant Vehicle No: SKE7231Y

Insured Vehicle No: SML5598S

Date of Loss: 23/07/2019

Nature of Claim: TP

Claim No: 600804

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE7231Y**
Make & Model: VOLKSWAGEN GOLF, 2.0 GTI (A)
Reg. Date: 28/05/2007 (Man. Year: 2006)
Colour: Grey
Engine Capacity: 1984 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: AXX049809
Chassis No: WVVZZZ1KZ6W042326
Odometer: 255122 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40/18 Rear Tyre Size: 225/40/18
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 4 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,161.44	4,499.30	9,662.14	68.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,580.00	1,550.00	49.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,291.44	6,079.30	11,212.14	64.84
Approved Total (Overridden) (S\$)		4,850.00		
(S\$)	17,291.44	4,850.00	12,441.44	71.95
+ GST 7.00/7.00% (S\$)	1,210.40	339.50	870.90	71.95
Nett Amount (S\$)	18,501.84	5,189.50	13,312.34	71.95

INSPECTION

Date of Assignment: 13/08/2019

Date Inspected: 26/07/2019 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2019)
Parts:	144	VOLKSWAGEN GOLF 2.0 GTI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE7231Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,896.00 F	*1,203.75 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	160.31 F	*160.31 FL
3	1		*FRONT LH DOOR	Repair	2,285.29 F	*- FL
4	1		*FRONT LH DOOR PROTECTOR	Not Necessary	258.95 F	*- FL
5	1		*FRONT LH DOOR SIDE MIRROR	Damaged	1,294.76 F	*914.32 FL
6	1		*FRONT LH DOOR SIDE MIRROR SIDE LAMP	Grazed	90.23 F	*90.23 FL
7	1		*FRONT LH FENDER	Dented	600.71 F	*600.71 FL
8	1		*FRONT LH FENDER INNER SHIELD	Cracked	233.96 F	*233.96 FL
9	1		*FRONT LH KNUCKLE ARM	Distorted	897.70 F	*607.90 FL
10	1		*FRONT LH KNUCKLE ARM BEARING	Bent	600.31 F	*543.60 FL
11	1		*FRONT LH LOWER ARM	Not Necessary	689.89 F	*- FL
12	1		*FRONT LH SHOCK ABSORBER	Not Necessary	488.96 F	*- FL
13	1		*FRONT LH SHOCK ABSORBER TOP MOUNTING	Not Necessary	233.70 F	*- FL
14	1		*FRONT LH STABILIZER LINK	Not Necessary	123.05 F	*- FL
15	1		*FRONT LH TIE ROD END	Not Necessary	65.90 F	*- FL
16	1		*REAR LH DOOR	Repair	2,285.29 F	*- FL
17	1		*ROCKER GARNISH LH	Not Necessary	416.43 F	*- FL
18	1		*SET FRONT LH FENDER INNER SHIELD CLIPS		50.00 FS	*30.00 FS
19	1		*FRONT LH SPORT RIM	Grazed	940.00 FS	*550.00 FS
20	1		*FRONT LH TYRE 225/40 R18	Not Necessary	500.00 FS	*- FS
21	1		*SET ROCKER GARNISH CLIPS LH	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,161.44	4,934.78
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	435.48
Total Parts (\$\$)	14,161.44	4,499.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION.	New	400.00	150.00
2	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENT SYSTEM.	New	150.00	30.00
3	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE	New	180.00	0.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,400.00	800.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,000.00	600.00
Gross Labour Cost (\$\$)			3,130.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >