

22/05/2002

ASS. REC. BY:

REF: CF/MSG 1904364/09f3

Special Instruction:

Surveyor: Simon

ASSIGNMENT (Office)

From (Person): Jocelyn Ng Shin Bun of MSIG

Date/Time: 14.8.19 16.53p.m

Estimated Cost: Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKH 26925

Insured:

at Workshop m/s King's Auto Air-conditioning

Tel: 64578629

of Blk 176 Sin Ming Drive #10210

Policy No: 27416199

Claim No: 600239

Sum Insured:

Excess: \$500.00

Make of Veh:

D.O.A. 17.7.2019

(Client's Record)

CA REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14.8.19 5.03p.m

Person Contacted: Annie

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKH 26925 - CV1 / VAL 19013121 / BQ Don - 17/07/2019
22/8/19 @ 1.20pm	Annie said she will go to check with her boss on finalisation
29/7/19 @ 3.15pm	Jocelyn Ng already informed workshop proceed repair at unit \$4500. MSIG will pay \$3750 (after deduct excess \$500)
	& insured have to top up the balance of \$1250 inclusive \$500.
	Print buyer's sample of reinforcement no photo. given
	due to benefit of doubt.

# MS16 DD vehicle: SKH 26925 (RE-ASSIGNED CASES)

WKSP: KING'S AUTO AIR-CONDITIONING

DOR: 17/07/2017 EXCESS: \$500.

US \$450, 6 days. (Red \$4704.16, 51%)

RECEIVED 27 SEP 2019

150  
11  
161



MSIG Insurance (Singapore Pte. Ltd)

(Co. Reg. No 200412212G)

4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

[www.msig.com.sg](http://www.msig.com.sg)Executive  
Claims Services**Inspection Report****Type of Survey:**

OD - Excess	\$500/-
TP Without Prejudice	

**Vehicle Details:**

Vehicle Reg No

Make

Model

Passenger capacity

Paint colour &amp; code

Paint type

SKH 26925
Mazda 3
3
05
White

**Vehicle Extras:**

In-built camera

Modification

Yes / No  
Yes / ~~No~~**Vehicle Data:**

Odometer reading

Engine No

VIN No

Engine capacity

Engine modification

65554km

**Vehicle Condition:**

Seviceable

Yes / No

Handbrake

Footbrake

Steering

Body

Paint


**Tyre Condition:**

Tread mm

Size

Condition

Front right

Front left

Rear left

Rear right

5	Michelin	205 / 55 / 16	
5		"	
4		"	
4		"	

**General Data:**

Date of accident

Date of inspection

Date of assignment

Inspection location

17-07-19
22-07-19
19-07-19
King's Auto

**Painting Process:**

Prepare off vehicle

Painting off vehicle

Neither (default)


**Cost Details:**

Parts

Supplementary

Miscellaneous

Body Labour

Paint labour

Paint material

TOTAL

Towing

Excess

Total less excess

Estimated days for repair

Repairer

Adjuster


**Body Panel Repair:**

Panel repair calculator used

Yes / No


**Remarks:**

Lump / Global Sum

--

Reason(s)

Margin Repair / Fast-line

**Others:**


Repair Authorised

Date:

--

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jul 2019		14 Aug 2019 16:53 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All																				
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>																					
Insured:	CHEN YIH LIN, ID: S2199156B, Tel: +6581180654, Email: YIHLIN@GMAIL.COM																							
Vehicle Reg. No.:	SKH2692S	Date of Loss:	17/07/2019 08:00 - :59 [79 Months and 26 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	OD / 600239	Policy/Cover Note No.:	27416199 (Comprehensive) Coverage: 21/11/2018 - 20/11/2019																					
		Excess:	S\$500.00																					
Repairer:	King's Auto Air-Conditioning Service (HQ) Block 176 Sin Ming Drive, #02-10, 575721 Sin Ming - Tel: 6457 8629																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]																							
Driver/Custodian:	CHEN YIH LIN (50 / Female), NRIC: S2199156B, Tel: +6581180654 Email: YIHLIN@GMAIL.COM																							
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. Survey & revert. Please check brake and tyre conditions, thank you.																							
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>																				
There are no mail for this case.																								
<div> <b>ALL ASSOCIATED TASKS</b> </div> <div> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

## Jocelyn Ng

---

**From:** Jocelyn Ng  
**Sent:** Monday, 29 July, 2019 3:15 PM  
**To:** ALEX QUEK  
**Cc:** yihlin@gmail.com; Keny Ong  
**Subject:** RE: Skh2692s

Dear Alex,

Please proceed to repair at limit \$4,500.00 including check items and supplementary parts.

MSIG will pay \$3,250.00 (after deduct excess of \$500.00) and insured have to top-up the balance of \$1,250.00 (inclusive excess).

Thank you  
*Have a great week ahead!*

**Jocelyn Ng**  
Executive, Claims Services  
D: +65 6594 2539 | F: +65 6225 7402 | [jocelyn\\_ng@sg.msig-asia.com](mailto:jocelyn_ng@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** ALEX QUEK [mailto:yenking13@hotmail.com]  
**Sent:** Monday, 29 July, 2019 11:59 AM  
**To:** Jocelyn Ng <jocelyn\_ng@sg.msig-asia.com>  
**Subject:** Skh2692s

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Hi Jocelyn,

This is to confirm that the repair to Skh2692s will be done on lump sum basis.

The total amount need is \$4,500

Thank you

Alex quek  
King's auto

Get [Outlook for Android](#)


**MSIG**

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)  
16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581  
Tel 6220 9644, Fax 6225 6371  
www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.  
16 Raffles Quay  
#24-01 Hong Leong Building  
Singapore 048581

Attn: Jocelyn Ng Shin Bun

Date: 23 Jul 2019

### Preliminary Advice

Vehicle No	: SKH2692S	Accident Date	: 17/07/2019
Make	: MAZDA 3	Policy No.	: 27416199
Assignment Date	: 19/07/2019	Excess	: S\$500.00
Date of Inspection	: 22/07/2019	Est. Duration of Repair	: 6.00
Inspection At	: KING'S AUTO AIR-CONDITIONING SERVICE (HQ) BLOCK 176 SIN MING DRIVE, #02-10 SINGAPORE 575721		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front portion.

Repairer's Estimate (Gross)	:S\$	9,204.16
Revised Amount	:S\$	4,922.87
Check Items (Estimated)	:S\$	2,983.79
Total	:S\$	

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	37,000.00
COE / PARF Rebate	:S\$	37,926.00
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

- ( x ) The vehicle is ~~economical~~/not economical for repair.
- ( x ) Others: Tyres 80% threads. Brakes - pads 80% left for all sides, rotors are in good conditions. Total rebate amount on the high side due to high COE paid when brought this car.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	156B
<b>Vehicle Details</b>	
Vehicle No.:	SKH2692S
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jul 2019
Vehicle Make:	MAZDA
Vehicle Model:	3 SP 1.6L A/T ABS D/AB 2WD 4DR HID
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	Z6A59218
Chassis No.:	JM6BL10Z2C0338018
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$18,833.00
Original Registration Date:	21 Nov 2012
First Registration Date:	21 Nov 2012
Transfer Count:	0
Actual ARF Paid:	\$18,833.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Nov 2022
PARF Rebate Amount:	\$12,241.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	20 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$77,201.00
COE Rebate Amount:	\$25,755.00
<b>Total Rebate Amount:</b>	<b>\$37,996.00</b>

The information contained herein is correct as at 19 Jul 2019

OK

> Back to OneMotoring

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SKH2692S		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MAZDA		
Vehicle Model :	3 SP 1.6L A/T ABS D/AB 2WD 4DR HID		
Chassis No. :	JM6BL10Z2C0338018		
Propellant :	Petrol		
Engine No. :	Z6A59218		
Engine Capacity :	1598 cc		
Maximum Power Output :	77.0 kW ( 103 bhp)		
Maximum Laden Weight :	1755 kg		
Unladen Weight :	1275 kg		
Year Of Manufacture :	2012		
Original Registration Date :	21 Nov 2012		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$77,201.00		
COE Expiry Date :	20 Nov 2022		
Road Tax Expiry Date :	20 Nov 2019		
PARF Eligibility Expiry Date :	20 Nov 2022		
Inspection Due Date :	20 Nov 2019		
Intended Transfer Date :	19 Jul 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print





MSIG

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

[www.msig.com.sg](http://www.msig.com.sg)

# PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : \_\_\_\_\_  
Date : \_\_\_\_\_

Policy No : \_\_\_\_\_  
Claim No : \_\_\_\_\_

Insured Vehicle No : SKH 2692 S

Date of Accident : 17-07-19

TP Vehicle No : -

Place of Survey : King's Auto

Make & Model : Mazda 3

Date of Survey : 22-07-19

Point of Impact / Damages :


Front

Recommended Reserve :

Repairer's Estimate : \$ 9204.16

Interim Adjustment : \$ 4922.87

Check Items : \$ 2983.79



Proposed : Part by Part / Lump Sum Repair

Excess : \$ 500 /-

Estimate Repair Period : 06 days

Pre-accident Market Value (for total loss consideration) : \$ 37000.00

COE / PARF to owner : \$ 37926.00

Vehicle ~~within~~ / not within limit of economical repair.

Others :

\* Tyres 80% threads

\* Brakes - Pads 80% left for all sides, Rotors are in good Conditions.

Surveyed By :

\* Total Rebate amount on the high side due to High COE paid when bought this car.

MSIG Insurance (Singapore) Pte. Ltd.

☒ OD Claim  
Excess : \$ 500/-  
(Authorised / Revert)

☐ TP Claim  
(Without Prejudice)

Vehicle No. SKH 26925

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 6 days.

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 22-07-19.

Victor - Seng @ sg.msig-asia.com

# KING'S AUTO AIR-CONDITIONING SERVICE

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721

TEL: 6457-8629 FAX: 451-7651

Reg. No. 095956/00W

156B

37926

Nov '17

DATE 19th July 2019  
TO MSIG INSURANCE SINGAPORE PTE LTD  
4 SHENTON WAY, #21-01 SGX CENTRE 2, SINGAPORE 068807  
RE QUOTATION FOR VEHICLE SKH 2692 S Mazda 3

Quantity	Item	Unit Price (\$\$)	Amount (\$\$)
1	Front Bonnet / Deformed		450.00
1	Front Bonnet Lock / Deformed		75.00
2	Front Bonnet Hinge / Deformed	25	50.00
1	Front Bonnet Rubber / Deformed		25.00
1	Front Bonnet Insulator / Deformed		75.00
2	Front Fender X repair. ✓ mng	150	300.00
2	Front Fender Signal Lamp X nm	25	50.00
2	Front Head Lamp (HID) / cracked	850	1,700.00
1	Front Bumper / Deformed		340.00
2	Front Bumper Side Retainer ? xnn	15.00	30.00
2	Front Bumper Bracket ? xnn	8.00	16.00
1	Front Bumper Sponge ? ✓ mng		40.00
1	Front Bumper Reinforcement ? ✓ mng		200.00
1	Front Bumper Grille (outer) / Deformed		100.00
1	Front Bumper Griller (inner) / cracked		45.00
2	Front Fog Lamp ? xnn	140	280.00
2	Front Fog Lamp Grille ? xnn	40	80.00
1	Front Emblem / cracked		19.20
1	License Plate with Holder / Deformed		45.00
1	Front Support Panel / cracked		220.00
1	Aircon Condensor ?		450.00
1	Radiator Assy ? xnn		750.00
1	Fan Motor assy ?		748.60
SUB-TOTAL			6,088.80
ADD 15%			155.36
TOTAL			6,244.16

# KING'S AUTO AIR-CONDITIONING SERVICE

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721

TEL: 6457-8629 FAX: 451-7651

Reg. No. 095956/00W

DATE 19th July 2019  
TO MSIG INSURANCE SINGAPORE PTE LTD  
4 SHENTON WAY, #21-01 SGX CENTRE 2, SINGAPORE 068807  
RE QUOTATION FOR VEHICLE SKH 2692 S Mazda 3

## FOR LABOUR CHARGES

Quantity	Item	Unit Price (S\$)	Amount (S\$)
	Panel Beating		700 1,200.00
	Spray Painting	600 850	1,400.00
	Wiring	30	50.00
	Labour to remove and replaced aircon condensor	80	150.00
	Labour to remove and replaced radiator assy	60	80.00
	Towing Service	invoice	80.00
	TOTAL		2,960.00

GRAND TOTAL FOR THIS QUOTATION 9,204.16

## KING'S AUTO AIR-CONDITIONING SERVICE

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721  
TEL: 6457-8629 FAX: 6451-7651  
Reg. No. 095950/00W

MSIG Insurance Singapore Pte Ltd  
4 Shenton Way,  
#21-01, SGX Centre 2,  
Singapore 068807

Date: 12th Sept 2019  
Invoice No.: INS 11603  
Our Reference: SKH 2692 S  
Vehicle Make/Model: Mazda 3

Quantity	Description	Unit Price	Amount
1	Lumpsum		\$4,500.00
		less excess	\$500.00
		owner top-up	\$750.00
TOTAL AMOUNT PAYABLE			<u>\$3,250.00</u>

Please cross your cheque and pay to  
"King's Auto Air-Conditioning Service"

King's Auto Air-Conditioning Service

Authorised Signature



# KING'S AUTO AIR-CONDITIONING SERVICE

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721

TEL : 457 8629 FAX : 4517651

Reg. No. 095956/00W


Date: 10th Sept 2019

## SATISFACTION CUM DISCHARGE VOUCHER

To: MSZ 67

I/We hereby declare that the repair to my/our MAZDA 3  
vehicle Registration No. SKH 2692 S have been completed to my/our  
satisfaction and I/we agree that the payment of the sum of \$ 4500/- (Dollars  
)

paid to KING'S AUTO AIR-CONDITIONING SERVICES for such repairs is in full  
discharge of my/our claims under Policy No. A27416199QMY in respect of the  
damage caused in the accident which occurred on the 17 day of  
July 2019.

  
Signature of Insured

Adjuster Letter/DV not verified.  
This claim is to be authorized on the insurer's behalf.  
Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.  
Click on 'View Letter/DV' to verify the offer.

You cannot authorize this offer because  
Adjuster Letter/DV not verified.  
File to be authorized by your superior.

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CF/MSG19014364/DQF3

Date: 09/10/2019

#### REFERENCE

Insured/Claimant:	CHEN YIH LIN	Policy No:	27416199	Claim No:	600239
Date of Loss:	17/07/2019	Nature of Claim:	OD		

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH2692S	Engine No:	Z6A59218
Make & Model:	MAZDA 3, 1.6 L SP ABS D/AB 2WD 4DR (A)	Chassis No:	JM6BL10Z2C0338018
Reg. Date:	21/11/2012 (Man. Year: 2012)	Odometer:	65554 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Yes	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	205/55/16	Rear Tyre Size:	205/55/16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,002.12	4,236.83	2,765.29	39.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,470.00	1,490.00	50.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,962.12</b>	<b>5,706.83</b>	<b>4,255.29</b>	<b>42.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
- Excess (S\$)	500.00	500.00	0.00	0.00
- Top-Up Amount (S\$)	750.00	750.00	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>8,712.12</b>	<b>3,250.00</b>	<b>5,462.12</b>	<b>62.70</b>

#### INSPECTION

Date of Assignment:	14/08/2019	Inspected At:	King's Auto Air-Conditioning Service (HQ) Block 176 Sin Ming Drive, #02-10 Singapore 575721
Date Inspected:	22/07/2019		
Estimated Period of Repair:	6.0 days		

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2019)
<b>Parts:</b>	144	MAZDA 3 1.6 L SP ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKH2692S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRONT BONNET</b> (WCP)	Deformed	450.00 F	*450.00 F
2	1		<b>*FRONT BONNET LOCK</b> (WCP)	Dented	75.00 F	*75.00 F
3	2		<b>*FRONT BONNET HINGE</b> (WCP)	Dented	50.00 F	*50.00 F
4	1		<b>*FRONT BONNET RUBBER</b> (WCP)	Deformed	25.00 F	*25.00 F
5	1		<b>*FRONT BONNET INSULATOR</b> (WCP)	Deformed	75.00 F	*75.00 F
6	2		<b>*FRONT FENDER</b> (WCP)	Damaged	300.00 F	*300.00 F
7	2		<b>*FRONT FENDER SIGNAL LAMP</b> (WCP)	Not Necessary	50.00 F	*- F
8	2		<b>*FRONT HEAD LAMP (HID)</b> (WCP)	Cracked	1,700.00 F	*1,700.00 F
9	1		<b>*FRONT BUMPER</b> (WCP)	Deformed	340.00 F	*340.00 F
10	2		<b>*FRONT BUMPER SIDE RETAINER</b> (WCP)	Not Necessary	30.00 F	*- F
11	2		<b>*FRONT BUMPER BRACKET</b> (WCP)	Not Necessary	16.00 F	*- F
12	1		<b>*FRONT BUMPER SPONGE</b> (WCP)	Damaged	40.00 F	*40.00 F
13	1		<b>*FRONT BUMPER REINFORCEMENT</b> (WCP)	Damaged	200.00 F	*200.00 F
14	1		<b>*FRONT BUMPER GRILLE (OUTER)</b> (WCP)	Deformed	100.00 F	*100.00 F
15	1		<b>*FRONT BUMPER GRILLE (INNER)</b> (WCP)	Cracked	45.00 F	*45.00 F
16	2		<b>*FRONT FOG LAMP</b> (WCP)	Not Necessary	280.00 F	*- F
17	2		<b>*FRONT FOG LAMP GRILLE</b> (WCP)	Not Necessary	80.00 F	*- F
18	1		<b>*FRONT EMBLEM</b> (WCP)	Cracked	19.20 F	*19.20 F
19	1		<b>*LICENSE PLATE WITH HOLDER</b> (WCP)	Deformed	45.00 F	*45.00 F
20	1		<b>*FRONT SUPPORT PANEL</b> (WCP)	Cracked	220.00 F	*220.00 F
21	1		<b>*AIRCON CONDENSOR</b> (WCP)	Not Necessary	450.00 F	*- F
22	1		<b>*RADIATOR ASSY</b> (WCP)	Not Necessary	750.00 F	*- F
23	1		<b>*FAN MOTOR ASSY</b> (WCP)	Not Necessary	748.60 F	*- F

F=Franchise part.

<b>Sub Total (S\$)</b>	<b>6,088.80</b>	<b>3,684.20</b>
<b>+ Margin on L,N Items 15.00/15.00% (S\$)</b>	913.32	552.63
<b>Total Parts (S\$)</b>	<b>7,002.12</b>	<b>4,236.83</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items  
There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING.	New	1,200.00	700.00
2	SPRAY PAINTING.	New	1,400.00	600.00
3	WIRING.	New	50.00	30.00
4	LABOUR TO REMOVE AND REPLACED AIRCON CONDENSOR.	New	150.00	80.00
5	LABOUR TO REMOVE AND REPLACED RADIATOR ASSY.	New	80.00	60.00
6	TOWING SERVICE.	New	80.00	-
<b>Gross Labour Cost (S\$)</b>			<b>2,960.00</b>	<b>1,470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >