

23/09/2019

ASS. REC. BY:

REF: CF/MSG 19014368/Dqf30x

Special Instruction:

SUIVOYOT

Simon

ASSIGNMENT (Office)

From (Person): Fievel Foo Van Yao

of

MSG

Date/Time: 15.8.19 18:11p.m

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SGV 8828C

Insured: SJZ 1789x

at Workshop in/s Vin's motor

Tel: 64532121

of 160 sh my drive #03-03

Policy No: 804697756mx

Claim No: 596241

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 9.6.2019

CA / REV / REP. / REV 24 HRS

mp'

Date/Time: 14.8.2019 10:32a.m

Person Contacted: Raymond

I.L.O.D. Endowment:

Vehicle: IN/OUT

| Date/Time | Action/Instruction           |
|-----------|------------------------------|
|           | Estimate                     |
|           | SGV 8828C - X                |
|           | SJZ 1789x - CI/TPD K011234PC |
|           | ROA - 09/06/2019             |
|           | RECEIVED 27 SEP 2019         |
|           | * FIA Report - 30/8          |

16/9/19 @ 3.50pm confirmed with Raymond LS @ 10800, 8 days.  
 Cled @ 4581.17.30%

150211

=161

Minimum



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)  
4 Shenton Way. #27-01, SGX Centre 2, Singapore 068807  
Tel +65 6827 7888, Fax +65 6827 7800  
[www.msig.com.sg](http://www.msig.com.sg)

Executive  
Claims Services

## Inspection Report

### Type of Survey:

|                      |  |
|----------------------|--|
| OD - Excess          |  |
| TP Without Prejudice |  |

### Vehicle Details:

Vehicle Reg No  
Make  
Model  
Passenger capacity  
Paint colour & code  
Paint type

|           |
|-----------|
| SV 8828 C |
| Toyota    |
| Alpha     |
| 08        |
| White     |
|           |

### Vehicle Extras:

In-built camera  
Modification

Yes / No  
Yes / No

### Vehicle Data:

Odometer reading  
Engine No  
VIN No  
Engine capacity  
Engine modification

|        |
|--------|
|        |
| Faulty |
|        |
|        |
|        |
|        |

### Vehicle Condition:

Seviceable Yes / No

Handbrake  
Footbrake  
Steering  
Body  
Paint

|  |
|--|
|  |
|  |
|  |
|  |
|  |

### Tyre Condition:

Front right  
Front left  
Rear left  
Rear right

| Tread mm | Size                  | Condition |
|----------|-----------------------|-----------|
| 5        | Pirelli 245 / 45 / 19 |           |
| 5        | 11                    |           |
| 4        | 11                    |           |
| 4        | 11                    |           |

### General Data:

Date of accident  
Date of inspection  
Date of assignment  
Inspection location

|             |
|-------------|
| 09-06-19    |
| 05-07-19    |
| 04-07-19    |
| Vin's Auto. |

### Painting Process:

Prepare off vehicle  
Painting off vehicle  
Neither (default)

|  |
|--|
|  |
|  |
|  |

### Cost Details:

Parts  
Supplementary  
Miscellaneous  
Body Labour  
Paint labour  
Paint material  
TOTAL  
Towing  
Excess  
Total less excess  
Estimated days for repair

| Repaier | Adjuster |
|---------|----------|
|         |          |
|         |          |
|         |          |
|         |          |
|         |          |
|         |          |
|         |          |
|         |          |
|         |          |
|         |          |

### Body Panel Repair:

Panel repair calculator used  
Yes / No

|  |
|--|
|  |
|--|

### Remarks:

Lump / Global Sum

|  |
|--|
|  |
|--|

Reason(s)

Margin Repair / Fast-line

### Others:

|  |
|--|
|  |
|  |
|  |
|  |

Repair Authorised

Date:

|  |
|--|
|  |
|--|

## ...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING |                                      |                                      |                                |         |               |            |                                      |
|--------------------------|--------------------------------------|--------------------------------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Case                     | Notified                             | Est Submitted                        | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                               |
| Main                     | 03 Jul 2019<br>14:31<br>Sendback Est | 03 Jul 2019<br>14:32<br>S\$15,381.17 | 13 Aug 2019<br>18:11<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

| Main                                                                                                                                       | Reference | Claim Details                                                                                                                | Documents              | Show All                                                                        |         |             |              |            |       |
|--------------------------------------------------------------------------------------------------------------------------------------------|-----------|------------------------------------------------------------------------------------------------------------------------------|------------------------|---------------------------------------------------------------------------------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>                                                                                                             |           |                                                                                                                              |                        |                                                                                 |         |             |              |            |       |
| Insured:                                                                                                                                   |           | LEO CHEE BOO (JENSEN), ID: S7700729F                                                                                         |                        |                                                                                 |         |             |              |            |       |
| Main Claimant:                                                                                                                             |           | TEO PEI FERN, ID: S1768693C                                                                                                  |                        |                                                                                 |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                                          |           | SGV8828C                                                                                                                     | Date of Loss:          | 09/06/2019 11:00 - :59<br>[77 Months and 28 Days From LTA<br>Reg Date (Man Yr)] |         |             |              |            |       |
| Claim Type:                                                                                                                                |           | TP / 596241                                                                                                                  | Policy/Cover Note No.: | 80469775QMX (Comprehensive)<br>Coverage: 01/05/2019 -<br>30/04/2020             |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                                |           | SJZ1789X                                                                                                                     | Policy No. (Claimant): |                                                                                 |         |             |              |            |       |
|                                                                                                                                            |           |                                                                                                                              | Excess:                |                                                                                 |         |             |              |            |       |
| Repairer:                                                                                                                                  |           | Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121                |                        |                                                                                 |         |             |              |            |       |
| Handling Insurer:                                                                                                                          |           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]               |                        |                                                                                 |         |             |              |            |       |
| Adjuster:                                                                                                                                  |           | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/08/2019]                                           |                        |                                                                                 |         |             |              |            |       |
| Driver/Custodian (Insured):                                                                                                                |           | LEO CHEE BOO (JENSEN) (), NRIC: S7700729F Email:                                                                             |                        |                                                                                 |         |             |              |            |       |
| Adj Asg. Remarks:                                                                                                                          |           | As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. (manual assigned) Contact: 6453 2121 / 6458 1111 |                        |                                                                                 |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>                                                 |           |                                                                                                                              |                        |                                                                                 |         |             |              |            |       |
| There are no mail for this case.                                                                                                           |           |                                                                                                                              |                        |                                                                                 |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> |           |                                                                                                                              |                        |                                                                                 |         |             |              |            |       |
| Due Date                                                                                                                                   | Priority  | Type                                                                                                                         | Task Group             | Subject                                                                         | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                |           |                                                                                                                              |                        |                                                                                 |         |             |              |            |       |



MSIG

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

[www.msig.com.sg](http://www.msig.com.sg)

## PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : \_\_\_\_\_

Date : \_\_\_\_\_

Policy No : \_\_\_\_\_

Claim No : \_\_\_\_\_

Insured Vehicle No : 53Z 1789X Date of Accident : 09-06-19TP Vehicle No : SGV 8828C Place of Survey : Vin's AutoMake & Model : Toyota Alpha 2.4 Date of Survey : 05-07-19

Point of Impact / Damages :

Front.

Recommended Reserve :

Repairer's Estimate : \$ 15381.17Interim Adjustment : \$ 7256.97Check Items : \$ 6495.2011,500/-Proposed : Part by Part / Lump Sum Repair \$11000/- Excess : \$ -Estimate Repair Period : 08 daysPre-accident Market Value (for total loss consideration) : \$ 74000/-COE / PARF to owner : \$ 62013.00Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐ OD Claim  
Excess : \$ \_\_\_\_\_  
(Authorised / Revert)

☒ TP Claim  
(Without Prejudice)

Vehicle No. SAV 8828 C

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 08 days.

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 05-07-19

Victor - Seng @ sg.msig-asia.com

## Shiau Chan (LKKAuto)

---

**From:** Raymond @ VAuG <raymondteo@vinsautogroup.com.sg>  
**Sent:** Thursday, 26 September 2019 3:56 PM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** Re: FINALISE TP VEHICLE SGV 8828C (09/06/2019)

Hi Shiau Chan,

We accept the offer.

Please proceed

Thanks!  
Best Regards  
Raymond Teo

On Thu, Sep 26, 2019 at 3:45 PM Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)> wrote:

Dear Raymond,

WITHOUT PREJUDICE

As per our conversation, kindly confirm the repair cost at Lump Sum \$10,800.00 before GST and 8 repair days.

Please note that the finalisation subject to insurer's approval.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


**MSIG**

**MSIG Insurance (Singapore) Pte. Ltd.** (Co. Reg. No. 200412212G)  
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581  
 Tel 6220 9644, Fax 6225 6371  
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.  
 4 Shenton Way  
 #21-01 SGX Centre 2  
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.  
 16 Raffles Quay  
 #24-01 Hong Leong Building  
 Singapore 048581

Attn: Fievel Foo Wenyao

Date: 09 Jul 2019

### Preliminary Advice

|                    |                                                                                                       |                         |              |
|--------------------|-------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SJZ1789X                                                                                            | Accident Date           | : 09/06/2019 |
| TP Vehicle No      | : SGV8828C                                                                                            | Assignment Date         | : 09/07/2019 |
| Make               | : TOYOTA ALPHARD                                                                                      | Est. Duration of Repair | : 8.00       |
| Date of Inspection | : 05/07/2019                                                                                          |                         |              |
| Inspection At      | : VIN'S MOTOR PTE LTD (SIN MING)<br>160 SIN MING DRIVE, #03-03, SIN MING AUTOCITY<br>SINGAPORE 575722 |                         |              |

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front portion.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 15,381.17 |
| Revised Amount              | :S\$ | 7,256.97  |
| Check Items (Estimated)     | :S\$ | 6,495.20  |
| Total                       | :S\$ |           |

|                 |      |           |
|-----------------|------|-----------|
| Lump Sum Repair | :S\$ | 11,000.00 |
|-----------------|------|-----------|

### **Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 24,000.00 |
| COE / PARF Rebate  | :S\$ | 62,013.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ |           |

### Remarks

- ( x ) The vehicle is economical/~~not economical~~ for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

8693C

### Vehicle Details

Vehicle No.:

5GV8828C

Vehicle to be Exported:

No

Intended Deregistration Date:

14 Jun 2019

Vehicle Make:

TOYOTA

Vehicle Model:

ALPHARD MOONROOF CVT

Primary Colour:

White

Manufacturing Year:

2012

Engine No.:

2AZH948321

Chassis No.:

JTEGD21H208255040

Maximum Power Output:

125.0 kW (167 bhp)

Open Market Value:

\$47,807.00

Original Registration Date:

12 Dec 2012

First Registration Date:

12 Dec 2012

Transfer Count:

0

Actual ARF Paid:

\$47,807.00

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

11 Dec 2022

PARF Rebate Amount:

\$31,074.00

### Intended COE Rebate Details

COE Expiry Date:

11 Dec 2022

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

QP Paid:

\$90,200.00

COE Rebate Amount:

\$31,485.00

**Total Rebate Amount:**

**\$62,559.00**

The information contained herein is correct as at 14 Jun 2019

OK

14313

3-6

50,097.1

23,903

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**



**Claim Reference:**  
**Assessment number: TP/072019/3931**  
**Version: 1810**  
**Date calculated: 03/07/2019 2:24 PM**

**Full Report**  
**Registration: SGV8828C**  
**Printed: 03/07/2019 2:25 PM**

### Summary Information

#### Claim

|                        |                 |                   |                                       |
|------------------------|-----------------|-------------------|---------------------------------------|
| Location:              | Singapore (SG)  | Work Provider:    | MSIG Insurance<br>(Singapore) Pte Ltd |
| Printed by:            | Khong Keng Leng | Currency:         | SGD                                   |
| Claim Reference:       |                 | Date of Incident: | 09/06/19                              |
| Estimated Repair Time: |                 | Hire Car Start:   |                                       |
| Actual Repair Days:    |                 | Hire Car End:     |                                       |

### Vehicle Details

#### Vehicle

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | TOYOTA            |
| Model:              | ALPHARD           |
| Sub Model:          | BASE MODEL        |
| Model Sheet Number: | 70 AD 01          |
| Registration:       | SGV8828C          |
| VIN number:         | JTEGD21H208255040 |
| Odometer:           |                   |

#### Model Specs

|                   |                      |                      |                   |
|-------------------|----------------------|----------------------|-------------------|
| AIR CONDITIONING  | 2.4 LTR 117KW        | WHEELS 7J X 17 ALLOY | STABILITY PROGRAM |
| FRONT DRIVE       | L/ELECT SLIDING DOOR | R/ELEC SLIDING DOOR  | JAPAN VERSION     |
| TWO COAT METALLIC | PREPARE OFF VEHICLE  |                      |                   |

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

**Vin's**

Claim Reference:  
 Assessment number: TP/072019/3931  
 Version: 1810  
 Date calculated: 03/07/2019 2:24 PM

Full Report  
 Registration: SGV8828C  
 Printed: 03/07/2019 2:25 PM


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
 Date of Inspection:

### Damage Areas

All ☐  
 Underbody ☐



## Labour

| Code      | Description                                                                                                    | Time Base 10 WU/h | Price = 50.00 SGD/h |           |
|-----------|----------------------------------------------------------------------------------------------------------------|-------------------|---------------------|-----------|
|           |                                                                                                                |                   | WU                  | Price SGD |
| NO NUMBER | R + R L/ENGINE COMPARTMENT COVER                                                                               |                   | 1.0                 | 5.00      |
| NO NUMBER | R + R R/ENGINE COMPARTMENT COVER                                                                               |                   | 1.0                 | 5.00      |
| NO NUMBER | RENEW RADIATOR GRILLE                                                                                          |                   | 5.0                 | 25.00     |
| NO NUMBER | RENEW FRONT BUMPER<br>(RADIATOR GRILLE REMOVED)<br>INCLUDES: FRONT BUMPER AND REQUIRED<br>ATTACHED PARTS R + R |                   | 11.0                | 55.00     |
| NO NUMBER | RENEW L/HEADLAMP<br>(BUMPER REMOVED)<br>INCLUDES: ADJUST HEADLAMPS.                                            |                   | 3.0                 | 15.00     |
| NO NUMBER | RENEW R/HEADLAMP<br>(BUMPER REMOVED)<br>INCLUDES: ADJUST HEADLAMPS.                                            |                   | 3.0                 | 15.00     |
| NO NUMBER | R + R FRONT BUMPER REINFORCEMENT<br>(BUMPER REMOVED)<br>INCLUDES: ABSORBER REMOVE AND REFIT                    |                   | 2.0                 | 10.00     |

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

*Vin's*

Claim Reference:  
 Assessment number: TP/072019/3931  
 Version: 1810  
 Date calculated: 03/07/2019 2:24 PM

Full Report  
 Registration: SGV8828C  
 Printed: 03/07/2019 2:25 PM

| Code      | Description                                                                                                                       | WU   | Price SGD |
|-----------|-----------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| NO NUMBER | RENEW BONNET<br>INCLUDES: R + R BONNET,<br>ATTACH PARTS ASSEMBLE AND IF NEC RENEW                                                 | 5.0  | 25.00     |
| NO NUMBER | RENEW L/FRT WING<br>INCLUDES: WHEELHOUSE LINER AND REQUIRED<br>ATTACHED PARTS R + R<br>NOT INCLUDED: HEADLAMP AND<br>R + R BUMPER | 7.0  | 35.00     |
| NO NUMBER | RENEW R/FRT WING<br>INCLUDES: WHEELHOUSE LINER AND REQUIRED<br>ATTACHED PARTS R + R<br>NOT INCLUDED: HEADLAMP AND<br>R + R BUMPER | 7.0  | 35.00     |
| NO NUMBER | R + R BONNET HINGE/S                                                                                                              | 1.0  | 5.00      |
| NO NUMBER | RENEW FRONT LOCK CARRIER                                                                                                          | 6.0  | 30.00     |
| NO NUMBER | R + R WIRE LINKAGE                                                                                                                | 1.0  | 5.00      |
| NO NUMBER | R + R COWL PANEL TRIM<br>INCLUDES: WIPER ARMS<br>REMOVE AND REFIT                                                                 | 2.0  | 10.00     |
| NO NUMBER | REMOVE AND REFIT WATER BOX COVER                                                                                                  | 2.0  | 10.00     |
| NO NUMBER | RENEW CONDENSER<br>(BUMPER REMOVED)<br>INCLUDES: REFILL AIR CONDITIONING                                                          | 12.0 | 60.00     |
| NO NUMBER | RENEW RADIATOR<br>INCLUDES: BLEED COOLING SYSTEM                                                                                  | 15.0 | 75.00     |
| NO NUMBER | R + R STEERING COLUMN TRIM                                                                                                        | 1.0  | 5.00      |
| NO NUMBER | R + R STEERING BOX                                                                                                                | 7.0  | 35.00     |
| NO NUMBER | R + R LEFT FRONT WHEEL                                                                                                            | 2.0  | 10.00     |
| NO NUMBER | R + R RIGHT FRONT WHEEL                                                                                                           | 2.0  | 10.00     |
| NO NUMBER | R + R R/F BRAKE DISC<br>INCLUDES: R + R BRAKE CALIPER AND BRAKE<br>PADS                                                           | 1.0  | 5.00      |
| NO NUMBER | R + R FRONT SHOCK ABSORBER ADD/WORK                                                                                               | 6.0  | 30.00     |
| NO NUMBER | R + R RIGHT FRONT SHOCK ABSORBER                                                                                                  | 2.0  | 10.00     |
| NO NUMBER | R + R FRONT STABILIZER<br>INCLUDES: FRT STABILISER CONTROL ROD AND<br>BRACKET REMOVE AND REFIT.                                   | 6.0  | 30.00     |
| NO NUMBER | R + R FRONT AXLE CARRIER                                                                                                          | 5.0  | 25.00     |
| NO NUMBER | R + R L/F CONTROL ARM REAR                                                                                                        | 1.0  | 5.00      |
| NO NUMBER | R + R R/F CONTROL ARM REAR                                                                                                        | 1.0  | 5.00      |
| NO NUMBER | RENEW RIGHT FRONT SHOCK ABSORBER                                                                                                  | 1.0  | 5.00      |
| NO NUMBER | R + R R/F STEERING KNUCKLE                                                                                                        | 3.0  | 15.00     |

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

*Vin's*

Claim Reference:  
 Assessment number: TP/072019/3931  
 Version: 1810  
 Date calculated: 03/07/2019 2:24 PM

Full Report  
 Registration: SGV8828C  
 Printed: 03/07/2019 2:25 PM

| Code                             | Description                           | WU         | Price SGD |
|----------------------------------|---------------------------------------|------------|-----------|
| NO NUMBER                        | R + R FRONT STEERING KNUCKLE ASS WORK | 7.0        | 35.00     |
| NO NUMBER                        | R + R RIGHT FRONT WHEEL HUB           | 1.0        | 5.00      |
| NO NUMBER                        | R + R RIGHT FRONT SUPPORT JOINT       | 1.0        | 5.00      |
| NO NUMBER                        | DETACH + REFIT L/F STEERING KNUCKLE   | 1.0        | 5.00      |
| NN                               | SupportPanelTopCover R&R / NEW PARTS  | 5 10.0*    | 50.00     |
| NN                               | Bumper Centre Grille R&R / NEW PARTS  | 5 10.0*    | 50.00     |
| NN                               | Bumper Sponge,R&R / NEW PARTS         | 5 5.0*     | 25.00     |
| NN                               | F Bumper Under Cover R&R / NEW PARTS  | 5 10.0*    | 50.00     |
| NN                               | F WS wiper garnish R&R / NEW PARTS    | 5 3.0*     | 15.00     |
| NN                               | F Bonnet Moulding R&R / NEW PARTS     | 5 10.0*    | 50.00     |
| 1015                             | Remove&Refit Engine Engine            | ? 95.0*    | 475.00    |
| <b>Labour Cost</b>               |                                       | <b>Hrs</b> | <b>WU</b> |
| <b>Panel / Mechanical Labour</b> |                                       | 27.50      | 275.0     |
| <b>Total of Labour</b>           |                                       |            | 1,375.00  |

**Paint**

| Paint Work | SYSTEM AZT                             | Time Basis 10WU/h |
|------------|----------------------------------------|-------------------|
| Code       | Description - TWO COAT METALLIC        | WU Price SGD      |
|            | BONNET NEW PART PAINTING               | 18.0              |
|            | L/F WING NEW PART PAINTING             | 12.0              |
|            | R/F WING NEW PART PAINTING             | 12.0              |
|            | FRONT SUPPORT SURFACE PAINT            | 4.0               |
|            | FRONT BUMPER NEW PART PAINT K1R        | 13.0              |
|            | L/F BUMPER PROT CVR NEW PART PAINT K1R | 3.0               |
|            | R/F BUMPER PROT CVR NEW PART PAINT K1R | 3.0               |
|            | GRILLE NEW PART PAINT K1R              | 7.0               |
|            | FRT BUMPER REINF SURFACE PAINT         | 4.0               |

**Paint Material Per Part**

| Code | Description                            | Price SGD |
|------|----------------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING               | 52.63     |
| 0741 | L/F WING NEW PART PAINTING             | 26.32     |
| 0742 | R/F WING NEW PART PAINTING             | 26.32     |
| 1018 | FRONT SUPPORT SURFACE PAINT            | 2.99      |
| 0281 | FRONT BUMPER NEW PART PAINT K1R        | 64.94     |
| 0347 | L/F BUMPER PROT CVR NEW PART PAINT K1R | 0.49      |
| 0348 | R/F BUMPER PROT CVR NEW PART PAINT K1R | 0.49      |
| 0410 | GRILLE NEW PART PAINT K1R              | 24.60     |

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

**Vin's**

Claim Reference:  
 Assessment number: TP/072019/3931  
 Version: 1810  
 Date calculated: 03/07/2019 2:24 PM

Full Report  
 Registration: SGV8828C  
 Printed: 03/07/2019 2:25 PM

**Paint Material Per Part**

| Code | Description                    | Price SGD |
|------|--------------------------------|-----------|
| 0340 | FRT BUMPER REINF SURFACE PAINT | 2.99      |

**Labour Cost - Paint**

|                                | Hrs            | WU           | Price SGD     |
|--------------------------------|----------------|--------------|---------------|
| Factor                         | 50.00 SGD/h    |              |               |
| Time Paint                     |                | 76.0         |               |
| Preparation Main Work Metal    | 2.50           | 25.0         | 125.00        |
| Preparation Comp. Work Plastic | 0.50           | 5.0          | 25.00         |
| <b>Total</b>                   | <b>10 WU/h</b> | <b>106.0</b> | <b>530.00</b> |

**Material Cost - Paint**

|                                     | Price SGD     |
|-------------------------------------|---------------|
| New Part Painting                   | 105.27        |
| New Part Painting - Plastic K1R     | 90.52         |
| Surface-/Blend Paint                | 5.98          |
| Material-constant Metal Preparation | 28.60         |
| Material-constant Plastic           | 9.00          |
| <b>Total</b>                        | <b>239.37</b> |

**Spare Parts**

| Code   | Description         | Part Number   | Supplier | prices as at 2015-06-01/01 | Price SGD |
|--------|---------------------|---------------|----------|----------------------------|-----------|
| 0281   | FRONT BUMPER        | 52119 58050A0 | Deformed |                            | 270.00    |
| 0340   | FRT BUMPER REINF    | 52131 58010   | Deformed |                            | 170.00    |
| 0347 x | L/F BUMPER PROT CVR | 52128 58020A0 | Deformed |                            | 20.00     |
| 0348   | R/F BUMPER PROT CVR | 52127 58020A0 | missing  |                            | 20.00     |
| 0397   | L/F BUMPER BRACKET  | 52116 58010   | cracked  |                            | 30.00     |
| 0398   | R/F BUMPER BRACKET  | 52145 58010   | cracked  |                            | 30.00     |
| 0410   | GRILLE              | 53111 58030A0 | cracked  |                            | 280.00    |
| 0431 x | BADGE TOYOTA        | 75301 58020   | damaged  |                            | 50.00     |
| 0471   | BONNET              | 53301 58010   | Deformed |                            | 340.00    |
| 0475   | L/F HINGE           | 53420 58010   | dented   |                            | 40.00     |
| 0476   | R/F HINGE           | 53410 58010   | dented   |                            | 40.00     |
| 0481 x | BONNET INSULATION   | 53341 58010   | x        |                            | 160.00    |
| 0482   | MOUNTING CLAMP      | 90467 08124   | necc     |                            | 24.00     |
| 0486   | R/BONNET SEAL       | 53381 58010   | necc     |                            | 40.00     |
| 0493   | BONNET LOCK         | 53510 58010   | necc     |                            | 50.00     |
| 0559 x | LEFT HEADLAMP ASSY  | 81150 58010   | cracked  |                            | 810.00    |
| 0560   | RIGHT HEADLAMP ASSY | 81110 58010   | cracked  |                            | 810.00    |
| 0741   | L/F WING            | 53812 58020   | dented   |                            | 290.00    |

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

**Vin's**

Claim Reference:  
 Assessment number: TP/072019/3931  
 Version: 1810  
 Date calculated: 03/07/2019 2:24 PM

Full Report  
 Registration: SGV8828C  
 Printed: 03/07/2019 2:25 PM

| Code              | Description            | Part Number   | Supplier     | Price SGD |
|-------------------|------------------------|---------------|--------------|-----------|
| 0742              | R/F WING               | 53811 58020   | Deformed     | 290.00    |
| 0841 x            | L/F WHEELHOUSE COVER   | 53806 58010   | ? X N N      | 110.00    |
| 0842              | R/F WHEELHOUSE COVER   | 53805 58010   | Torn         | 110.00    |
| 1018              | FRONT SUPPORT          | 53205 58020   | Deformed     | 600.00    |
| 4466 x            | CONDENSER              | 88461 58011   | ? X N N ✓ Br | 610.00    |
| 7011 x            | - FRT AXLE CARRIER     | 51100 33070   | ? X N N      | 1,300.00  |
| 7027 x            | x L/F AXLE CARRIER BRG | 52211 28020   | x            | 0.00      |
| 7028 x            | - R/F AXLE CARRIER BRG | 52211 28020   | x            | 0.00      |
| 7029 x            | x L/R CONTROL ARM BUSH | 52217 28020   | x            | 0.00      |
| 7030 x            | - R/R CONTROL ARM BUSH | 52215 28020   | x            | 0.00      |
| 7034 x            | - R/F TRACK CONT ARM   | 48068 58010   | } ? X N N    | 140.00    |
| 7078 x            | - R/F SHOCK ABSORBER   | 48510 80250   |              | 220.00    |
| 7082 x            | - R/F STEERING KNUCKLE | 43211 58010   |              | 260.00    |
| 7132 x            | - R/F DRIVING FLANGE   | 90942 02049   |              | 280.00    |
| 7300 x            | - CONTROL ROD CPL      | 44200 58012   | } ?          | 770.00    |
| 7761 x            | RADIATOR CPL           | 16041 28371   |              | 770.00    |
| 1000              | SupportPanelTopCover   | Support Panel | crunched     | 160.00    |
| 1001              | Bumper Centre Grille   | Bumper        | crunched     | 70.00     |
| 1002              | Bumper Sponge          | Sponge        | crunched     | 40.00     |
| 1003              | F Bumper Sensor        | Bumper        | missing      | 320.00    |
| 1004              | F Bumper Under Cover   | Bumper        | missing      | 140.00    |
| 1005 x            | Air Duct               | Air Condenser | ? X N N      | 120.00    |
| 1006 x            | Inner Fiber Clips      | Inner Fiber   | ? X N N      | 48.00     |
| 1007              | F WS wiper garnish     | Windscreen    | crunched     | 260.00    |
| 1008 x            | F Bonnet Moulding      | Bonnet        | } ? X N N    | 210.00    |
| 1009 x            | F Bumper Top Beam      | Bumper        |              | 130.00    |
| f: OEM Parts      |                        |               |              | 0.00      |
| n: Non-OEM Parts  |                        |               |              | 10,432.00 |
| u: Used parts     |                        |               |              | 1,564.80  |
| Savings           |                        |               |              | 0.00      |
| Subtotal          |                        |               |              | 10,432.00 |
| Addition(+15.00%) |                        |               |              | 1,564.80  |
| Total             |                        |               |              | 11,996.80 |

**Extras**

| Code   | Description                     | Price SGD   |
|--------|---------------------------------|-------------|
| 1010   | To Reset Programme Programme    | 100 150.00* |
| 1011   | To Refill Coolant Coolant       | 80 120.00*  |
| 1012 x | Front Number Plate Number Plate | X 40.00*    |
| 1013   | Front RH Tyre Tyre              | 240 350.00* |

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

**Vin's**

Claim Reference:  
 Assessment number: TP/072019/3931  
 Version: 1810  
 Date calculated: 03/07/2019 2:24 PM

Full Report  
 Registration: SGV8828C  
 Printed: 03/07/2019 2:25 PM

| Code | Description                  | Price SGD       |
|------|------------------------------|-----------------|
| 1014 | Front RH Sport Rim Sport Rim | 580.00*         |
|      | <b>Total Extras</b>          | <b>1,240.00</b> |

*Brazed/  
Cut*

### Final Calculation

|                                       | SGD       | SGD              |
|---------------------------------------|-----------|------------------|
| <b>Parts</b>                          | 10,432.00 |                  |
| Addition(+15.00%)                     | 1,564.80  |                  |
| <b>Total Parts</b>                    |           | <b>11,996.80</b> |
| <b>Labour Time Base 10 WU/h</b>       |           |                  |
| Total 275.0 WU X 50.00 SGD/h          | 1,375.00  |                  |
| <b>Total of Labour</b>                |           | <b>1,375.00</b>  |
| <b>Total Of Extras</b>                |           | <b>1,240.00</b>  |
| <b>Paint Work Time Base 10 WU/h</b>   |           |                  |
| Labour Cost 106.0 WU X 50.00 SGD/h    | 530.00    |                  |
| Material Cost                         | 239.37    |                  |
| <b>Total Paint Including Material</b> |           | <b>769.37</b>    |
| <b>Repair Cost Excludes GST</b>       |           | <b>15,381.17</b> |
| GST (+7.0%)                           |           | <b>1,076.68</b>  |
| <b>Repair Cost Included GST</b>       |           | <b>16,457.85</b> |

### Comments

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

**Vin's**

**Claim Reference:**  
**Assessment number: TP/072019/3931**  
**Version: 1810**  
**Date calculated: 05/07/2019 1:08 PM**

**Full Report**  
**Registration: SGV8828C**  
**Printed: 05/07/2019 1:08 PM**

### Summary Information

#### Claim

|                        |                 |                   |                                       |
|------------------------|-----------------|-------------------|---------------------------------------|
| Location:              | Singapore (SG)  | Work Provider:    | MSIG Insurance<br>(Singapore) Pte Ltd |
| Printed by:            | Khong Keng Leng | Currency:         | SGD                                   |
| Claim Reference:       |                 | Date of Incident: | 09/06/19                              |
| Estimated Repair Time: |                 | Hire Car Start:   |                                       |
| Actual Repair Days:    |                 | Hire Car End:     |                                       |

### Vehicle Details

#### Vehicle

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | TOYOTA            |
| Model:              | ALPHARD           |
| Sub Model:          | BASE MODEL        |
| Model Sheet Number: | 70 AD 01          |
| Registration:       | SGV8828C          |
| VIN number:         | JTEGD21H208255040 |
| Odometer:           |                   |

#### Model Specs

|                   |                      |                      |                   |
|-------------------|----------------------|----------------------|-------------------|
| AIR CONDITIONING  | 2.4 LTR 117KW        | WHEELS 7J X 17 ALLOY | STABILITY PROGRAM |
| FRONT DRIVE       | L/ELECT SLIDING DOOR | R/ELEC SLIDING DOOR  | JAPAN VERSION     |
| TWO COAT METALLIC | PREPARE OFF VEHICLE  |                      |                   |

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

**Vin's**

Claim Reference:  
Assessment number: TP/072019/3931  
Version: 1810  
Date calculated: 05/07/2019 1:08 PM

Full Report  
Registration: SGV8828C  
Printed: 05/07/2019 1:08 PM


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Labour

| Code      | Description                                                                                                    | Time Base 10 WU/h | Price = 50.00 SGD/h |           |
|-----------|----------------------------------------------------------------------------------------------------------------|-------------------|---------------------|-----------|
|           |                                                                                                                |                   | WU                  | Price SGD |
| NO NUMBER | RENEW RADIATOR GRILLE                                                                                          |                   | 5.0                 | 25.00     |
| NO NUMBER | RENEW FRONT BUMPER<br>(RADIATOR GRILLE REMOVED)<br>INCLUDES: FRONT BUMPER AND REQUIRED<br>ATTACHED PARTS R + R |                   | 11.0                | 55.00     |
| NO NUMBER | R + R LEFT HEADLAMP<br>(BUMPER REMOVED)<br>INCLUDES: ADJUST HEADLAMPS.                                         |                   | 3.0                 | 15.00     |
| NO NUMBER | RENEW R/HEADLAMP<br>(BUMPER REMOVED)<br>INCLUDES: ADJUST HEADLAMPS.                                            |                   | 3.0                 | 15.00     |
| NO NUMBER | R + R FRONT BUMPER REINFORCEMENT<br>(BUMPER REMOVED)<br>INCLUDES: ABSORBER REMOVE AND REFIT                    |                   | 2.0                 | 10.00     |
| NO NUMBER | RENEW BONNET<br>INCLUDES: R + R BONNET,                                                                        |                   | 5.0                 | 25.00     |

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

**Vin's**

Claim Reference:  
 Assessment number: TP/072019/3931  
 Version: 1810  
 Date calculated: 05/07/2019 1:08 PM

Full Report  
 Registration: SGV8828C  
 Printed: 05/07/2019 1:08 PM

| Code                             | Description                                                                                                                                                                 | WU          | Price SGD     |
|----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|---------------|
| NO NUMBER                        | ATTACH PARTS ASSEMBLE AND IF NEC RENEW<br>RENEW L/FRT WING<br>INCLUDES: WHEELHOUSE LINER AND REQUIRED<br>ATTACHED PARTS R + R<br>NOT INCLUDED: HEADLAMP AND<br>R + R BUMPER | 7.0         | 35.00         |
| NO NUMBER                        | RENEW R/FRT WING<br>INCLUDES: WHEELHOUSE LINER AND REQUIRED<br>ATTACHED PARTS R + R<br>NOT INCLUDED: HEADLAMP AND<br>R + R BUMPER                                           | 7.0         | 35.00         |
| NO NUMBER                        | R + R BONNET HINGE/S                                                                                                                                                        | 1.0         | 5.00          |
| NO NUMBER                        | RENEW FRONT LOCK CARRIER                                                                                                                                                    | 6.0         | 30.00         |
| NO NUMBER                        | R + R COWL PANEL TRIM<br>INCLUDES: WIPER ARMS<br>REMOVE AND REFIT                                                                                                           | 2.0         | 10.00         |
| NN                               | SupportPanelTopCover R&R / NEW PARTS                                                                                                                                        | 5.0*        | 25.00         |
| NN                               | Bumper Centre Grille R&R / NEW PARTS                                                                                                                                        | 5.0*        | 25.00         |
| NN                               | Bumper Sponge R&R / NEW PARTS                                                                                                                                               | 5.0*        | 25.00         |
| NN                               | F Bumper Under Cover R&R / NEW PARTS                                                                                                                                        | 10.0*       | 50.00         |
| NN                               | F WS wiper garnish R&R / NEW PARTS                                                                                                                                          | 3.0*        | 15.00         |
| <b>Labour Cost</b>               |                                                                                                                                                                             | <b>Hrs</b>  | <b>WU</b>     |
| <b>Panel / Mechanical Labour</b> |                                                                                                                                                                             | <b>8.00</b> | <b>80.0</b>   |
| <b>Total of Labour</b>           |                                                                                                                                                                             |             | <b>400.00</b> |

## Paint

| Code       | Description - TWO COAT METALLIC        | WU                | Price SGD |
|------------|----------------------------------------|-------------------|-----------|
| Paint Work |                                        | SYSTEM AZT        |           |
|            |                                        | Time Basis 10WU/h |           |
|            | BONNET NEW PART PAINTING               | 18.0              |           |
|            | L/F WING NEW PART PAINTING             | 12.0              |           |
|            | R/F WING NEW PART PAINTING             | 12.0              |           |
|            | FRONT SUPPORT SURFACE PAINT            | 4.0               |           |
|            | FRONT BUMPER NEW PART PAINT K1R        | 13.0              |           |
|            | L/F BUMPER PROT CVR NEW PART PAINT K1R | 3.0               |           |
|            | R/F BUMPER PROT CVR NEW PART PAINT K1R | 3.0               |           |
|            | GRILLE NEW PART PAINT K1R              | 7.0               |           |
|            | FRT BUMPER REINF SURFACE PAINT         | 4.0               |           |

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

**Vin's**

Claim Reference:  
 Assessment number: TP/072019/3931  
 Version: 1810  
 Date calculated: 05/07/2019 1:08 PM

Full Report  
 Registration: SGV8828C  
 Printed: 05/07/2019 1:08 PM

#### Paint Material Per Part

| Code | Description                            | Price SGD |
|------|----------------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING               | 52.63     |
| 0741 | L/F WING NEW PART PAINTING             | 26.32     |
| 0742 | R/F WING NEW PART PAINTING             | 26.32     |
| 1018 | FRONT SUPPORT SURFACE PAINT            | 2.99      |
| 0281 | FRONT BUMPER NEW PART PAINT K1R        | 64.94     |
| 0347 | L/F BUMPER PROT CVR NEW PART PAINT K1R | 0.49      |
| 0348 | R/F BUMPER PROT CVR NEW PART PAINT K1R | 0.49      |
| 0410 | GRILLE NEW PART PAINT K1R              | 24.60     |
| 0340 | FRT BUMPER REINF SURFACE PAINT         | 2.99      |

#### Labour Cost - Paint

|                                | Hrs            | WU           | Price SGD     |
|--------------------------------|----------------|--------------|---------------|
| Factor                         | 50.00 SGD/h    |              |               |
| Time Paint                     |                | 76.0         |               |
| Preparation Main Work Metal    | 2.50           | 25.0         | 125.00        |
| Preparation Comp. Work Plastic | 0.50           | 5.0          | 25.00         |
| <b>Total</b>                   | <b>10 WU/h</b> | <b>106.0</b> | <b>530.00</b> |

#### Material Cost - Paint

|                                     | Price SGD     |
|-------------------------------------|---------------|
| New Part Painting                   | 105.27        |
| New Part Painting - Plastic K1R     | 90.52         |
| Surface-/Blend Paint                | 5.98          |
| Material-constant Metal Preparation | 28.60         |
| Material-constant Plastic           | 9.00          |
| <b>Total</b>                        | <b>239.37</b> |

#### Spare Parts

| Code | Description         | Part Number   | Supplier | prices as at 2015-06-01/01 | Price SGD |
|------|---------------------|---------------|----------|----------------------------|-----------|
| 0281 | FRONT BUMPER        | 52119 58050A0 |          |                            | 270.00    |
| 0340 | FRT BUMPER REINF    | 52131 58010   |          |                            | 170.00    |
| 0348 | R/F BUMPER PROT CVR | 52127 58020A0 |          |                            | 20.00     |
| 0397 | L/F BUMPER BRACKET  | 52116 58010   |          |                            | 30.00     |
| 0398 | R/F BUMPER BRACKET  | 52145 58010   |          |                            | 30.00     |
| 0410 | GRILLE              | 53111 58030A0 |          |                            | 280.00    |
| 0471 | BONNET              | 53301 58010   |          |                            | 340.00    |
| 0475 | L/F HINGE           | 53420 58010   |          |                            | 40.00     |
| 0476 | R/F HINGE           | 53410 58010   |          |                            | 40.00     |
| 0482 | MOUNTING CLAMP      | 90467 08124   |          |                            | 24.00     |

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

**Vin's**

Claim Reference:  
 Assessment number: TP/072019/3931  
 Version: 1810  
 Date calculated: 05/07/2019 1:08 PM

Full Report  
 Registration: SGV8828C  
 Printed: 05/07/2019 1:08 PM

| Code             | Description          | Part Number   | Supplier | Price SGD                |
|------------------|----------------------|---------------|----------|--------------------------|
| 0486             | R/BONNET SEAL        | 53381 58010   |          | 40.00                    |
| 0493             | BONNET LOCK          | 53510 58010   |          | 50.00                    |
| 0560             | RIGHT HEADLAMP ASSY  | 81110 58010   |          | 810.00                   |
| 0741             | L/F WING             | 53812 58020   |          | 290.00                   |
| 0742             | R/F WING             | 53811 58020   |          | 290.00                   |
| 0842             | R/F WHEELHOUSE COVER | 53805 58010   |          | 110.00                   |
| 1018             | FRONT SUPPORT        | 53205 58020   |          | 600.00                   |
| 1000             | SupportPanelTopCover | Support Panel |          | 160.00                   |
| 1001             | Bumper Centre Grille | Bumper        |          | 70.00                    |
| 1002             | Bumper Sponge        | Sponge        |          | 40.00                    |
| 1003             | F Bumper Sensor      | Bumper        |          | 320.00                   |
| 1004             | F Bumper Under Cover | Bumper        |          | 140.00                   |
| 1007             | F WS wiper garnish   | Windscreen    |          | 260.00                   |
| f: OEM Parts     |                      |               |          | Savings 0.00             |
| n: Non-OEM Parts |                      |               |          | Subtotal 4,424.00        |
| u: Used parts    |                      |               |          | Addition(+15.00%) 663.60 |
| <b>Total</b>     |                      |               |          | <b>5,087.60</b>          |

**Extras**

| Code                | Description                  | Price SGD       |
|---------------------|------------------------------|-----------------|
| 1010                | To Reset Programme Programme | 100.00*         |
| 1011                | To Refill Coolant Coolant    | 80.00*          |
| 1013                | Front RH Tyre Tyre           | 240.00*         |
| 1014                | Front RH Sport Rim Sport Rim | 580.00*         |
| <b>Total Extras</b> |                              | <b>1,000.00</b> |

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160**  
**Sin Ming Drive**  
**575722**

**Vin's**

Claim Reference:  
Assessment number: TP/072019/3931  
Version: 1810  
Date calculated: 05/07/2019 1:08 PM

Full Report  
Registration: SGV8828C  
Printed: 05/07/2019 1:08 PM

### Final Calculation

|                                       | SGD      | SGD             |
|---------------------------------------|----------|-----------------|
| <b>Parts</b>                          | 4,424.00 |                 |
| Addition(+15.00%)                     | 663.60   |                 |
| <b>Total Parts</b>                    |          | <b>5,087.60</b> |
| <b>Labour Time Base 10 WU/h</b>       |          |                 |
| Total 80.0 WU X 50.00 SGD/h           | 400.00   |                 |
| <b>Total of Labour</b>                |          | <b>400.00</b>   |
| <b>Total Of Extras</b>                |          | <b>1,000.00</b> |
| <b>Paint Work Time Base 10 WU/h</b>   |          |                 |
| Labour Cost 106.0 WU X 50.00 SGD/h    | 530.00   |                 |
| Material Cost                         | 239.37   |                 |
| <b>Total Paint Including Material</b> |          | <b>769.37</b>   |
| <b>Repair Cost Excludes GST</b>       |          | <b>7,256.97</b> |
| GST (+7.0%)                           |          | <b>507.99</b>   |
| <b>Repair Cost Included GST</b>       |          | <b>7,764.96</b> |

### Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS



Sin Ming Autocity,  
 160 Sin Ming Drive #03-03  
 Singapore 575722  
 6453 2121 (4 lines) / 6458 1111 (24 hrs)  
 6459 9795 / 6459 0433  
 admin@vinsautogroup.com.sg  
 www.vinsautogroup.com.sg

**TP INSURER:**  
**TEO PEI FERN**  
 130 Braddell Road S359918  
 Singapore

**MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

#### PARTICULARS OF CLAIM

|                               |                                      |                    |                   |
|-------------------------------|--------------------------------------|--------------------|-------------------|
| Claim Type:                   | THIRD PARTY                          | Ref. No:           | TP/072019/3931    |
| Policy No:                    |                                      | Date of Loss:      | 09/06/2019        |
| Vehicle Reg. No.:             | SGV8828C                             | Driveable?         |                   |
| Party At Fault:               | UNKNOWN                              |                    |                   |
| Make/Model:                   | TOYOTA ALPHARD, 2.4 MOONROOF CVT (A) | Vehicle Reg. Date: | 12/12/2012        |
| Vehicle Colour:               | WHITE                                | Chassis No:        | JTEGD21H208255040 |
| Engine No:                    | 2AZH948321                           |                    |                   |
| Odometer:                     | 0 KM                                 |                    |                   |
| Paint Type:                   |                                      |                    |                   |
| Total Loss?                   | NO                                   |                    |                   |
| Est. Duration of Repair (day) | 14                                   |                    |                   |
| Description of Accident/Loss  | REFER TO SKETCH PLAN                 |                    |                   |
| Present Location:             | VIN'S MOTOR PTE LTD (SIN MING)       |                    |                   |

#### COST OF CLAIMS

|                          | Amount           |
|--------------------------|------------------|
| Parts                    | 13,236.80        |
| Miscellaneous Items      | 0.00             |
| Labour                   | 2,144.37         |
| Paintwork Labour         | 0.00             |
| Towing                   | 0.00             |
| <b>Gross Total (S\$)</b> | <b>15,381.17</b> |
| <b>+ GST 7.00% (S\$)</b> | <b>1,076.68</b>  |
| <b>Nett Amount (S\$)</b> | <b>16,457.85</b> |

This claim is handled by: **RAYMOND TEO YUN LOONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jul 2019)

Parts: M1-MPV TOYOTA ALPHARD 2.4 MOONROOF CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Vin's Motor Pte Ltd/SGV8828C/03/07/2019 14:32

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                      | %Disc | %Depr | Amount      |
|-----|-----|----------|----------------------------------|-------|-------|-------------|
| 1   | 1   | NA       | *Air Duct                        | 0.00  | 0.00  | *120.00 F   |
| 2   | 1   | NA       | *BADGE TOYOTA                    | 0.00  | 0.00  | *50.00 F    |
| 3   | 1   | NA       | *BONNET                          | 0.00  | 0.00  | *340.00 F   |
| 4   | 1   | NA       | *BONNET INSULATION               | 0.00  | 0.00  | *160.00 F   |
| 5   | 1   | NA       | *BONNET LOCK                     | 0.00  | 0.00  | *50.00 F    |
| 6   | 1   | NA       | *Bumper Centre Grille            | 0.00  | 0.00  | *70.00 F    |
| 7   | 1   | NA       | *Bumper Sponge                   | 0.00  | 0.00  | *40.00 F    |
| 8   | 1   | NA       | *CONDENSER                       | 0.00  | 0.00  | *610.00 F   |
| 9   | 1   | NA       | *CONTROL ROD CPL                 | 0.00  | 0.00  | *770.00 F   |
| 10  | 1   | NA       | *F Bonnet Moulding               | 0.00  | 0.00  | *210.00 F   |
| 11  | 1   | NA       | *F Bumper Sensor                 | 0.00  | 0.00  | *320.00 F   |
| 12  | 1   | NA       | *F Bumper Top Beam               | 0.00  | 0.00  | *130.00 F   |
| 13  | 1   | NA       | *F Bumper Under Cover            | 0.00  | 0.00  | *140.00 F   |
| 14  | 1   | NA       | *FRONT BUMPER                    | 0.00  | 0.00  | *270.00 F   |
| 15  | 1   | NA       | *FRONT SUPPORT                   | 0.00  | 0.00  | *600.00 F   |
| 16  | 1   | NA       | *FRT AXLE CARRIER                | 0.00  | 0.00  | *1,300.00 F |
| 17  | 1   | NA       | *FRT BUMPER REINF                | 0.00  | 0.00  | *170.00 F   |
| 18  | 1   | NA       | *F WS wiper garnish              | 0.00  | 0.00  | *280.00 F   |
| 19  | 1   | NA       | *GRILLE                          | 0.00  | 0.00  | *280.00 F   |
| 20  | 1   | NA       | *Inner Fiber Clips               | 0.00  | 0.00  | *48.00 F    |
| 21  | 1   | NA       | *L/F AXLE CARRIER BRG            | 0.00  | 0.00  | *F          |
| 22  | 1   | NA       | *L/F BUMPER BRACKET              | 0.00  | 0.00  | *30.00 F    |
| 23  | 1   | NA       | *L/F BUMPER PROT CVR             | 0.00  | 0.00  | *20.00 F    |
| 24  | 1   | NA       | *L/F HINGE                       | 0.00  | 0.00  | *40.00 F    |
| 25  | 1   | NA       | *L/F WHEELHOUSE COVER            | 0.00  | 0.00  | *110.00 F   |
| 26  | 1   | NA       | *L/F WING                        | 0.00  | 0.00  | *290.00 F   |
| 27  | 1   | NA       | *L/R CONTROL ARM BUSH            | 0.00  | 0.00  | *F          |
| 28  | 1   | NA       | *LEFT HEADLAMP ASSY              | 0.00  | 0.00  | *810.00 F   |
| 29  | 1   | NA       | *MOUNTING CLAMP                  | 0.00  | 0.00  | *24.00 F    |
| 30  | 1   | NA       | *R/BONNET SEAL                   | 0.00  | 0.00  | *40.00 F    |
| 31  | 1   | NA       | *R/F AXLE CARRIER BRG            | 0.00  | 0.00  | *F          |
| 32  | 1   | NA       | *R/F BUMPER BRACKET              | 0.00  | 0.00  | *30.00 F    |
| 33  | 1   | NA       | *R/F BUMPER PROT CVR             | 0.00  | 0.00  | *20.00 F    |
| 34  | 1   | NA       | *R/F DRIVING FLANGE              | 0.00  | 0.00  | *280.00 F   |
| 35  | 1   | NA       | *R/F HINGE                       | 0.00  | 0.00  | *40.00 F    |
| 36  | 1   | NA       | *R/F SHOCK ABSORBER              | 0.00  | 0.00  | *220.00 F   |
| 37  | 1   | NA       | *R/F STEERING KNUCKLE            | 0.00  | 0.00  | *260.00 F   |
| 38  | 1   | NA       | *R/F TRACK CONT ARM              | 0.00  | 0.00  | *140.00 F   |
| 39  | 1   | NA       | *R/F WHEELHOUSE COVER            | 0.00  | 0.00  | *110.00 F   |
| 40  | 1   | NA       | *R/F WING                        | 0.00  | 0.00  | *290.00 F   |
| 41  | 1   | NA       | *R/R CONTROL ARM BUSH            | 0.00  | 0.00  | *F          |
| 42  | 1   | NA       | *RADIATOR CPL                    | 0.00  | 0.00  | *770.00 F   |
| 43  | 1   | NA       | *RIGHT HEADLAMP ASSY             | 0.00  | 0.00  | *810.00 F   |
| 44  | 1   | NA       | *SupportPanelTopCover            | 0.00  | 0.00  | *160.00 F   |
| 45  | 1   | NA       | *SUNDRY PARTS                    | 0.00  | 0.00  | *F          |
| 46  | 1   | NA       | *Front Number Plate Number Plate | 0     | 0.00  | *40.00 FS   |
| 47  | 1   | NA       | *Front RH Sport Rim Sport Rim    | 0     | 0.00  | *580.00 FS  |
| 48  | 1   | NA       | *Front RH Tyre Tyre              | 0     | 0.00  | *350.00 FS  |
| 49  | 1   | NA       | *To Refill Coolant Coolant       | 0     | 0.00  | *120.00 FS  |
| 50  | 1   | NA       | *To Reset Programme Programme    | 0     | 0.00  | *150.00 FS  |

F=Franchise part, S=SpcNet.

|                                     |                  |
|-------------------------------------|------------------|
| Sub Total (\$\$)                    | 11,672.00        |
| + Margin on L,N Items 15.00% (\$\$) | 1,564.80         |
| <b>Total Parts (\$\$)</b>           | <b>13,236.80</b> |

Vin's Motor Pte Ltd/SGV8828C/03/07/2019 14:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                       | Particulars                   | Lab.Type | Amount            |
|--------------------------|-------------------------------|----------|-------------------|
| <u>Labour Items</u>      |                               |          |                   |
| 1                        | Total Paint Labour            | New      | 515 530.00        |
| 2                        | Total Paint Materials         | New      | 239.37 239.37     |
| 3                        | Total Panel/Mechanical Labour | New      | 1,375.00 1,375.00 |
| Gross Labour Cost (\$\$) |                               |          | 2,144.37          |

Vin's Motor Pte Ltd/SGV8828C/03/07/2019 14:32. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park, 51**  
**Ubi Avenue 1**  
**408933**

**Insurer Reference:**  
**Repairer Reference: TP/072019/3931**  
**Date calculated: 26/09/2019 3:01 PM**

**Full Report**  
**Registration: SGV8828C**  
**Printed: 26/09/2019 3:01 PM**

### Summary Information

#### Claim

|                        |                |                   |                                       |
|------------------------|----------------|-------------------|---------------------------------------|
| Location:              | Singapore (SG) | Work Provider:    | MSIG Insurance<br>(Singapore) Pte Ltd |
| Printed by:            | KK LAU         | Currency:         | SGD                                   |
| Claim Reference:       |                | Date of Incident: | 09/06/19                              |
| Estimated Repair Time: |                | Hire Car Start:   |                                       |
| Actual Repair Days:    |                | Hire Car End:     |                                       |

### Vehicle Details

#### Vehicle

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | TOYOTA            |
| Model:              | ALPHARD           |
| Sub Model:          | BASE MODEL        |
| Model Sheet Number: | 70 AD 01          |
| Registration:       | SGV8828C          |
| VIN number:         | JTEGD21H208255040 |
| Odometer:           |                   |

#### Model Specs

|                   |                      |                      |                   |
|-------------------|----------------------|----------------------|-------------------|
| AIR CONDITIONING  | 2.4 LTR 117KW        | WHEELS 7J X 17 ALLOY | STABILITY PROGRAM |
| FRONT DRIVE       | L/ELECT SLIDING DOOR | R/ELEC SLIDING DOOR  | JAPAN VERSION     |
| TWO COAT METALLIC | PREPARE OFF VEHICLE  |                      |                   |


### Vehicle Condition

#### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

#### Damage Areas

All ☐  
Underbody ☐



## Labour

| Code      | Description                                                                                                                       | Time Base 10 WU/h | Price = 50.00 SGD/h |           |
|-----------|-----------------------------------------------------------------------------------------------------------------------------------|-------------------|---------------------|-----------|
|           |                                                                                                                                   |                   | WU                  | Price SGD |
| NO NUMBER | R + R L/ENGINE COMPARTMENT COVER                                                                                                  | 1.0               | 1.0                 | 5.00      |
| NO NUMBER | R + R R/ENGINE COMPARTMENT COVER                                                                                                  | 1.0               | 1.0                 | 5.00      |
| NO NUMBER | RENEW RADIATOR GRILLE                                                                                                             | 5.0               | 5.0                 | 25.00     |
| NO NUMBER | RENEW FRONT BUMPER<br>(RADIATOR GRILLE REMOVED)<br>INCLUDES: FRONT BUMPER AND REQUIRED<br>ATTACHED PARTS R + R                    | 11.0              | 11.0                | 55.00     |
| NO NUMBER | RENEW L/HEADLAMP<br>(BUMPER REMOVED)<br>INCLUDES: ADJUST HEADLAMPS.                                                               | 3.0               | 3.0                 | 15.00     |
| NO NUMBER | RENEW R/HEADLAMP<br>(BUMPER REMOVED)<br>INCLUDES: ADJUST HEADLAMPS.                                                               | 3.0               | 3.0                 | 15.00     |
| NO NUMBER | R + R FRONT BUMPER REINFORCEMENT<br>(BUMPER REMOVED)<br>INCLUDES: ABSORBER REMOVE AND REFIT                                       | 2.0               | 2.0                 | 10.00     |
| NO NUMBER | RENEW BONNET<br>INCLUDES: R + R BONNET,<br>ATTACH PARTS ASSEMBLE AND IF NEC RENEW                                                 | 5.0               | 5.0                 | 25.00     |
| NO NUMBER | RENEW L/FRT WING<br>INCLUDES: WHEELHOUSE LINER AND REQUIRED<br>ATTACHED PARTS R + R<br>NOT INCLUDED: HEADLAMP AND<br>R + R BUMPER | 7.0               | 7.0                 | 35.00     |
| NO NUMBER | RENEW R/FRT WING<br>INCLUDES: WHEELHOUSE LINER AND REQUIRED<br>ATTACHED PARTS R + R<br>NOT INCLUDED: HEADLAMP AND<br>R + R BUMPER | 7.0               | 7.0                 | 35.00     |
| NO NUMBER | R + R BONNET HINGE/S                                                                                                              | 1.0               | 1.0                 | 5.00      |
| NO NUMBER | RENEW FRONT LOCK CARRIER                                                                                                          | 6.0               | 6.0                 | 30.00     |
| NO NUMBER | R + R WIRE LINKAGE                                                                                                                | 1.0               | 1.0                 | 5.00      |
| NO NUMBER | R + R COWL PANEL TRIM<br>INCLUDES: WIPER ARMS<br>REMOVE AND REFIT                                                                 | 2.0               | 2.0                 | 10.00     |
| NO NUMBER | REMOVE AND REFIT WATER BOX COVER                                                                                                  | 2.0               | 2.0                 | 10.00     |
| NO NUMBER | RENEW CONDENSER<br>(BUMPER REMOVED)<br>INCLUDES: REFILL AIR CONDITIONING                                                          | 12.0              | 12.0                | 60.00     |
| NO NUMBER | RENEW RADIATOR<br>INCLUDES: BLEED COOLING SYSTEM                                                                                  | 15.0              | 15.0                | 75.00     |
| NO NUMBER | R + R STEERING COLUMN TRIM                                                                                                        | 1.0               | 1.0                 | 5.00      |
| NO NUMBER | R + R STEERING BOX                                                                                                                | 7.0               | 7.0                 | 35.00     |
| NO NUMBER | R + R LEFT FRONT WHEEL                                                                                                            | 2.0               | 2.0                 | 10.00     |
| NO NUMBER | R + R RIGHT FRONT WHEEL                                                                                                           | 2.0               | 2.0                 | 10.00     |
| NO NUMBER | R + R R/F BRAKE DISC<br>INCLUDES: R + R BRAKE CALIPER AND BRAKE<br>PADS                                                           | 1.0               | 1.0                 | 5.00      |
| NO NUMBER | R + R FRONT SHOCK ABSORBER ADD/WORK                                                                                               | 6.0               | 6.0                 | 30.00     |
| NO NUMBER | R + R RIGHT FRONT SHOCK ABSORBER                                                                                                  | 2.0               | 2.0                 | 10.00     |
| NO NUMBER | R + R FRONT STABILIZER<br>INCLUDES: FRT STABILISER CONTROL ROD AND                                                                | 6.0               | 6.0                 | 30.00     |

| Code                             | Description                           | WU           | Price SGD     |
|----------------------------------|---------------------------------------|--------------|---------------|
|                                  | BRACKET REMOVE AND REFIT.             |              |               |
| NO NUMBER                        | R + R FRONT AXLE CARRIER              | 5.0          | 25.00         |
| NO NUMBER                        | R + R L/F CONTROL ARM REAR            | 1.0          | 5.00          |
| NO NUMBER                        | R + R R/F CONTROL ARM REAR            | 1.0          | 5.00          |
| NO NUMBER                        | RENEW RIGHT FRONT SHOCK ABSORBER      | 1.0          | 5.00          |
| NO NUMBER                        | R + R R/F STEERING KNUCKLE            | 3.0          | 15.00         |
| NO NUMBER                        | R + R FRONT STEERING KNUCKLE ASS WORK | 7.0          | 35.00         |
| NO NUMBER                        | R + R RIGHT FRONT WHEEL HUB           | 1.0          | 5.00          |
| NO NUMBER                        | R + R RIGHT FRONT SUPPORT JOINT       | 1.0          | 5.00          |
| NO NUMBER                        | DETACH + REFIT L/F STEERING KNUCKLE   | 1.0          | 5.00          |
| NN                               | SupportPanelTopCover R&R / NEW PARTS  | 5.0*         | 25.00         |
| NN                               | Bumper Centre Grille R&R / NEW PARTS  | 5.0*         | 25.00         |
| NN                               | Bumper Sponge R&R / NEW PARTS         | 5.0*         | 25.00         |
| NN                               | F Bumper Under Cover R&R / NEW PARTS  | 5.0*         | 25.00         |
| NN                               | F WS wiper garnish R&R / NEW PARTS    | 3.0*         | 15.00         |
| <b>Labour Cost</b>               |                                       | <b>Hrs</b>   | <b>WU</b>     |
| <b>Panel / Mechanical Labour</b> |                                       | <b>15.50</b> | <b>155.0</b>  |
| <b>Total of Labour</b>           |                                       |              | <b>775.00</b> |

## Paint

| Paint Work | SYSTEM AZT                             | Time Basis 10 WU/h |
|------------|----------------------------------------|--------------------|
| Code       | Description - TWO COAT METALLIC        | WU Price SGD       |
|            | BONNET NEW PART PAINTING               | 18.0               |
|            | L/F WING NEW PART PAINTING             | 12.0               |
|            | R/F WING NEW PART PAINTING             | 12.0               |
|            | FRONT SUPPORT SURFACE PAINT            | 4.0                |
|            | FRONT BUMPER NEW PART PAINT K1R        | 13.0               |
|            | R/F BUMPER PROT CVR NEW PART PAINT K1R | 3.0                |
|            | GRILLE NEW PART PAINT K1R              | 7.0                |
|            | FRT BUMPER REINF SURFACE PAINT         | 4.0                |

## Paint Material Per Part

| Code | Description                            | Price SGD |
|------|----------------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING               | 52.63     |
| 0741 | L/F WING NEW PART PAINTING             | 26.32     |
| 0742 | R/F WING NEW PART PAINTING             | 26.32     |
| 1018 | FRONT SUPPORT SURFACE PAINT            | 2.99      |
| 0281 | FRONT BUMPER NEW PART PAINT K1R        | 64.94     |
| 0348 | R/F BUMPER PROT CVR NEW PART PAINT K1R | 0.49      |
| 0410 | GRILLE NEW PART PAINT K1R              | 24.60     |
| 0340 | FRT BUMPER REINF SURFACE PAINT         | 2.99      |

## Labour Cost - Paint

|                                | Hrs            | WU           | Price SGD     |
|--------------------------------|----------------|--------------|---------------|
| Factor                         | 50.00 SGD/h    |              |               |
| Time Paint                     |                | 73.0         |               |
| Preparation Main Work Metal    | 2.50           | 25.0         | 125.00        |
| Preparation Comp. Work Plastic | 0.50           | 5.0          | 25.00         |
| <b>Total</b>                   | <b>10 WU/h</b> | <b>103.0</b> | <b>515.00</b> |

|                                     |                  |
|-------------------------------------|------------------|
| <b>Material Cost - Paint</b>        | <b>Price SGD</b> |
| New Part Painting                   | 105.27           |
| New Part Painting - Plastic K1R     | 90.03            |
| Surface-/Blend Paint                | 5.98             |
| Material-constant Metal Preparation | 28.60            |
| Material-constant Plastic           | 9.00             |
| <b>Total</b>                        | <b>238.88</b>    |

## Spare Parts

|                  |                          |               |          | prices as at 2015-06-01/01 |
|------------------|--------------------------|---------------|----------|----------------------------|
| Code             | Description              | Part Number   | Supplier | Price SGD                  |
| 0281             | FRONT BUMPER             | 52119 58050A0 |          | 270.00                     |
| 0340             | FRT BUMPER REINF         | 52131 58010   |          | 170.00                     |
| 0347             | L/F BUMPER PROT CVR      | 52128 58020A0 |          | 20.00                      |
| 0348             | R/F BUMPER PROT CVR      | 52127 58020A0 |          | 20.00                      |
| 0397             | L/F BUMPER BRACKET       | 52116 58010   |          | 30.00                      |
| 0398             | R/F BUMPER BRACKET       | 52145 58010   |          | 30.00                      |
| 0410             | GRILLE                   | 53111 58030A0 |          | 280.00                     |
| 0471             | BONNET                   | 53301 58010   |          | 340.00                     |
| 0475             | L/F HINGE                | 53420 58010   |          | 40.00                      |
| 0476             | R/F HINGE                | 53410 58010   |          | 40.00                      |
| 0482             | MOUNTING CLAMP           | 90467 08124   |          | 24.00                      |
| 0486             | R/BONNET SEAL            | 53381 58010   |          | 40.00                      |
| 0493             | BONNET LOCK              | 53510 58010   |          | 50.00                      |
| 0559             | LEFT HEADLAMP ASSY       | 81150 58010   |          | 810.00                     |
| 0560             | RIGHT HEADLAMP ASSY      | 81110 58010   |          | 810.00                     |
| 0741             | L/F WING                 | 53812 58020   |          | 290.00                     |
| 0742             | R/F WING                 | 53811 58020   |          | 290.00                     |
| 0842             | R/F WHEELHOUSE COVER     | 53805 58010   |          | 110.00                     |
| 1018             | FRONT SUPPORT            | 53205 58020   |          | 600.00                     |
| 4466             | CONDENSER                | 88461 58011   |          | 610.00                     |
| 7011             | FRT AXLE CARRIER         | 51100 33070   |          | 1,300.00                   |
| 7027             | L/F AXLE CARRIER BRG     | 52211 28020   |          | 0.00                       |
| 7028             | R/F AXLE CARRIER BRG     | 52211 28020   |          | 0.00                       |
| 7029             | L/R CONTROL ARM BUSH     | 52217 28020   |          | 0.00                       |
| 7030             | R/R CONTROL ARM BUSH     | 52215 28020   |          | 0.00                       |
| 7034             | R/F TRACK CONT ARM       | 48068 58010   |          | 140.00                     |
| 7078             | R/F SHOCK ABSORBER       | 48510 80250   |          | 220.00                     |
| 7082             | R/F STEERING KNUCKLE     | 43211 58010   |          | 260.00                     |
| 7132             | R/F DRIVING FLANGE       | 90942 02049   |          | 280.00                     |
| 7300             | CONTROL ROD CPL          | 44200 58012   |          | 770.00                     |
| 7761             | RADIATOR CPL             | 16041 28371   |          | 770.00                     |
| 1000             | SupportPanelTopCover     | Support Panel |          | 160.00                     |
| 1001             | Bumper Centre Grille     | Bumper        |          | 70.00                      |
| 1002             | Bumper Sponge            | Sponge        |          | 40.00                      |
| 1003             | F Bumper Sensor          | Bumper        |          | 320.00                     |
| 1004             | F Bumper Under Cover     | Bumper        |          | 140.00                     |
| 1007             | F WS wiper garnish       | Windscreen    |          | 260.00                     |
| f: OEM Parts     | <b>Savings</b>           |               |          | <b>0.00</b>                |
| n: Non-OEM Parts | <b>Subtotal</b>          |               |          | <b>9,604.00</b>            |
| u: Used parts    | <b>Addition(+15.00%)</b> |               |          | <b>1,440.60</b>            |

|              |                  |
|--------------|------------------|
| <b>Total</b> | <b>11,044.60</b> |
|--------------|------------------|

## Extras

| Code                | Description                  | Price SGD       |
|---------------------|------------------------------|-----------------|
| 1010                | To Reset Programme Programme | 100.00*         |
| 1011                | To Refill Coolant Coolant    | 80.00*          |
| 1013                | Front RH Tyre Tyre           | 240.00*         |
| 1014                | Front RH Sport Rim Sport Rim | 580.00*         |
| <b>Total Extras</b> |                              | <b>1,000.00</b> |

## Final Calculation

|                                       | SGD      | SGD              |
|---------------------------------------|----------|------------------|
| <b>Parts</b>                          | 9,604.00 |                  |
| Addition(+15.00%)                     | 1,440.60 |                  |
| <b>Total Parts</b>                    |          | <b>11,044.60</b> |
| <b>Labour Time Base 10 WU/h</b>       |          |                  |
| Total 155.0 WU X 50.00 SGD/h          | 775.00   |                  |
| <b>Total of Labour</b>                |          | <b>775.00</b>    |
| <b>Total Of Extras</b>                |          | <b>1,000.00</b>  |
| <b>Paint Work Time Base 10 WU/h</b>   |          |                  |
| Labour Cost 103.0 WU X 50.00 SGD/h    | 515.00   |                  |
| Material Cost                         | 238.88   |                  |
| <b>Total Paint Including Material</b> |          | <b>753.88</b>    |
| <b>Repair Cost Excludes GST</b>       |          | <b>13,573.48</b> |
| GST (+7.0%)                           |          | 950.14           |
| <b>Repair Cost Included GST</b>       |          | <b>14,523.62</b> |

## Comments

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

## Assessment Note

No assessment notes entered.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

## CLAIM SUBFOLDER TRACKING

| Case | Notified                                             | Est Submitted                               | Adj Assigned                                         | Adj Rpt                                               | Adj Submitted                                   | Ins Auth'd | Status                                                          |
|------|------------------------------------------------------|---------------------------------------------|------------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|------------|-----------------------------------------------------------------|
| Main | 03 Jul 2019<br>14:33<br><a href="#">Sendback Est</a> | 03 Jul 2019<br>14:32<br><b>S\$15,381.17</b> | 13 Aug 2019<br>18:11<br><a href="#">Edit Adj Rpt</a> | <b>S\$10,800.00</b><br><a href="#">Edit Estimates</a> | <b>S\$10,800.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                       | Reference                                                                                                                    | Claim Details          | Documents                                                                    | Show All |         |             |              |            |       |
|--------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>                                                                                                             |                                                                                                                              |                        |                                                                              |          |         |             |              |            |       |
| Insured:                                                                                                                                   | LEO CHEE BOO (JENSEN), ID: S7700729F                                                                                         |                        |                                                                              |          |         |             |              |            |       |
| Main Claimant:                                                                                                                             | TEO PEI FERN, ID: S1768693C                                                                                                  |                        |                                                                              |          |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                                          | SGV8828C                                                                                                                     | Date of Loss:          | 09/06/2019 11:00 - :59<br>[77 Months and 28 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:                                                                                                                                | TP / 596241                                                                                                                  | Policy/Cover Note No.: | 80469775QMX (Comprehensive)<br>Coverage: 01/05/2019 - 30/04/2020             |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                                | SJZ1789X                                                                                                                     | Policy No. (Claimant): |                                                                              |          |         |             |              |            |       |
|                                                                                                                                            |                                                                                                                              | Excess:                |                                                                              |          |         |             |              |            |       |
| Repairer:                                                                                                                                  | Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121                |                        |                                                                              |          |         |             |              |            |       |
| Handling Insurer:                                                                                                                          | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]                |                        |                                                                              |          |         |             |              |            |       |
| Adjuster:                                                                                                                                  | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Imm.Advice due 14/08/2019]               |                        |                                                                              |          |         |             |              |            |       |
| Driver/Custodian (Insured):                                                                                                                | LEO CHEE BOO (JENSEN) (), NRIC: S7700729F Email:                                                                             |                        |                                                                              |          |         |             |              |            |       |
| Adj Asg. Remarks:                                                                                                                          | As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. (manual assigned) Contact: 6453 2121 / 6458 1111 |                        |                                                                              |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>                                                 |                                                                                                                              |                        |                                                                              |          |         |             |              |            |       |
| There are no mail for this case.                                                                                                           |                                                                                                                              |                        |                                                                              |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> |                                                                                                                              |                        |                                                                              |          |         |             |              |            |       |
| Due Date                                                                                                                                   | Priority                                                                                                                     | Type                   | Task Group                                                                   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                |                                                                                                                              |                        |                                                                              |          |         |             |              |            |       |

## Claim Documents

SGV8828C (596241)  
[SJZ1789X]  
TP  
TEO PEI FERN  
Jun 9 2019 11:00AM  
[LEO CHEE BOO (JENSEN)]  
Vin's Motor Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

| Assessment Reports |                |                                                          |                    | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|----------------------------------------------------------|--------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   |                                                          |                    | Thumbnail                                                                                      | Print                               |
| 1                  | 03/07/19 14:32 | Vin's Motor Pte Ltd (Sin Ming)                           | Repairer Estimates |  Load HTM   |                                     |
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) |                    | Thumbnail                                                                                      | Print                               |
| 1                  | 09/07/19 18:05 | Adjuster Immediate Advice                                |                    |  Load HTM   |                                     |
| Photos/Images      |                |                                                          |                    | 3 per page                                                                                     | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) |                    | Thumbnail                                                                                      | Print                               |
| 1                  | 19/07/19 18:14 | SURVEY PHOTO                                             |                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 2                  | 19/07/19 18:14 | SURVEY PHOTO                                             |                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 3                  | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 4                  | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 5                  | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG  | <input checked="" type="checkbox"/> |
| 6                  | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 7                  | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 8                  | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 9                  | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 10                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 11                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 12                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 13                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 14                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 15                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 16                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 17                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 18                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 19                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 20                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 21                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 22                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 23                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 24                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 25                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 26                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 27                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 28                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 29                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 30                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 31                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 32                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 33                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 34                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 35                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 36                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 37                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |
| 38                 | 19/07/19 18:15 | SURVEY PHOTO                                             |                    |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|--------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | Vin's Motor Pte Ltd (Sin Ming) | Thumbnail                                                                                      | Print                               |
| 39                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 54                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 55                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 56                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 57                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 58                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 59                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 60                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 61                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 62                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 63                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG  | <input checked="" type="checkbox"/> |
| 64                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 65                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 66                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 67                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 68                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 69                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 70                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 71                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 72                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 73                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 74                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 75                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 76                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 77                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 78                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 79                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 80                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 81                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 82                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 83                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 84                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 85                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 86                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 87                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 88                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 89                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 90                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 91                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 92                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 93                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 94                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|--------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | Vin's Motor Pte Ltd (Sin Ming) | Thumbnail                                                                                      | Print                               |
| 95                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 96                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 97                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 98                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 99                 | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 100                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 101                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 102                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 103                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 104                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 105                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 106                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 107                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 108                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 109                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 110                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 111                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 112                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 113                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 114                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 115                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 116                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 117                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 118                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 119                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG  | <input checked="" type="checkbox"/> |
| 120                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 121                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 122                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 123                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 124                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 125                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 126                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 127                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 128                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 129                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 130                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 131                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 132                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 133                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 134                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 135                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 136                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 137                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 138                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 139                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 140                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 141                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 142                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 143                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 144                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 145                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 146                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 147                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 148                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 149                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |
| 150                | 19/07/19 18:15 | SURVEY PHOTO                   |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--------------------------------|------------|-------------------------------------|
| No                 | Finalized On   | Vin's Motor Pte Ltd (Sin Ming) | Thumbnail  | Print                               |
| 151                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 152                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 153                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 154                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 155                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 156                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 157                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 158                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 159                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 160                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 161                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 162                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 163                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 164                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 165                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 166                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 167                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 168                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 169                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 170                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 171                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 172                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 173                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 174                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 175                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 176                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 177                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 178                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 179                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 180                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 181                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 182                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 183                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 184                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 185                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 186                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 187                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 188                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 189                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 190                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 191                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 192                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 193                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 194                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 195                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 196                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 197                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 198                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 199                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 200                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 201                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 202                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 203                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 204                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 205                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |
| 206                | 19/07/19 18:15 | SURVEY PHOTO                   |            | <input checked="" type="checkbox"/> |

| Assessment Reports |                 |                                                          |                                | 1 per page                                                                          | <input checked="" type="checkbox"/>          |
|--------------------|-----------------|----------------------------------------------------------|--------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------|
| No                 | Finalized On    |                                                          |                                | Thumbnail                                                                           | Print                                        |
| 207                | 19/07/19 18:15  | Vin's Motor Pte Ltd (Sin Ming)                           | <b>SURVEY PHOTO</b>            |  | Load JPG <input checked="" type="checkbox"/> |
| 208                | 19/07/19 18:15  |                                                          | <b>SURVEY PHOTO</b>            |  | Load JPG <input checked="" type="checkbox"/> |
| 209                | 19/07/19 18:15  |                                                          | <b>SURVEY PHOTO</b>            |  | Load JPG <input checked="" type="checkbox"/> |
| 210                | 19/07/19 18:15  |                                                          | <b>SURVEY PHOTO</b>            |  | Load JPG <input checked="" type="checkbox"/> |
| 211                | 19/07/19 18:15  |                                                          | <b>SURVEY PHOTO</b>            |  | Load JPG <input checked="" type="checkbox"/> |
| Documentation      |                 |                                                          |                                | 1 per page                                                                          | <input checked="" type="checkbox"/>          |
| No                 | Finalized On    |                                                          |                                | Thumbnail                                                                           | Print                                        |
| 1                  | 05/07/19 10:46  | MSIG Insurance (Singapore) Pte. Ltd. (HQ)                | <b>F8B5997G GIA Rpt</b>        |  | Load PDF                                     |
| 2                  | 05/07/19 10:47  |                                                          | <b>XE1410H GIA Rpt</b>         |  | Load PDF                                     |
| 3                  | 05/07/19 10:49  |                                                          | <b>SGQ1003M GIA Rpt</b>        |  | Load PDF                                     |
| 4                  | 05/07/19 10:50  |                                                          | <b>SJZ1789X GIA Rpt</b>        |  | Load PDF                                     |
| No                 | Finalized On    | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) |                                | Thumbnail                                                                           | Print                                        |
| 1                  | 09/07/19 18:06  |                                                          | <b>Preliminary Loss Advise</b> |  | Load PDF                                     |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                        |                                | Thumbnail                                                                           | Print                                        |
| 1                  | 04/09/19 13:57  |                                                          | <b>TP GIA REPORT</b>           |  | Load PDF                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                                                  | Reset | Save | Print |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured.                                                                                                                                         |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>                                         |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014368/DQF3E2

Date: 14/10/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80469775QMX

Claimant

Vehicle No: SGV8828C

Insured Vehicle No: SJZ1789X

Date of Loss: 09/06/2019

Nature of Claim: TP

Claim No: 596241

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGV8828C

Make &amp; Model: TOYOTA ALPHARD, 2.4 MOONROOF CVT (A)

Engine No: 2AZH948321

Reg. Date: 12/12/2012 (Man. Year: 2012)

Chassis No: JTEGD21H208255040

Colour: White

Odometer: 0 km

Engine Capacity: 2362 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/45 R19

Rear Tyre Size:

245/45/19

Front Left Side: Pirelli 5 mm

Rear Left Side:

Pirelli 4 mm

Front Right Side: Pirelli 5 mm

Rear Right Side:

Pirelli 4 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's       | Adjuster's       | Difference      | Diff %       |
|------------------------------------------|------------------|------------------|-----------------|--------------|
| Parts                                    | 13,236.80        | 12,044.60        | 1,192.20        | 9.01         |
| Miscellaneous Items                      | 0.00             | 0.00             | 0.00            |              |
| Labour                                   | 2,144.37         | 1,528.88         | 615.49          | 28.70        |
| Paintwork Labour                         | 0.00             | 0.00             | 0.00            |              |
| Towing                                   | 0.00             | 0.00             | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>15,381.17</b> | <b>13,573.48</b> | <b>1,807.69</b> | <b>11.75</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>10,800.00</b> |                 |              |
| <b>(S\$)</b>                             | 15,381.17        | 10,800.00        | 4,581.17        | 29.78        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,076.68         | 756.00           | 320.68          | 29.78        |
| <b>Nett Amount (S\$)</b>                 | <b>16,457.85</b> | <b>11,556.00</b> | <b>4,901.85</b> | <b>29.78</b> |

### INSPECTION

Date of Assignment: 13/08/2019 Present Location:

Vin's Motor Pte Ltd (Sin Ming)

Date Inspected: 05/07/2019 Inspected At:

Vin's Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive, #03-03, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

|                      |                                                                                                                                                                              |                                                                       |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|
| <b>Reference</b>     |                                                                                                                                                                              |                                                                       |
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 14 Oct 2019)                         |
| <b>Parts:</b>        | M1-MPV                                                                                                                                                                       | TOYOTA ALPHARD 2.4 MOONROOF CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                     |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SGV8828C)                                                                                                                                    |                                                                       |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                       |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                       |

## Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition     | Repairer's | Amount      |
|-----|-----|----------|--------------------------------|---------------|------------|-------------|
| 1   | 1   | NA       | *Air Duct<br>(WCP)             | Not Necessary | 120.00 F   | *- F        |
| 2   | 1   | NA       | *BADGE TOYOTA<br>(WCP)         | Not Necessary | 50.00 F    | *- F        |
| 3   | 1   | NA       | *BONNET<br>(WCP)               | Deformed      | 340.00 F   | *340.00 F   |
| 4   | 1   | NA       | *BONNET INSULATION<br>(WCP)    | Not Necessary | 160.00 F   | *- F        |
| 5   | 1   | NA       | *BONNET LOCK<br>(WCP)          | Dented        | 50.00 F    | *50.00 F    |
| 6   | 1   | NA       | *Bumper Centre Grille<br>(WCP) | Cracked       | 70.00 F    | *70.00 F    |
| 7   | 1   | NA       | *Bumper Sponge<br>(WCP)        | Cracked       | 40.00 F    | *40.00 F    |
| 8   | 1   | NA       | *CONDENSER<br>(WCP)            | Bent          | 610.00 F   | *610.00 F   |
| 9   | 1   | NA       | *CONTROL ROD CPL<br>(WCP)      | Distorted     | 770.00 F   | *770.00 F   |
| 10  | 1   | NA       | *F Bonnet Moulding<br>(WCP)    | Not Necessary | 210.00 F   | *- F        |
| 11  | 1   | NA       | *F Bumper Sensor<br>(WCP)      | Missing       | 320.00 F   | *320.00 F   |
| 12  | 1   | NA       | *F Bumper Top Beam<br>(WCP)    | Not Necessary | 130.00 F   | *- F        |
| 13  | 1   | NA       | *F Bumper Under Cover<br>(WCP) | Missing       | 140.00 F   | *140.00 F   |
| 14  | 1   | NA       | *FRONT BUMPER<br>(WCP)         | Deformed      | 270.00 F   | *270.00 F   |
| 15  | 1   | NA       | *FRONT SUPPORT<br>(WCP)        | Dented        | 600.00 F   | *600.00 F   |
| 16  | 1   | NA       | *FRT AXLE CARRIER<br>(WCP)     | Distorted     | 1,300.00 F | *1,300.00 F |
| 17  | 1   | NA       | *FRT BUMPER REINF<br>(WCP)     | Deformed      | 170.00 F   | *170.00 F   |
| 18  | 1   | NA       | *F WS wiper garnish<br>(WCP)   | Cracked       | 260.00 F   | *260.00 F   |
| 19  | 1   | NA       | *GRILLE<br>(WCP)               | Cracked       | 280.00 F   | *280.00 F   |
| 20  | 1   | NA       | *Inner Fiber Clips<br>(WCP)    | Not Necessary | 48.00 F    | *- F        |
| 21  | 1   | NA       | *L/F AXLE CARRIER BRG<br>(NPA) | Distorted     | 0.00 F     | *- F        |
| 22  | 1   | NA       | *L/F BUMPER BRACKET<br>(WCP)   | Cracked       | 30.00 F    | *30.00 F    |
| 23  | 1   | NA       | *L/F BUMPER PROT CVR<br>(WCP)  | Cut           | 20.00 F    | *20.00 F    |
| 24  | 1   | NA       | *L/F HINGE<br>(WCP)            | Dented        | 40.00 F    | *40.00 F    |
| 25  | 1   | NA       | *L/F WHEELHOUSE COVER<br>(WCP) | Not Necessary | 110.00 F   | *- F        |
| 26  | 1   | NA       | *L/F WING<br>(WCP)             | Dented        | 290.00 F   | *290.00 F   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                      | Condition     | Repairer's | Amount     |
|-----|-----|----------|----------------------------------|---------------|------------|------------|
| 27  | 1   | NA       | *L/R CONTROL ARM BUSH<br>(NPA)   | Distorted     | 0.00 F     | *- F       |
| 28  | 1   | NA       | *LEFT HEADLAMP ASSY<br>(WCP)     | Cracked       | 810.00 F   | *810.00 F  |
| 29  | 1   | NA       | *MOUNTING CLAMP<br>(WCP)         | Necessary     | 24.00 F    | *24.00 F   |
| 30  | 1   | NA       | *R/BONNET SEAL<br>(WCP)          | Necessary     | 40.00 F    | *40.00 F   |
| 31  | 1   | NA       | *R/F AXLE CARRIER BRG<br>(NPA)   | Distorted     | 0.00 F     | *- F       |
| 32  | 1   | NA       | *R/F BUMPER BRACKET<br>(WCP)     | Cracked       | 30.00 F    | *30.00 F   |
| 33  | 1   | NA       | *R/F BUMPER PROT CVR<br>(WCP)    | Missing       | 20.00 F    | *20.00 F   |
| 34  | 1   | NA       | *R/F DRIVING FLANGE<br>(WCP)     | Distorted     | 280.00 F   | *280.00 F  |
| 35  | 1   | NA       | *R/F HINGE<br>(WCP)              | Dented        | 40.00 F    | *40.00 F   |
| 36  | 1   | NA       | *R/F SHOCK ABSORBER<br>(WCP)     | Distorted     | 220.00 F   | *220.00 F  |
| 37  | 1   | NA       | *R/F STEERING KNUCKLE<br>(WCP)   | Distorted     | 260.00 F   | *260.00 F  |
| 38  | 1   | NA       | *R/F TRACK CONT ARM<br>(WCP)     | Distorted     | 140.00 F   | *140.00 F  |
| 39  | 1   | NA       | *R/F WHEELHOUSE COVER<br>(WCP)   | Torn          | 110.00 F   | *110.00 F  |
| 40  | 1   | NA       | *R/F WING<br>(WCP)               | Deformed      | 290.00 F   | *290.00 F  |
| 41  | 1   | NA       | *R/R CONTROL ARM BUSH<br>(NPA)   | Distorted     | 0.00 F     | *- F       |
| 42  | 1   | NA       | *RADIATOR CPL<br>(WCP)           | Bent          | 770.00 F   | *770.00 F  |
| 43  | 1   | NA       | *RIGHT HEADLAMP ASSY<br>(WCP)    | Cracked       | 810.00 F   | *810.00 F  |
| 44  | 1   | NA       | *SupportPanelTopCover<br>(WCP)   | Cracked       | 160.00 F   | *160.00 F  |
| 45  | 1   | NA       | *SUNDRY PARTS<br>(NPA)           | Not Necessary | 0.00 F     | *- F       |
| 46  | 1   | NA       | *Front Number Plate Number Plate | Not Necessary | 40.00 FS   | *- FS      |
| 47  | 1   | NA       | *Front RH Sport Rim Sport Rim    | Grazed / Cut  | 580.00 FS  | *580.00 FS |
| 48  | 1   | NA       | *Front RH Tyre Tyre              | Punctured     | 350.00 FS  | *240.00 FS |
| 49  | 1   | NA       | *To Refill Coolant Coolant       |               | 120.00 FS  | *80.00 FS  |
| 50  | 1   | NA       | *To Reset Programme Programme    |               | 150.00 FS  | *100.00 FS |

F=Franchise part. S=SpcNett.

|                                                  |                  |                  |
|--------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                          | <b>11,672.00</b> | <b>10,604.00</b> |
| <b>+ Margin on L,N Items 15.00/15.00% (\$\$)</b> | <b>1,564.80</b>  | <b>1,440.60</b>  |
| <b>Total Parts (\$\$)</b>                        | <b>13,236.80</b> | <b>12,044.60</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                   | Lab.Type | Repairer's | Amount   |
|-------------------------|-------------------------------|----------|------------|----------|
| <u>Labour Items</u>     |                               |          |            |          |
| 1                       | Total Paint Labour            | New      | 530.00     | 515.00   |
| 2                       | Total Paint Materials         | New      | 239.37     | 238.88   |
| 3                       | Total Panel/Mechanical Labour | New      | 1,375.00   | 775.00   |
| Gross Labour Cost (S\$) |                               |          | 2,144.37   | 1,528.88 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >