

ASS. REC. BY:

REF: CP/MSG 19010369/09 f302

Special Instruction:

Surveyor: Simeon

ASSIGNMENT (Office)

From (Person): Pauline Tham

of MSIG

Date/Time: 13.8.19 18.30 p.m

Estimated Cost: _____ Bill to: _____

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKH 406 R

Insured: SL m 8069

at Workshop m/s Vision Auto work

Tel: 9856 4815

of B Kaki Bukit Ave 4 #08-09

Policy No: 2911 4756

Claim No: 600790

Sum Insured: _____

Excess: _____

Make of Veh: _____
(Client's Record)

D.O.A. 22.7.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 14.8.19 10.47 a.m

Person Contacted: Michelle

Vehicle: IN/OUT

Date/Time	Action/Instruction () Estimate
	SKH 46R - X
	SLM 8069 - X
	Submit US \$ 7350 - Unconfirmed, 5 days.

RECEIVED 20 SEP 2019

minna



Inspection Report

Type of Survey:

OD - Excess	<input type="checkbox"/>
TP Without Prejudice	<input checked="" type="checkbox"/>

Vehicle Details:

Vehicle Reg No
 Make
 Model
 Passenger capacity
 Paint colour & code
 Paint type

SKH 406R
Mazda
2
05
white

Vehicle Extras:

In-built camera
 Modification

Yes / No
 Yes / No

Vehicle Data:

Odometer reading
 Engine No
 VIN No
 Engine capacity
 Engine modification

41514 Km

Vehicle Condition:

Seviceable Yes / No

Handbrake
 Footbrake
 Steering
 Body
 Paint

Tyre Condition:

Front right
 Front left
 Rear left
 Rear right

	Tread mm	Size	Condition
Front right	4	Yokohama 205 / 45 / 16	
Front left	4	u	
Rear left	4	u	
Rear right	4	u	

General Data:

Date of accident
 Date of inspection
 Date of assignment
 Inspection location

22-07-2019
24-07-2019
23-07-2019
vision

Painting Process:

Prepare off vehicle
 Painting off vehicle
 Neither (default)

Cost Details:

Parts
 Supplementary
 Miscellaneous
 Body Labour
 Paint labour
 Paint material
 TOTAL
 Towing
 Excess
 Total less excess
 Estimated days for repair

	Repairer	Adjuster

Body Panel Repair:

Panel repair calculator used
 Yes / No

Remarks:

Lump / Global Sum

--

Reason(s)

Margin Repair / Fast-line

Others:

Repair Authorised

Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jul 2019		13 Aug 2019 18:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	LEE YUEN, ID: S0591392F								
Vehicle Reg. No.:	SKH406R	Date of Loss:	22/07/2019 12:00 - :59 [80 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 600790	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLM806G	Policy No. (Claimant):	Excess:						
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/08/2019]								
Driver/Custodian (Insured):	NORAZLINA BINTE MANAP (39 / Female), NRIC: S7940838G Email:								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. (manual assigned) Liab: 100%. Contact: Michelle @ 9856 4815								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____ Policy No : _____
 Date : _____ Claim No : _____

Insured Vehicle No : SKH 406 R Date of Accident : 22-07-19
 TP Vehicle No : SLM 806 R Place of Survey : Vision
 Make & Model : Mazda 2 Date of Survey : 24-07-19

Point of Impact / Damages : Side Right.

Recommended Reserve :

Repairer's Estimate	: \$ <u>12398.56</u>	
Interim Adjustment	: \$ <u>3902.00</u>	
Check Items	: \$ <u>2429.20</u>	

Proposed : Part by Part / Lump Sum Repair \$5100 Excess : \$ -

Estimate Repair Period : 05 days

Pre-accident Market Value (for total loss consideration) : \$ 38000.00

COE / PARF to owner : \$ 35039.00

Vehicle within / not within limit of economical repair.

Others : * Repairer agree All in repair at \$3000 no supplementary

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

OD Claim
Excess : \$ _____
(Authorised / Revert)

TP Claim
(Without Prejudice)

Vehicle No. SKH 406R

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 05 days.

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 24-07-19

Victor_Seng @ sg.msig-asia.com

* Repairer agree \$3000/- All in no supplementary.

Victor. 24/07/19.



MSIG

MSIG Insurance (Singapore) Pte. Ltd., (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Pauline Tham

Date: 25 Jul 2019

Preliminary Advice

Insured Vehicle No	: SLM806G	Accident Date	: 22/07/2019
TP Vehicle No	: SKH406R	Assignment Date	: 24/07/2019
Make	: MAZDA MAZDA5	Est. Duration of Repair	: 5.00
Date of Inspection	: 24/07/2019		
Inspection At	: VISION AUTOWORK PTE LTD (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages Right Side portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,398.56
Revised Amount	:S\$	3,902.00
Check Items (Estimated)	:S\$	2,429.20
Total	:S\$	

Lump Sum Repair	:S\$	5,100.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	38000.00
COE / PARF Rebate	:S\$	35039.00
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- (x) The vehicle is ~~economical~~/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.
- (x) * Repairer agree all in repair at \$3000.00 no supplementary.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 392F

Vehicle Details

Vehicle No.: SKH406R
Vehicle to be Exported: No
Intended Deregistration Date: 24 Jul 2019
Vehicle Make: MAZDA
Vehicle Model: MAZDA2 1.5L 4EAT ABS AIRBAGS 5DR 2WD
Primary Colour: White
Manufacturing Year: 2012
Engine No.: ZYB10777
Chassis No.: JM6DE10Y2C0231770
Maximum Power Output: 76.0 kW (101 bhp)
Open Market Value: \$18,261.00
Original Registration Date: 30 Oct 2012
First Registration Date: 30 Oct 2012
Transfer Count: 1
Actual ARF Paid: \$18,261.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Oct 2022
PARF Rebate Amount: \$11,869.00

Intended COE Rebate Details

COE Expiry Date: 29 Oct 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$71,001.00
COE Rebate Amount: \$23,170.00
Total Rebate Amount: \$35,039.00

The information contained herein is correct as at 24 Jul 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SKH406R		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MAZDA		
Vehicle Model :	MAZDA2 1.5L 4EAT ABS AIRBAGS 5DR 2WD		
Chassis No. :	JM6DE10Y2C0231770		
Propellant :	Petrol		
Engine No. :	ZYB10777		
Engine Capacity :	1498 cc		
Maximum Power Output :	76.0 kW (101 bhp)		
Maximum Laden Weight :	1488 kg		
Unladen Weight :	1046 kg		
Year Of Manufacture :	2012		
Original Registration Date :	30 Oct 2012		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$71,001.00		
COE Expiry Date :	29 Oct 2022		
Road Tax Expiry Date :	29 Oct 2019		
PARF Eligibility Expiry Date :	29 Oct 2022		
Inspection Due Date :	29 Oct 2019		
Intended Transfer Date :	05 Sep 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 29 Oct 2019. You may renew the road tax from 30 Jul 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 29 Oct 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 30 Oct 2019 to 29 Apr 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	342.00	-	342.00
Total Amount Payable :			367.00
Amount Payable (From 30 Oct 2019 to 29 Oct 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	684.00	-	684.00
Total Amount Payable :			709.00

You may print this page for reference.

OK

Print

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)
 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Tel : 6341 6789 Fax: 6341 6778
 E-mail:visionautowork@gmail.com

DATE : 22.07.19

TO : **MSIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKH406R**
 MODEL : **MAZDA 2**
 DATE OF ACCIDENT : 22.07.19
 TIME OF ACCIDENT : 12:45HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH / Deformed	1	\$ 975.10	\$ 975.10
2	REAR DOOR HINGE RH / Dented	2	\$ 39.90	\$ 79.80
3	REAR DOOR WEATHER STRIP RH / necc	1	\$ 141.00	\$ 141.00
4	REAR DOOR INNER LOCK RH ? XNN	1	\$ 276.80	\$ 276.80
5	REAR DOOR GLASS REGULATOR GEAR MOTOR RH ?	1	\$ 545.60	\$ 545.60
6	REAR DOOR OUTER MOULDING RH ?	1	\$ 52.80	\$ 52.80
7	REAR DOOR GLASS CHANNEL RH ?	1	\$ 144.90	\$ 144.90
8	REAR DOOR INNER TRIM BOARD RH ?	1	\$ 764.80	\$ 764.80
9	SIDE SKIRT RH / Cracked	1	\$ 694.10	\$ 694.10
10	REAR ABS SENSOR RH ?	1	\$ 279.40	\$ 279.40
11	REAR AXLE X	1	\$ 2,496.70	\$ 2,496.70
12	REAR WHEEL HUP C/W BEARING RH ?	1	\$ 595.40	\$ 595.40
13	REAR SHOCK ABSORBER RH ?	1	\$ 376.80	\$ 376.80

TOTAL PRICE \$ 7,423.20
 LESS 20% \$ 1,484.64
SUB TOTAL PRICE \$ 5,938.56

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR DOOR SEALANT RH ✓	1	\$ 150.00	\$ 150.00
2	REAR DOOR INNER TRIM CLIP (SET) ✓	1	\$ 50.00	\$ 50.00
3	SIDE SKIRT CLIP RH (SET) ✓	1	\$ 50.00	\$ 50.00
4	REAR WHEEL TYRE RH X	1	\$ 480.00	\$ 480.00
5	REAR WHEEL RIM RH / Brazed	1	\$ 850.00	\$ 850.00
6	TAIL LAMP CLIP (SET) X	1	\$ 30.00	\$ 30.00
7	BRAKE OIL ✓	1	\$ 50.00	\$ 50.00

TOTAL \$ 1,660.00

XNN
 X
 X XNN
 ✓ REC
 X XNN
 X XNN
 X XNN
 X XNN
 X XNN
 X XNN
 X XNN

50
 30 } rec
 40
 X NN
 350
 X NN
 20 X NN

TO : **MSIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKH406R**
 MODEL : **MAZDA 2**
 DATE OF ACCIDENT : 22.07.19
 TIME OF ACCIDENT : 12:45HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,200.00	700 400
2	TO SPRAY PAINT	\$ 1,200.00	700 400
3	TUFF COAT	\$ 250.00	50
4	WIRING, BULB CHECKING	\$ 180.00	30
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	X
6	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	X
7	TRANFER REAR DOOR MECHANISM	\$ 80.00	50
8	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
9	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	150 X
10	FOUR WHEEL ALIGNMNET	\$ 120.00	60
11	REMOVE AND REFIX REAR WINDOW GLASS	\$ 100.00	50 X
12	RESET ABS LIGHT	\$ 350.00	150 X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$- 4,800.00

TOTAL PARTS COST : \$ 7,598.56
 TOTAL LABOUR COST : \$ 4,800.00
 TOTAL REPAIR COST : \$ 12,398.56

parts = 1942.80
 -70%
 SN 490
 labour 1940
 3984.24
 x 80%
 3187.39

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY
 SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)
 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Tel : 6341 6789 Fax: 6341 6778
 E-mail:visionautowork@gmail.com

DATE : 22.07.19

TO : **MSIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKH406R**
 MODEL : **MAZDA 2**
 DATE OF ACCIDENT : 22.07.19
 TIME OF ACCIDENT : 12:45HRS

cor 5days.

\$ 5100.00 (X)

** Repair limit agreed \$ 3000*

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH / <i>Deformed</i>	1	\$ 975.10	\$ 975.10
2	REAR DOOR HINGE RH / <i>Dented</i>	2	\$ 39.90	\$ 79.80
3	REAR DOOR WEATHER STRIP RH / <i>necc</i>	1	\$ 141.00	\$ 141.00
4	REAR DOOR INNER LOCK RH ?	1	\$ 276.80	\$ 276.80
5	REAR DOOR GLASS REGULATOR GEAR MOTOR RH ?	1	\$ 545.60	\$ 545.60
6	REAR DOOR OUTER MOULDING RH ?	1	\$ 52.80	\$ 52.80
7	REAR DOOR GLASS CHANNEL RH ?	1	\$ 144.90	\$ 144.90
8	REAR DOOR INNER TRIM BOARD RH ?	1	\$ 764.80	\$ 764.80
9	SIDE SKIRT RH / <i>Cracked</i>	1	\$ 694.10	\$ 694.10
10	REAR ABS SENSOR RH <i>Wtr ?</i>	1	\$ 279.40	\$ 279.40
11	REAR AXLE <i>X</i>	1	\$ 2,496.70	\$ 2,496.70 <i>X</i>
12	REAR WHEEL HUP C/W BEARING RH ?	1	\$ 595.40	\$ 595.40
13	REAR SHOCK ABSORBER RH ?	1	\$ 376.80	\$ 376.80

TOTAL PRICE \$ 7,423.20
 LESS 20% \$ 1,484.64
 SUB TOTAL PRICE \$ 5,938.56

49-6.50
985.30
5441.20 ✓

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR DOOR SEALANT RH / ✓	1	\$ 150.00	\$ 150.00 <i>50</i>
2	REAR DOOR INNER TRIM CLIP (SET) / ✓	1	\$ 50.00	\$ 50.00 <i>30</i>
3	SIDE SKIRT CLIP RH (SET) / ✓	1	\$ 50.00	\$ 50.00 <i>40</i>
4	REAR WHEEL TYRE RH <i>X</i>	1	\$ 480.00	\$ 480.00 <i>X</i>
5	REAR WHEEL RIM RH / <i>Grazed</i>	1	\$ 850.00	\$ 850.00 <i>350</i>
6	TAIL LAMP CLIP (SET) <i>X</i>	1	\$ 30.00	\$ 30.00 <i>X</i>
7	BRAKE OIL / ✓	1	\$ 50.00	\$ 50.00 <i>20</i>

TOTAL \$ 1,660.00

490 ✓

TO : **MSIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKH406R**
 MODEL : **MAZDA 2**
 DATE OF ACCIDENT : 22.07.19
 TIME OF ACCIDENT : 12:45HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/ N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,200.00	700
2	TO SPRAY PAINT	\$ 1,200.00	700
3	TUFF COAT	\$ 280.00	50
4	WIRING, BULB CHECKING	\$ 180.00	30
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY &ROOF LINING TO FACILITATE REPAIR	\$ 250.00	X
6	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	X
7	TRANSFER REAR DOOR MECHANISM	\$ 80.00	50
8	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
9	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	150
10	FOUR WHEEL ALIGNMNET	\$ 120.00	60
11	REMOVE AND REFIX REAR WINDOW GLASS	\$ 100.00	50
12	RESET ABS LIGHT	\$ 350.00	150
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$- 4,800.00 1940 ✓

TOTAL PARTS COST : \$ 7,598.56
 TOTAL LABOUR COST : \$ 4,800.00
 TOTAL REPAIR COST : \$ 12,398.56

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
 CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
 ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

3941.20
 490
 1940

6374.20
 1274.24
5096.96

MSIG Insurance (Singapore) Pte. Ltd.

OD Claim
Excess : \$ _____
(Authorised / Revert)

TP Claim
(Without Prejudice)

Vehicle No. SKH 406R

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 05 days.

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 24-07-19

Victor - Seng @ sq. msig-asia.com

* Repair agree \$3000/- All in no supplementary.

Victor. 24/07/19.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jul 2019		13 Aug 2019 18:26 Edit Adj Rpt	S\$2,350.00 Edit Estimates	S\$2,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	LEE YUEN, ID: S0591392F								
Vehicle Reg. No.:	SKH406R	Date of Loss:	22/07/2019 12:00 - :59 [80 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 600790	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLM806G	Policy No. (Claimant):							
		Excess:							
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Imm.Advice due 14/08/2019]								
Driver/Custodian (Insured):	NORAZLINA BINTE MANAP (39 / Female), NRIC: S7940838G Email:								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. (manual assigned) Liab: 100%. Contact: Michelle @ 9856 4815								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKH406R (600790)
[SLM806G]
TP
LEE YUEN
Jul 22 2019 12:00PM
[GRAB RENTALS PTE LTD]
Vision Autowork Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>
Assessment Reports				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	25/07/19 11:15	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images				3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	24/07/19 23:27	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
2	24/07/19 23:27	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
3	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
4	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
5	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
6	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
7	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
8	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
9	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
10	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
11	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
12	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
13	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
14	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
15	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
16	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
17	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
18	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
19	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
20	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
21	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
22	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
23	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
24	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
25	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
26	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
27	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
28	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
29	24/07/19 23:28	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/07/19 10:32	PRI	Load PDF	<input type="checkbox"/>
2	24/07/19 10:32	OI Accident Report	Load PDF	<input type="checkbox"/>
3	24/07/19 10:32	TP SKH406R E-REPORT	Load PDF	<input type="checkbox"/>
4	24/07/19 11:45	email from workshop	Load PDF	<input type="checkbox"/>
5	24/07/19 14:06	liab from CH	Load PDF	<input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	24/07/19 14:19	Manual assigned 23/07/19.	Load PDF	<input type="checkbox"/>
2	25/07/19 14:29	Preliminary Loss Advise	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014369/DQF3E2

Date: 03/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant	Insured Vehicle No :	SLM806G
Vehicle No : SKH406R	Nature of Claim:	TP
Date of Loss: 22/07/2019	Claim No:	600790

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH406R	Engine No:	ZYB10777
Make & Model:	MAZDA 2, 1.5 (A)	Chassis No:	JM6DE10Y2C0231770
Reg. Date:	30/10/2012 (Man. Year: 2012)	Odometer:	41514 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,598.56	1,960.40	5,638.16	74.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	990.00	3,810.00	79.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,398.56	2,950.40	9,448.16	76.20
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	12,398.56	2,350.00	10,048.56	81.05
+ GST 7.00/7.00% (S\$)	867.90	164.50	703.40	81.05
Nett Amount (S\$)	13,266.46	2,514.50	10,751.96	81.05

INSPECTION

Date of Assignment:	13/08/2019	
Date Inspected:	24/07/2019 Inspected At:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4., #08-09 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2019)
Parts: 143	MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKH406R)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR DOOR RH	Deformed	975.10 FL	*975.10 FL
2	2	*REAR DOOR HINGE RH	Not Necessary	79.80 FL	*- FL
3	1	*REAR DOOR WEATHER STRIP RH	Necessary	141.00 FL	*141.00 FL
4	1	*REAR DOOR INNER LOCK RH	Not Necessary	276.80 FL	*- FL
5	1	*REAR DOOR GLASS REGULATOR GEAR MOTOR RH	Not Necessary	545.60 FL	*- FL
6	1	*REAR DOOR OUTER MOULDING RH	Necessary	52.80 FL	*52.80 FL
7	1	*REAR DOOR GLASS CHANNEL RH	Not Necessary	144.90 FL	*- FL
8	1	*REAR DOOR INNER TRIM BOARD RH	Not Necessary	764.80 FL	*- FL
9	1	*SIDE SKIRT RH	Cracked	694.10 FL	*694.10 FL
10	1	*REAR ABS SENSOR RH	Not Necessary	279.40 FL	*- FL
11	1	*REAR AXLE	Not Necessary	2,496.70 FL	*- FL
12	1	*REAR WHEEL HUP C/W BEARING RH	Not Necessary	595.40 FL	*- FL
13	1	*REAR SHOCK ABSORBER RH	Not Necessary	376.80 FL	*- FL
14	1	*REAR DOOR SEALANT RH	Necessary	150.00 FS	*50.00 FS
15	1	*SET REAR DOOR INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
16	1	*SET SIDE SKIRT CLIP RH	Necessary	50.00 FS	*40.00 FS
17	1	*REAR WHEEL TYRE RH	Not Necessary	480.00 FS	*- FS
18	1	*REAR WHEEL RIM RH	Grazed	850.00 FS	*350.00 FS
19	1	*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
20	1	*BRAKE OIL	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,083.20	2,333.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,484.64	372.60
Total Parts (S\$)	7,598.56	1,960.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	New	1,200.00	400.00
2	TO SPRAY PAINT	New	1,200.00	400.00
3	TUFF COAT	New	250.00	50.00
4	WIRING, BULB CHECKING	New	180.00	30.00
5	REMOVE & REFIX CUSHION SEAT / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	0.00
6	REMOVE & REFIX AUDIO SPEAKER	New	120.00	0.00
7	TRANFER REAR DOOR MECHANISM	New	80.00	50.00
8	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
9	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	60.00
11	REMOVE AND REFIX REAR WINDOW GLASS	New	100.00	0.00
12	RESET ABS LIGHT	New	350.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			4,800.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >