

ASS. REC. BY:

REF: CS/MSG 190143741 C9F312

Special Instruction:

Surveyor: Simon

ASSIGNMENT (Office)

From (Person):

Najden how

of

MELB

Date/Time:

14/8/19 4:33pm

Estimated Cost:

Bill to:

OI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 50632

Insured:

SLR 52184

at Workshop m/s

Juek cars

Tel:

67488824

of

Blk 3007 Ubi Rd 1 # 01-450

Policy No:

29114756

Claim No:

606932

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Thana

Vehicle: IN / OUT

Date/Time	Action/Instruction
	SLR 50632 - X
	SLR 52184 - X
29/10/19 @ 3.30pm	checked with Thana, the vehicle has not yet repair as liability just issued 50/50 from insurance.
29/10/19	Submit prei report. - The vehicle has not send in for repair.

RECEIVED 28 OCT 2019



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
4 Shenton Way. #27-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

Executive
Claims Services

Inspection Report

Type of Survey:

OD - Excess	<input checked="" type="checkbox"/>
TP Without Prejudice	<input checked="" type="checkbox"/>

Vehicle Details:

Vehicle Reg No
Make
Model
Passenger capacity
Paint colour & code
Paint type

SLR 5063Z
Toyota
C-HR 1.8A
05
Yellow

Vehicle Extras:

In-built camera
Modification

Yes / No
Yes / ☒

Vehicle Data:

Odometer reading
Engine No
VIN No
Engine capacity
Engine modification

63445 km

Vehicle Condition:

Seviceable Yes / No

Handbrake
Footbrake
Steering
Body
Paint

Tyre Condition:

Front right
Front left
Rear left
Rear right

Tread mm	Size	Condition
5	Michelin 215/60 17	
5	"	
4	"	
4	"	

General Data:

Date of accident
Date of inspection
Date of assignment
Inspection location

24-07-19
29-07-19
26-07-19
Tack Cars

Painting Process:

Prepare off vehicle
Painting off vehicle
Neither (default)

Cost Details:

Parts
Supplementary
Miscellaneous
Body Labour
Paint labour
Paint material
TOTAL
Towing
Excess
Total less excess
Estimated days for repair

Repairer	Adjuster

Body Panel Repair:

Panel repair calculator used
Yes / No

--

Remarks:

Lump / Global Sum

--

Reason(s)

Margin Repair / Fast-line

Others:

Repair Authorised
Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jul 2019		14 Aug 2019 16:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	CAROLINE HENG SWEE LAN, ID: S7420855Z		
Vehicle Reg. No.:	SLR5063Z	Date of Loss:	24/07/2019 09:00 - :59 [23 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 600932	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLR5218U	Policy No. (Claimant):	
		Excess:	
Repairer:	Jack Cars Enterprise Pte Ltd - Ubi (HQ) BLK 3007 UBI ROAD 1 #01-450, 408701 Ubi - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]		
Driver/Custodian (Insured):	MAU YONG CHAN (), NRIC: S8782218D, Tel: +6591543613 Email:		
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. (OI: Grab. Liab: 100%. TP agree on SJE - assign AutoProbe. Contact: S.Thanaletchumi (Ms) @ Office : 67488824/ Mobile : 91701900		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



MSIG

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____
Date : _____

Policy No : _____
Claim No : _____


Insured Vehicle No : SLR 5218U Date of Accident : 24-07-19
TP Vehicle No : SLR 5063Z Place of Survey : Jack Cars
Make & Model : Toyota C-HR 1.8A Date of Survey : 29-07-19.

Point of Impact / Damages :

Front Left

Recommended Reserve :

Repairer's Estimate : \$ 5492.50
Interim Adjustment : \$ 2992.50
Check Items : \$ -



Proposed : Part by Part / Lump Sum Repair

Excess : \$ -

Estimate Repair Period : 04 days

Pre-accident Market Value (for total loss consideration) : \$ 82000.00

COE / PARF to owner : \$ 43965.00

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐ OD Claim
Excess : \$ _____
(Authorised / Revert)

☒ TP Claim
(Without Prejudice)

Vehicle No. SLR 5063 Z

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 04 days

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 22-07-19

Victor - Seng @ sg.msig-asia.com


MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: NG CHEN HOW

Date: 31 Jul 2019

Preliminary Advice

Insured Vehicle No	: SLR5218U	Accident Date	: 24/07/2019
TP Vehicle No	: SLR5063Z	Assignment Date	: 29/07/2019
Make	: HONDA VEZEL	Est. Duration of Repair	: 4.00
Date of Inspection	: 30/07/2019		
Inspection At	: JACK CARS ENTERPRISE PTE LTD - UBI (HQ) BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408701		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front left portion.

Repairer's Estimate (Gross)	:S\$	5,492.50
Revised Amount	:S\$	2,992.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000
COE / PARF Rebate	:S\$	43,965
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- (X) The vehicle is economical/~~not economical~~ for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	855Z
Vehicle Details	
Vehicle No.:	SLR5063Z
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Yellow
Manufacturing Year:	2017
Engine No.:	2ZR8119911
Chassis No.:	ZYX102044380
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,957.00
Original Registration Date:	17 Aug 2017
First Registration Date:	17 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	16 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,001.00
COE Rebate Amount:	\$38,992.00
Total Rebate Amount:	\$42,742.00

The information contained herein is correct as at 29 Oct 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
SLR5063Z

Make / Model
TOYOTA / C-HR HYBRID 1.8S CVT

Vehicle Type :
P11 - Passenger Station Wagon/Jeep/Land Rover

Vehicle Attachment 1 :
No Attachment

Vehicle Scheme :
Normal

Chassis No. :
ZYX102044380

Propellant :
Petrol-Electric

Engine No. :
2ZR8119911

Motor No. :
20A317411580

Engine Capacity :
1797 cc

Power Rating :
53.0 kW

Maximum Power Output :
90.0 kW (120 bhp)

Maximum Laden Weight :

1715 kg

Unladen Weight :

1440 kg

Year Of Manufacture :

2017

Original Registration Date :

17 Aug 2017

Lifespan Expiry Date :

-

COE Category :

B - Car above 1600cc or 97kW (130bhp)

Quota Premium :

\$50,001.00

COE Expiry Date :

16 Aug 2027

Road Tax Expiry Date :

16 Feb 2020

PARF Eligibility Expiry Date :

16 Aug 2027

Inspection Due Date :

16 Aug 2020

Intended Transfer Date :

29 Oct 2019

CO2 Emission :

88.00 (g/km)

CEV/VES Rebate Utilised Amount :

\$24,740.00

CO Emission :

-

HC Emission :

-

NOx Emission :

-

PM Emission :

-

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
---------------	---------

Print

OK →

Save as PDF

Copy as Text

ESTIMATE

DATE OF ACCIDENT : 24/07/2019
VEHICLE : SLR5063Z
MAKE & MODEL : TOYOTA CHR HYBRID
INSURANCE : MSIG NSURANCE
SURVEYOR : MSIG

PARTS		CONDITION	AMOUNT
1.	HEADLIGHT - LEFT <i>X Not consistent (scr)</i>		\$ 1800
2.	FRONT FENDER - LEFT <i>/ Deformed</i>		\$ 650
3.	SIDE MIRROR - LEFT <i>/ Grazed</i>		\$ 500
4.	WHEELARCH - LEFT <i>/ Deformed</i>		\$ 210
5.	FRONT BUMPER <i>/ Deformed</i>		\$ 850
6.	FRONT BUMPER LOWER LIPS <i>/ Grazed</i>		\$ 380
SPECIAL NETT			
1.	CLIPS <i>ncc</i>		\$ 100
			<i>50</i>
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	<i>450</i>	\$ 900
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	<i>500</i>	\$ 700
3.	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	<i>50</i>	\$ 150

4.	PROGRAMMING OF HEADLIGHT	X	\$ 350
	PARTS – 25% :	\$ 3,292.50	
	SPECIAL NETT :	\$ 100	
	LABOUR :	\$ 2,100	
	TOTAL :	\$ 5,492.50	
	7% GST :	\$ 384.47	
	GRAND TOTAL :	\$ 5,876.97	

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2019		14 Aug 2019 16:33 Edit Adj Rpt	\$2,992.50 Edit Estimates	\$2,992.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	CAROLINE HENG SWEE LAN, ID: S7420855Z								
Vehicle Reg. No.:	SLR5063Z	Date of Loss: 24/07/2019 09:00 - :59 [23 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 600932	Policy/Cover Note No.: 29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020							
Vehicle Reg. No. (Insured):	SLR5218U	Policy No. (Claimant):							
		Excess:							
Repairer:	Jack Cars Enterprise Pte Ltd - Ubi (HQ) BLK 3007 UBI ROAD 1 #01-450, 408701 Ubi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by SIMON HO LEONG CHUAN] ... [Imm.Advice due 15/08/2019]								
Driver/Custodian (Insured):	MAU YONG CHAN (), NRIC: S8782218D, Tel: +6591543613 Email:								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. (OI: Grab. Liab: 100%. TP agree on SJE - assign AutoProbe. Contact: S.Thanaletchumi (Ms) @ Office : 67488824/ Mobile : 91701900								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR5063Z (600932)
[SLR5218U]
TP
CAROLINE HENG SWEE LAN
Jul 24 2019 9:00AM
[GRAB RENTALS PTE LTD]
Jack Cars Enterprise Pte Ltd - Ubi

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/07/19 14:42	Video - Accident - from OI	Load MP4	
2	31/07/19 14:02	Video - Accident from 3P	Load MP4	

Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/07/19 14:39	Accident Statement From: SC - Reg. No: SLR5218U, Claimant: GRAB RENTALS PTE LTD	Load HTM	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	31/07/19 14:42	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	30/07/19 19:39	SURVEY PHOTO	Load JPG	
2	30/07/19 19:39	SURVEY PHOTO	Load JPG	
3	30/07/19 19:39	SURVEY PHOTO	Load JPG	
4	30/07/19 19:39	SURVEY PHOTO	Load JPG	
5	30/07/19 19:39	SURVEY PHOTO	Load JPG	
6	30/07/19 19:39	SURVEY PHOTO	Load JPG	
7	30/07/19 19:39	SURVEY PHOTO	Load JPG	
8	30/07/19 19:39	SURVEY PHOTO	Load JPG	
9	30/07/19 19:39	SURVEY PHOTO	Load JPG	
10	30/07/19 19:39	SURVEY PHOTO	Load JPG	
11	30/07/19 19:39	SURVEY PHOTO	Load JPG	
12	30/07/19 19:39	SURVEY PHOTO	Load JPG	
13	30/07/19 19:39	SURVEY PHOTO	Load JPG	
14	30/07/19 19:39	SURVEY PHOTO	Load JPG	
15	30/07/19 19:39	SURVEY PHOTO	Load JPG	
16	30/07/19 19:39	SURVEY PHOTO	Load JPG	
17	30/07/19 19:39	SURVEY PHOTO	Load JPG	
18	30/07/19 19:39	SURVEY PHOTO	Load JPG	
19	30/07/19 19:39	SURVEY PHOTO	Load JPG	
20	30/07/19 19:39	SURVEY PHOTO	Load JPG	
21	30/07/19 19:39	SURVEY PHOTO	Load JPG	
22	30/07/19 19:39	SURVEY PHOTO	Load JPG	
23	30/07/19 19:39	SURVEY PHOTO	Load JPG	
24	30/07/19 19:39	SURVEY PHOTO	Load JPG	
25	30/07/19 19:39	SURVEY PHOTO	Load JPG	
26	30/07/19 19:39	SURVEY PHOTO	Load JPG	

Documentation

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/07/19 14:39	SLR5063Z GIA Rpt	Load PDF	
2	29/07/19 14:40	Notice of PRI	Load PDF	
3	29/07/19 14:40	Email - PRI	Load PDF	
4	29/07/19 15:00	Liab from CH	Load PDF	
5	30/07/19 14:45	ScreenGRab. both vehicles changed lane	Load JPG	
6	30/07/19 14:48	DISPUTE LIABILITY	Load PDF	

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	29/07/19 15:26	Manul Assigned 26/07/19		Load PDF	
2	29/07/19 15:28	Email - Survey 30/07/19		Load PDF	
3	31/07/19 15:57	Preliminary Loss Advise		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014374/CQF3E2

Date: 08/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756

Claimant Vehicle No : SLR5063Z

Insured Vehicle No : SLR5218U

Date of Loss: 24/07/2019

Nature of Claim: TP

Claim No: 600932

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR5063Z

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A)

Engine No: 2ZR8119911

Reg. Date: 17/08/2017 (Man. Year: 2017)

Chassis No: ZYX102044380

Colour: Yellow

Odometer: 63445 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60/17

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,392.50	1,992.50	1,400.00	41.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,000.00	1,100.00	52.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,492.50	2,992.50	2,500.00	45.52
+ GST 7.00/7.00% (S\$)	384.48	209.48	175.00	45.52
Nett Amount (S\$)	5,876.98	3,201.98	2,675.00	45.52

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 29/07/2019 Inspected At:

Jack Cars Enterprise Pte Ltd - Ubi
(HQ)
BLK 3007 UBI ROAD 1 #01-450
Singapore 408701

Estimated Period of Repair: 4.0 days

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2019)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR5063Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLIGHT - LEFT (SCRATCHED)	Not Consistent With The Impact	1,800.00 FL	*- FL
2	1		*FRONT FENDER - LEFT	Deformed	650.00 FL	*650.00 FL
3	1		*SIDE MIRROR - LEFT	Grazed	500.00 FL	*500.00 FL
4	1		*WHEELARCH - LEFT	Deformed	210.00 FL	*210.00 FL
5	1		*FRONT BUMPER	Deformed	850.00 FL	*850.00 FL
6	1		*FRONT BUMPER LOWER LIPS	Grazed	380.00 FL	*380.00 FL
7	1		*CLIPS	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,490.00	2,640.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,097.50	647.50
Total Parts (\$\$)	3,392.50	1,992.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	900.00	450.00
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	700.00	500.00
3	TO CHECK LIGHTING SYSTEM, WIRING & REWIRE	New	150.00	50.00
4	PROGRAMMING OF HEADLIGHT	New	350.00	0.00
Gross Labour Cost (S\$)			2,100.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >