

22/02/2004

ASS. REC. BY:

REF: CF/MSG 190/4376/ CFB

Special Instruction:

Surveyor: Simon

ASSIGNMENT (Office)

Meinen

From (Person): Vimmala

of M81G

Date/Time: 13/8/19 @ 6:15pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 6458T

Insured:

at Workshop m/s Kai Motor

Tel: 67474006

of Blk 3007 Ubi Rd 1 # 01-440

Policy No: 28887001 MKC

Claim No: 592068

Sum Insured:

Excess: \$500.00

Make of Veh:

D.O.A. 29/4/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3:13pm @ 14/8/19

Person Contacted: Ms. Kim

Vehicle: IN / OUT

| Date/Time | Action/Instruction |
|------------------|--|
| | Estimate / GBF 6458T - CF1 / VAL 19027681 JV |
| | D.O.A. - 29/04/2019 |
| 29/8/19 @ 5:17pm | confirmed with Ms Kym LS \$15200, 14 days. (Red \$10846.50, 42%) MV: \$561K; CTA: 34829; NV: \$21171 |

RECEIVED 04 SEP 2019



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
 4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
 www.msig.com.sg

Victor Seng (132),
 Executive
 Claims Services

Handwritten signature and checkmark

Inspection Report

Type of Survey:

| | |
|----------------------|---------|
| OD - Excess | \$500/- |
| TP Without Prejudice | |

Vehicle Data:

| | |
|---------------------|-----------|
| Odometer reading | 106606 km |
| Engine No | |
| VIN No | |
| Engine capacity | |
| Engine modification | |

Vehicle Details:

| | |
|---------------------|------------|
| Vehicle Reg No | GBF 6458T |
| Make | Toyota |
| Model | Hiace 3.0M |
| Passenger capacity | 2 |
| Paint colour & code | White. |
| Paint type | |

Vehicle Condition:

| | | |
|-----------|------------|----------|
| | Seviceable | Yes / No |
| Handbrake | | |
| Footbrake | | |
| Steering | | |
| Body | | |
| Paint | | |

Vehicle Extras:

| | |
|-----------------|----------|
| In-built camera | Yes / No |
| Modification | Yes / No |

Tyre Condition:

| | Tread mm | Size | Condition |
|-------------|----------|-----------------|-----------|
| Front right | 4 | HIFLY 195 / R15 | |
| Front left | 4 | " | |
| Rear left | 4 | " | |
| Rear right | 4 | " | |

General Data:

| | |
|---------------------|-----------|
| Date of accident | 29-04-19 |
| Date of inspection | 13-05-19 |
| Date of assignment | 10-05-19 |
| Inspection location | KAL MOTOR |

Painting Process:

| | |
|----------------------|--|
| Prepare off vehicle | |
| Painting off vehicle | |
| Neither (default) | |

Cost Details:

| | Repairer | Adjuster |
|---------------------------|----------|----------|
| Parts | 19156.50 | 15345.00 |
| Supplementary | - | - |
| Miscellaneous | - | - |
| Body Labour | 3890.00 | 2060.00 |
| Paint labour | 3000.00 | 1700.00 |
| Paint material | - | - |
| TOTAL | 26046.50 | |
| Towing | | |
| Excess | | |
| Total less excess | | |
| Estimated days for repair | | 14 days. |

Body Panel Repair:

| | |
|------------------------------|--|
| Panel repair calculator used | |
| Yes / No | |

Remarks:

| | |
|-------------------|---------------------------|
| Lump / Global Sum | |
| Reason(s) | Margin Repair / Fast-line |

Others:

| |
|--|
| |
| |
| |
| |

Repair Authorised

| | |
|-------|--|
| Date: | |
|-------|--|

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--------------------------------|---------|---------------|-------------|--------------------------------------|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 02 May 2019 | | 13 Aug 2019 18:15 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|--|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | | [Created by insurer] | | | | | | |
| Insured: | TREKNOLOGY BIKES 3 PTE LTD, Co. Reg. No.: 200206328Z | | | | | | | | |
| Vehicle Reg. No.: | GBF6458T | Date of Loss: | 29/04/2019 15:00 - :59 [39 Months and 28 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | OD / 592068 | Policy/Cover Note No.: | 28887001MKC (Comprehensive) Coverage: 03/02/2019 - 02/02/2020 | | | | | | |
| | | Excess: | S\$500.00 | | | | | | |
| Repairer: | KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440, 408701 Ubi - Tel: | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmla D/O Raja Singam - 65942471] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/08/2019] | | | | | | | | |
| Driver/Custodian: | ABDILLAH BIN BIDIN (52 / Male) , NRIC: S1733488C, Tel: +6594759058 Email: trek1@treknoology3.com | | | | | | | | |
| Adj Asg. Remarks: | As per Jason instruction, re-assigned to LKK to follow-up this case. To revert. To arrange to survey the vehicle at KAI MOTOR TRADING Bik 3007, Ubi Road 1, #01-440, Singapore 408701. No OD estimate yet. To call Ms Kym at Kai Motor Trading at Telephone: 67474006. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | | View All Compose Case Mail | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS | | | | | | | | | |
| View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Shiau Chan (LKKAuto)

From: Kai Motor <kaimotor@gmail.com>
Sent: Thursday, 29 August 2019 5:12 PM
To: Shiau Chan (LKKAuto)
Subject: Re: KINDLY ADVISE THE STATUS OF GBF 6458T (DOA: 29/04/2019)

Hi Shiau,

We confirmed Lump Sum \$15,200.00 .

🍷 Have a nice day w thanks.

Ms Kym

On Wed, 28 Aug 2019 at 10:12, Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Ms Kym,

WITHOUT PREJUDICE

Offer Lump Sum \$15,200.00 before excess \$500.00 & GST and 14 repair days.

Kindly check and confirm.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Vimimala D/O Raja Singam

Date: 14 May 2019

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|---------------|
| Vehicle No | : GBF6458T | Accident Date | : 29/04/2019 |
| Make | : TOYOTA HIACE | Policy No. | : 28887001MKC |
| Assignment Date | : 10/05/2019 | Excess | : S\$500.00 |
| Date of Inspection | : 13/05/2019 | Est. Duration of Repair | : 14.00 |
| Inspection At | : KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440 SINGAPORE 408701 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the left side portion.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 26,045.50 |
| Revised Amount | :S\$ | 7,292.50 |
| Check Items (Estimated) | :S\$ | 14,894.00 |
| Total | :S\$ | |

| | | |
|-----------------|------|--------|
| Lump Sum Repair | :S\$ | 17,800 |
|-----------------|------|--------|

Total Loss Consideration

| | | |
|--------------------|------|--------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 56,000 |
| COE / PARF Rebate | :S\$ | 34,732 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

- (X) The vehicle is economical/~~not economical~~ for repair.
- () The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP





MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____ Policy No : _____
 Date : _____ Claim No : _____

Insured Vehicle No : GBF 6458T Date of Accident : 29-04-2019
 TP Vehicle No : - Place of Survey : KAE MOTOR
 Make & Model : Toyota Hiace 3.0m Date of Survey : 13-05-2019

Point of Impact / Damages :
LEFT SIDE

Recommended Reserve :

| | | |
|---------------------|-------------------------|--|
| Repairer's Estimate | : \$ <u>27,870.00</u> - | |
| Interim Adjustment | : \$ <u>7,292.50</u> | |
| Check Items | : \$ <u>14,894.00</u> | |

Proposed : Part by Part / Lump Sum Repair \$17,800.00 Excess : \$ 500/-

Estimate Repair Period : 14 days

Pre-accident Market Value (for total loss consideration) : \$ 56,000/-

COE / PARF to owner : \$ 34,732.00

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

OD Claim
Excess : \$ 500/-
(Authorised / Revert)

TP Claim
(Without Prejudice)

Vehicle No. GBF 6458T

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 14

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 13-05-19

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|-------------------------|
| Owner ID Type: | Company |
| Owner ID: | 6328Z |
| Vehicle Details | |
| Vehicle No.: | GBF6458T |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 06 May 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | HIACE DX 3.0 MANUAL |
| Primary Colour: | White |
| Manufacturing Year: | 2016 |
| Engine No.: | 1KD2623838 |
| Chassis No.: | KDH2015022819 |
| Maximum Power Output: | - |
| Open Market Value: | \$28,643.00 |
| Original Registration Date: | 03 Feb 2017 |
| First Registration Date: | 03 Feb 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$1,433.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 02 Feb 2027 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| PQP Paid: | \$45,000.00 |
| COE Rebate Amount: | \$34,829.00 |
| Total Rebate Amount: | \$34,829.00 |

The information contained herein is correct as at 03 May 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

| Vehicle Details | | | |
|--|---|---------------------|---------------------------|
| Vehicle No.: | GBF6458T | | |
| Vehicle Type: | A50 - Goods (Closed) Van/Van Panel (Delivery) | | |
| Vehicle Attachment 1: | No Attachment | | |
| Vehicle Scheme: | Normal | | |
| Vehicle Make: | TOYOTA | | |
| Vehicle Model: | HIACE DX 3.0 MANUAL | | |
| Chassis No.: | KDH2015022819 | | |
| Propellant: | Diesel | | |
| Engine No.: | 1KD2623838 | | |
| Engine Capacity: | 2982 cc | | |
| Maximum Power Output: | - | | |
| Maximum Laden Weight: | 3225 kg | | |
| Unladen Weight: | 1760 kg | | |
| Year Of Manufacture: | 2016 | | |
| Original Registration Date: | 03 Feb 2017 | | |
| Lifespan Expiry Date: | 02 Feb 2037 | | |
| COE Category: | C - Goods Vehicle & Bus | | |
| PQP Paid: | \$45,000.00 | | |
| COE Expiry Date: | 02 Feb 2027 | | |
| Road Tax Expiry Date: | 02 Feb 2020 | | |
| Inspection Due Date: | 02 Feb 2020 | | |
| Intended Transfer Date: | 05 Sep 2019 | | |
| CO2 Emission: | 180.00 (g/km) | | |
| CEV/VES Rebate Utilised Amount: | - | | |
| CO Emission: | - | | |
| HC Emission: | - | | |
| NOx Emission: | - | | |
| PM Emission: | - | | |
| Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable. | | | |
| Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred. | | | |
| Amount Payable | | | |
| | Amount Before GST (S\$) | GST Amount (S\$) | Amount After GST (S\$) |
| Transfer Fee: | 25.00 | - | 25.00 |
| Total Amount Payable: | | | 25.00 |
| Message | | | |
| This vehicle has a road tax Over Payment of \$2.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable. | | | |

You may print this page for reference.

OK

Print



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

\$17,800.00 *14 days*

Date : 10/05/2019

Attn: The Motor Claims Department
Our Insured veh no : ~~GBG 1745S~~ **GBF 6458T**
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Trekology Bikes 3 Pte Ltd
Blk 3007 Ubi Rd 1
#01-440
Singapore 408701

62942535

tel: 66431391

Dear Sir / Madam

Estimate Cost Repair Bill To VEHICLE NO GBF 6458 T TOYOTA HIACE ON 29/04/2019 AT 15:50

| To Supply:- | | | | | |
|-------------|---|--------|----------|--|-----------------------|
| 1pc | LH Sliding Door / <i>Deformed</i> | | | | 875.00 |
| 1pc | LH Sliding Door Inner Lock / <i>Deformed</i> | | | | 120.00 |
| 1pc | LH Sliding Door Rail / <i>Deformed</i> | | | | 190.00 |
| 1pc | LH Sliding Door Outer Handle / <i>Deformed</i> | | | | 90.00 |
| 2pcs | LH Sliding Door Inner Trim Board / <i>Deformed</i> | 2x680 | (By Air) | | 1,360.00 |
| 10pcs | LH Sliding Door Trim Board Clips / <i>necc</i> | 20x10 | (By Air) | | 200.00 100 |
| 1pc | LH Sliding Door Rubber / <i>Deformed</i> | | | | 165.00 |
| 1pc | LH Sliding Door Top Hinge / <i>Deformed</i> | | | | 75.00 |
| 1pc | LH Sliding Door Centre Hinge / <i>Deformed</i> | | | | 100.00 |
| 1pc | LH Sliding Door Bottom Hinge / <i>Deformed</i> | | | | 135.00 |
| 1pc | LH Body Panel ? / <i>Deformed</i> | | | | 700.00 |
| 1pc | LH Body Panel Inner Panel ? / <i>Deformed</i> | | | | 300.00 |
| 1pc | LH Centre Rocker Panel ? / <i>Deformed</i> | | | | 300.00 |
| 2pcs | LH Body Panel Inner Trim Board ? / <i>Deformed / Torn</i> | 2x580 | (By Air) | | 1,160.00 |
| 20pcs | LH Body Panel Trim Board Clips ? / <i>necc</i> | 20x10 | (By Air) | | 200.00 |
| 1pc | Roof Panel ? <i>repair</i> | | (By Air) | | 2,550.00* |
| 2pcs | Roof Lining ? / <i>Deformed</i> | 2x1150 | (By Air) | | 2,300.00 |
| 1pc | LH Roof Gutter Panel ? <i>repair</i> | | (By Air) | | 510.00 |
| 1pc | Rear LH Wheel Rim / <i>Deformed</i> | | (By Air) | | 240.00 |
| 1pc | Reard LH Tyre / <i>at</i> | | (By Air) | | 150.00 50 |
| 1pc | Rear LH Leaf Spring / <i>Bent</i> | | (By Air) | | 1,440.00 |
| 1pc | Rear LH Half Shaft / <i>Bent</i> | | (By Air) | | 420.00 |
| 1pc | Rear LH Half Shaft Bearing / <i>Bent</i> | | (By Air) | | 75.00 |
| 1pc | Rear Axle / <i>boards</i> | | (By Air) | | 3,060.00 |
| 1set | Body Sticker / <i>necc</i> | | | | 700.00 500 |
| | | | | | 17,415.00 |

To dismanlte & replace damage parts, panel beat where necessary
To putty, apply primer & spray paint on the affecte portion.
To check wiring functions.
To remove uphdstery.

Add 10% 1,741.50
19,156.50
Re-survey 21-05-19 @ 1100hrs.
Victor
2000 1800 3,800.00
1700 1500 3,000.00
~~40 50.00~~
~~20 30.00~~
26,046.50
7% 1,823.50
27,870.00

14 days
13/05/2019 @ 1300 hrs. GST
Victor_Song @ sg.msig-asia.com
87747011
Not Authorised / To Revert

L/S After paint.

14055



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
 TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
 BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 10/05/2019

Attn: The Motor Claims Department

Our Insured veh no : ~~GBG 1745 S~~ **GBF 6458 T**

MSIG Insurance (S) Pte Ltd

4 Shenton Way

#21-01 SGX Centre 2

Singapore 068807

Trekology Bikes 3 Pte Ltd

Blk 3007 Ubi Rd 1

#01-440

Singapore 408701

62942535

Dear Sir / Madam

Estimate Cost Repair Bill To VEHICLE NO GBF 6458 T TOYOTA HIACE ON 29/04/2019 AT 15:50

To Supply:-

| | | | | |
|-------|---|--------|------------|--------------------|
| 1pc | LH Silding Door / Deformed | | | 875.00 |
| 1pc | LH Silding Door Inner Lock / Deformed | | | 120.00 |
| 1pc | LH Silding Door Rail / Deformed | | | 190.00 |
| 1pc | LH Silding Door Outer Handle / Deformed | | | 90.00 |
| 2pcs | LH Silding Door Inner Trim Board / Deformed | 2x680 | (By Air) | 1,360.00 |
| 10pcs | LH Silding Door Trim Board Clips / necc | 20x10 | (By Air) | 200.00 / 100 |
| 1pc | LH Silding Door Rubber / Deformed | | | 165.00 |
| 1pc | LH Silding Door Top Hinge / Deformed | | | 75.00 |
| 1pc | LH Silding Door Centre Hinge / Deformed | | | 100.00 |
| 1pc | LH Silding Door Bottom Hinge ? | | | 135.00 |
| 1pc | Lh Body Panel ? | | | 700.00 |
| 1pc | LH Body Panel Inner Panel ? | | | 300.00 |
| 1pc | LH Centre Rocker Panel ? | | | 300.00 |
| 2pcs | LH Body Panel Inner Trim Board ? | 2x580 | (By Air) | 1,160.00 |
| 20pcs | LH Body Panel Trim Board Clips ? | 20x10 | (By Air) | 200.00 |
| 1pc | Roof Panel ? X | | (By Air) | 2,550.00 |
| 2pcs | Roof Lining ? | 2x1150 | (By Air) | 2,300.00 |
| 1pc | LH Roof Gutter Panel ? X | | (By Air) | 510.00 |
| 1pc | Rear LH Wheel Rim | | (By Air) | 240.00 |
| 1pc | Rear LH Tyre 30/61 | | (By Air) | 150.00 |
| 1pc | Rear LH Leaf Spring | | (By Air) | 1,440.00 |
| 1pc | Rear LH Half Shaft | | (By Air) | 420.00 |
| 1pc | Rear LH Half Shaft Bearing | | (By Air) | 75.00 |
| 1pc | Rear Axle | | (By Air) | 3,060.00 |
| 1set | Body Sticker / necc | | | 700.00 / 500 |
| | | | | 17,415.00 |
| | | Add | 10% | 1,741.50 |
| | | | | 19,156.50 |
| | | | | 7000 1800 3,800.00 |
| | | | | 1700 1500 3,000.00 |
| | | | | 40 60.00 |
| | | | | 20 30.00 |
| | | | | 26,046.50 |
| | | | 7% | 1,823.50 |
| | | | | 27,870.00 |

- To dismanlte & replace damage parts,panel beat where necessary
- To putty,apply primer & spray paint on the affecte portion.
- To check wiring functions.
- To remove uphdstery.

14 days

13/05/2019 @ 1300 hrs. GST

Victor_Seng@sg.msig-asia.com

87707011

Not Authorised / To Revert

L/S After paint.



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
 TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
 BUS. REG. NO: 44223100L GST NO: M90371531Y

01

專業服務：汽車意外保險賠償·拖車·汽車修理及維修服務·打嗎呷·噴漆。
 Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

\$17,800.00

14 days

Date : 10/05/2019

Attn: The Motor Claims Department
 Our Insured veh no : G8G-1743'S GBF 6458T
MSIG Insurance (S) Pte Ltd
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

Trekology Bikes 3 Pte Ltd
 Blk 3007 Ubi Rd 1
 #01-440
 Singapore 408701

8518 8073 Joseph

62942535

tel: 66431391 成豪

Dear Sir / Madam

Estimate Cost Repair Bill To VEHICLE NO GBF 6458 T TOYOTA HIACE ON 29/04/2019 AT 15:50

| To Supply:- | | | | | |
|-------------|--|--------|----------|--|--------------|
| 1pc | LH Sliding Door / Deformed | | | | 875.00 |
| 1pc | LH Sliding Door Inner Lock / Deformed | | | | 120.00 |
| 1pc | LH Sliding Door Rail / Deformed | | | | 190.00 |
| 1pc | LH Sliding Door Outer Handle / Deformed | | | | 90.00 |
| 2pcs | LH Sliding Door Inner Trim Board / Deformed | 2x680 | (By Air) | | 1,360.00 |
| 10pcs | LH Sliding Door Trim Board Clips / necc | 20x10 | (By Air) | | 200.00 / 100 |
| 1pc | LH Sliding Door Rubber / Deformed | | | | 165.00 |
| 1pc | LH Sliding Door Top Hinge / Deformed | | | | 75.00 |
| 1pc | LH Sliding Door Centre Hinge / Deformed | | | | 100.00 |
| 1pc | LH Sliding Door Bottom Hinge / Deformed | | | | 135.00 |
| 1pc | LH Body Panel ? / Deformed | | | | 700.00 |
| 1pc | LH Body Panel Inner Panel ? / Deformed | | | | 300.00 |
| 1pc | LH Centre Rocker Panel ? / Deformed | | | | 300.00 |
| 2pcs | LH Body Panel Inner Trim Board ? / Deformed / Torn | 2x580 | (By Air) | | 1,160.00 |
| 20pcs | LH Body Panel Trim Board Clips ? / necc | 20x10 | (By Air) | | 200.00 |
| 1pc | Roof Panel ? repair | | (By Air) | | 2,550.00 x |
| 2pcs | Roof Lining ? / Deformed | 2x1150 | (By Air) | | 2,300.00 |
| 1pc | LH Roof Gutter Panel ? repair | | (By Air) | | 510.00 |
| 1pc | Rear LH Wheel Rim / Deformed | | (By Air) | | 240.00 |
| 1pc | Rear LH Tyre / 30p | | (By Air) | | 150.00 |
| 1pc | Rear LH Leaf Spring / Bent | | (By Air) | | 1,440.00 |
| 1pc | Rear LH Half Shaft / Bent | | (By Air) | | 420.00 |
| 1pc | Rear LH Half Shaft Bearing / Bent | | (By Air) | | 75.00 |
| 1pc | Rear Axle / Bent | | (By Air) | | 3,060.00 |
| 1set | Body Sticker / necc | | | | 700.00 / 500 |
| | | | | | 17,415.00 |
| | | | | | 1,741.50 |
| | | | | | 19,156.50 |
| | | | | | 3,800.00 |
| | | | | | 3,000.00 |
| | | | | | 400.00 |
| | | | | | 200.00 |
| | | | | | 26,046.50 |
| | | | | | 1,823.50 |
| | | | | | 27,870.00 |

To dismantle & replace damage parts, panel beat where necessary
 To putty, apply primer & spray paint on the affected portion.
 To check wiring functions.
 To remove upholstery.

14 days
 13/05/2019 @ 1300 hrs.

Victor_Seng @ sq.msig-asia.com
 87747011
 Not Authorised / To Revert

L/S After paint.

Add 10%
 Re-summit 21-05-19 @ 1100 hrs.
 2000 + 800 = 3,800.00
 1700 + 1500 = 3,000.00
 400.00
 200.00





凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 27/08/2019

Attn: The Motor Claims Department

Our Insured veh no : GBG 1745 S

Treknology Bikes 3 Pte Ltd

Blk 3007 Ubi Rd 1

#01-440

Singapore 408701

MSIG Insurance (S) Pte Ltd

4 Shenton Way

#21-01 SGX Centre 2

Singapore 068807

Dear Sir / Madam

Final Cost Repair Bill To VEHICLE NO GBF 6458 T TOYOTA HIACE ON 29/04/2019 AT 15:50

To Supply:-

Total Lumpsum As Of Repair Costs Recommended By Surveyor And

Agreed By Ourselves : \$ 15,200.00

Excess \$ 500.00

\$ 14,700.00

GST 7% \$ 1,029.00

\$ 15,729.00



Kai Motor Trading

Blk 3007 Ubi Road 1 #01-440, SG-408701

Telephone : 67474006 Fax : 67437591

E-mail : kaimotor@gmail.com

REG. NO: 44223100L GST Reg No

M90371531Y

Tax Invoice

| | |
|-----------|-----------|
| Date | Invoice # |
| 29/8/2019 | KM045176 |

| |
|------------|
| Invoice To |
| Cash |

| Vehicle No. | Make/Model | Mileage(KM) | PO/WO/RO# | Terms | Rep |
|-------------|--------------|-------------|-----------|-------|-----|
| GBF 6458 T | Toyota Hiace | | | | |

| Quantity | U/M | Description | Unit Price | Amount | Tax |
|----------|-----|--|--------------------|-----------------------|-----|
| | | Cost of Repair Tax collected on sales | 14,700.00 7.00% | 14,700.00 1,029.00 | SR |

| | | |
|---------|------------------|-------------|
| E & O.E | Subtotal | \$14,700.00 |
| | GST @ 7% | \$1,029.00 |
| | Total S\$ | \$15,729.00 |

Customer's Signature / co.
Stamp

For Kai Motor Trading

SATISFACTION CUM DISCHARGE VOUCHER

I/We hereby declare that the repairs to my/our motor vehicle No: GBF 6458T
have been completed by M/s KAI MOTOR TRADING of Block 3007 Ubi Road 1,
#01-440, Singapore 408701 to my/our satisfaction and I/we agree that the payment of the
sum of S\$ 15,729.00 to the repairer for such repairs shall be in full
discharge of my/our claim under Policy No: _____
of M/s MSIG in respect of the damaged
caused to my/our said motor vehicle in the accident which occurred on 29.04.2019



Signature (Insured) :



Name :

Nric No :

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---|---|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 02 May 2019 | | 13 Aug 2019 18:15 Edit Adj Rpt | S\$15,200.00 Edit Estimates | S\$15,200.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|----------------------------------|--|--|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | [Created by insurer] | | | | | | | |
| Insured: | TREKNOLOGY BIKES 3 PTE LTD, Co. Reg. No.: 200206328Z | | | | | | | | |
| Vehicle Reg. No.: | GBF6458T | Date of Loss: | 29/04/2019 15:00 - :59 [26 Months and 26 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | OD / 592068 | Policy/Cover Note No.: | 28887001MKC (Comprehensive) Coverage: 03/02/2019 - 02/02/2020 | | | | | | |
| | | Excess: | S\$500.00 | | | | | | |
| Repairer: | KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440, 408701 Ubi - Tel: | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmla D/O Raja Singam - 65942471] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by SIMON HO LEONG CHUAN] ... [Imm.Advice due 14/08/2019] | | | | | | | | |
| Driver/Custodian: | ABDILLAH BIN BIDIN (52 / Male) , NRIC: S1733488C, Tel: +6594759058 Email: trek1@treknoology3.com | | | | | | | | |
| Adj Asg. Remarks: | As per Jason instruction, re-assigned to LKK to follow-up this case. To revert. To arrange to survey the vehicle at KAI MOTOR TRADING BIK 3007, Ubi Road 1, #01-440, Singapore 408701. No OD estimate yet. To call Ms Kym at Kai Motor Trading at Telephone: 67474006. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | View All Compose Case Mail | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS | | View All Search Tasks Create New Task Complete | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*GBF6458T (592068)
OD
Apr 29 2019 3:00PM
[TREKNOLOGY BIKES 3 PTE LTD]
KAI MOTOR TRADING

| Upload Documents | | | Upload Photos | | | Compose New Letter | | | View | View in Browser | |
|---------------------------|----------------|--|---------------|--|--|--------------------|--|-----------|-------------------------------------|-----------------|-------------------------------------|
| Assessment Reports | | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | National Assessment Centre Services (Bukit Merah) | | | | | | Thumbnail | Print | | |
| 1 | 30/04/19 10:44 | Accident Statement | | | | | | Load HTM | | | |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) | | | | | | Thumbnail | Print | | |
| 1 | 14/05/19 10:22 | Adjuster Immediate Advice | | | | | | Load HTM | | | |
| Photos/Images | | | | | | | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | National Assessment Centre Services (Bukit Merah) | | | | | | Thumbnail | Print | | |
| 1 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 2 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 3 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 4 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 5 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 6 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 7 | 30/04/19 10:33 | Driving License [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 8 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 9 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 10 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 11 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 12 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 13 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 14 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 15 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 16 | 30/04/19 10:33 | Accident Photo [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 17 | 30/04/19 10:34 | Identification Card [Linked Accident Report Documents] | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) | | | | | | Thumbnail | Print | | |
| 1 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 2 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 3 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 4 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 5 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 6 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 7 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 8 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 9 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 10 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 11 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 12 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 13 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 14 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 15 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 16 | 13/05/19 19:31 | SURVEY PHOTO | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No | Finalized On | National Assessment Centre Services (Bukit Merah) | Thumbnail | Print |
| 17 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 13/05/19 19:31 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 07/08/19 10:42 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 07/08/19 10:47 | SURVEY PHOTO | Load JPG | <input checked="" type="checkbox"/> |
| 72 | 07/08/19 10:47 | SURVEY PHOTO | Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|----------------------|----------------|--|------------|-------------------------------------|
| No | Finalized On | National Assessment Centre Services (Bukit Merah) | Thumbnail | Print |
| Documentation | | | | |
| | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 03/05/19 08:12 | PARF/COE rebate details | Load PDF | |
| 2 | 10/05/19 13:33 | Email from Kai Motor Trading to arrange for survey | Load PDF | |
| No | Finalized On | National Assessment Centre Services (Bukit Merah) | Thumbnail | Print |
| 1 | 30/04/19 10:34 | Accident Sketch Plan [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 30/04/19 10:34 | Accident Sketch Plan [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 30/04/19 10:34 | POLICE REPORT [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 30/04/19 10:34 | POLICE REPORT [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 30/04/19 10:34 | POLICE REPORT [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) | Thumbnail | Print |
| 1 | 14/05/19 11:05 | Preliminary Loss Advise | Load PDF | |
| 2 | 14/05/19 16:28 | Email - Repair Instruction | Load PDF | |

Linked Accident Report Documents

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|----------------------|----------------|---|------------|-------------------------------------|
| No | Finalized On | National Assessment Centre Services (Bukit Merah) | Thumbnail | Print |
| 1 | 30/04/19 10:44 | Accident Statement | Load HTM | |
| 2 | 11/05/19 09:33 | Addendum Sheet | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 11/05/19 09:34 | Accident Statement Addm. #1 | Load HTM | |
| Photos/Images | | | | |
| | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | National Assessment Centre Services (Bukit Merah) | Thumbnail | Print |
| 1 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 30/04/19 10:33 | Driving License | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 30/04/19 10:33 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 30/04/19 10:34 | Identification Card | Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | | |
| | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | National Assessment Centre Services (Bukit Merah) | Thumbnail | Print |
| 1 | 30/04/19 10:34 | Accident Sketch Plan | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 30/04/19 10:34 | POLICE REPORT | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 30/04/19 10:34 | POLICE REPORT | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 30/04/19 10:34 | POLICE REPORT | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 11/05/19 09:33 | Accident Sketch Plan | Load JPG | <input checked="" type="checkbox"/> |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CF/MSG19014376/CQF3E2

Date: 16/09/2019

REFERENCE

| | | | |
|-------------------|----------------------------|------------------|-------------|
| Insured/Claimant: | TREKNOLOGY BIKES 3 PTE LTD | Policy No: | 28887001MKC |
| Date of Loss: | 29/04/2019 | Nature of Claim: | OD |
| | | Claim No: | 592068 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|---------------|
| Reg No: | GBF6458T | Engine No: | 1KD2623838 |
| Make & Model: | TOYOTA HIACE, 2.0 (M) | Chassis No: | KDH2015022819 |
| Reg. Date: | 03/02/2017 (Man. Year: 2016) | Odometer: | 106606 km |
| Colour: | White | | |
| Engine Capacity: | 2982 cc | | |
| Market Value/New Car Price: | S\$56,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------|------------------|------------|
| Front Tyre Size: | 195 R15 | Rear Tyre Size: | 195 R15 |
| Front Left Side: | HIFLY 4 mm | Rear Left Side: | HIFLY 4 mm |
| Front Right Side: | HIFLY 4 mm | Rear Right Side: | HIFLY 4 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|------------------|------------------|--------------|
| Parts | 19,156.50 | 15,350.50 | 3,806.00 | 19.87 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,890.00 | 3,760.00 | 3,130.00 | 45.43 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 26,046.50 | 19,110.50 | 6,936.00 | 26.63 |
| Approved Total (Overridden) (S\$) | | 15,200.00 | | |
| - Excess (S\$) | 500.00 | 500.00 | 0.00 | 0.00 |
| (S\$) | 25,546.50 | 14,700.00 | 10,846.50 | 42.46 |
| + GST 7.00/7.00% (S\$) | 1,788.26 | 1,029.00 | 759.26 | 42.46 |
| Nett Amount (S\$) | 27,334.76 | 15,729.00 | 11,605.76 | 42.46 |

INSPECTION

Date of Assignment: 13/08/2019

Date Inspected: 13/05/2019 Inspected At:

KAI MOTOR TRADING (HQ)
BLK 3007 UBI ROAD 1, #01-440
Singapore 408701

Estimated Period of Repair: 14.0 days

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|--|--|
| Reference | | |
| Part Source: | (Last Synchronised: 16 Sep 2019) | |
| Parts: | N/A | TOYOTA HIACE 2.0 (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBF6458T) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|-----------------|------------|-------------|
| 1 | 1 | | *LH SLIDING DOOR (WCP) | Deformed | 875.00 F | *875.00 F |
| 2 | 1 | | *LH SLIDING DOOR INNER LOCK (WCP) | Deformed | 120.00 F | *120.00 F |
| 3 | 1 | | *LH SLIDING DOOR RAIL (WCP) | Deformed | 190.00 F | *190.00 F |
| 4 | 1 | | *LH SLIDING DOOR OUTER HANDLE (WCP) | Deformed | 90.00 F | *90.00 F |
| 5 | 2 | | *LH SLIDING DOOR INNER TRIM BOARD (WCP) | Deformed | 1,360.00 F | *1,360.00 F |
| 6 | 10 | | *LH SLIDING DOOR TRIM BOARD CLIPS (WCP) | Necessary | 200.00 F | *100.00 F |
| 7 | 1 | | *LH SLIDING DOOR RUBBER (WCP) | Deformed | 165.00 F | *165.00 F |
| 8 | 1 | | *LH SLIDING DOOR TOP HINGE (WCP) | Deformed | 75.00 F | *75.00 F |
| 9 | 1 | | *LH SLIDING DOOR CENTRE HINGE (WCP) | Deformed | 100.00 F | *100.00 F |
| 10 | 1 | | *LH SLIDING DOOR BOTTOM HINGE (WCP) | Deformed | 135.00 F | *135.00 F |
| 11 | 1 | | *LH BODY PANEL (WCP) | Deformed | 700.00 F | *700.00 F |
| 12 | 1 | | *LH BODY PANEL INNER PANEL (WCP) | Deformed | 300.00 F | *300.00 F |
| 13 | 1 | | *LH CENTRE ROCKER PANEL (WCP) | Deformed | 300.00 F | *300.00 F |
| 14 | 2 | | *LH BODY PANEL INNER TRIM BOARD (WCP) | Deformed / Torn | 1,160.00 F | *1,160.00 F |
| 15 | 20 | | *LH BODY PANEL TRIM BOARD CLIPS (WCP) | Necessary | 200.00 F | *200.00 F |
| 16 | 1 | | *ROOF PANEL (WCP) | Repair | 2,550.00 F | *- F |
| 17 | 2 | | *ROOF LINING (WCP) | Deformed | 2,300.00 F | *2,300.00 F |
| 18 | 1 | | *LH ROOF GUTTER PANEL (WCP) | Repair | 510.00 F | *- F |
| 19 | 1 | | *REAR LH WHEEL RIM (WCP) | Deformed | 240.00 F | *240.00 F |
| 20 | 1 | | *REAR LH TYRE (WCP) | Bent | 150.00 F | *50.00 F |
| 21 | 1 | | *REAR LH LEAF SPRING (WCP) | Bent | 1,440.00 F | *1,440.00 F |
| 22 | 1 | | *REAR LH HALF SHAFT (WCP) | Bent | 420.00 F | *420.00 F |
| 23 | 1 | | *REAR LH HALF SHAFT BEARING (WCP) | Bent | 75.00 F | *75.00 F |
| 24 | 1 | | *REAR AXLE (WCP) | Grazed | 3,060.00 F | *3,060.00 F |
| 25 | 1 | | *SET BODY STICKER (WCP) | Necessary | 700.00 F | *500.00 F |

F=Franchise part.

| | | |
|-------------------------|------------------|------------------|
| Sub Total (\$\$) | 17,415.00 | 13,955.00 |
|-------------------------|------------------|------------------|

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------|--|------------|-----------|
| | | | | + Margin on L,N Items 10.00/10.00% (S\$) | 1,741.50 | 1,395.50 |
| | | | | Total Parts (S\$) | 19,156.50 | 15,350.50 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO DISMANTLE & REPLACE DAMAGE PARTS, PANEL BEAT WHERE NECESSARY | New | 3,800.00 | 2,000.00 |
| 2 | TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTE PORTION | New | 3,000.00 | 1,700.00 |
| 3 | TO CHECK WIRING FUNCTIONS | New | 60.00 | 40.00 |
| 4 | TO REMOVE UPHOLSTERY | New | 30.00 | 20.00 |
| Gross Labour Cost (\$\$) | | | 6,890.00 | 3,760.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >