

Surveyor:

MARCUS

DOI: 19/08/2019

Date / Time: 19/08/2019

Registered in Merimen: 19/08/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SMK 4994T

Claim No. : 7965611833SG

Name of Insured : HOR SOK JING

Policy No. : 1900087304

Insured Tel No. : HP: +65-97924655

Make / Model :

Excess Sec II : \$\$ D.O.A : 17/08/2019 16:50

Place of Accident : PIE NEAR STEVEN ROAD EXIT

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SJP 348U

INSRS:
WSP: FASTECH
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	SJP 348U - X	SMK 4994T - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List: Handler Typist	
			Notification ltr (if non-pickup)	☐
			After call ltr to OI:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice:	☐
			LTA / GIA :	☒
			Medical Bill:	☐
			PIR:	☐
			Mandate/Reject Instruction:	☐
			LOD	☒
			Payment Breakdown Form:	☐
			Post-Repair Photos:	☐
			Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	\$S	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time: 4/1/2020	Confirm with: Jason
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	29
Repair Cost: (w/hst)	\$S 8774.00	Email:	Call:
Loss of Rental (LOR):	\$S 500.00	(5 days) x \$100	
Loss of Use (LOU):	\$S -	(\$ x days)	
Loss of Income (LOI):	\$S -	(\$ x days)	
LOR only ☒	LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]	
GIA/LTA Search	\$S 2.00		
Medical:	\$S -		
Disbursement:	\$S -	(e.g. Tow/ Independent)	
Legal Cost	\$S -		
Total:	\$S 9276.00	Global Sum \$S:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$S 9276.00	Name 1:	Fastech Auto Pte Ltd
Payee 2: (Strike if N.A.)	\$S	Name 2:	
Payee 3: (Strike if N.A.)	\$S	Name 3:	

COPY SENT
14/01/20201) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: 3320

08/11/13 wef

ASS. REC. BY: MARUS

REF:

A16/

July

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 5JP3484

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 42k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

7710

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction Ref 17636

LTA2484 COE 8-3-2029 hmm 9/13

10/9/19 4/5 @ 8200 confused with Alan
(Red # 12428 / 602)

Veh No:

5JP3484

Yr Regn:

3.09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

mit colt RALLIART

1468

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

203608

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

227A 050 1109

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

17/8/19

D.O.I.

19/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or

Ree 015.6

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

2)

Add Fee:

☐

Site Insp (\$

) S + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

2)

Add Fee:

☐

Site Insp (\$

) S + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

not Authorized
2/5 28200
10dy.
19/8/19

VEHICLE NO: SJP 348U

QTY	PARTICULAR			
1 PCS	REAR WINDSCREEN MOULDING	66.00	net	\$110.00
1 PCS	TAILGATE	1050.00	Body	\$1,205.00
1 PCS	TAILGATE 'COLT' EMBLEM		net	\$38.00
1 PCS	TAILGATE 'PLUS' EMBLEM	35.00	net	\$39.00
1 PCS	TAILGATE 'RALLIART' EMBLEM		net	\$45.00
1 PCS	TAILGATE OUTER PROTECTOR	525.00	net	\$650.00
1 PCS	TAILGATE INNER LOCK		11	\$165.00 X
1 PCS	TAILGATE INNER TRIM BOARD		de/cr	\$245.00
1 PCS	TAILGATE INNER TRIM BOARD CLIPS		net	\$40.00
1 PCS	TAILGATE WEATHERSTRIP		tw	\$191.00
1 PCS	REAR BUMPER SPORT	920	o/s	\$1,280.00
2 PCS	REAR BUMPER SIDE HOLDERS @\$65.00		11	\$130.00 X
2 PCS	REAR BUMPER SIDE GARNISHS @\$105.00		o/s cr	\$210.00 1PC
1 SET	REAR BUMPER CLIPS		net	\$50.00
1 PCS	REAR END PANEL	450	Body	\$605.00
1 PCS	REAR END PANEL TOP GARNISH	215	tw	\$245.00
2 PCS	TAILLAMPS @\$485.00	375	o/s cr	\$970.00 1PC
2 PCS	TAILLAMP HOUSING PANELS @\$188.00		o/s	\$376.00 1PC
1 PCS	REAR FENDER O/S	899	Body	\$919.00
1 PCS	REAR FENDER INNER TRIM BOARD O/S	365	o/s	\$428.00
1 PCS	REAR FENDER WHEEL HOUSING PANEL O/S	910.00	Body	\$965.00
1 PCS	REAR FLOOR PANEL		2	\$945.00 X
1 PCS	REAR FLOOR PANEL TOP BOARD	311.00	o/s	\$420.00
1 PCS	REAR DOOR O/S		2	\$866.00 X
1 PCS	REAR DOOR INNER LOCK O/S		11	\$245.00 X
1 PCS	REAR FENDER OUTER PROTECTOR O/S		11	\$265.00 X
1 PCS	ROOF MOULDING O/S	288.00	net	\$311.00
1 PCS	REAR SHOCK ABSORBER O/S		11	\$365.00 X
1 PCS	REAR WHEEL HUB BEARING O/S		11	\$425.00 X
1 PCS	REAR AXLE		11	\$1,180.00 X
		7311		\$13,928.00
	S.NETT			
1 PCS	REAR WINDSCREEN SEALANT		net	\$50.00 40
1 SET	REAR BUMPER REVERSE SENSOR		Shut	280.00 200
1 PCS	REAR END PANEL SEALANT		net	\$50.00
1 PCS	REAR EXHAUST		Bent	\$1,800.00 LR 1005.1
1 PCS	REAR LICENCE PLATE W/HOLDER		net	\$50.00 X
	LABOUR CHARGES			
	TO CHECK WIRING			\$80.00 30
	TO DISMANTLE & REFIX REVERSE SENSOR			\$80.00 50
	TO DISMANTLE & REFIX REAR WINDSCREEN			\$150.00 120
	TO TRANSFER TAILGATE MECHANISM			\$100.00 60
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY			\$120.00 80
	TO DISMANTLE & REFIX FUEL TANK		11	\$100.00 X

TO Dismantle & Refix rear window screen
 TO DISMANTLE & REFIX REAR UNDERCARRIAGE
 TO DISMANTLE & REFIX REAR EXHAUST
 TO MOUNT VEHICLE ON CAR O-LINER
 TO DISMANTLE & REFIX REAR FENDER GLASS O/S
 TO SPRAY RUST PROOFING
 LABOUR FOR PANEL BEATING & REPLACING PARTS
 TO PUTTY & SPRAY PAINTING

	\$100.00	✓
11	\$280.00	X
	\$100.00	60
11	\$380.00	X
	\$80.00	60
	\$120.00	90
	\$1,500.00	1400
	\$1,480.00	1200
TOTAL	\$20,628.00	

10299.8
 4235

UKK Auto Consultants hence notify
 the Repairer of the following:
 • To ensure adequate spray painting
 • To ensure damaged parts during repairs
 • Parts of car are subject to corrosion
 • The repair work is a "Warranted" work
 • The repair work is approved
 • The repair work must be reviewed and
 approved by the Insurance Company

Approved by Repairer

Signature

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	771D

Vehicle Details

Vehicle No.:	SJP348U
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	COLT RALLIART 1.5 M
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	4G15JS9464
Chassis No.:	Z27A0501109
Maximum Power Output:	113.0 kW (151 bhp)
Open Market Value:	\$18,970.00
Original Registration Date:	09 Mar 2009
First Registration Date:	09 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$12,502.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	08 Mar 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$25,525.00
COE Rebate Amount:	\$24,364.00
Total Rebate Amount:	\$24,364.00

The information contained herein is correct as at 19 Aug 2019

OK



VGLOBAL CAR SALON @ SGCM CARNIVAL 2019
31 Aug - 1 Sept 2019 • 10am - 8pm • BOOTH 1
Downtown East, Tentage next to Carpark B

**LUCKY DRAW**
Winning car for 1000



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an AdAdvertiser LoginWays of Selling

**New 5 Years Coe Renewal Toyota Altis 1.6A**
3.08% p.p.a \$0 Down \$0 Admin
STA Grade B No Major Dmg. 2
Years Warranty. Mhly \$538
GV Credit Pte Ltd StarAd

**HIN LUNG AUTO**
No Bee Concept
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

Browse by Category

Sort by Date Posted20 results/page

5 vehicles

colt

Advanced SearchSubmit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
colt		Any	Any	2009	Any	Any	Any	Available
	Mitsubishi Colt Plus Ralliart Turbo (COE till 04/2024)	\$31,800	\$6,860 /yr	07-Apr-2009	1,468 cc	185,000 km	Sports	Available
Ralliart Version. Well Maintain. Stock Condition. D1 Spec BKK. HKS Turbo Timer. Wear And Tear Been Replaced Recently. Low Deposit...								
Posted: 17-Aug-2019Tags: 2009 Mitsubishi Colt, 2009 mitsubishi colt, Mitsubishi Colt, mitsubishi colt, Mitsubishi, Colt, colt, Used Mitsubishi								
	Mitsubishi Colt Version-R Turbo (New 10-yr COE)	\$49,800	\$4,980 /yr	12-Aug-2009	1,468 cc	-	Sports	Available
Well Maintained, No Repairs Needed. The Only Few Left In Town, Is A Collector Stock Condition. None Dekit Unit,n Is A None Smoker C...								
Posted: 16-Aug-2019Tags: 2009 Mitsubishi Colt, 2009 mitsubishi colt, Mitsubishi Colt, mitsubishi colt, Mitsubishi, Colt, colt, Used Mitsubishi								
	Mitsubishi Colt Plus 1.5A (New 5-yr COE)	\$31,800	\$6,350 /yr	06-Aug-2009	1,499 cc	-	Hatchback	Available
1 Owner, 1 Year In House Warranty, Full Loan Available, 2 x Free Servicing, Warranty Not By 3rd Party Workshop, Price Stated Above Is...								
Carway								
Posted: 05-Aug-2019Tags: 2009 Mitsubishi Colt, 2009 mitsubishi colt, Mitsubishi Colt, mitsubishi colt, Mitsubishi, Colt, colt, Used Mitsubishi								
	Mitsubishi Colt Plus Ralliart Turbo (COE till 04/2024)	\$29,900	\$6,400 /yr	20-Apr-2009	1,468 cc	105,000 km	Sports	Available
Well Maintained Throughout The Years. Powerful Hatchback That Comes With Spacious Boot Space. Call To View! Price Neg!								
Posted: 30-Jul-2019Tags: 2009 Mitsubishi Colt, 2009 mitsubishi colt, Mitsubishi Colt, mitsubishi colt, Mitsubishi, Colt, colt, Used Mitsubishi								
GET YOUR COE RENEWAL LOAN								
Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Mitsubishi Colt Version-R Turbo (New 10-yr COE)	\$49,800	\$4,980 /yr	07-Aug-2009	1,468 cc	140,000 km	Sports	Available
Peace Of Mind Choice! 1 Year Extended Engine And Gear Box Warranty! Attractive Interest Rate Available! Great Criteria, 1 Owner! Low...								
Posted: 28-Jul-2019Tags: 2009 Mitsubishi Colt, 2009 mitsubishi colt, Mitsubishi Colt, mitsubishi colt, Mitsubishi, Colt, colt, Used Mitsubishi								

Save this search criteria, to get email alerts whenever a match is found.

MakeModelPriceDepreciationReg DateEng CapMileageVeh TypeStatus

For old advertisements, view Expired ads Compare

20 results/page

View Received Message

This mail is associated with :

***SJP348U (7965611833SG)
[SMK4994T]**

TP
POH QI YUAN
Aug 17 2019 4:00PM
[HOR SOK JING]
Fastech Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 02/01/2020 16:40 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9276.00) - SJP348U - Claim Handler: Ler, Bernard-JQ

Approved:9276.00:Cost of Repair : \$8,774.00 As per surveyor finalization Loss of Rental : \$500.00 5 days @ S\$ 100/day LTA/ GIA Search Fee : \$2.00
Total : \$9,276.00 *Mandate subject to ATA

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Aug 2019 Edit Reg		19 Aug 2019 00:00 Edit Adj Rpt	S\$8,200.00 Edit Estimates	S\$8,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HOR SOK JING, ID: S8507040A								
Main Claimant:	POH QI YUAN, ID: S8915771D								
Vehicle Reg. No.:	SJP348U	Date of Loss:	17/08/2019 16:00 - :59 [125 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7965611833SG	Policy/Cover Note No.:	1900087304 (Comprehensive) Coverage: 12/04/2019 - 11/04/2020						
Vehicle Reg. No. (Insured):	SMK4994T	Policy No. (Claimant):	DMPC18S010671						
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 28/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (02/01/2020): Alert - Adj Mandate Approved (S\$9276.00) - SJP348U - Claim Handler: Ler, Bernard... - AIG_SG (20/08/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJP348U (7965611833SG)
[SMK4994T]
TP
POH QI YUAN
Aug 17 2019 4:00PM
[HOR SOK JING]
Fastech Auto Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/08/19 17:57	Odometer Reading	1	Load JPG	☒
2	19/08/19 17:57	Chassis Number	1	Load JPG	☒
3	19/08/19 17:57	General View	1	Load JPG	☒
4	19/08/19 17:57	General View	1	Load JPG	☒
5	19/08/19 17:57	General View	1	Load JPG	☒
6	19/08/19 17:57	General View	1	Load JPG	☒
7	19/08/19 17:57	General View	1	Load JPG	☒
8	19/08/19 17:57	General View	1	Load JPG	☒
9	19/08/19 17:57	General View	1	Load JPG	☒
10	19/08/19 17:57	General View	1	Load JPG	☒
11	19/08/19 17:57	General View	1	Load JPG	☒
12	19/08/19 17:57	General View	1	Load JPG	☒
13	19/08/19 17:57	General View	1	Load JPG	☒
14	19/08/19 17:57	General View	1	Load JPG	☒
15	19/08/19 17:57	General View	1	Load JPG	☒
16	19/08/19 17:57	General View	1	Load JPG	☒
17	19/08/19 17:57	General View	1	Load JPG	☒
18	19/08/19 17:57	General View	1	Load JPG	☒
19	19/08/19 17:57	General View	1	Load JPG	☒
20	19/08/19 17:57	General View	1	Load JPG	☒
21	19/08/19 17:57	General View	1	Load JPG	☒
22	19/08/19 17:57	General View	1	Load JPG	☒
23	19/08/19 17:57	General View	1	Load JPG	☒
24	19/08/19 17:57	General View	1	Load JPG	☒
25	19/08/19 17:57	General View	1	Load JPG	☒
26	19/08/19 17:57	General View	1	Load JPG	☒
27	19/08/19 17:57	General View	1	Load JPG	☒
28	19/08/19 17:57	General View	1	Load JPG	☒
29	19/08/19 17:57	General View	1	Load JPG	☒
30	19/08/19 17:57	General View	1	Load JPG	☒
31	19/08/19 17:57	General View	1	Load JPG	☒
32	19/08/19 17:57	General View	1	Load JPG	☒
33	19/08/19 17:57	General View	1	Load JPG	☒
34	19/08/19 17:57	General View	1	Load JPG	☒
35	19/08/19 17:57	General View	1	Load JPG	☒
36	19/08/19 17:57	General View	1	Load JPG	☒
37	19/08/19 17:57	General View	1	Load JPG	☒
38	19/08/19 17:57	General View	1	Load JPG	☒
39	19/08/19 17:57	General View	1	Load JPG	☒
40	19/08/19 17:57	General View	1	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	19/08/19 17:57	General View	 Load JPG	☒
42	19/08/19 17:57	General View	 Load JPG	☒
43	19/08/19 17:57	General View	 Load JPG	☒
44	19/08/19 17:57	General View	 Load JPG	☒
45	19/08/19 17:57	General View	 Load JPG	☒
46	19/08/19 17:57	General View	 Load JPG	☒
47	19/08/19 17:57	General View	 Load JPG	☒
48	19/08/19 17:57	General View	 Load JPG	☒
49	19/08/19 17:57	General View	 Load JPG	☒
50	19/08/19 17:57	General View	 Load JPG	☒
51	19/08/19 17:57	General View	 Load JPG	☒
52	19/08/19 17:57	General View	 Load JPG	☒
53	19/08/19 17:57	General View	 Load JPG	☒
54	19/08/19 17:57	General View	 Load JPG	☒
55	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
56	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
57	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
58	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
59	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
60	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
61	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
62	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
63	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
64	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
65	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
66	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
67	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
68	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
69	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
70	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
71	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
72	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
73	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
74	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
75	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
76	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
77	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
78	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
79	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
80	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
81	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
82	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
83	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
84	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
85	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
86	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
87	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
88	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
89	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
90	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
91	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
92	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
93	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
94	19/08/19 17:58	Reinspection Photo	 Load JPG	☒
95	19/08/19 17:58	Reinspection Photo	 Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
96	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
97	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
98	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
99	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
100	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
101	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
102	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
103	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
104	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
105	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
106	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
107	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
108	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
109	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
110	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
111	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
112	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
113	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
114	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
115	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
116	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
117	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
118	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
119	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
120	19/08/19 17:58	Reinspection Photo	1	Load JPG	☒
121	19/08/19 17:59	Reinspection Photo	1	Load JPG	☒
122	19/08/19 17:59	Reinspection Photo	1	Load JPG	☒
123	19/08/19 17:59	Reinspection Photo	1	Load JPG	☒
124	19/08/19 17:59	Reinspection Photo	1	Load JPG	☒
125	19/08/19 17:59	Reinspection Photo	1	Load JPG	☒
126	19/08/19 17:59	Reinspection Photo	1	Load JPG	☒
127	19/08/19 17:59	Reinspection Photo	1	Load JPG	☒
128	19/08/19 17:59	Reinspection Photo	1	Load JPG	☒
129	19/08/19 17:59	Reinspection Photo	1	Load JPG	☒
130	19/08/19 17:59	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/08/19 13:50	TP GIA REPORT	1	Load PDF	
2	04/12/19 16:25	RENTAL RECEIPT	1	Load PDF	
3	04/12/19 16:25	LOD	1	Load PDF	
4	04/12/19 16:25	GIA SEARCH	1	Load PDF	
5	04/12/19 16:25	LETTER TO OI	1	Load PDF	
6	15/01/20 10:41	WORKSHOP INVOICE	1	Load PDF	
7	15/01/20 10:41	AUTHORISATION TO ACT FORM	1	Load PDF	
8	15/01/20 10:41	Release Voucher	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	20/08/19 17:17	OI GIA REPORT	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMK4994T (Insd veh)	Model:	MITSUBISHI COLT 1.5
	SJP348U (TP veh)		RALLIART VERSION-R (M)
Date of Accident:	17/08/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	22,285.96
Final Repair Cost	:	\$	8,774.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	500.00 5 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	9,276.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 9,276.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

15 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19014393/UDA3Q2

Date: 15/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900087304
Claimant
Vehicle No : SJP348U **Insured Vehicle No :** SMK4994T
Date of Loss: 17/08/2019 **Nature of Claim:** TP **Claim No:** 7965611833SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJP348U
 Make & Model: MITSUBISHI COLT, 1.5 RALLIART VERSION-R (M) Engine No: 4G15JS9464
 Reg. Date: 09/03/2009 (Man. Year: 2008) Chassis No: Z27A0501109
 Colour: White Odometer: 203608 km
 Engine Capacity: 1468 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50R15 Rear Tyre Size: 195/50R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,158.00	6,969.90	9,188.10	56.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,670.00	3,330.00	1,340.00	28.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,828.00	10,299.90	10,528.10	50.55
Approved Total (Overridden) (S\$)		8,200.00		
(S\$)	20,828.00	8,200.00	12,628.00	60.63
+ GST 7.00/7.00% (S\$)	1,457.96	574.00	883.96	60.63
Nett Amount (S\$)	22,285.96	8,774.00	13,511.96	60.63
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,276.00		

INSPECTION

Date of Assignment: 19/08/2019
 Date Inspected: 19/08/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	110.00 F	*66.00 FL
2	1		*TAILGATE	Badly Dented	1,205.00 F	*1,050.00 FL
3	1		*TAILGATE COLT EMBLEM	Necessary	38.00 F	*38.00 FL
4	1		*TAILGATE PLUS EMBLEM	Necessary	39.00 F	*35.00 FL
5	1		*TAILGATE RALLIART EMBLEM	Necessary	45.00 F	*45.00 FL
6	1		*TAILGATE OUTER PROTECTOR	Deformed	650.00 F	*525.00 FL
7	1		*TAILGATE INNER LOCK	Not Necessary	165.00 F	*- FL
8	1		*TAILGATE INNER TRIM BOARD	Deformed/Cracked	245.00 F	*245.00 FL
9	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	40.00 F	*40.00 FL
10	1		*TAILGATE WEATHERSTRIP	Twisted	191.00 F	*191.00 FL
11	1		*REAR BUMPER SPORT	Distorted	1,280.00 F	*920.00 FL
12	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	130.00 F	*- FL
13	1		*REAR BUMPER SIDE GARNISHS	O/s Cracked	210.00 F	*105.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	1		*REAR END PANEL	Badly Dented	605.00 F	*450.00 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	245.00 F	*215.00 FL
17	1		*TAILLAMPS	O/s Cracked	970.00 F	*375.00 FL
18	1		*TAILLAMP HOUSING PANELS	O/s Dented	376.00 F	*188.00 FL
19	1		*REAR FENDER O/S	Badly Dented	919.00 F	*899.00 FL
20	1		*REAR FENDER INNER TRIM BOARD O/S	Distorted	428.00 F	*365.00 FL
21	1		*REAR FENDER WHEEL HOUSING PANEL O/S	Badly Dented	965.00 F	*910.00 FL
22	1		*REAR FLOOR PANEL	Repair	945.00 F	*- FL
23	1		*REAR FLOOR PANEL TOP BOARD	Torn	420.00 F	*311.00 FL
24	1		*REAR DOOR O/S	Repair	866.00 F	*- FL
25	1		*REAR DOOR INNER LOCK O/S	Not Necessary	245.00 F	*- FL
26	1		*REAR FENDER OUTER PROTECTOR O/S	Not Necessary	265.00 F	*- FL
27	1		*ROOF MOULDING O/S	Necessary	311.00 F	*288.00 FL
28	1		*REAR SHOCK ABSORBER O/S	Not Necessary	365.00 F	*- FL
29	1		*REAR WHEEL HUB BEARING O/S	Not Necessary	425.00 F	*- FL
30	1		*REAR AXLE	Not Necessary	1,180.00 F	*- FL
31	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
32	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
34	1		*REAR EXHAUST (LOCAL REPAIR)	Bent	1,800.00 FS	*100.00 FS
35	1		*REAR LICENCE PLATE W/HOLDER	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,158.00	7,701.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	731.10

Total Parts (\$\$)	16,158.00	6,969.90
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REFIX REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	120.00	80.00
6	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
7	TO DISMANTLE & REFIX REAR WINDSCREEN	New	100.00	100.00
8	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	280.00	0.00
9	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
10	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
11	TO DISMANTLE & REFIX REAR FENDER GLASS O/S	New	80.00	60.00
12	TO SPRAY RUST PROOFING	New	120.00	90.00
13	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,500.00	1,480.00
14	TO PUTTY & SPRAY PAINTING	New	1,480.00	1,200.00
Gross Labour Cost (S\$)			4,670.00	3,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >