

INS. CASE OWNER:

Surveyor:

MARCUS

DOI:

ASSIGNMENT

19/08/2019

Date / Time : 19/08/2019

Registered in Merimen: 19/08/2019

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGJ 7870Z

Name of Insured:

Leong Yee Wai

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A : 14/08/2019

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

9871223356SG

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

GW 2288U



INSRS:

WSP: ABWIN SERVICE

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	GW 2288U - X	SGJ 7870Z - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	☐ ☐
			After call ltr to OI:	☒ ☐
			Authorisation To Act:	☒ ☐
			Release Voucher:	☒ ☐
			Final Repair Bill:	☒ ☐
			Car Rental Invoice:	☒ ☐
			Towing Invoice	☐ ☐
			LTA / GIA :	☒ ☐
			Medical Bill:	☐ ☐
			PIR:	☐ ☐
			Mandate/Reject Instruction:	☐ ☐
			LOD	☒ ☐
			Payment Breakdown Form:	☐ ☐
			Post-Repair Photos:	☐ ☐
			Others:	☐ ☐
PRELIMINARY ADVICE	Date/Time:	Sent By:		

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm by:
FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	(days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time: 15/11/19	Confirm with: Shau Kah	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 27		If NO or B 28, Ass. Lia :
Repair Cost: (w/bst)	SS 1605.00			
Loss of Rental (LOR):	SS 600.00	(4 days) x \$150		
Loss of Use (LOU):	SS -	(\$ x days)		
Loss of Income (LOI):	SS -	(\$ x days)		
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	SS 2.00			
Medical:	SS -			
Disbursement:	SS -	(e.g. Tow/ Independent)		
Legal Cost	SS -			
Total:	SS 2207.00	Global Sum SS: 2200.00		
FINAL PAYMENT		Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 2200.00	Name 1:	Abwin Service Pte Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

COPY SENT
20/11/191) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$320

(08/11/13) waf

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 12357 on 8-1-2014

\$1500 (Red \$3069.60 / 671)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS \$

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	473D

Vehicle Details

Vehicle No.:	GW2288U
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL 3SEATER
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1KD1896561
Chassis No.:	JTFAT35Y00K200304
Maximum Power Output:	-
Open Market Value:	\$24,243.00
Original Registration Date:	09 Jan 2009
First Registration Date:	09 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$1,213.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	08 Jan 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$14,086.00
COE Rebate Amount:	\$12,351.00
Total Rebate Amount:	\$12,351.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 19 Aug 2019

OK




DAVANTI
Proven Performance Tyre



31 Aug & 1 Sep 110am - 8pm
Downtown East Carpark B

SEE YOU @ BOOTH 2!



SPARKO @ \$356
FREE 1 Essential Servicing & 1 Grooming (worth \$236 total)
Plus Many Other Benefits!



Follow us

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



3.18% P/A \$0 Down \$0 Admin
STA Grade B No Major Dmg. 2
Years Warranty. Mthly \$488
GV Credit Pte Ltd StarAd



ABWIN ONE-STOP
MULTI-BRAND ALL-AT-ONCE

Browse by Category

Back (1 2 3) Next >

Sort by Date Posted 20 results/page

57 vehicles

dyna

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	dyna		Any	Any	2009	Any	Any	Any	Available
	Toyota	Dyna 150 3.0M (COE till 06/2024)	\$27,388	\$5,640 /yr	26-Jun-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel New 5 Years COE, Free 6 Months Road Tax, Super Low Mileage And Powerful Aircon, Tip Top Condition, Warranty Provided, Price Negoti...									
ABWIN Bus Pte Ltd									
Posted: 19-Aug-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota	Dyna 150 3.0M (COE till 04/2024)	\$25,888	\$5,540 /yr	21-Apr-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel Full Loan Available! 1 Owner! Best Price In Town! Ready Condition! Serviced All Done! Low Fuel Consumption! New Paintwork! New Uph...									
Net Link Partners Pte Ltd									
Posted: 19-Aug-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota	Dyna 150 3.0M (COE till 04/2024)	\$26,800	\$5,730 /yr	21-Apr-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel 100% Loan Available! 3 Days Hand Over! High Trade In Available! Top Condition With All Servicing Done! New Paint! New Cushion! Call...									
Net Link Partners Pte Ltd									
Posted: 19-Aug-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota	Dyna 150 3.0M (COE till 05/2024)	\$32,800	\$6,900 /yr	19-May-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel Class 3 Box Lorry! New 5-Years COE! Cheapest In The Market! No Need Repair! Fast Approval And Delivery! Don'T Wait Before Is Gone!...									
Net Link Partners Pte Ltd									
Posted: 19-Aug-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Toyota	Dyna 150 3.0M (COE till 05/2024)	\$25,800	\$5,410 /yr	27-May-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel 100% Loan! 1 Owner! 3 Days Hand Over! Best Selling Lorry With Box! New Paintwork And Servicing Done! Ready For Immediate Deliver...									
Net Link Partners Pte Ltd									
Posted: 19-Aug-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
Compare	Toyota	Dyna 150 3.0M (COE till 05/2024)	\$26,800	\$5,660 /yr	13-May-2009	2,982 cc	-	Truck	Available

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

LKK Auto Consultants hence notify

the Repairee of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No ill. or modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairee:

Signature:

Date:

ABWIN 論輝
 Service Centre

ESTIMATED COST: HQQ000079

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 19-AUG-2019
 MAKE : TOYOTA
 MODEL : DYNA 150 M
 CHASSIS NO : JTFAT35Y00K200304
 ENGINE NO :
 SERVICE ADVISOR : ABBY LIM
 PAGE : 1 OF 2

GW2288U**IBUILDERS PTE LTD**

45 KALLANG PUDDING
 ROAD
 #10-11, ALPHA BUILDING
 SINGAPORE 349317
 CONTACT NO : 81233113

Not Accepted
1/2 of 3 days
19/8/19
Take the other
exp

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	TAIL LAMP R/H	11 250.70 X	
1	TAIL LAMP L/H	CM 250.70 —	
1	TAIL LAMP BRACKET R/H	AN 75.80 X	
1	TAIL LAMP BRACKET L/H	SL 75.80 —	
1	TAIL GATE LOCK	N 155.60 X	
1	TAILGATE BRACKET	SL 85.60 —	
1	TAILGATE LOCK CATCH	11 95.60 X	
1	STEP END PANEL	SL 350.60 —	
1	REAR NUMBER PLATE BRACKET	N 191.60 X	
1	TOYOTA "DYNA" EMBLEM	CM 35.70 —	
1	EXHAUST PIPE	1/10 492.20 X	
	Rear Stopper AS	MS —	
	Sub Total	2,059.90	0.00

SPECIAL NETT

1	REAR BUMPER REVERSE SENSOR	CM 350.00 2025.00	
1	REAR NUMBER PLATE	SL 50.00 145.00	
	Sub Total	400.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	800.00 500	
1	TO SPRAY PAINT ON AFFECTED AREAS	800.00 450	
1	TO APPLY TUFF COAT ON AFFECTED AREAS	11 150.00 X	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	150.00 50	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REAR TAILGATE COMPONENTS	11 150.00 X	
	Sub Total	2,050.00	0.00

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000079**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

GW2288U
IBUILDERS PTE LTD
45 KALLANG PUDDING
ROAD
#10-11, ALPHA BUILDING
SINGAPORE 349317
CONTACT NO : 81233113

DATE : 19-AUG-2019
MAKE : TOYOTA
MODEL : DYNA 150 M
CHASSIS NO : JTFAT35Y00K200304
ENGINE NO :
SERVICE ADVISOR : ABBY LIM
PAGE : 2 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

SUB-TOTAL	4,509.90	0.00
GST - 7 %	315.69	0.00
TOTAL	4,825.59	0.00

ABWIN SERVICE PTE LTD

Prepared By

PRE-REPAIR INSPECTION REQUEST – GW2288U vs SGJ7870Z (OI) on D.O.A.: 14/08/2019

From: Hor, Yinnul
To: "assignments@ikauto.com", Admin A (admin-a@ikauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divy
Sent: 8/18/2019 11:09:03 AM

Hi,

Please refer to the enclosed request from Abwin Service Pte Ltd.

Claim no : 9871223356SG003
Case Owner : Norsiah Bte Md Noor

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

yinnul.hor@aig.com | [+65 6713 9420](tel:+6567139420)

11:20am @ 10/8/19
Person @ Abby
vehicle in

From: Abby Lim (mailto:abbylim@abwinm9.com)
Sent: Monday, August 19, 2019 11:05 AM
To: Hor, Yinnul
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGJ7870Z AND GW2288U ON 14/08/2019

This message is from an external sender; be cautious with links and attachments.

Hi Yinnul

Please appoint LKK

Warmest regards,

Abby Lim

Claims Department
DID +65 6713 9420

Abwin Service Pte Ltd
T +65 6713 9400 | F +65 6713 9415
No. 8 Kaki Bukit Avenue 4
#07-48 Premier @ Kaki Bukit Gate 2 Singapore 415875

From: Hor, Yinnul (mailto:Yinnul.Hor@aig.com)
Sent: Monday, 19 August, 2019 10:57 AM
To: abbylim@abwinm9.com
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Tong, Wahxin <Wahxin.Tong@aig.com>
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGJ7870Z AND GW2288U ON 14/08/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-08-26 10:57 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul.Hor@aig.com
To: abbylim@abwinm9.com
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariasa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Theerthan.Parthiban@aig.com, Divyashni.Subramaniam@aig.com, Wahain.Tong@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGJ7870Z AND GW2288U ON 14/08/2019
Date: Mon, 19 Aug 2019 02:56:54 +0000
Without Prejudice

Your Reference : GW2288U
Our Reference : 9871223356SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Ning Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hoi Yin Rui (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL (Claims Operations – Auto)

Yinnul.Hor@aig.com | www.aig.as

From: Abby Lim [mailto:abbylim@abwinm9.com]
Sent: Monday, August 19, 2019 10:35 AM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] ACCIDENT INVOLVING GW 2288U AND SGJ7870Z ALONG ENG NEO AVENUE SLIP ROAD TO VANDA ROAD ON 14/08/2019 AT ABOUT 0805 HOURS. OUR REF: GW 2288U

This message is from an external sender; be cautious with links and attachments.

Hi,

We refer to the above accident.

We have been appointed by the owner, **IBUILDERS PTE LTD.**, the registered owner of vehicle no. **GW2288U**.

Kindly arrange your surveyor to attend the Pre-repair inspection within 2 working days.

The said vehicle can be inspected at: **No. 8 Kaki Bukit Avenue 4, #07-48 Premier @ Kaki Bukit Gate 2 Singapore 415875**

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you.

Warmest regards,

Abby Lim
Claims Department
DID +65 6713 9420

Abwin Service Pte Ltd
T +65 6713 9400 | F +65 6713 9415
No. 8 Kaki Bukit Avenue 4
#07-48 Premier @ Kaki Bukit Gate 2 Singapore 415875

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Aug 2019 Edit Reg		19 Aug 2019 00:00 Edit Adj Rpt	S\$1,500.00 Edit Estimates	S\$1,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LEONG YEE WAI , ID: S8032038H								
Main Claimant:	IBUILDERS PTE LTD , Co. Reg. No.: 200509473D								
Vehicle Reg. No.:	GW2288U	Date of Loss:	14/08/2019 00:00 - :59 [127 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9871223356SG	Policy/Cover Note No.:	2100213578 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGJ7870Z	Policy No. (Claimant):	5106671037						
	Excess:								
Repairer:	Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2, 415875 Kaki Bukit - Tel: 6713 9400								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 28/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (31/10/2019): Alert - Adj Mandate Approved (S\$2327.00) - GW2288U - Claim Handler: MdNoor, Nors... - AIG_SG (20/08/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GW2288U (9871223356SG)
[SGJ7870Z]

TP
IBUILDERS PTE LTD
Aug 14 2019 12:00AM
[LEONG YEE WAI]
Abwin Service Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Letters/Correspondences			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit
Assessment Reports			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	25/10/19 17:28	Adjuster Immediate Advice	1	Load HTM
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	19/08/19 18:03	Chassis Number	1	Load JPG ☒
2	19/08/19 18:03	Odometer Reading	1	Load JPG ☒
3	19/08/19 18:03	General View	1	Load JPG ☒
4	19/08/19 18:03	General View	1	Load JPG ☒
5	19/08/19 18:03	General View	1	Load JPG ☒
6	19/08/19 18:03	General View	1	Load JPG ☒
7	19/08/19 18:03	General View	1	Load JPG ☒
8	19/08/19 18:03	General View	1	Load JPG ☒
9	19/08/19 18:03	General View	1	Load JPG ☒
10	19/08/19 18:03	General View	1	Load JPG ☒
11	19/08/19 18:03	General View	1	Load JPG ☒
12	19/08/19 18:03	General View	1	Load JPG ☒
13	19/08/19 18:03	General View	1	Load JPG ☒
14	19/08/19 18:03	General View	1	Load JPG ☒
15	19/08/19 18:03	General View	1	Load JPG ☒
16	19/08/19 18:03	General View	1	Load JPG ☒
17	19/08/19 18:03	General View	1	Load JPG ☒
18	19/08/19 18:03	General View	1	Load JPG ☒
19	19/08/19 18:03	General View	1	Load JPG ☒
20	19/08/19 18:03	General View	1	Load JPG ☒
21	19/08/19 18:03	General View	1	Load JPG ☒
22	19/08/19 18:03	General View	1	Load JPG ☒
23	19/08/19 18:03	General View	1	Load JPG ☒
24	19/08/19 18:03	General View	1	Load JPG ☒
25	19/08/19 18:03	General View	1	Load JPG ☒
26	19/08/19 18:03	General View	1	Load JPG ☒
27	19/08/19 18:03	General View	1	Load JPG ☒
28	19/08/19 18:03	General View	1	Load JPG ☒
29	19/08/19 18:03	General View	1	Load JPG ☒
30	19/08/19 18:03	General View	1	Load JPG ☒
31	19/08/19 18:03	General View	1	Load JPG ☒
32	19/08/19 18:03	General View	1	Load JPG ☒
33	19/08/19 18:03	General View	1	Load JPG ☒
34	19/08/19 18:03	General View	1	Load JPG ☒
35	19/08/19 18:03	General View	1	Load JPG ☒
36	19/08/19 18:03	General View	1	Load JPG ☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
37	19/08/19 18:03	General View		Load JPG	☒
38	28/08/19 08:45	After Repair Photo		Load JPG	☒
39	28/08/19 08:45	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/08/19 14:16	EMAIL FROM AIG DD 19.08.2019		Load PDF	
2	19/08/19 14:16	ACKNOWLEDGEMENT EMAIL TO AIG DD 19.08.2019		Load PDF	
3	23/08/19 10:29	TP ESTIMATE - MARKED		Load PDF	
4	23/08/19 10:29	TP GIA REPORT		Load PDF	
5	25/10/19 17:20	GIA SEARCH FEE		Load PDF	
6	25/10/19 17:20	LOD		Load PDF	
7	25/10/19 17:20	RENTAL RECEIPT		Load PDF	
8	25/10/19 17:20	TP_ESTIMATE_MARKED_(FINAL)		Load PDF	
9	27/11/19 09:30	WORKSHOP INVOICE		Load PDF	
10	27/11/19 09:30	AUTHORISATION TO ACT FORM		Load PDF	
11	27/11/19 09:30	Release Voucher		Load PDF	
12	27/11/19 09:30	LETTER TO OI		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	20/08/19 16:57	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGJ7870Z (Insd veh)	Model:	TOYOTA DYNA 150
	GW2288U (TP veh)		MANUAL 3SEATER 3.0 D
Date of Accident:	14/08/2019		(M)

Global Sum Settlement	: ☒ [X] Yes	: ☐ [] No	
Repair Estimate	: \$		5,037.91
Final Repair Cost	: \$		2,200.00
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$		4 days
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (Global Sum)	: \$		2,200.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Abwin Service Pte Ltd	: \$	2,200.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

27 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19014396/UDA3Q2

Date: 27/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100213578
 Claimant: GW2288U Insured Vehicle No: SGJ7870Z
 Vehicle No: Date of Loss: 14/08/2019 Nature of Claim: TP Claim No: 9871223356SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GW2288U
 Make & Model: TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M) Engine No: 1KD1896561
 Reg. Date: 09/01/2009 (Man. Year: 2008) Chassis No: JTFAT35Y00K200304
 Colour: Silver Odometer: 280553 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12 (D)
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6/6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,658.33	916.85	1,741.48	65.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,000.00	1,050.00	51.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,708.33	1,916.85	2,791.48	59.29
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	4,708.33	1,500.00	3,208.33	68.14
+ GST 7.00/7.00% (S\$)	329.58	105.00	224.58	68.14
Nett Amount (S\$)	5,037.91	1,605.00	3,432.91	68.14
+ Car Rental (4.0 x S\$150.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,207.00		
Global Sum Settlement (S\$)		2,200.00		

INSPECTION

Date of Assignment: 19/08/2019
 Date Inspected: 19/08/2019 Inspected At:

Abwin Service Pte Ltd (HQ)
 No. 8 Kaki Bukit Avenue 4, #07-48
 Premier@Kaki Bukit Gate 2
 Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP R/H	Not Necessary	250.70 F	*- FL
2	1		*TAIL LAMP L/H	Cracked	250.70 F	*250.70 FL
3	1		*TAIL LAMP BRACKET R/H	Not Necessary	75.80 F	*- FL
4	1		*TAIL LAMP BRACKET L/H	Bent	214.53 F	*214.53 FL
5	1		*TAIL GATE LOCK	Repair	155.60 F	*- FL
6	1		*TAILGATE BRACKET	Bent	85.60 F	*85.60 FL
7	1		*TAILGATE LOCK CATCH	Not Necessary	95.60 F	*- FL
8	1		*STEP END PANEL	Bent	350.60 F	*350.60 FL
9	1		*REAR NUMBER PLATE BRACKET	Repair	191.60 F	*- FL
10	1		*TOYOTA DYNA EMBLEM	Necessary	35.70 F	*35.70 FL
11	1		*TAIL GATE STOPPER	Not Necessary	59.70 F	*- FL
12	1		*EXHAUST PIPE (DENTED)	Not Consistent With The Impact	492.20 F	*- FL
13	1		*REAR BUMPER REVERSE SENSOR	Cracked	350.00 FS	*200.00 FS
14	1		*REAR NUMBER PLATE	Scratched	50.00 FS	*14.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,658.33	1,151.13
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	234.28
Total Parts (S\$)	2,658.33	916.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGE AREAS	New	800.00	500.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	800.00	450.00
3	TO APPLY TUFF COAT ON AFFECTED AREAS	New	150.00	0.00
4	TO DISMANTLE ,REPLACE AND /OR REPAIR REVERSE SENSOR & TESTING	New	150.00	50.00
5	TO DISMANTLE ,REPLACE AND /OR REPAIR REAR TAILGATE COMPONENTS	New	150.00	0.00
Gross Labour Cost (S\$)			2,050.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >