

ASS. REC. BY:

REF: CS/SMO19014392/Avf302

Special Instruction:

Surveyor

Adrian

## ASSIGNMENT (Office)

From (Person):

Ruth Chua Cel Tiang

of

SMO

Date/Time:

19.8.19 13:58 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGQ 7479H

Insured:

FBP 13082

at Workshop m/s

Kang Car Repairer

Tel:

67477636

of

NO 1 Kaki Bukit Ave 6 #02-06

Policy No:

D19MTR 0100039

Claim No:

CM121403921

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15.8.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

19.8.19 2:13 PM

Person Contacted:

Sharon

H.O.D. Endorsement:

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SGQ 7479H - NBA / ALG 1901305317

ROA - 09/09/2019

FBP 13082 - x

22/8/19

Informed Ruth pending workshop est by merimen

26/11/19

Adrian confirmed LS \$3550 (Red 2852.72, 4419)

27/11/19

Send preli revised via merimen

ASS. REQ. BY:

REF:

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: 56Q7979H Yr Regn: 2018 / Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle cc 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading 113854 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 6P71119195

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.L. 21/08/19

Survey held at Kany

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rees O/S, O/S.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sample

RECEIVED 27 NOV 2019

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1) 27/11 - TP sample

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

250

11

261

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607199R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Ruth Chua Gek Tiang	Date: 27 Nov 2019

**Preliminary Advice**

Insured Vehicle No	: FBP1308Z		
TP Vehicle No	: SGQ7979H	Accident Date	: 15/08/2019
Make	: HONDA SHUTTLE HYBRID	Assignment Date	: 19/08/2019
Date of Inspection	: 21/8/2019	Est. Duration of Repair	: 6
Inspection At	: KANG CAR REPAIRERS PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,402.72
Revised Amount	:S\$	3,550.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,550.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

<input type="checkbox"/>	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
<input type="checkbox"/>	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
<input checked="" type="checkbox"/>	Other comments : The above survey was conducted on a 'Without Prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2019		19 Aug 2019 13:38 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KWONG XIANG YAO(KUANG XIANGYAO), ID: S8815506H		
Main Claimant:	CHIN TONG SENG, ID: S25516241		
Vehicle Reg. No.:	SGQ7979H	Date of Loss:	15/08/2019 09:00 - :59
Claim Type:	TP / CMTD1903921	Policy/Cover Note No.:	D19MTMC01001039 (Comprehensive)
Vehicle Reg. No. (Insured):	FBP1308Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Kang Car Repairers Pte Ltd (HQ) NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT, 17883 Kaki Bukit - Tel: 6747 7636 / 6747 3005		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/08/2019]		
Adj Asg. Remarks:	WS: SHARON 6747 7636		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Sent Message

This mail is associated with :

**\*SGQ7979H (CMTD1903921)  
[FBP1308Z]**

TP  
CHIN TONG SENG  
Aug 15 2019 9:00AM  
[KWONG XIANG YAO(KUANG XIANGYAO)]  
Kang Car Repairers Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 22/08/2019 09:05 AM.  
**To** ruth.chua@sompo.com.sg  
**Subject** TP SURVEY SGQ 7979H

Dear Ruth,

Please be informed that we have inspected the vehicle SGQ 7979H on 21/8/19. We are pending estimate from repairer.

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.

**Veron Chen (LKKAUTO)**

---

**From:** kangcar@singnet.com.sg  
**Sent:** Wednesday, 21 August 2019 5:29 PM  
**To:** Chua, Gek Tiang Ruth  
**Cc:** Kang Car (yahoo); Ye, Yong Kang Melvin; Henry, Irene James; Teo, Grace; Admin A  
**Subject:** Re: CMTD1903921/RUC - FBP1308Z & SGQ7979H ACC ON 15.08.2019

WITHOUT PREJUDICE

Dear Ruth,

Our client's vehicle was surveyed by LKK Auto Consultants on 21.08.2019.

We would like to proceed for Direct Settlement and kindly advise if your insured reported the accident and the liability.

Kindly revert.

Thank you & Regards,  
Sharon  
Kang Car Repairers Pte Ltd  
Tel: 6747 7636  
Fax: 6748 5071

On Mon Aug 19 2019 12:46:17 GMT+0800 (Singapore Standard Time) <kangcar@singnet.com.sg> wrote:

----- Original Message -----

WITHOUT PREJUDICE

Dear Sirs,

Please appoint LKK Auto Consultants, Marcus Chua to conduct the pre-repair survey on our client's vehicle.

Thank you & Regards,  
Sharon  
Kang Car Repairers Pte Ltd  
Tel: 6747 7636  
Fax: 6748 5071

On Mon Aug 19 2019 09:52:45 GMT+0800 (Singapore Standard Time) Teo, Grace  
<grace.teo@sompo.com.sg> wrote:

----- Original Message -----

Our Reference: CMTD1903921/RUC

Your Reference: SGQ7979H

Without Prejudice

Date: 19/08/2019

EMAIL ONLY

Attention:

M/S KANG CAR REPAIRERS PTE LTD

Dear Sharon,

ACCIDENT INVOLVING FBP1308Z & SGQ7979H 15.08.2019

We refer to your Notice of Accident dated 16/08/2019.



Please be informed that **Ms. Ruth Chua** is the handler of this case who can be contacted at 63295 153.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	

2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

**D**  
: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

☐ Do not remove this box. It is used for tracking the status of the document.

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](http://www.facebook.com/SompoSG)

**Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG**

Download now @



or



<sup>1</sup>

For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:**

This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:**

kangcar@singnet.com.sg [mailto:kangcar@singnet.com.sg]

**Sent:** Friday, August 16, 2019 2:56 PM

**To:** Claims - Motor Survey

**Cc:** Kang Car (yahoo); Henry, Irene James; Claims - Motor Survey

**Subject:** NOTICE TO INSPECT OUR CLIENT'S VEHICLE SGQ7979H; ACCDT INVLG SGQ7979H & FBP1308Z ON 15.08.2019

WITHOUT PREJUDICE

Dear Sirs,

Our client's motor vehicle no: SGQ7979H, which was damaged as a result of the above accident, is now lying at our premises/workshop, awaiting for repairs to be carried out.

As you are the insurers of motor vehicle FBP1308Z, we hereby give you NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR VEHICLE at our premises/workshop. If your representative/surveyor does not inspect our client's damaged motor vehicle within the next two(2) days, we shall proceed to repair our client's damaged motor vehicle without any further notice and our client will thereafter look to you/your insured for the repair costs. This is without prejudice to our client's claim for damages, loss of use and incidental loss.

We enclosed herewith our estimate cost of repairs and our client's accident report for your reference.

Kindly forward us a list of your panel surveyors for our consideration.

Thank you & Regards,

Sharon

Kang Car Repairers Pte Ltd

Tel: 6747 7636

Fax: 6748 5071

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST 201300201N

M/S : SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#05-01/06 SINGAPORE LAND TOWER  
SINGAPORE 048623

TEL: 64616555 FAX: 62213147  
ATTN: Motor Claim Department

Claim Type: Third Party  
Accident Date: 15/08/2019  
TP Veh Reg No: FBP1308Z

Estimate No: EST1900248  
Date: 16 Aug 2019

Veh Reg No: SGQ7979H  
Make/Model: HONDA SHUTTLE 1.5  
HYBRID AT  
Chasis No: GP71119195  
Reg. Date: 14/02/2019  
Your Ref No: FBP1308Z

*Vagon*

## Estimate Repair Cost to Vehicle No :SGQ7979H

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	<b>List Price</b>		
1	1 PC REAR BUMPER <i>Dehd</i>	1,260.80	<del>1,260.80</del> 1150.
2	1 PC REAR BUMPER SIDE RETAINER RH <i>seen</i>	66.70	✓
3	1 PC REAR BUMPER REFLECTOR - RH <i>seen</i>	76.10	✓
4	1 PC REAR BUMPER REFLECTOR COVER RH <i>seen</i>	81.60	✓
5	1 PC REAR BUMPER SPONGE - RH <i>seen</i>	88.40	✓
6	1 PC TAIL LAMP - RH <i>at</i>	580.50	✓
7	1 PC BOOT LID LAMP RH <i>seen</i>	380.70	✓
8	1 PC HYBRID LOGO <i>seen</i>	80.10	✓
9	1 PC SHUTTLE LOGO <i>seen</i>	76.50	✓
10	1 PC FRT DOOR RH <i>Dented</i>	887.10	✓
11	1 PC FRT DOOR OUTER HANDLE RH <i>seen</i>	108.00	✓
12	1 PC FRT DOOR SIDE MIRROR RH <i>Damaged</i>	566.90	✓
		4,253.40	
		3407.80 Less 20%	
		2726.24	
	<b>Special Net</b>		
13	1 SET REVERSE SENSORS <i>seen</i>	250.00	✓
		250.00	250.00
	<b>Labour</b>		
14	1 TO CHECK WIRING	50.00	30.
15	1 TO REMOVE AND REFIX DOOR GLASS	100.00	80
16	1 TO SPRAY UNDERSEAL	100.00	✓
17	1 TO REMOVE AND REFIT INNER TRIM	100.00	40.
18	1 TO SPRAY PAINTING	1,400.00	900
19	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	650
		2,750.00	2,750.00

*\**



# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST: 201300201N

M/S : SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#05-01/06 SINGAPORE LAND TOWER  
SINGAPORE 048623

TEL: 64616555 FAX: 62213147  
ATTN: Motor Claim Department

Claim Type: Third Party  
Accident Date: 15/08/2019  
TP Veh Reg No: FBP1308Z

Estimate No: EST1900248  
Date: 16 Aug 2019

Veh Reg No: SGQ7979H  
Make/Model: HONDA SHUTTLE 1.5  
HYBRID AT  
Chasis No: GP71119195  
Reg. Date: 14/02/2019  
Your Ref No: FBP1308Z

## Estimate Repair Cost to Vehicle No :SGQ7979H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 6,402.72
	Add GST @ 7%		448.19
	Total Amount Payable		<u>S\$ 6,850.91</u>

TOTAL: SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED FIFTY AND CENTS NINETY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

  
AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Adrian Hg  
h/s 21/08/19.  
05 Aug  
Total: 6826.24  
h/s: 3550  
3550

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19014398/AVF3N2

Date: 28/11/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTMC01001039
Claimant Vehicle No :	SGQ7979H	Insured Vehicle No :	FBP1308Z
Date of Loss:	15/08/2019	Nature of Claim:	TP
		Claim No:	CMTD1903921

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGQ7979H	Engine No:	LEB6323535
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71119195
Reg. Date:	14/02/2018 (Man. Year: 2017)	Odometer:	113884 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,652.72	2,726.24	926.48	25.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,700.00	1,050.00	38.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,402.72</b>	<b>4,426.24</b>	<b>1,976.48</b>	<b>30.87</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,550.00</b>		
<b>(\$\$)</b>	6,402.72	3,550.00	2,852.72	44.55
<b>+ GST 7.00/7.00% (\$\$)</b>	448.19	248.50	199.69	44.55
<b>Nett Amount (\$\$)</b>	<b>6,850.91</b>	<b>3,798.50</b>	<b>3,052.41</b>	<b>44.55</b>

## INSPECTION

Date of Assignment:	19/08/2019	
Date Inspected:	21/08/2019	Inspected At:
		Kang Car Repairers Pte Ltd (HQ)
		NO.1 KAKI BUKIT AVE 6 #02-06
		AUTOBAY @ KAKI BUKIT
		Singapore 17883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 28 Nov 2019)	
<b>Parts:</b>	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGQ7979H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,260.80 FL	*1,150.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Necessary	66.70 FL	*66.70 FL
3	1		*REAR BUMPER REFLECTOR-RH	Not Necessary	76.10 FL	*- FL
4	1		*REAR BUMPER REFLECTOR COVER RH	Not Necessary	81.60 FL	*- FL
5	1		*REAR BUMPER SPONGE-RH	Not Necessary	88.40 FL	*- FL
6	1		*TAIL LAMP-RH	Cut	580.50 FL	*580.50 FL
7	1		*BOOT LID LAMP RH	Not Necessary	380.70 FL	*- FL
8	1		*HYBRID LOGO	Necessary	80.10 FL	*80.10 FL
9	1		*SHUTTLE LOGO	Necessary	76.50 FL	*76.50 FL
10	1		*FRT DOOR RH	Dented	887.10 FL	*887.10 FL
11	1		*FRT DOOR OUTER HANDLE RH	Not Necessary	108.00 FL	*- FL
12	1		*FRT DOOR SIDE MIRROR RH	Damaged	566.90 FL	*566.90 FL
13	1		*SET REVERSE SENSORS	Not Necessary	250.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,503.40</b>	<b>3,407.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	850.68	681.56
<b>Total Parts (\$\$)</b>	<b>3,652.72</b>	<b>2,726.24</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIX DOOR GLASS	New	100.00	80.00
3	TO SPRAY UNDERSEAL	New	100.00	0.00
4	TO RMEOVE AND REFIT INNER TRIM	New	100.00	40.00
5	TO SPRAY PAINTING	New	1,400.00	900.00
6	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS.AND FOR CUTTING/WELDING WORKS	New	1,000.00	650.00
<b>Gross Labour Cost (S\$)</b>			<b>2,750.00</b>	<b>1,700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >