

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0736/2019/KK
Date : 11-Jun-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no. : **SJM 1008 K**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tran Quan
Address : 36 Wilby Road
#10-24
Singapore 276308
Telephone : (HP) +65 96696926
Type of Claim : Own Damage Claims
Policy No. : 1700083569-02
Vehicle No : **SJM 1008 K**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Nov-22
Engine No : CVN 045345
Chassis No : WAUZZZF45JA023388
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 31-May-19
Place of Accident : The Tessarina Condo Carpark

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJM 1008 K

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlight, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00 750	
3	To respray front bumper.	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 2,852.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJM 1008 K

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,946.00	de ✓
2	FRONT BUMPER FIXING PARTS	\$ 258.00	?
3	FRONT BUMPER GRILLE - CENTER	\$ 178.00	X
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	\$ 191.00	X
5	FRONT BUMPER AIR GUIDE - RH	\$ 56.00	?
6	RADIATOR GRILLE	\$ 1,053.00	cus ✓
7	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 123.00	?
8	FRONT BUMPER CARRIER	\$ 733.00	?
9	FOAM FILLER PIECE	\$ 113.00	?
10	FRONT BUMPER COVER	\$ 116.00	X
11	FRONT BUMPER GUIDE SECTION - RH	\$ 34.00	X
12	SIGN "COUTION"	\$ 13.00	X
13	AIR CONDITIONER STICKER	\$ 7.00	X
14	FRONT BUMPER BRACKET LOCK CARRIER	\$ 125.00	?
15	FRONT BUMPER BRACKET - LH	\$ 26.00	?
16	FRONT BUMPER BRACKET - RH	\$ 26.00	?
17	FRONT LOW TONE HORN FANFARE - RH	\$ 262.00	?
18	FRONT HORN MOUNT BRACKET - RH	\$ 26.00	?
19	LED HEADLIGHT - RH	\$ 7,087.00	?
20	LIFT CYLINDER - RH	\$ 192.00	?
SUB-TOTAL SPARE PARTS		\$ 12,565.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SJM 1008 K

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	RADIATOR AIR GUIDE OUTER - RH	\$ 33.00	?
22	RADIATOR AIR GUIDE INNER - RH	\$ 46.00	?
23	FRONT NO PLATE	\$ 40.00	X
24	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 12,984.00	
TOTAL LABOUR CHARGES		: \$ 2,852.00	
GRAND TOTAL		: \$ 15,836.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Taufik 97495749
Surveyed Date : 14/2/19 @ 1045
Authorised Date : Repair, Not Authorise
Excess Cost : Ex: to be advise
Liability : Resurvey before paint
Remarks : sure the auto-wm.
03 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant