

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SAJAC05D2BFR973²⁰

CHOO KIM LIAN
28 CEYLON ROAD
#05-03
S 429621

TRAILER
Ashes

Date :29.08.2019
Vehicle No :SLT 2313 L
Make/Model :JAGUAR XF
Accident date :14.08.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>new</i>	1	\$ 1300 156
2	Rear RH fender <i>Distorted</i>	1	\$ 5310 4537
3	Rear RH fender inner shield <i>torn</i>	1	\$ 437
4	Rear RH fender inner shield clips (1 set) <i>new</i>	1	\$ 66 30
5	Rear RH door <i>Distorted</i>	1	\$ 4050 3090
6	Rear RH door glass outer moulding <i>Bent</i>	1	\$ 462
7	Rear RH door outer handle <i>Repis</i>	1	\$ 361 x
8	Rear RH door inner rubber <i>new</i>	1	\$ 266
9	Rear RH door inner top rubber	1	\$ 85.5 x
10	Rear RH door inner top rubber garnish	1	\$ 171 x
11	Rear RH door inner board <i>cracked</i>	1	\$ 2850 2116
12	Rear RH door power window motor	1	\$ 551
13	Rear RH door power window regulator	1	\$ 551
14	Rear RH door top hinge	1	\$ 104.5 x
15	Rear RH door lower hinge	1	\$ 104.5 x
16	Rear RH door stopper	1	\$ 66.5 x
17	Rear RH door inner speaker	1	\$ 85 x
18	Rear RH door glass frame	1	\$ 361 x
19	RH rocker panel <i>outer Garnish. deformed</i>	1	\$ 1482
20	Front RH door <i>Repis</i>	1	\$ 3870 x
21	Rear RH lower arm	1	\$ 532 x
22	Rear RH knuckle arm	1	\$ 988 x
23	Rear RH knuckle arm bearing	1	\$ 123.5 x
24	Rear RH shock absorber	1	\$ 494 x
Total			\$ 24120.5

Special Nett Items

- 1 Rear RH sport rim *at*
2 Rear RH tyre *new*

1	\$ 1500
1	\$ 550
Total	\$ 2050

1200

13127
11814.30

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

CHOO KIM LIAN
28 CEYLON ROAD
#05-03
S 429621

Date :29.08.2019
Vehicle No :SLT 2313 L
Make/Model :JAGUAR XF
Accident date :14.08.2019

No	DESCRIPTION	Qty	Amount (\$S)
<u>Labour Cost</u>			
1	To check wheel alignment		\$ 100 ⁸⁰
2	To supply rear windscreen sealant		\$ 50 ✓
3	Remove & reinstall rear windscreen		\$ 150 ¹²⁰
4	Remove & reinstall roof lining + cushion		\$ 250 ¹⁰⁰
5	Remove & reinstall door glass ^{things}		\$ 200 ¹⁰⁰
6	Remove & reinstall rear RH suspension	2110	\$ 450 ^x
7	Remove, replace & repair consistent to the accident		\$ 1800 ⁸⁰⁰
8	Respray painting		\$ 1600 ⁸⁰⁰
9	Tuff kote		\$ 150 ⁶⁰
Total			\$ 4750
Grand Total			\$ 30920.5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 15114.30

H/s : 11K (Nett Value).

09 days

11K 90m