

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference:
Repairer Reference: 013549
Date calculated: 27/11/2019 8:23 PM

Full Report
Registration: SLN155X
Printed: 27/11/2019 8:23 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AIG Asia Pacific Insurance Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:		Date of Incident:	08/08/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: TOYOTA
Model: PRIUS IV
Sub Model: BASE MODEL
Model Sheet Number: 70 P5 01
Registration: SLN155X
VIN number:
Odometer:

Model Specs

TWO COAT METALLIC


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All
Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
B410	R + R REAR BUMPER		5.0	25.00
NO NUMBER	R + R REAR BUMPER COVER		1.0	5.00
Labour Cost			Hrs	WU
Panel / Mechanical Labour			0.60	6.0
Total of Labour				30.00

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	
				WU	Price SGD
2587	REAR COVER BUMPER	52453 47010			582.60
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				582.60
u: Used parts	Subtotal Discount(+30.00%)				-174.78
Total					407.82

Final Calculation

	SGD	SGD
Parts		
Total Discount(+30.00%)	582.60	
	-174.78	
Total Parts		407.82
Labour Time Base 10 WU/h		
Total 6.0 WU X 50.00 SGD/h	30.00	
Total of Labour		30.00
Repair Cost Excludes GST		437.82
GST (+7.0%)		30.65
Repair Cost Included GST		468.47

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.